Autel®

# MX-Sensor_V6.10 Function List For JP Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New,Yellow: Modify)

Special Declaration:

1).If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2).All the Automatic Relearn Procedure for MX-Sensor,the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Acura | NSX | 2017/01-2020/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Audi | A8 | 2010/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Audi | A8 | 2002/10-2009/10 | 433Mhz | 4E | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Audi | Q7 | 2017/01-2017/12 | 433MHz | 4L/AU726 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Audi | R8 | 2007/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Audi | RS6 | 2013/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Audi | RS7 | 2013/01-2018/12 | 315MHz | | ● | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Audi | S8 | 2010/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Audi | S8 | 2002/10-2009/10 | 433MHz | D3 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2010/07-2020/06 | 433MHz | F20/F21/F40 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 1 Series | 2014/03-2018/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 1 Series | 2010/09-2014/02 | 433MHz | E88/E82 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2006/12-2010/08 | 433MHz | E88/E82 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2014/01-2019/12 | 433Mhz | F22/F23/F45 /F46 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 3 Series | 1999/03-2011/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 2018/12-2019/12 | 315Mhz | G20 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 3 Series | 2006/01-2009/08 | 433MHz | E9x | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 1999/01-2005/12 | 433MHz | E46 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2018/12-2020/06 | 433Mhz | G20 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2009/09-2010/09 | 433MHz | E9x | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2014/01-2019/12 | 433Mhz | F31/F35 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 3 Series | 2018/06-2019/06 | 315Mhz | G02 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 3 Series GT | 2014/03-2019/12 | 433MHz | F34 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 4 Series | 2014/03-2020/06 | F32/F33/F36 433MHz | F32/F33/F36 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | 5 Series | 2017/01-2019/12 | 433Mhz | G30/G31/G38 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | 5 Series | 2014/03-2017/12 | 433MHz | F10/F11 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2017/01-2019/12 | 315Mhz | G30/G31/G38 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 5 Series | 2001/01-2006/12 | 433MHz | E65 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2006/03-2010/08 | 433MHz | E60/E61/F07 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 1998/09-2003/07 | 433MHz | E39 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2010/09-2015/02 | 433MHz | F10/F11/F07 /F18 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 2014/04-2018/12 | 433MHz | F07 LCI | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 5 Series GT | 2017/01-2019/12 | 315Mhz | G32 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 5 Series GT | 2017/01-2019/12 | 433Mhz | G32 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BMW | 5 Series GT | 2017/01-2018/12 | 315Mhz | | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 6 Series | 2016/09-2020/06 | 433Mhz G14/G32 | G14/G32 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | 6 Series | 2006/01-2009/12 | 433MHz | E63/E64 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2016/09-2019/12 | 315Mhz | G14/G32 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 6 Series | 2014/03-2019/12 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2010/01-2014/02 | 433MHz | F12/F13/F06 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 1998/09-2005/12 | 433MHz | E38 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2015/06-2020/06 | 433Mhz | G11/G12 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | 7 Series | 2010/09-2014/02 | 433MHz | F01/F02/F03 /F04 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2006/01-2010/08 | 433MHz | E65/E66 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2015/06-2019/12 | 315Mhz | G11/G12 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | 7 Series | 2014/03-2015/05 | 433MHz | F01/F02/F03 /F04 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 8 Series | 2017/10-2020/06 | 433Mhz | G15 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | 8 Series | 2017/10-2019/12 | 315Mhz | G15 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | M3 | 2014/01-2018/12 | 433Mhz | F80 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | M4 | 2014/04-2019/12 | 433Mhz | F82/F83 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | M5 | 2014/03-2017/12 | 433MHz | F10 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M6 | 2014/03-2018/12 | 433MHz | F12 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | M7 | 2014/03-2017/12 | 433MHz | F01 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | Motorcycle | 2010/01-2019/12 | 433MHz | | ○ | ● | ○ | C | 433Mhz | Schrader | ● | ● |
| BMW | X1 | 2008/09-2014/02 | 433MHz | E84 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X1 | 2015/08-2019/12 | 433MHz | F48 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X1 | 2014/03-2015/09 | 433MHz | E84 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X2 | 2016/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X3 | 2017/01-2020/06 | G01/G08 433MHz | | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | X3 | 2010/11-2014/03 | 433MHz | F25 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X3 | 2014/04-2017/12 | 433Mhz | F25 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X3 | 2017/01-2019/12 | 315Mhz | | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | X3 | 2003/03-2010/10 | 433MHz | E83 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X4 | 2017/03-2020/06 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | X4 | 2013/05-2019/12 | 433MHz | F26 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X4 | 2017/03-2019/12 | 315Mhz | G02 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | X5 | 2010/10-2013/06 | 433MHz | E70 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X5 | 2013/05-2019/12 | 433Mhz | F15/F85 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X5 | 2006/11-2010/09 | 433MHz | E70 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X5 | 1999/10-2006/10 | 433MHz | E53 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X6 | 2014/08-2019/12 | 433MHz | F16/F86 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | X6 | 2011/12-2014/07 | 433MHz | E71 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X6 | 2007/12-2011/11 | 433MHz | E71 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X6 HYBRID | 2012/07-2019/12 | 433MHz | | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | X7 | 2019/06-2019/12 | 315Mhz | G02 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | X7 | 2018/01-2019/12 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BMW | Z4 | 2006/03-2010/08 | 433MHz | E86/E89 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| BMW | Z4 | 2019/03-2020/06 | 433Mhz | G02 | ● | ● | ○ | A | 433Mhz | Schrader | ● | ● |
| BMW | Z4 | 2019/03-2019/12 | 315Mhz | G02 | ● | ● | ○ | A | 315Mhz | Schrader | ● | ● |
| BMW | Z4 | 2010/09-2014/02 | 433MHz | E89/E71 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | Z4 | 2014/03-2019/02 | 433MHz | E89 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| BMW | i3 | 2013/01-2019/12 | 433Mhz | I01/I12 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| BMW | i8 | 2013/01-2019/12 | 433MHz | I01/I12 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Cadillac | CT6 | 2019/01-2020/06 | 433MHz 13516165 | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | CT6 | 2019/01-2020/06 | 315MHz | | ● | ● | ● | O/S | 315Mhz | Schrader | ● | ● |
| Cadillac | CT6 | 2016/01-2018/12 | 315Mhz | | ● | ● | ● | O/S | 315Mhz | Schrader | ● | ● |
| Cadillac | CT6 | 2016/01-2019/12 | 433Mhz 13598773 | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XT5 | 2018/01-2020/06 | 315MHz 13516164 | | ● | ● | ● | O/S | 315Mhz | Schrader | ● | ● |
| Cadillac | XT5 | 2016/01-2018/12 | 433Mhz 13598773 | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Cadillac | XT5 | 2018/01-2020/06 | 433MHz 13516165 | | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Camaro | 2017/01-2020/06 | 433MHz | 1AG37/ A1BC | ● | ● | ● | O/S | 433Mhz | Schrader | ● | ● |
| Chevrolet | Corvette | 2006/01-2017/12 | 315MHz | GMX245 | ● | ● | ○ | O/S | 315Mhz | Schrader | ● | ● |
| Daihatsu | ACTIS | 2017/01-2017/12 | 315Mhz | | ○ | ● | ○ | C | 315MHz | Pacific | ● | ● |
| Ferrari | 458 Italia | 2011/01-2013/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 2014/01-2016/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | 488 | 2015/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 2017/01-2017/12 | 315MHz | | ○ | ● | ○ | C | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | California | 2008/10-2013/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 2012/10-2016/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 2016/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | FF | 2011/01-2019/06 | 315MHz | F151 | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 2016/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 2017/01-2017/12 | 315MHz | | ○ | ● | ○ | C | 315Mhz | Huf/Beru | ● | ● |
| Ford | Explorer | 2016/01-2016/12 | 315MHz | U502 | ● | ● | ○ | O/S | 315Mhz | Schrader | ● | ● |
| Ford | Explorer | 2011/01-2011/12 | 315MHz | U502 | ● | ● | ● | S | 315Mhz | Schrader | ● | ● |
| Ford | Explorer | 2012/01-2012/12 | 315MHz | U502 | ● | ● | ● | S | 315Mhz | Schrader | ● | ● |
| Ford | Explorer | 2013/01-2015/09 | 315MHz | U502 | ● | ● | ● | S | 315Mhz | Schrader | ● | ● |
| Honda | Legend Hybrid | 2015/01-2017/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | TRW | ● | ● |
| Honda | NSX | 2016/01-2019/12 | Direct 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 2007/05-2014/03 | 433MHz | FD/Fde | ● | ● | ○ | O | 433Mhz | Continental | ● | ● |
| Lexus | GS Series | 2012/04-2019/12 | 315Mhz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | GS Series | 2006/01-2010/12 | 315Mhz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | IS Series | 2013/04-2019/12 | PMV-C010 315MHz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | LC Series | 2017/01-2017/12 | 315Mhz | Z100 | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 2017/10-2019/12 | 315Mhz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | LS Series | 2012/09-2017/09 | 315Mhz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Lexus | LS Series | 2006/08-2011/12 | 315MHz | XF40 | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | LX Series | 2015/09-2019/12 | 315Mhz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 2014/01-2019/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | RC Series | 2014/01-2019/12 | 315Mhz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | RX Series | 2015/10-2019/12 | 315MHZ | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 2013/07-2015/9 | 315MHz Japan | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Lexus | SC Series | 2006/08-2010/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Maserati | Ghibli | 2013/01-2020/09 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Maserati | Levante | 2016/01-2020/06 | 433MHz | M161 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Maserati | Quattroporte | 2013/01-2020/06 | 433MHz | M156 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Maybach | Landaulet | 2008/10-2014/12 | 433MHz | Ma009-127 | ● | ● | ○ | O/S | 433Mhz | Huf/Beru | ● | ● |
| Maybach | Landaulet | 2018/01-2019/12 | 433Mhz | | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Maybach | Maybach 57 | 2002/02-2013/12 | 433Mhz | Ma007 | ● | ● | ○ | O/S | 433Mhz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 2002/02-2013/12 | 433Mhz | Ma007 | ● | ● | ○ | O/S | 433Mhz | Huf/Beru | ● | ● |
| Maybach | S Series | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Mazda | CX-5 | 2012/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| McLaren | 500 Series | 2015/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | 570GT | 2016/01-2018/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 2014/01-2018/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| McLaren | 675LT | 2015/01-2018/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 2017/01-2019/12 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 2012/01-2014/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| McLaren | P1 | 2013/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Huf/Beru | ● | ● |
| McLaren | Senna | 2017/01-2019/12 | 433Mhz | | ○ | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2018/06-2019/12 | 433Mhz | W177 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2014/04-2018/05 | 433Mhz | W176 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | A Class | 2012/01-2014/03 | 433MHz | W176 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | AMG | 2010/01-2019/12 | 433MHz | W197 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | AMG GT | 2018/11-2019/12 | X290 | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2014/01-2020/06 | C190 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | AMG GT | 2018/11-2019/12 | X290 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | B Class | 2011/11-2019/01 | W246/W242 433MHz | W246 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | B Class | 2019/02-2020/06 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | C Class | 2007/04-2014/02 | 433MHz | W204/W203 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | C Class | 2018/06-2020/06 | 433MHz | W205 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | C Class | 2014/03-2018/05 | 433MHz | W205 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CL Class | 1998/01-2006/02 | 433MHz | C215 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 2009/06-2019/06 | 433MHz | C216/C217 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLA Class | 2012/12-2014/05 | 433MHz | C117 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLA Class | 2014/06-2019/04 | 433MHz | C117 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLC Class | 2008/01-2018/06 | 433MHz | CL203 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLK Class | 2007/04-2018/06 | 433MHz | W209/W207 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLS Class | 2009/07-2017/12 | 433MHz | W218 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | CLS Class | 2005/01-2009/06 | 433MHz | W219 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Mercedes | CLS Class | 2004/10-2004/12 | 433MHz | W219 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 2018/01-2019/12 | C257 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2018/01-2020/06 | C257 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Citan | 2012/09-2020/06 | 433MHz | W415 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Citan | 2017/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class | 2016/01-2019/12 | SCH 315Mhz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | E Class | 2015/11-2019/12 | W213/BR238 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class | 2014/06-2018/12 | W212 433MHz | W212 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class | 2014/01-2015/10 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class | 2002/01-2005/05 | 433MHz | W211 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | E Class | 2005/06-2009/06 | 433MHz | W211 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | E Class | 2009/07-2014/05 | 433MHz | W212 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | E Class AMG | 1999/07-2002/03 | 433MHz | W210 | ● | ● | ○ | O/S | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | G Class | 2018/01-2019/12 | 315Mhz | G463/461 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 2007/04-2018/05 | 433MHz | 463 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | G Class | 2018/06-2020/06 | 433Mhz | G463/461 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GL Class | 2013/01-2019/06 | 433MHz | X166 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GL Class | 2009/06-2012/12 | 433MHz | X164 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GL Class | 2006/04-2009/09 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | GLA Class | 2019/08-2020/03 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLA Class | 2014/06-2019/07 | 433MHz | X156 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLB Class | 2019/01-2020/06 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 2015/01-2019/07 | 433MHz | X253 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLE Class | 2015/09-2019/11 | 433MHz | X166 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLE Class | 2019/01-2020/06 | 433Mhz | V167 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | GLK Class | 2015/10-2019/06 | 433MHz | X253 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLK Class | 2008/01-2015/09 | 433MHz | X204 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLS Class | 2013/01-2019/06 | X166 433MHz | X164 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | GLT | 2017/06-2019/12 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Pacific | ● | ● |
| Mercedes | GT-S AMG | 2014/01-2019/12 | 433MHz | C190 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | M Class | 2010/01-2014/12 | 433MHz | W166 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | M Class | 2005/01-2011/05 | 433Mhz | W164 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | ML Class | 2011/06-2019/12 | 433MHz | W166 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | ML Class | 2009/08-2011/05 | 433MHz | W164 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | ML Class | 2005/07-2009/07 | 433MHz | W164 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | Marco Polo | 2014/01-2019/12 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Metris | 2015/01-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | R Class | 2005/06-2009/07 | 433MHz | W251 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | R Class | 2009/08-2018/06 | 433MHz | W251 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class | 2009/06-2013/06 | 433MHz | W221 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class | 1999/07-2005/09 | 433MHz | W220 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | S Class | 2005/10-2009/05 | 433MHz | W221 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | S Class | 2013/07-2019/07 | 433MHz | W222 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | S Class coupe | 1999/07-2002/12 | 433MHz | C215 | ● | ● | ○ | O/S | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 2003/01-2005/09 | 433MHz | C215 | ● | ● | ○ | O/S | 433Mhz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Mercedes | SL Class | 2005/05-2011/12 | 433Mhz | W230 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | SL Class | 2012/01-2020/06 | 433Mhz | W231 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SL Class | 2012/07-2019/12 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SL Class | 2000/01-2005/04 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SL Roadster | 2001/08-2005/06 | 433MHz | R230 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SLC Class | 2016/01-2019/07 | 433MHz | R172 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SLK Class | 2007/04-2019/05 | 433MHz | R171,R172 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | SLR Class | 2004/04-2015/12 | 433MHz | R199 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 2004/01-2011/12 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 2010/01-2019/06 | 433MHz | 197 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Sprinter | 2011/11-2020/06 | 433MHz | 906(NVC3) | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Sprinter | 2018/01-2020/06 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | Sprinter | 2006/06-2011/10 | 433MHz | W906 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 2018/10-2019/12 | 433Mhz | 906 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mercedes | Sprinter Combi | 2011/11-2018/09 | 433MHz | 906 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Sprinter Combi | 2006/01-2011/10 | 433MHz | 906 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | V Class | 2014/01-2019/12 | 433Mhz | W447 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vario | 2014/03-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vario | 2012/12-2013/12 | 433MHz | | ● | ● | ○ | O/S | 433Mhz | Schrader | ● | ● |
| Mercedes | Viano | 2014/06-2019/06 | SCH 433Mhz | W639 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Viano | 2003/07-2014/05 | Continental 433MHz | W639 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | Vito | 2014/07-2020/06 | 433MHz | W640 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Mercedes | Vito | 2003/05-2014/06 | 433MHz | W639 | ● | ● | ○ | O/A | 433Mhz | Continental | ● | ● |
| Mercedes | X Class | 2017/01-2019/12 | 433Mhz | | ● | ● | ○ | O | 433Mhz | Pacific | ● | ● |
| Mini | All | 2007/08-2013/10 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Cabrio | 2016/01-2019/12 | F57 433MHz | F57 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Cabrio | 2014/07-2015/12 | R57 433MHz | R57 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Clubman | 2009/09-2013/10 | 433MHz | R55 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Clubman | 2013/11-2019/12 | 433Mhz | F54 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Clubman | 2007/08-2009/08 | 433MHz | R55 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Clubvan | 2016/01-2019/12 | 433MHz | F54 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Clubvan | 2012/07-2015/12 | 433MHz | R55 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Cooper | 2015/06-2019/12 | F55,F56 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Cooper | 2014/03-2015/05 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Cooper | 2007/09-2009/09 | 433MHz | R58 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Cooper S Cabrio | 2014/07-2017/12 | 433MHz | R57 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Countryman | 2015/07-2020/06 | 433Mhz | F60 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Countryman | 2014/07-2018/12 | 433Mhz | R60 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Coupe | 2011/07-2018/06 | 433MHz | R58 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Hatchback | 2013/11-2019/12 | 433Mhz | F56 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Mini | 2014/03-2019/12 | 433MHz | F55/F56 | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Mini | 2010/01-2013/12 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | One | 2014/03-2019/12 | 433MHz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Mini | Paceman | 2018/07-2019/12 | 433Mhz | | ● | ● | ○ | A | 433Mhz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel(MX-Sensor) | Support by Autel(Tool) |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Mini | Paceman | 2014/07-2018/06 | 433Mhz | R61 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Roadster | 2014/05-2019/12 | 433Mhz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | Roadster | 2011/12-2014/12 | 433MHz | R59 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mini | SAV Studie | 2014/07-2014/12 | 433MHz | R58 | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |
| Mitsubishi | Proudia | 2012/01-2016/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | Continental | ● | ● |
| Nissan | Cima | 2017/01-2019/06 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Nissan | Cima | 2012/01-2016/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Nissan | Elgrand | 2010/01-2017/12 | 315MHz | E52 | ● | ● | ○ | O | 315Mhz | Pacific | ● | ● |
| Nissan | Fuga | 2015/01-2018/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | Continental | ● | ● |
| Nissan | GT-R | 2013/01-2019/12 | 315MHz | R35 | ● | ● | ○ | O | 315Mhz | Schrader | ● | ● |
| Nissan | GT-R | 2007/01-2012/12 | 315Mhz | | ● | ● | ○ | C | 315MHz | Schrader | ● | ● |
| Nissan | Skyline | 2014/01-2018/12 | 315MHz | | ● | ● | ○ | O | 315Mhz | Continental | ● | ● |
| Porsche | 911 | 2013/01-2016/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Porsche | 911 | 2012/02-2016/12 | 433MHz | 991 | ● | ● | ○ | A | 433Mhz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 2011/12-2019/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Porsche | Boxster | 2012/01-2018/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2010/09-2016/12 | 315MHz | 92A | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Porsche | Cayman | 2012/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 2014/01-2015/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 2009/01-2017/12 | 315MHz | | ● | ● | ○ | O/A | 315Mhz | Huf/Beru | ● | ● |
| Smart | Forfour | 2005/01-2020/06 | 433Mhz | A453 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Smart | Fortwo | 2014/03-2020/06 | 433MHz | A452 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Smart | Fortwo | 2007/01-2014/02 | 433MHz | A451 | ● | ● | ○ | O/A | 433Mhz | Schrader | ● | ● |
| Tesla | Model S | 2014/09-2020/08 | 433MHz | | ○ | ● | ○ | A | 433Mhz | Continental | ● | ● |
| Tesla | Model S | 2008/01-2014/12 | 315MHz | | ○ | ● | ○ | A | 315Mhz | Continental | ● | ● |
| Toyota | Camry | 2014/09-2019/12 | C015 315Mhz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 2014/09-2017/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Pacific | ● | ● |
| Toyota | Crown | 2013/09-2019/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2015/10-2019/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2017/10-2019/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Pacific | ● | ● |
| Volkswagen | Touareg | 2011/01-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433Mhz | Huf/Beru | ● | ● |