



MX-Sensor_V1.50 Function List For JP Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Acura | NSX | 2016/06-2020/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Alfa Romeo | 159 | 2005/07-2016/12 | 433MHz | 939 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | 4C | 2013/01-2021/12 | 433MHz | 960/961 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Giulia | 2017/07-2023/12 | 315MHz 50554748 | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 2010/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Tonale | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B3 | 2006/03-2009/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 2014/03-2019/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B3 | 2009/09-2014/03 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 2022/07-2024/06 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | B4 | 2014/03-2020/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B4 | 2020/09-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B5 | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B5 | 2014/03-2016/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B5 | 2005/01-2014/12 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B5 | 2010/02-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B6 | 2006/03-2010/11 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B6 | 2014/03-2018/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B6 | 2010/12-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 2015/07-2022/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B7 | 2015/07-2022/07 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | B7 | 2006/01-2010/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 2010/09-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B8 | 2021/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D3 | 2005/06-2009/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 2009/09-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D4 | 2014/03-2020/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D4 | 2020/09-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D5 | 2010/02-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D5 | 2014/03-2016/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Alpina | D5 | 2017/01-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D5 | 2011/09-2014/12 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XB7 | 2020/01-2022/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XB7 | 2022/07-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | XB7 | 2020/01-2022/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | XB7 | 2022/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 2010/09-2014/02 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 2010/09-2014/03 | 433MHz | F25 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 2017/08-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XD3 | 2017/08-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | XD3 | 2014/04-2017/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD4 | 2018/09-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XD4 | 2018/01-2024/06 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Aston Martin | DB11 | 2017/01-2019/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Aston Martin | DB9 | 2010/01-2015/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 2008/01-2008/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 2011/01-2019/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 2013/01-2018/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 | 2019/01-2023/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A7 | 2019/01-2023/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A8 | 2002/10-2012/12 | 433MHz | 4E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 2003/01-2023/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q2 | 2017/01-2023/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 2016/01-2023/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 2017/01-2017/12 | 433MHz | 4L/AU726 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 2007/01-2015/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | R8 | 2007/01-2022/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS Q3 | 2018/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 2019/01-2020/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 2013/01-2018/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 2013/01-2018/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 2010/01-2017/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 2002/10-2009/10 | 433MHz | D3 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2019/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2019/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2014/01-2024/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 1 Series | 2007/01-2010/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2010/09-2013/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 2014/03-2018/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 2 Series | 2019/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2019/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2012/11-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 2014/03-2024/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 3 Series | 2014/03-2022/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 2010/10-2014/03 | 433MHz | F30/F31/F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2009/09-2013/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2005/01-2009/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 1999/03-2013/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 2019/03-2024/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 3 Series | 2019/03-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2019/03-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 1998/01-2003/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 2019/03-2024/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 3 Series | 1999/01-2002/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 2013/07-2021/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 4 Series | 2020/07-2024/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 4 Series | 2020/07-2024/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 4 Series | 2020/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2014/03-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2010/09-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2023/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2016/11-2024/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 5 Series | 2016/11-2024/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 2023/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 1998/08-2004/05 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 2003/05-2013/12 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2003/08-2012/10 | 433MHz | E63/E64 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2011/01-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 2014/04-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 2017/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 6 Series GT | 2017/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 2014/03-2015/05 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2015/06-2022/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 7 Series | 2006/01-2010/08 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2022/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2022/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2015/06-2022/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 2002/01-2005/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 2010/09-2014/02 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 1998/09-2005/12 | 433MHz | E38 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 8 Series | 2018/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 8 Series | 2018/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | M2 | 2014/11-2021/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M2 | 2022/12-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M2 | 2022/12-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M3 | 2020/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M3 | 2014/01-2019/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 2020/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M4 | 2014/03-2021/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M4 | 2021/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M4 | 2021/07-2024/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M5 | 2010/09-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 2014/03-2017/12 | 433MHz 36106874830 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 2011/06-2015/12 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 2014/03-2018/12 | 433MHz | F12 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M7 | 2014/03-2017/12 | 433MHz | F01 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Motorcycle | 2010/01-2019/12 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |
| BMW | X1 | 2022/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2022/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2015/08-2023/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X1 | 2014/03-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 2008/09-2014/02 | 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X2 | 2023/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X2 | 2023/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X2 | 2016/01-2023/12 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 2003/03-2011/07 | 433MHz | E83 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 2014/04-2017/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 2010/11-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 2017/01-2024/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X3 | 2017/01-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X4 | 2018/04-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X4 | 2018/04-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X4 | 2013/05-2018/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 2014/01-2018/12 | 433MHz 36106790054 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2023/04-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 1999/10-2007/09 | 433MHz | E53 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2023/04-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X5 | 2018/08-2023/03 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X5 | 2018/08-2023/03 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 2015/01-2018/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X5 | 2010/10-2013/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | X5 | 2006/11-2010/09 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2023/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2023/01-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2019/08-2023/12 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X6 | 2014/08-2019/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 | 2010/10-2014/07 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 2019/08-2023/12 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X6 | 2007/12-2010/09 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X7 | 2022/08-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X7 | 2022/08-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X7 | 2018/12-2022/07 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X7 | 2018/12-2022/07 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | XM | 2022/12-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | XM | 2022/12-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2018/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2014/03-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2002/10-2011/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2006/01-2014/02 | 433MHz 36106790054 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 2018/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i3 | 2013/01-2022/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i3 | 2022/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i4 | 2021/01-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i4 | 2021/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i5 | 2023/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i5 | 2023/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i7 | 2022/07-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i7 | 2022/07-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i8 | 2013/01-2022/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | iX | 2021/01-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX | 2021/01-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 2022/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 2022/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX2 | 2023/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX2 | 2023/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX3 | 2017/08-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | iX3 | 2017/08-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BYD | ATTO 3 | 2021/12-2024/12 | 433MHz SC3609200 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | ATTO 3 | 2022/02-2024/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| BYD | Dolphin | 2022/12-2024/12 | 433MHz Right-hand drive | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | Dolphin | 2021/08-2024/12 | 433MHz SC3609200B | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|-----------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Dolphin | 2021/08-2024/12 | 433MHz SC3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Dolphin | 2021/08-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Seal | 2022/07-2024/12 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | Seal | 2022/07-2024/12 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Bentley | Continental GT | 2009/01-2014/01 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 2011/01-2015/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 2005/01-2010/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 2012/01-2012/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Cadillac | ATS | 2016/01-2019/06 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 2013/01-2013/12 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 2013/01-2015/12 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 2015/01-2015/12 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 2015/01-2017/12 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 2018/01-2019/12 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 2016/01-2017/12 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 2014/01-2014/12 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 2018/01-2020/12 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT5 | 2022/01-2023/12 | 433MHz Snap in | | ● | ● | ○ | 0/S/A | 433MHz | BaoLong | ● | ● |
| Cadillac | CT5 | 2023/01-2024/12 | 433MHz 13549707 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | CT5 | 2023/01-2023/12 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 2019/01-2023/12 | 433MHz 13530661 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 2020/01-2023/12 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT6 | 2016/01-2018/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT6 | 2019/01-2020/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT6 | 2019/01-2022/12 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 2016/01-2021/12 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2009/01-2009/12 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2009/01-2009/12 | 433MHz | GMX206/GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2008/01-2008/12 | 433MHz | GMX206/GMX226 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2007/10-2008/12 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2007/01-2007/09 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2006/01-2007/12 | 433MHz | GMX322 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|--------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | CTS | 2014/01-2014/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2014/01-2014/12 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2014/01-2015/12 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2013/06-2013/12 | 433MHz | A1LL | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2014/01-2015/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2016/01-2019/12 | 315MHz 13598786 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2016/01-2019/12 | 433MHz 13598787 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2016/01-2021/12 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2004/01-2005/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2006/01-2006/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2014/01-2014/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2009/01-2009/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2013/01-2013/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2012/01-2012/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2012/01-2012/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2010/01-2013/12 | 433MHz | GMX206/ GMX226 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 2010/01-2011/12 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2013/01-2013/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2010/01-2011/12 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 2009/01-2012/12 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | DTS | 2008/01-2008/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2009/01-2013/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2007/01-2007/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 2006/01-2006/12 | 315MHz 25920615 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2020/01-2020/12 | 433MHz 13540603 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2021/01-2023/12 | 433MHz 13530661 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2021/01-2021/12 | 433MHz 13528563 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2021/01-2021/12 | 433MHz 13540603 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 2020/01-2020/12 | 433MHz 13528563 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | Lyriq | 2022/06-2023/12 | 433MHz 13530661 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Cadillac | Lyriq | 2024/01-2024/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------|-----------------|--------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | Lyriq | 2022/06-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| Cadillac | SRX | 2014/01-2015/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 2003/08-2011/02 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 2024/01-2024/12 | 433MHz 13549707 | | ● | ● | ○ | O/S | 433MHz | BHSENS | ● | ● |
| Cadillac | XT4 | 2021/01-2023/12 | 315MHz 13512346 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 2021/01-2023/12 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 2020/01-2021/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 2018/11-2022/12 | 433MHz | E2UL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 2018/01-2020/06 | 315MHz 13516164 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT5 | 2018/01-2022/12 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 2020/01-2024/12 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 2016/01-2021/06 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 2021/01-2023/06 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT6 | 2019/01-2022/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 2019/01-2023/12 | 315MHz 13516164 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT6 | 2020/01-2024/12 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2013/01-2013/12 | 315MHz 12768826 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2014/01-2015/12 | 315MHz 22854866 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2014/01-2015/12 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2014/01-2015/12 | 433MHz | GMX521 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2020/01-2020/12 | 433MHz Clamp in | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2016/01-2019/12 | 433MHz 13598787 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2018/01-2019/12 | 315MHz 13598786 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2024/01-2024/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2021/01-2023/12 | 433MHz Clamp in | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2020/01-2023/12 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2020/01-2023/12 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2017/01-2022/06 | 433MHz | 1AG37/ A1BC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2017/01-2020/12 | 433MHz Snap in | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2009/01-2011/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2012/01-2012/12 | 315MHz 12768826 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 2012/01-2013/12 | 315MHz 20964159 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Captiva | 2020/01-2023/12 | 433MHz | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Captiva | 2016/01-2019/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 2013/01-2018/12 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2010/01-2013/12 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2021/01-2024/12 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2022/01-2024/12 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2014/01-2014/12 | 433MHz | C7 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2015/01-2019/12 | 433MHz 13581560 | C7 | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2016/01-2019/12 | 315MHz 13581559 | C7 | ● | ● | ● | 0/S/A | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2020/01-2022/12 | 433MHz 13593957 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2006/01-2017/12 | 315MHz | GMX245 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2005/01-2009/12 | 433MHz 25758221 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 2005/01-2009/12 | 315MHz 25758220 | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 2007/06-2008/12 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 2009/01-2010/12 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 2010/01-2013/12 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 2008/01-2008/12 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 2009/01-2009/12 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 2001/01-2006/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 2006/01-2008/12 | 433MHz | GMT360 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 2007/01-2009/12 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 2009/01-2012/12 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 2005/01-2006/12 | 315MHz | LX | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Chrysler | 300C | 2009/06-2017/12 | 433MHz 18 inch | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 2005/06-2009/05 | 433MHz | LE48 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | 300C | 2009/06-2017/12 | 433MHz 20 inch | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300M | 2002/01-2004/12 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 2003/01-2008/12 | 433MHz | ZH | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | PT Cruiser | 2007/11-2010/12 | 315MHz | PT | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Citroen | Berlingo | 2018/07-2024/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C3 | 2009/09-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C4 | 2008/08-2010/07 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 2010/08-2024/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C4 | 2014/10-2018/10 | 433MHz | B58 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 2004/09-2008/07 | 433MHz | B5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C4 Cactus | 2014/05-2021/04 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 Picasso | 2006/05-2013/02 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Citroen | C5 | 2000/12-2004/07 | 433MHz | X40 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 2004/08-2013/08 | 433MHz | X3/X40 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C5 | 2013/09-2020/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C5 Aircross | 2017/09-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C6 | 2005/01-2013/12 | 433MHz | X6 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | DS3 | 2009/01-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 2010/12-2014/01 | 433MHz | B75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 2014/02-2020/07 | 433MHz | B81 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 2014/02-2018/11 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 2011/06-2014/01 | 433MHz | B81 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS7 | 2018/01-2024/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS7 | 2017/03-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Daihatsu | ACTIS | 2017/01-2017/12 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Pacific | ● | ● |
| Dodge | Avenger | 2011/01-2014/12 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Nitro | 2007/06-2011/12 | 433MHz | KA | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Ferrari | 296GTB | 2022/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 296GTB | 2021/01-2023/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 2011/01-2017/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 488 | 2015/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 2002/01-2006/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 2006/01-2012/12 | 315MHz | F141 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 2017/01-2017/12 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Huf/Beru | ● | ● |
| Ferrari | California | 2008/10-2017/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 2003/01-2004/12 | 315MHz | F140 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 2012/10-2016/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 2016/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 2005/01-2009/12 | 315MHz | F131E | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 2011/01-2019/06 | 315MHz | F151 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 2016/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 2013/01-2020/12 | 315MHz | F150 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 2017/01-2017/12 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Huf/Beru | ● | ● |
| Fiat | 500 | 2014/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Panda | 2012/01-2024/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Ecosport | 2017/07-2023/12 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 2017/11-2023/12 | 433MHz | CR6 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 2015/06-2017/06 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 2014/10-2017/12 | 433MHz | B515 | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 2013/06-2014/09 | 433MHz | B515 | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 2011/01-2011/12 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 2013/01-2015/09 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 2011/01-2015/05 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 2012/01-2012/12 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 2018/01-2019/12 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 2015/10-2017/12 | 315MHz | U502 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 2015/06-2019/12 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 2014/05-2019/06 | 433MHz | CCN | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Focus | 2013/01-2013/12 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 2014/01-2016/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 2014/01-2019/12 | 433MHz | C520 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 2010/01-2011/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 2012/01-2014/09 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 2014/10-2017/12 | 315MHz | S550 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 2020/01-2023/12 | 433MHz | S550 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 2020/01-2023/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 2018/01-2019/12 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 2015/01-2019/12 | 433MHz | S550 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 2024/01-2024/12 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Honda | Legend | 2015/01-2021/12 | 315MHz | Hybrid | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | NSX | 2016/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | NSX | 2016/01-2021/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 2021/01-2024/12 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 2017/01-2023/12 | 433MHz 42753T6NA01 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 2014/01-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| HongQi | H9 | 2020/08-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | HS5 | 2023/05-2024/12 | 433MHz 3778080DB01A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Hyundai | Elantra N | 2022/01-2024/12 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 2022/01-2024/12 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis Coupe | 2011/01-2016/12 | 315MHz Hi Line | BK | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 2008/01-2012/12 | 315MHz Lo Line | BK | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 2022/01-2024/12 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 6 | 2021/01-2024/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Nexo | 2020/01-2024/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i30 | 2007/01-2016/12 | 433MHz | FD/Fde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 2022/01-2024/12 | 433MHz M8E21A159AA | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 2019/01-2022/12 | 433MHz | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 2017/01-2018/12 | 433MHz | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 2022/01-2024/12 | 433MHz M8E21A159AA | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 2019/01-2022/12 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 2015/01-2018/12 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2016/05-2018/12 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2021/01-2023/12 | 433MHz M8E21A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2019/01-2023/12 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2019/01-2021/06 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jaguar | F-Type | 2016/05-2018/12 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2012/11-2016/04 | 433MHz AH521A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 2012/11-2016/04 | 315MHz AH521A159CA | X152 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | F-Type | 2012/11-2016/04 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 2021/01-2024/12 | 433MHz M8E21A159AA | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 2019/01-2023/12 | 433MHz GX631A159AA | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 1998/10-2011/08 | 433MHz | X200 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 1998/10-2011/08 | 315MHz | X200 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | X-Type | 2001/01-2009/12 | 315MHz | X400 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | X-Type | 2001/01-2009/12 | 433MHz | X400 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2015/01-2018/12 | 433MHz GX631A159AA | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2022/01-2024/12 | 433MHz M8E21A159AA | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2019/01-2022/12 | 433MHz GX631A159AA | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 2015/04-2018/12 | 433MHz FW931A159AB | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2019/01-2024/12 | 433MHz GX631A159AA | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2007/01-2015/08 | 433MHz | X250 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 2008/01-2017/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | XF | 2009/04-2015/08 | 315MHz | X250 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | XF | 2015/09-2018/12 | 433MHz | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2002/12-2009/12 | 315MHz | X350 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | XJ | 2002/12-2009/12 | 433MHz | X350 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2010/01-2020/04 | 433MHz GX631A159AA | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 2010/01-2020/04 | 315MHz AH521A159CA | X351 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | XJ | 2010/01-2020/04 | 433MHz AH521A159AA | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 2010/01-2015/12 | 315MHz | X150 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | XK | 2010/01-2015/12 | 433MHz | X150 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 2006/01-2009/12 | 433MHz | X150 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 2006/01-2009/12 | 315MHz | X150 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Cherokee | 2019/01-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2019/01-2022/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 2018/01-2023/12 | 433MHz | KL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2018/01-2018/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 2017/01-2017/12 | 433MHz | KL | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 2015/01-2017/12 | 315MHz | | ● | ● | ● | 0/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 2014/01-2016/12 | 433MHz | KL | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Commander | 2008/01-2010/12 | 433MHz | XK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 2006/01-2007/12 | 315MHz | XK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Compass | 2019/01-2024/12 | 315MHz Continental | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 2019/01-2024/12 | 433MHz | MP/MX | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 2013/01-2014/12 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 2012/01-2015/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Gladiator | 2021/07-2024/12 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2021/01-2023/12 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2021/01-2023/12 | 433MHz | WL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2006/06-2010/12 | 433MHz | WH | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2006/01-2007/12 | 315MHz | WK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 2005/01-2006/05 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 2004/05-2005/12 | 315MHz | WK | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Patriot | 2009/01-2014/12 | 315MHz | MK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 2007/01-2008/12 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Renegade | 2017/01-2017/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 2015/01-2016/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 2019/01-2023/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 2018/01-2024/12 | 433MHz 68193586AC | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 2018/01-2018/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Wrangler | 2021/07-2024/12 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 2021/01-2024/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2018/01-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2015/01-2017/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2013/01-2014/12 | 433MHz | JK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2010/01-2012/12 | 315MHz | JK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2010/01-2012/12 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2007/01-2009/12 | 315MHz | JK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Wrangler | 2006/06-2010/08 | 433MHz | JK72 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Lamborghini | Aventador | 2011/01-2012/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 2015/01-2016/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 2019/01-2024/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Defender | 2020/01-2023/12 | 433MHz FW931A159AB | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 1997/01-2019/12 | 433MHz BH521A159AA | L316 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 2020/01-2023/12 | 433MHz GX631A159AA | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 2020/01-2024/12 | 433MHz M8E21A159AA | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz AH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/01-2016/12 | 315MHz BH521A159CA | L319 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 2004/06-2009/11 | 315MHz | L319 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 2004/06-2009/11 | 433MHz | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2002/01-2004/05 | 433MHz | L318 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Discovery | 2017/01-2018/12 | 433MHz GX631A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Discovery | 2021/01-2024/12 | 433MHz M8E21A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz BH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz GX631A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 433MHz FW931A159AB | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 2009/12-2016/12 | 315MHz AH521A159CA | L319 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery | 2019/01-2022/12 | 433MHz GX631A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2019/01-2022/12 | 433MHz BH521A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2019/01-2022/12 | 433MHz GX631A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2015/01-2016/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2021/01-2024/12 | 433MHz M8E21A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2014/01-2018/12 | 433MHz BH521A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 2014/06-2018/12 | 433MHz GX631A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 315MHz AH521A159CA | L359 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 433MHz BH521A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 315MHz 4H231A159CA | L359 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 433MHz FW931A159AB | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 315MHz BH521A159CA | L359 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | FreeLander | 2006/01-2014/12 | 433MHz GX631A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2016/01-2018/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2020/02-2021/12 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 315MHz AH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2005/01-2009/12 | 315MHz | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2019/01-2021/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2022/01-2024/12 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2010/01-2012/12 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover | 2010/01-2012/12 | 315MHz BH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2022/01-2023/12 | 433MHz GX631A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2005/01-2009/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2002/01-2004/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 315MHz AH521A159CA | L405 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2013/01-2015/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 2016/01-2018/01 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2018/12 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2018/12 | 433MHz GX631A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 433MHz AH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2018/12 | 315MHz BH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2012/01-2014/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2021/07-2024/12 | 433MHz M8E21A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2019/01-2023/12 | 433MHz GX631A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2015/07-2017/12 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 315MHz AH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 2011/07-2015/06 | 315MHz BH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2021/01-2022/09 | 433MHz M8E21A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2022/10-2024/12 | 433MHz | L461 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2019/01-2022/09 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2019/01-2022/09 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2016/01-2018/12 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2016/01-2018/12 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 433MHz AH521A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2013/07-2015/12 | 315MHz AH521A159CA | L494 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2013/06 | 433MHz BH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2013/06 | 315MHz AH521A159CA | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2013/06 | 433MHz GX631A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2013/06 | 433MHz FW931A159AB | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2013/06 | 315MHz BH521A159CA | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2010/01-2013/06 | 433MHz AH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2005/01-2009/12 | 433MHz | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 2005/01-2009/12 | 315MHz | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 2021/01-2024/12 | 433MHz M8E21A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 2019/01-2023/12 | 433MHz GX631A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 2017/01-2018/12 | 433MHz | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 315MHz AH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2022/01-2024/12 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2010/01-2012/12 | 315MHz BH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2002/01-2004/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover Vogue | 2005/01-2009/12 | 315MHz | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2005/01-2009/12 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2022/01-2023/12 | 433MHz GX631A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2020/02-2021/12 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Vogue | 2019/01-2021/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2016/01-2018/12 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2016/01-2018/01 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 2013/01-2015/12 | 315MHz AH521A159CA | L405 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Lexus | ES Series | 2020/01-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 2018/08-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 2005/08-2010/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 2012/01-2023/12 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 2020/09-2022/12 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 2013/04-2020/12 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LC Series | 2021/11-2024/12 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 2020/01-2024/12 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LC Series | 2017/01-2024/12 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 2020/10-2022/10 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 2017/10-2024/12 | 315MHz Hi | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 2012/09-2021/12 | 315MHz Lo | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 2006/01-2011/12 | 315MHz | XF40 | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 2022/01-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 2015/01-2024/12 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 2014/01-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 2021/11-2024/12 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RC Series | 2020/01-2023/01 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RC Series | 2014/01-2023/01 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 2015/10-2020/12 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 2019/08-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 2013/07-2015/09 | 315MHz Japan | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 2006/01-2021/01 | 315MHz 33021 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | SC Series | 2006/08-2010/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 2018/10-2024/12 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 2020/05-2024/12 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lincoln | Town Car | 2012/01-2013/12 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Town Car | 2010/01-2011/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Town Car | 2009/01-2009/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Town Car | 2008/01-2008/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Town Car | 2006/01-2007/12 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lotus | Elise | 2008/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evora | 2010/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 2021/01-2023/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Maserati | Ghibli | 2018/01-2020/12 | 433MHz | M156/M157 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 2013/01-2017/12 | 433MHz | M156/M157 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Maserati | Grecale | 2022/01-2023/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 2020/01-2023/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Maserati | Levante | 2016/01-2019/12 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | MC20 | 2020/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Quattroporte | 2018/01-2023/12 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 2013/01-2017/12 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Spyder | 2001/07-2008/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maybach | Landulet | 2018/01-2020/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 2008/10-2014/12 | 433MHz | Ma009-127 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 2002/02-2013/12 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 2002/02-2013/12 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | S Series | 2021/01-2024/12 | 315MHz A0009058513 | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maybach | S Series | 2021/01-2024/12 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 2021/01-2024/12 | 315MHz | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maybach | S Series | 2021/01-2024/12 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 2015/01-2021/12 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Mazda | CX-5 | 2012/01-2017/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| McLaren | 500 Series | 2015/01-2022/12 | 433MHz RDE011 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 500 Series | 2016/01-2018/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 2014/01-2018/12 | 315MHz 36118378681 | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 2017/01-2024/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 2012/01-2014/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 2013/01-2017/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 2017/01-2019/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2012/01-2014/03 | 433MHz | 176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 2014/04-2018/05 | 433MHz | 176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 2015/01-2019/12 | 315MHz A0009050130 | 176 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | A Class | 2018/06-2024/12 | 433MHz | 177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 2018/06-2024/12 | 315MHz A0009054204 | 177 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | AMG | 2010/01-2020/12 | 433MHz | W197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2023/06-2024/12 | 315MHz A0009058513 | 192 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2023/06-2024/12 | 433MHz A0009058706 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2023/06-2024/12 | 433MHz A0009058413 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2014/01-2023/12 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2018/11-2023/12 | 433MHz | 290 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 2018/11-2023/12 | 315MHz | 290 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | B Class | 2019/02-2024/12 | 433MHz A0009054104 | 247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 2019/02-2024/12 | 315MHz | 247 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 2011/11-2019/01 | 433MHz | 246 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2016/01-2021/12 | 315MHz | A0009052202 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | C Class | 2022/09-2024/12 | 315MHz A0009058513 | 206 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | C Class | 2022/09-2024/12 | 433MHz A0009058413 | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2021/06-2024/12 | 433MHz | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2020/01-2022/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | C Class | 2018/06-2023/12 | 433MHz A0009053907 | C205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2007/04-2020/12 | 433MHz | W205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 2015/01-2019/12 | 315MHz | A0009050130 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | CL Class | 1998/01-2006/12 | 433MHz | 215 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 2010/01-2015/12 | 433MHz | 216 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 2006/07-2019/06 | 433MHz A0009054100 | 216 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 2019/05-2024/12 | 315MHz A0009054204 | 118 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 2019/05-2024/12 | 433MHz | 118 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 2019/01-2020/12 | 315MHz A0009050130 | 117 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 2015/01-2017/12 | 315MHz | 117 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 2014/06-2019/04 | 433MHz | 117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 2012/12-2014/05 | 433MHz | 117 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLC Class | 2008/01-2018/06 | 433MHz | 216 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 2023/06-2024/12 | 433MHz A0009058413 | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 2023/06-2024/12 | 315MHz A0009058513 | 236 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 2002/01-2018/06 | 433MHz | 209 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2009/07-2017/12 | 433MHz | 218 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2004/10-2004/12 | 433MHz A0055422318 | 219 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 2004/09-2011/12 | 433MHz A0025408017 | 219 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | CLS Class | 2018/01-2024/12 | 315MHz | 257 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 2018/01-2024/12 | 433MHz | 257 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Citan | 2012/01-2023/12 | 433MHz | 415 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Mercedes | Citan | 2021/09-2022/12 | 433MHz A4204012400 | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Mercedes | Citan | 2017/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class | 2023/10-2024/12 | 315MHz A0009058513 | 214 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | E Class | 2014/01-2015/10 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class | 2014/06-2018/12 | 433MHz | W212 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2009/07-2014/05 | 433MHz | W212/C207 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2023/10-2024/12 | 433MHz A0009058413 | 214 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2015/11-2023/12 | 433MHz | W213/BR238 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 2002/01-2005/05 | 433MHz | W211 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 2016/01-2023/12 | 315MHz | 213 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | E Class | 2005/06-2011/10 | 433MHz | W211 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | E Class AMG | 1999/01-2002/12 | 433MHz | W210 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQA | 2020/01-2024/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | EQA | 2020/01-2024/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 2022/01-2024/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 2021/01-2024/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQC | 2019/01-2024/12 | 433MHz | 293 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQC | 2019/01-2024/12 | 315MHz | 293 | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/01-2024/12 | 315MHz | 295 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/01-2024/12 | 433MHz | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/09-2024/12 | 433MHz A0009058413 | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 2022/09-2024/12 | 315MHz A0009058513 | 295 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQS | 2021/01-2024/12 | 433MHz | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 2021/01-2024/12 | 315MHz | 297 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQS | 2022/09-2024/12 | 433MHz A0009058413 | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 2022/09-2024/12 | 315MHz A0009058513 | 297 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 2018/01-2018/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 2007/04-2018/05 | 433MHz | G463/461 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 2018/06-2024/12 | 315MHz | 463 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | G Class | 2018/06-2024/12 | 433MHz | 463 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 2006/04-2009/09 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 2009/06-2012/12 | 433MHz | X164 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 2013/01-2019/06 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 2015/01-2020/12 | 315MHz A0009050130 | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 2020/01-2024/12 | 433MHz A0009054104 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 2020/01-2024/12 | 315MHz A0009054204 | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 2013/12-2020/06 | 433MHz | X156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLB Class | 2019/01-2024/12 | 433MHz | 247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLB Class | 2019/01-2024/12 | 315MHz | 247 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 2016/09-2022/12 | 433MHz A0009053907 | C253 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2022/01-2024/12 | 315MHz | 254 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2022/09-2024/12 | 315MHz A0009058513 | 254 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2016/01-2021/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2015/01-2021/12 | 315MHz | X253 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 2015/01-2019/07 | 433MHz | X253 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 2018/01-2023/12 | 315MHz | W167 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 2020/01-2021/12 | 315MHz | A0009052202 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 2018/10-2023/12 | 433MHz | V167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 2015/04-2019/11 | 433MHz | X166/C292 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 2015/01-2020/12 | 315MHz | A0009050130 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 2015/10-2019/06 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 2008/01-2015/09 | 433MHz | X204 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 2020/01-2024/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | GLS Class | 2019/07-2024/12 | 433MHz | X167 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLS Class | 2013/01-2019/06 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 2016/01-2019/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GT | 2019/01-2021/12 | 315MHz | A0009052202 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GT | 2015/01-2021/12 | 315MHz | A0009050130 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 2014/01-2019/12 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 2005/01-2011/05 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | M Class | 2010/01-2014/12 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 2004/12-2009/07 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | ML Class | 2009/08-2011/05 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 2011/06-2019/12 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Marco Polo | 2014/01-2022/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Metris | 2015/01-2023/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 2009/08-2018/06 | 433MHz | W251 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 2005/06-2014/12 | 433MHz Continental | W251 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 2021/06-2024/12 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 2022/01-2024/12 | 315MHz | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 2022/09-2024/12 | 315MHz A0009058513 | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 2022/09-2024/12 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 2015/01-2021/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 2009/06-2020/12 | 433MHz | W222/C217 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 2005/10-2009/05 | 433MHz | W221 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 1999/07-2005/09 | 433MHz | W220 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 1999/07-2002/12 | 433MHz | C215 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 2003/01-2005/09 | 433MHz | C215 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 2021/09-2024/12 | 433MHz | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2021/09-2024/12 | 433MHz A0009058413 | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2021/09-2024/12 | 315MHz | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2021/09-2024/12 | 315MHz A0009058513 | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2012/01-2021/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 2000/01-2005/04 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 2005/01-2012/06 | 433MHz | W230 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | SL Class | 2012/01-2020/12 | 433MHz | W231 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Roadster | 2001/08-2005/06 | 433MHz | R230 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLC Class | 2016/01-2021/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 2016/01-2020/06 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 2004/01-2021/12 | 433MHz | R171, R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 2007/04-2019/05 | 315MHz | R172 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | SLR Class | 2004/04-2015/12 | 433MHz | R199 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 2004/01-2011/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 2010/01-2015/12 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Mercedes | SLS Class | 2010/01-2019/06 | 433MHz | 197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 2011/11-2020/06 | 433MHz | 906 (NVC3) | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | Sprinter | 2018/01-2024/12 | 433MHz A0009054104 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter | 2006/06-2011/10 | 433MHz | W906 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 2006/01-2011/10 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 2011/11-2018/09 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter Combi | 2018/10-2021/06 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | V Class | 2014/01-2024/12 | 433MHz | W447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vario | 2012/01-2013/12 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Mercedes | Vario | 2014/01-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Viano | 2003/07-2014/05 | 433MHz A0025409517 | W639 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Viano | 2014/06-2021/12 | 433MHz A4479050500 | W639 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vito | 2014/07-2024/12 | 433MHz | W447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vito | 2003/05-2014/06 | 433MHz | W639 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | X Class | 2017/01-2020/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Mini | Cabrio | 2015/11-2024/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cabrio | 2014/07-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 2007/08-2016/12 | 433MHz 36236781847 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 2015/07-2024/06 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 2014/07-2014/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubvan | 2016/01-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubvan | 2012/07-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2023/11-2024/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2023/11-2024/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2015/07-2024/06 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Countryman | 2014/07-2018/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 2009/01-2014/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 2014/07-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 2011/07-2014/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 2009/01-2015/12 | 433MHz OYGTSSRE4D | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 2006/03-2024/06 | 433MHz Continental | F55/F56/R56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 2014/01-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 2009/01-2014/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 2014/07-2018/06 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 2018/07-2019/12 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Roadster | 2014/05-2015/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 2011/01-2014/12 | 433MHz 36106856227 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mitsubishi | Eclipse Cross | 2018/01-2021/10 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 2021/11-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross PHEV | 2021/12-2024/12 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Galant | 2007/07-2013/12 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | Galant | 2003/01-2006/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 2006/07-2013/12 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Mirage | 2021/04-2023/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 2013/07-2021/03 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 2021/02-2024/06 | 315MHz 4250G122 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 2016/01-2022/12 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Proudia | 2012/01-2017/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 2012/01-2016/12 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 2010/01-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Ariya | 2022/01-2023/10 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Caravan | 2021/12-2022/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cima | 2017/06-2022/12 | 315MHz 407005UVOA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cima | 2012/05-2019/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 2009/02-2009/07 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Cube | 2009/07-2009/10 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Cube | 2012/03-2012/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 2013/01-2016/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 2011/11-2015/12 | 315MHz 407001LA0E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 2010/10-2016/12 | 315MHz 407003AN1A | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Cube | 2009/10-2012/02 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Elgrand | 2010/08-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | FUGA | 2017/11-2022/12 | 315MHz 407005UVOA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | FUGA | 2012/06-2022/12 | 315MHz 40700JK00A | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | FUGA | 2012/06-2017/10 | 315MHz 407001LA0E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | FUGA | 2008/01-2012/05 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | FUGA | 2015/01-2022/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Fairlady Z | 2022/08-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 2008/12-2011/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 2008/03-2010/12 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 2008/03-2009/12 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 2022/09-2024/12 | 433MHz 407006GP1A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 2013/11-2022/08 | 433MHz 4070062B0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 2022/09-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 2020/05-2022/08 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 2017/11-2024/12 | 315MHz 407005UVOA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|---------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | GT-R | 2011/06-2020/04 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 2010/11-2020/04 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Juke | 2019/10-2021/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 2014/05-2019/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 2013/01-2014/10 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 2010/07-2020/12 | 315MHz 407001LAOE | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 2011/07-2012/02 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Juke | 2012/03-2012/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 2010/07-2012/03 | 315MHz 407001AAOB | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Kicks | 2019/09-2024/12 | 433MHz 407006LBOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Kicks | 2016/11-2021/03 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2013/01-2018/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Leaf | 2020/02-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2010/10-2012/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Leaf | 2018/01-2020/01 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2014/11-2017/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 2014/05-2016/02 | 433MHz 407006WYOB | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | March | 2016/04-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | March | 2016/04-2020/12 | 433MHz 407003VUOA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 2002/09-2006/07 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Murano | 2011/11-2012/12 | 315MHz 40700JK00E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Murano | 2008/10-2012/08 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Murano | 2006/08-2008/09 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Murano | 2013/01-2014/09 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | NV200 | 2017/09-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV200 | 2014/02-2017/08 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Note | 2013/08-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Primera | 2002/01-2009/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Skyline | 2013/11-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Sylphy | 2019/05-2022/12 | 433MHz 407006LBOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Sylphy | 2020/07-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sylphy | 2017/10-2020/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sylphy | 2015/12-2017/09 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Teana | 2016/04-2022/12 | 433MHz 407006WYOB | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Teana | 2014/01-2019/12 | 433MHz 407003VUOA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Teana | 2013/02-2018/04 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Teana | 2018/01-2020/12 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 2022/09-2023/09 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | X-Trail | 2021/06-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|------------|-----------------|----------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | X-Trail | 2017/05-2022/04 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 2014/02-2017/04 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Astra H | 2004/01-2009/10 | 433MHz 13172567 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 2020/01-2024/12 | Indirect | F/Mk5 | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Grandland | 2017/01-2024/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Signum | 2002/01-2011/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra | 2002/01-2012/10 | 433MHz | Oe86/ GM Z3200 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Peugeot | 1007 | 2004/01-2011/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 2008 | 2013/02-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 207 | 2005/11-2013/09 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 207 | 2013/10-2016/12 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 208 | 2012/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 | 2008/11-2013/08 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 2013/09-2019/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 2016/06-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 307 | 2001/01-2007/02 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 307 | 2007/03-2008/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 2013/06-2019/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 2020/01-2024/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 308 | 2007/05-2013/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 407 | 2003/01-2012/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 5008 | 2017/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 5008 | 2013/09-2022/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 2017/07-2024/12 | Indirect | R83 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 508 | 2010/09-2013/09 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 508 | 2013/10-2022/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 607 | 1999/09-2004/09 | 433MHz | 6042/Z8 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 2013/10-2017/06 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 2009/12-2013/09 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Rifter | 2018/07-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Polestar | Polestar 2 | 2020/07-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Porsche | 718 (982) | 2017/01-2020/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 2011/01-2017/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 2012/02-2016/12 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 (991) | 2011/12-2016/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 (992) | 2019/01-2024/12 | 315MHz | 992 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 (997) | 2015/09-2019/12 | 315MHz | 997 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 2012/01-2024/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2010/01-2014/12 | 315MHz | 92A | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 2015/01-2023/12 | 315MHz | 9YA | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 2015/01-2024/12 | 315MHz | 92A | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 2012/01-2017/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 2014/01-2023/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 2009/01-2020/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | Panamera | 2017/01-2023/12 | 315MHz | 971 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 2020/01-2023/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Renault | Captur | 2016/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Captur | 2022/03-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Clio IV | 2016/01-2019/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | KOLEOS II/QM6 | 2016/01-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kadjar | 2016/09-2021/05 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kangoo | 2022/02-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Koleos | 2012/01-2013/12 | 315MHz 407001AA0D | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 2013/06-2016/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Koleos | 2010/06-2012/06 | 315MHz 407001AA0B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 2010/06-2016/12 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 2010/01-2016/12 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Megane II | 2005/01-2009/12 | 433MHz | B32/X84 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane III | 2008/10-2016/12 | 433MHz | X95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 2021/02-2023/12 | 433MHz 407004CB0A | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 2017/06-2023/12 | 433MHz 407005663R | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 2021/02-2023/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic I | 1997/01-2003/12 | 433MHz | J64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Scenic II | 2003/01-2009/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic III | 2009/01-2016/06 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Twingo | 2022/03-2024/12 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Twingo | 2016/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Twingo | 2018/01-2024/12 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Rivian | R1S | 2022/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rolls Royce | Ghost | 2020/08-2024/06 | 433MHz 36106887147 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Ghost | 2020/01-2024/06 | 433MHz 36106877937 | RR21 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 2014/04-2021/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 2009/12-2014/03 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 2012/01-2017/12 | 433MHz | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 2003/02-2018/12 | 433MHz OYGTSSRE4TC | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 2007/01-2022/12 | 433MHz 36106798872 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 2017/01-2024/06 | 433MHz MRXAG5SP4 | RR11/RR02 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Spectre | 2023/08-2024/06 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Spectre | 2023/08-2024/06 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 2012/01-2021/12 | 433MHz 36106790054 | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 2014/04-2023/12 | 433MHz | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------------|-----------------|----------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| SGMW | hongguang MINIEV | 2020/01-2024/12 | 433MHz 23642755 | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| SGMW | wulingrongguang | 2021/04-2024/12 | 433MHz 23642755 | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| SGMW | wulingrongguang | 2021/04-2024/12 | 433MHz 23561540 | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Saab | 9-3 | 2003/01-2006/09 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 2006/10-2009/05 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 2009/06-2012/12 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 2006/11-2009/09 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 2009/10-2013/12 | 433MHz | YS3G | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 2002/07-2006/10 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 2005/01-2023/12 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 2007/01-2014/02 | 433MHz | A451 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 2014/03-2023/12 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Suzuki | Alto | 2014/06-2017/12 | 433MHz | YC5 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Alto | 2014/01-2015/06 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Baleno | 2016/01-2024/12 | 433MHz | YR | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 2021/02-2024/12 | 433MHz | MF | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 2016/01-2021/01 | 433MHz | YJ | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 2021/02-2024/12 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 2014/01-2021/01 | 433MHz | YR7/YW5 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 2009/01-2019/12 | 433MHz | YW1 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 2009/01-2019/12 | 315MHz | | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Suzuki | SX4 | 2013/01-2023/12 | 433MHz | YY1, YY3 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | SX4 | 2006/01-2014/12 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Suzuki | SX4 S-Cross | 2021/09-2023/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 2013/01-2021/08 | 433MHz | YAA | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Splash | 2013/09-2019/12 | 433MHz | YV1/YV4/ YV5 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 2021/02-2023/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 2013/08-2021/01 | 433MHz | YP6/YP7/YS | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Suzuki | Wagon R | 2020/09-2023/12 | 433MHz | | ● | ● | ○ | O | 433MHz | Unknown | ● | ● |
| Tesla | Model 3 | 2021/01-2024/12 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model 3 | 2019/05-2020/10 | 315MHz 107481400B | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Tesla | Model S | 2021/01-2024/12 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model S | 2021/01-2022/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 2014/09-2020/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 2012/03-2021/01 | 315MHz 107481400B | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Tesla | Model S | 2008/01-2014/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Tesla | Model X | 2021/01-2024/12 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model X | 2016/04-2024/06 | 315MHz 107481400B | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Tesla | Model X | 2016/01-2023/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model Y | 2020/01-2024/12 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Roadster | 2010/01-2012/12 | 433MHz Baolong | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|---------------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Tesla | Roadster | 2008/01-2010/12 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | Camry | 2014/09-2024/12 | 315MHz Clamp in | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 2017/09-2021/01 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 2014/09-2024/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Century | 2018/01-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Century | 2018/06-2024/12 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Crown | 2012/12-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Crown | 2018/06-2021/01 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Granace | 2019/12-2024/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Hiace | 2014/06-2024/12 | 433MHz E100 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hilux | 2019/05-2022/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2015/08-2021/04 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 2015/08-2024/12 | 315MHz Pacific C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2017/10-2021/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2021/06-2023/12 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 2008/08-2009/08 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Mirai | 2020/11-2024/12 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 2014/05-2019/12 | 433MHz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 2021/10-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Supra | 2019/03-2024/12 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Toyota | Supra | 2019/03-2024/12 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | Yaris Cross | 2021/07-2024/12 | 433MHz | XPB1F | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris GR | 2020/08-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | bZ4X | 2022/03-2024/12 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | bZ4X | 2022/03-2024/12 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Volkswagen | Arteon | 2017/01-2024/06 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | EOS | 2007/01-2011/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Golf | 2007/01-2011/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Jetta | 2011/01-2023/12 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 2006/01-2011/12 | 433MHz | VW314 | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Passat | 2006/01-2011/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Passat | 2015/01-2023/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat CC | 2009/01-2016/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | T-ROC | 2017/11-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 2017/01-2020/12 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 2018/01-2023/12 | 315MHz 5Q0907275A | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 2011/01-2017/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 2011/01-2020/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 2020/06-2024/06 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Volvo | C30 | 2006/01-2014/03 | 433MHz 31445474 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | C30 | 2006/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 2011/01-2014/03 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C40 | 2022/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | C70 | 2011/01-2014/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 2008/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 2006/01-2014/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 2006/01-2007/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | EX30 | 2023/06-2024/12 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Volvo | S40 | 2011/01-2014/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 2003/01-2014/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 2003/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 2019/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 2001/01-2010/12 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S60 | 2010/01-2019/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 2000/07-2010/02 | 433MHz 31329981 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | S60 | 2010/01-2019/12 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 1999/01-2013/12 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S80 | 2006/01-2017/01 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 2007/01-2009/12 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 2010/01-2016/12 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S90 | 2016/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 2015/01-2020/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 2012/01-2021/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V40 Cross Country | 2017/01-2021/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 Cross Country | 2012/01-2017/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 2011/01-2016/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 2004/01-2014/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 2003/01-2010/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 2019/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 | 2011/01-2019/12 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 Cross Country | 2019/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 Cross Country | 2015/01-2018/12 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 2007/01-2016/12 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V90 | 2016/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 Cross Country | 2016/01-2023/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Volvo | XC40 | 2017/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 2017/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 2009/01-2010/12 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Volvo | XC60 | 2008/01-2017/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 2008/01-2018/12 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC90 | 2016/01-2024/12 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC90 | 2015/01-2022/12 | 433MHz 31362304 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 2003/01-2016/12 | 433MHz 31329981 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 2003/01-2016/12 | 315MHz 31200923 | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |