



MX-Sensor_V2.40 Function List For KR Market (Note:For reference only)

NOTES:
● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)
Special Declaration:
1).If the “Relearn Type” of MX-Sensor is only OBD type, and the “OBD-II Function” has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
2).All the Automatic Relearn Procedure for MX-Sensor,the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Abarth	500C	2010/01-2019/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Acura	NSX	2016/06-2020/12	315MHz		●	●	○	0	315MHz	Continental	●	●
알파 로메오	기우리아	2020/01-2024/12	433MHz	952	●	●	○	0/A	433MHz	Continental	●	●
알파 로메오	기우리아	2025/01-2025/06	433MHz	952	○	●	○	A	433MHz	Continental	●	●
Alpina	B3	2006/03-2009/08	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B3	2009/09-2014/03	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B3	2014/03-2019/06	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
Alpina	B3	2022/07-2024/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B3	2022/07-2024/06	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
Alpina	B3	2022/07-2024/06	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	B4	2014/03-2020/07	433MHz		●	●	○	A	433MHz	Continental	●	●
Alpina	B4	2020/09-2023/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B5	2010/02-2014/02	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B5	2014/03-2016/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B5	2017/01-2024/06	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	B5	2005/01-2014/12	433MHz 36236798726		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B6	2014/03-2018/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B6	2006/03-2010/11	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B6	2010/12-2014/02	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B7	2006/01-2010/08	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B7	2010/09-2014/02	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	B7	2015/07-2022/07	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	B7	2015/07-2022/07	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	B8	2021/01-2024/06	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	D3	2005/06-2009/08	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D3	2009/09-2014/02	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D3	2022/07-2024/06	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	D3	2022/07-2024/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D4	2020/09-2023/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D4	2014/03-2020/07	433MHz		●	●	○	A	433MHz	Continental	●	●
Alpina	D5	2017/01-2024/06	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	D5	2010/02-2014/02	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D5	2011/09-2014/12	433MHz 36236798726		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	D5	2014/03-2016/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Alpina	XB7	2022/07-2024/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	XB7	2020/01-2022/06	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	XB7	2020/01-2022/06	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	XB7	2022/07-2024/06	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
Alpina	XD3	2010/09-2014/03	433MHz	F25	●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	XD3	2010/09-2014/02	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	XD3	2014/04-2017/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	XD3	2017/08-2024/06	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	XD3	2017/08-2024/06	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	XD4	2018/01-2024/06	315MHz		●	●	○	A	315MHz	Schrader	●	●
Alpina	XD4	2018/09-2024/06	433MHz		●	●	○	A	433MHz	Schrader	●	●
Aston Martin	DB11	2016/01-2025/06	433MHz	VH500	○	●	○	A	433MHz	Schrader	●	●
Aston Martin	DBS	2007/01-2015/12	433MHz	V12	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	DBS	2018/01-2025/06	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
Aston Martin	DBS Superleggera	2018/01-2022/12	433MHz	VH500	○	●	○	A	433MHz	Schrader	●	●
Aston Martin	DBX	2020/04-2025/06	433MHz Huf		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Rapide	2010/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Rapide S	2010/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vanquish	2005/01-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vanquish	2012/01-2020/12	433MHz	AM310	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vantage	2010/01-2025/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	A3	2012/06-2023/12	433MHz	8L	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	A4	2012/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	A4	2008/08-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A5	2006/12-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A5	2019/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	A6	2018/01-2023/12	433MHz	4G	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	A6	2002/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A6	2005/01-2018/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	A7	2010/09-2023/12	433MHz 5Q0907275	4G	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	A7	2012/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A8	2009/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	A8	2010/11-2016/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	A8	2017/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	Q2	2020/01-2023/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	Q3	2020/01-2023/12	433MHz	8U	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	Q5	2017/01-2023/12	433MHz	8R	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	Q5	2008/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	Q7	2015/01-2023/12	433MHz MLB		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	Q7	2005/09-2015/12	433MHz	4L/AU716	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	Q7	2013/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	Q8	2018/01-2023/12	433MHz	4M	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	R8	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	R8	2015/04-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
아우디	R8	2009/06-2024/12	433MHz 7PP907275F	AU714	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	RS5	2017/01-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
아우디	RS5	2010/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	S6	2005/01-2012/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	S6	2018/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	S6	2002/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	S7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	S8	2010/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	S8	2017/10-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	S8	2009/11-2017/10	433MHz	D4	●	●	○	A	433MHz	Huf/Beru	●	●
아우디	SQ5	2017/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	SQ5	2012/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	TT	2014/02-2023/12	433MHz	AU334	●	●	○	0/A	433MHz	Huf/Beru	●	●
아우디	TTS	2016/01-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
아우디	e-tron	2018/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BAIC HUANSU	S6	2015/11-2019/12	433MHz		●	●	○	0/A	433MHz	BAIC	●	●
BMW	1 Series	2014/01-2024/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	1 Series	2010/09-2013/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	1 Series	2008/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	1 Series	2019/07-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	1 Series	2019/07-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	2 Series	2014/03-2024/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	2 Series	2019/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	2 Series	2012/11-2014/02	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	2 Series	2019/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	3 Series	1999/01-2002/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	3 Series	1998/01-2003/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	2005/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	3 Series	2019/03-2025/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	3 Series	2019/03-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	2019/03-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	3 Series	2019/03-2025/12	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	3 Series	2014/03-2022/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	3 Series	2010/10-2014/03	433MHz	F30/F31/F34	●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	3 Series	2009/09-2013/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	3 Series	2005/01-2009/08	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	4 Series	2020/07-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	4 Series	2013/07-2021/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	4 Series	2020/07-2025/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	4 Series	2020/07-2025/12	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	4 Series	2020/07-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	5 Series	2016/11-2024/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	5 Series	2023/07-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	2016/11-2024/12	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	5 Series	1998/08-2004/05	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	2003/05-2013/12	433MHz 36236798726		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	2010/09-2014/02	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series	2014/03-2017/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series	2023/07-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	6 Series	2003/08-2012/10	433MHz	E63/E64	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	6 Series	2014/04-2018/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series	2011/01-2014/03	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series GT	2017/07-2024/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	6 Series GT	2017/07-2024/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	7 Series	2006/01-2010/08	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	7 Series	2002/01-2005/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	7 Series	2022/07-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	7 Series	2015/06-2022/12	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	7 Series	2015/06-2022/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	7 Series	2014/03-2015/05	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	7 Series	2022/07-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	7 Series	2010/09-2014/02	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	8 Series	2018/07-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	8 Series	2018/07-2025/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	M2	2014/11-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	M2	2022/12-2025/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	M2	2022/12-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M3	2020/11-2025/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	M3	2020/11-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M3	2014/01-2019/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	M4	2021/07-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M4	2014/03-2021/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	M4	2021/07-2025/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	M5	2014/03-2017/12	433MHz 36106874830		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M5	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	M5	2023/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	M5	2010/09-2014/03	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M6	2014/03-2018/12	433MHz	F12	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M6	2011/06-2015/12	433MHz 36106856227		●	●	○	O/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	M8	2019/01-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	M8	2019/01-2024/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	모터사이클	2010/01-2019/12	433MHz		○	○	○		433MHz	Schrader	Activate Only	●
BMW	X1	2008/09-2014/02	433MHz	E84	●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X1	2009/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X1	2014/03-2016/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X1	2015/08-2023/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	X1	2022/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X1	2022/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X2	2016/01-2023/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	X2	2023/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X2	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X3	2003/01-2010/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X3	2003/03-2011/07	433MHz	E83	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X3	2010/11-2014/03	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X3	2014/04-2017/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X3	2017/01-2025/12	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	X3	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X3	2023/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X3	2017/01-2025/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	X4	2014/01-2018/12	433MHz 36106790054		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X4	2018/04-2025/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	X4	2018/04-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	X4	2013/05-2018/03	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X5	2019/01-2023/03	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	X5	2015/01-2018/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	X5	2010/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X5	2023/04-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X5	2023/04-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X5	1999/10-2007/09	433MHz	E53	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X5	2019/01-2023/03	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	X5	2010/10-2013/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X6	2007/12-2010/09	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X6	2010/10-2014/07	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	X6	2014/08-2019/07	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	X6	2019/08-2023/12	315MHz Schrader		●	●	○	A	315MHz	Schrader	●	●
BMW	X6	2019/08-2023/12	433MHz Schrader		●	●	○	A	433MHz	Schrader	●	●
BMW	X6	2023/01-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X6	2023/01-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X6	2008/01-2014/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X7	2018/12-2022/07	433MHz		●	●	○	A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	X7	2022/08-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X7	2022/08-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	X7	2018/12-2022/07	315MHz		●	●	○	A	315MHz	Schrader	●	●
BMW	XM	2022/12-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	XM	2022/12-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	Z4	2018/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	Z4	2018/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	Z4	2014/03-2016/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	Z4	2009/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	Z4	2006/01-2014/02	433MHz 36106790054		●	●	○	0/A	433MHz	Huf/Beru	●	●
BMW	i3	2022/01-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i3	2013/01-2022/06	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
BMW	i4	2021/01-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i4	2021/01-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	i5	2023/07-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i5	2023/07-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	i7	2022/07-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	i7	2022/07-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	i8	2013/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	iX	2021/01-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	iX	2021/01-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	iX1	2022/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	iX1	2022/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	iX2	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
BMW	iX2	2023/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	iX3	2017/08-2025/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
BMW	iX3	2017/08-2025/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
BYD	SEALION 7 EV	2024/05-2025/06	315MHz		●	●	○	0	315MHz	BHSENS	●	●
BYD	Sea Lion 07 EV	2024/05-2025/06	315MHz		●	●	○	0	315MHz	BHSENS	●	●
벤틀리	벤타가	2016/01-2023/12	433MHz 5Q0907275		●	●	○	0/A	433MHz	Huf/Beru	●	●
벤틀리	Continental GT	2022/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
벤틀리	Continental GT	2005/06-2023/12	433MHz BY634		●	●	○	0/A	433MHz	Huf/Beru	●	●
벤틀리	플라잉 스퍼	2011/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
벤틀리	플라잉 스퍼	2019/01-2025/12	433MHz 5Q0907275		●	●	○	0	433MHz	Huf/Beru	●	●
벤틀리	물산	2001/01-2020/12	433MHz 7PP907275F		●	●	○	0/A	433MHz	Huf/Beru	●	●
캐딜락	ATS	2013/01-2014/12	433MHz	A1SL/A1BL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	ATS	2013/01-2015/12	315MHz 20964159		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	ATS	2015/01-2015/12	433MHz	A1SL/A1BL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	ATS	2016/01-2019/06	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	ATS	2016/01-2019/12	315MHz 20964159		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	ATS	2015/01-2017/12	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
캐딜락	ATS	2018/01-2020/12	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	ATS	2016/01-2020/12	433MHz	A1SL/A1BL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	ATS-V	2017/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	ATS-V	2015/01-2015/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	ATS-V	2016/01-2016/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	BLS	2006/01-2014/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
캐딜락	CT4	2020/01-2025/12	433MHz 13530661		●	●	○	0/S/A	433MHz	Schrader	●	●
캐딜락	CT4	2022/01-2023/12	433MHz 13593957		●	●	○	0/S/A	433MHz	Schrader	●	●
캐딜락	CT4	2021/01-2025/12	433MHz 13554170		●	●	○	0/S/A	433MHz	Schrader	●	●
캐딜락	CT5	2024/01-2025/12	433MHz 13556202		●	●	○	0/S	433MHz	Schrader	●	●
캐딜락	CT5	2024/01-2025/12	315MHz 13538759		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	CT5	2024/01-2025/12	433MHz		●	●	○	0/S	433MHz	BHSENS	●	●
캐딜락	CT5	2024/01-2025/12	433MHz 13554170		●	●	○	0/S	433MHz	Schrader	●	●
캐딜락	CT5	2024/01-2025/12	433MHz 13538565		●	●	○	0/S/A	433MHz	Baolong	●	●
캐딜락	CT5	2023/01-2023/12	433MHz 13549707		●	●	○	0/S	433MHz	BHSENS	●	●
캐딜락	CT5	2023/01-2023/12	433MHz 13554170		●	●	○	0/S/A	433MHz	Schrader	●	●
캐딜락	CT5	2022/01-2023/12	433MHz Snap in		●	●	○	0/S/A	433MHz	Baolong	●	●
캐딜락	CT5	2020/01-2023/12	315MHz 13538759		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	CT5	2019/01-2023/12	433MHz 13530661		●	●	○	0/S/A	433MHz	Schrader	●	●
캐딜락	CT5	2019/01-2020/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
캐딜락	CT6	2016/01-2018/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CT6	2016/01-2021/12	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CT6	2019/01-2022/12	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CT6	2023/01-2023/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
캐딜락	CT6	2021/01-2022/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CT6	2019/01-2020/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2007/10-2007/12	315MHz Snap in		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2016/01-2021/06	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2009/01-2011/12	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2013/01-2013/12	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2014/01-2014/12	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2014/01-2014/12	433MHz	GMX206/ GMX226	●	●	●	0/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
캐딜락	CTS	2014/01-2019/12	315MHz 13522628		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2009/01-2011/12	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2009/01-2013/12	433MHz	GMX206/ GMX226	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2012/01-2012/12	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2008/10-2008/12	315MHz Snap in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2016/01-2019/12	433MHz 13598787		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2014/01-2019/12	315MHz 13598786		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2014/01-2015/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2008/01-2008/12	433MHz	GMX206/ GMX226	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2014/01-2014/12	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2013/06-2013/12	433MHz	A1LL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2013/01-2013/12	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2012/01-2012/12	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2007/01-2007/09	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	CTS	2006/01-2007/12	433MHz	GMX322	●	●	○	0/S	433MHz	Schrader	●	●
캐딜락	CTS	2004/01-2006/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	CTS-V	2010/01-2015/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	DTS	2009/01-2013/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	DTS	2006/01-2006/12	315MHz 25920615		○	●	○	S	315MHz	Schrader	●	●
캐딜락	DTS	2007/01-2008/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	에스컬레이드	2017/01-2020/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	에스컬레이드	2020/01-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2021/01-2023/12	433MHz 13533166		●	●	○	0/S/A	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2015/01-2020/12	433MHz	GMT900/ GMTK2XL/ K2UL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2014/01-2014/12	433MHz	GMT900/ GMTK2XL/ K2UL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2009/01-2013/12	433MHz	GMT900/ GMTK2XL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2007/01-2008/12	433MHz	GMT926	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	SRX	2016/01-2016/12	433MHz	C1UL	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	SRX	2013/01-2016/12	433MHz	GMT166	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	SRX	2012/01-2012/09	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	SRX	2004/01-2006/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	SRX	2012/10-2015/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	SRX	2008/06-2012/12	433MHz	GMT166	●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT4	2018/11-2022/12	433MHz	E2UL	●	●	●	0/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
캐딜락	XT4	2020/01-2021/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	XT4	2022/01-2023/12	315MHz 13512346		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	XT4	2022/01-2023/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT4	2024/01-2024/12	433MHz 13538566		●	●	○	0/S	433MHz	Baolong	●	●
캐딜락	XT4	2024/01-2025/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
캐딜락	XT4	2024/01-2025/12	433MHz		●	●	○	0/S	433MHz	BHSENS	●	●
캐딜락	XT4	2024/01-2025/12	433MHz 13538761		●	●	○	0/S	433MHz	Schrader	●	●
캐딜락	XT5	2018/01-2022/12	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT5	2017/01-2019/12	315MHz 13589597		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	XT5	2016/01-2021/06	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT5	2018/01-2020/06	315MHz 13516164		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	XT5	2021/01-2023/06	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
캐딜락	XT5	2022/01-2024/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT6	2019/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT6	2020/01-2025/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
캐딜락	XT6	2022/01-2025/12	433MHz 13554187		●	●	●	0/S	433MHz	Baolong	●	●
캐딜락	XT6	2019/01-2023/12	315MHz 13516164		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	Alpheon	2011/01-2015/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
쉐보레	아베오	2015/01-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	아베오	2013/01-2014/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	아베오	2015/01-2020/06	433MHz	G1SC/G1JC/T250/T300	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	아베오	2011/01-2011/12	315MHz		●	●	○	0	315MHz	Schrader	●	●
쉐보레	아베오	2021/01-2022/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
쉐보레	Bolt	2017/01-2020/12	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	Bolt	2016/01-2024/12	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	Bolt	2017/01-2018/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	Bolt	2019/01-2021/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	카마로	2009/01-2013/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	카마로	2014/01-2015/12	315MHz 22854866		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	카마로	2016/01-2016/12	433MHz Snap in		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	카마로	2017/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	카마로	2020/01-2023/12	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	카마로	2024/01-2025/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
쉐보레	카마로	2020/01-2025/12	433MHz Clamp in		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	카마로	2020/01-2023/12	315MHz		●	●	●	0	315MHz	Schrader	●	●
쉐보레	카마로	2018/01-2019/12	315MHz 13598786		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	카마로	2014/01-2015/12	315MHz 20964159		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	카마로	2012/01-2013/12	315MHz 20964159		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	캡티바	2008/01-2018/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	캡티바	2011/01-2018/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	콜로라도	2017/01-2019/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	콜로라도	2020/01-2020/12	433MHz		●	●	●	0	433MHz	Schrader	●	●
쉐보레	콜로라도	2020/01-2022/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	콜로라도	2020/01-2022/12	433MHz 13512347		●	●	●	0	433MHz	Schrader	●	●
쉐보레	코벳	2014/01-2015/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	코벳	2014/01-2014/12	433MHz	C7	●	●	●	0/A	433MHz	Schrader	●	●
쉐보레	코벳	2010/01-2013/12	315MHz	C6	●	●	○	0/S	315MHz	Schrader	●	●
쉐보레	코벳	2010/01-2013/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
쉐보레	크루즈	2012/01-2012/12	433MHz	D1SC/ D1JC/ D1WC/ KL1J	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	크루즈	2013/01-2015/12	433MHz	D1SC/ D1JC/ D1WC/ KL1J	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	크루즈	2016/01-2019/06	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	에쿼녹스	2017/06-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	에쿼녹스	2018/01-2023/12	433MHz MRXAG6SP4		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	에쿼녹스	2022/01-2024/12	433MHz 13540606		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	에쿼녹스	2022/01-2023/12	315MHz 13512346		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	에쿼녹스	2017/06-2023/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2013/01-2013/09	315MHz 13598771		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2007/01-2008/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2006/01-2006/12	315MHz Clamp in		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2020/01-2020/12	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	임팔라	2017/01-2020/06	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2015/01-2016/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2014/01-2021/06	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	임팔라	2013/10-2016/12	315MHz Limited		●	●	●	0/S	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
쉐보레	임팔라	2020/01-2020/12	315MHz 13516164		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2015/01-2016/12	315MHz Limited 23445327		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2006/01-2007/12	315MHz Clamp in 15268606		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	말리브	2009/01-2012/06	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	말리브	2011/01-2012/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	말리브	2022/01-2025/12	433MHz 13554187		●	●	●	0/S	433MHz	Baolong	●	●
쉐보레	말리브	2013/01-2014/12	315MHz 22854866		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	말리브	2013/01-2016/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	말리브	2015/01-2016/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	말리브	2017/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	말리브	2017/01-2022/12	433MHz	V300	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	말리브	2022/01-2025/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	몬테 카를로	2007/01-2007/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	올랜도	2013/01-2015/12	433MHz	GMT166	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	올랜도	2016/01-2018/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	Seeker	2022/01-2024/12	433MHz		●	●	●	0/S	433MHz	Baolong	●	●
쉐보레	실버라도	2024/01-2025/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
쉐보레	스파크	2002/01-2014/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	스파크	2013/01-2023/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	스파크	2015/01-2015/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	스파크	2016/01-2022/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	타호	2021/01-2023/12	433MHz 13533166		●	●	○	0/S/A	433MHz	Schrader	●	●
쉐보레	타호	2021/01-2025/12	433MHz 13530661		●	●	○	0/S	433MHz	Schrader	●	●
쉐보레	타호	2022/01-2023/12	433MHz	T1UC	●	●	○	0/S	433MHz	Schrader	●	●
쉐보레	타호	2022/01-2023/12	433MHz 13545366		●	●	○	0/S	433MHz	Schrader	●	●
쉐보레	트레일브레이저	2017/01-2020/12	433MHz 13598773		●	●	●	0	433MHz	Schrader	●	●
쉐보레	트레일브레이저	2020/01-2025/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트래버스	2025/01-2025/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트래버스	2024/01-2024/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트래버스	2020/01-2023/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트래버스	2018/01-2023/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트랙스	2015/01-2023/12	433MHz	G1UC	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트랙스	2017/01-2022/06	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	트랙스	2012/01-2014/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	볼트	2016/01-2016/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	볼트	2019/01-2019/12	433MHz 13512347		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	볼트	2016/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
크라이슬러	200	2014/01-2016/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
크라이슬러	300C	2018/01-2021/06	433MHz 20 inch		●	●	○	0/A	433MHz	Schrader	●	●
크라이슬러	300C	2018/01-2021/06	433MHz 18 inch		●	●	○	0/A	433MHz	Schrader	●	●
크라이슬러	300C	2009/06-2017/12	433MHz 20 inch		●	●	●	0/A	433MHz	Schrader	●	●
크라이슬러	300C	2009/06-2017/12	433MHz 18 inch		●	●	●	0/A	433MHz	Schrader	●	●
크라이슬러	300C	2005/06-2009/05	433MHz	LE48	●	●	●	0/A	433MHz	Continental	●	●
크라이슬러	300M	2002/01-2004/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
크라이슬러	크로스파이어	2003/01-2008/12	433MHz	ZH	●	●	○	A	433MHz	Schrader	●	●
크라이슬러	그랜드 보예저	2018/01-2020/03	433MHz	RT	●	●	○	0/S	433MHz	Schrader	●	●
크라이슬러	그랜드 보예저	2011/01-2017/12	433MHz	RT	●	●	●	0/S	433MHz	Schrader	●	●
크라이슬러	퍼시픽카	2018/01-2025/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
크라이슬러	퍼시픽카	2016/01-2017/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
크라이슬러	퍼시픽카	2006/01-2008/12	315MHz	CS	●	●	○	A	315MHz	Continental	●	●
크라이슬러	퍼시픽카	2004/01-2005/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
크라이슬러	퍼시픽카	2004/01-2005/12	315MHz		●	●	○	A	315MHz	Continental	●	●
크라이슬러	퍼시픽카	2003/01-2003/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Citroen	C4	2010/08-2024/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	C4 Cactus	2014/05-2021/04	433MHz		○	●	○	A	433MHz	Schrader	●	●
Citroen	C5	2000/12-2004/07	433MHz	X40	●	●	○	0	433MHz	Schrader	●	●
Citroen	C5 Aircross	2017/09-2025/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Citroen	C8	2005/10-2015/12	433MHz	V3	●	●	○	0	433MHz	Continental	●	●
Citroen	DS3	2009/01-2019/12	433MHz		○	●	○	NA	433MHz	Schrader	●	●
Citroen	DS3	2015/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS4	2014/02-2020/07	433MHz	B81	●	●	○	0/A	433MHz	Schrader	●	●
Citroen	DS4	2010/12-2014/01	433MHz	B75	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS4 Crossback	2016/01-2020/06	433MHz		●	●	○	0	433MHz	Schrader	●	●
Citroen	DS5	2014/02-2018/11	433MHz	X2/50	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS5	2011/06-2014/01	433MHz	B81	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS7	2018/01-2024/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS7	2017/03-2021/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Daewoo	ALPHEON	2011/01-2017/12	433MHz		○	●	○	NA	433MHz	Schrader	●	●
Dodge	Nitro	2006/11-2008/12	315MHz	KA	●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Nitro	2007/06-2011/12	433MHz	KA	●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Ram 1500	2019/01-2025/12	433MHz DT		●	●	○	0/A	433MHz	Schrader	●	●
Dodge	Ram 1500	2020/01-2025/12	433MHz	DS	●	●	○	0/A	433MHz	TRW	●	●
Dodge	Ram 1500	2024/01-2024/12	433MHz		●	●	○	0/A	433MHz	TRW	●	●
Dodge	Ram 2500	2019/01-2025/06	433MHz		●	●	○	0/A	433MHz	TRW	●	●
Dodge	Ram 2500	2024/11-2025/06	433MHz Schrader		●	●	○	0/A	433MHz	Schrader	●	●
Dodge	Ram 3500	2019/01-2025/06	433MHz		●	●	○	0/A	433MHz	TRW	●	●
Dodge	Ram ProMaster	2018/01-2025/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Dodge	Ram ProMaster	2022/01-2025/12	433MHz Continental		●	●	○	0/A	433MHz	Continental	●	●
페라리	296GTB	2022/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
페라리	458 이탈리아	2009/01-2015/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	458 Spider	2009/01-2020/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	488	2015/01-2021/12	433MHz	F142	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	575M 마라넬로	2002/01-2006/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	595 GTB/GTO	2004/01-2011/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	599 GTB	2004/01-2014/12	433MHz	F141	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	599 GTO	2004/01-2012/12	433MHz	F141	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	612 스카글리에티	2004/01-2011/12	433MHz	F137	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	812 Superfast	2017/01-2018/12	315MHz		○	●	○	NA	315MHz	Huf/Beru	●	●
페라리	812 Superfast	2016/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	812 Superfast	2017/01-2024/12	315MHz 314821		○	●	○	NA	315MHz	Huf	●	●
페라리	캘리포니아	2008/01-2019/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	Daytona SP3	2022/01-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	엔조	2002/01-2006/12	433MHz	F140	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	F12 벨리네타	2012/10-2023/12	433MHz 282189	F151/ F152	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	F12 tdf	2015/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	F430	2007/07-2009/10	433MHz 282189	F131E	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	F430	2004/09-2007/06	433MHz	F131E	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	F8 Tributo	2019/01-2023/12	433MHz 282189	F151/ F152	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	FF	2011/01-2020/01	433MHz	F151	●	●	○	0/A	433MHz	Huf/Beru	●	●
페라리	FXX	2005/01-2006/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	GTC4 루소	2016/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	GTC4 루소	2016/01-2020/12	433MHz 314818		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	GTC4 Lusso T	2017/01-2021/12	433MHz F11001648001		○	●	○	NA	433MHz	Huf/Beru	●	●
페라리	GTC4 Lusso T	2017/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	GTC4 Lusso T	2017/01-2021/12	433MHz F11001495001		○	●	○	NA	433MHz	Huf/Beru	●	●
페라리	라 페라리	2013/01-2020/12	433MHz 282189		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Monza SP1/SP2	2019/01-2025/12	433MHz	F151/ F152	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Portofino	2016/01-2023/12	433MHz 314818		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Portofino	2016/01-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Portofino	2017/10-2023/12	433MHz F11001648001		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Purosangue	2022/01-2025/12	433MHz BHSENS		○	●	○	A	433MHz	BHSENS	●	●
페라리	Roma	2020/01-2025/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	SF90	2020/01-2025/06	433MHz 314818		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	SF90	2020/01-2025/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Fiat	500	2014/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500C	2013/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Fiat	500L	2012/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500X	2014/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	Freemont	2014/07-2016/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Fiat	Freemont	2011/01-2014/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
포드	Bronco	2021/01-2025/06	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	Bronco	2021/01-2023/12	433MHz JX7Z1A189A		●	●	○	0/S	433MHz	Schrader	●	●
포드	Bronco	2024/10-2025/12	433MHz PR3Z1A189M		●	●	○	0/S	433MHz	Schrader	●	●
포드	Bronco	2021/01-2025/06	315MHz ML3T1A180BA		●	●	○	0/S	315MHz	Schrader	●	●
포드	Bronco	2021/01-2025/06	315MHz 81C3A8189CA		●	●	○	0/S	315MHz	Schrader	●	●
포드	Bronco Sport	2020/10-2025/06	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
포드	Bronco Sport	2020/10-2025/06	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	에스케이프	2014/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
포드	에스케이프	2012/05-2013/12	433MHz		●	●	●	S	433MHz	Schrader	●	●
포드	Everest	2015/01-2018/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	엑스피디션	2023/01-2024/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	엑스피디션	2002/03-2004/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
포드	엑스피디션	2018/01-2024/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
포드	엑스피디션	2017/09-2017/12	315MHz HC3Z1A189A		●	●	●	S	315MHz	Schrader	●	●
포드	엑스피디션	2019/01-2021/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	익스플로러	2018/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
포드	익스플로러	2016/01-2017/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	익스플로러	2006/01-2010/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
포드	익스플로러	2010/11-2015/12	315MHz Schrader		●	●	●	S	315MHz	Schrader	●	●
포드	익스플로러	2015/05-2015/12	433MHz F2GZ1A189B		●	●	●	S	433MHz	Schrader	●	●
포드	익스플로러	2010/11-2015/06	433MHz BB5Z1A189A		●	●	●	S	433MHz	Schrader	●	●
포드	익스플로러	2021/01-2025/12	433MHz		●	●	○	0/S/A	433MHz	Schrader	●	●
포드	익스플로러	2020/01-2020/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
포드	익스플로러	2004/01-2005/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
포드	쿠가	2014/01-2019/12	433MHz		●	●	●	0/S/A	433MHz	Schrader	●	●
포드	몬데오	2019/06-2022/12	433MHz F2GZ1A189B		●	●	●	0/S	433MHz	Schrader	●	●
포드	몬데오	2017/09-2019/05	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
포드	몬데오	2007/01-2015/06	433MHz Clamp in		●	●	○	0/A	433MHz	Continental	●	●
포드	몬데오	2015/01-2017/08	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
포드	무스탕	2014/10-2019/12	433MHz		●	●	●	0/S/A	433MHz	Schrader	●	●
포드	무스탕	2020/01-2023/12	433MHz		●	●	○	0/S/A	433MHz	Schrader	●	●
포드	무스탕	2024/01-2025/06	433MHz		●	●	○	0/S/A	433MHz	Schrader	●	●
포드	무스탕	2024/01-2025/06	433MHz PR3Z1A189M		●	●	○	0/S/A	433MHz	Schrader	●	●
포드	Mustang Mach-E	2020/01-2025/06	433MHz		●	●	○	0/S/A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
포드	Mustang Mach-E	2020/10-2025/06	315MHz FR3Z1A189A		●	●	○	0/S	315MHz	Schrader	●	●
포드	Mustang Mach-E	2021/01-2024/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
포드	Mustang Mach-E	2024/07-2025/06	433MHz PR3Z1A189M		●	●	○	0/S/A	433MHz	Schrader	●	●
포드	레인저	2019/01-2023/12	433MHz Hi Line		●	●	○	0/S	433MHz	Schrader	●	●
포드	레인저	2018/01-2018/12	433MHz Hi Line		●	●	○	0/S	433MHz	Schrader	●	●
포드	레인저	2024/01-2025/06	433MHz Hi Line		●	●	○	0/S	433MHz	Schrader	●	●
포드	레인저	2024/01-2025/06	433MHz Lo Line		●	●	○	0/S	433MHz	Schrader	●	●
포드	레인저	2015/01-2017/12	433MHz Hi Line		●	●	●	0/S	433MHz	Schrader	●	●
포드	타우러스	2016/01-2019/12	433MHz		●	●	●	S	433MHz	Schrader	●	●
GMC	Sierra	2021/01-2023/12	433MHz 13530661		●	●	●	0	433MHz	Schrader	●	●
GMC	Sierra	2021/01-2023/12	315MHz 13538759		●	●	●	0/S	315MHz	Schrader	●	●
GMC	Sierra	2022/01-2023/12	433MHz 13545366		●	●	●	0/S	433MHz	Schrader	●	●
GMC	Sierra	2022/01-2023/12	433MHz 13542523		●	●	●	0/S	433MHz	Schrader	●	●
GMC	Sierra	2024/01-2025/12	433MHz 13542523		●	●	○	0/S	433MHz	Schrader	●	●
GMC	Sierra	2024/01-2025/12	315MHz 13538759		●	●	○	0/S	315MHz	Schrader	●	●
GMC	Sierra	2024/01-2025/12	433MHz 13538761		●	●	○	0/S	433MHz	Schrader	●	●
GMC	Sierra	2018/01-2023/12	433MHz 13516165		●	●	●	0/S	433MHz	Schrader	●	●
Geely	Monjaro	2022/01-2025/06	433MHz 8889081697		○	●	○	NA	433MHz	Schrader	●	●
Geely	Tugella L	2021/01-2025/06	433MHz 8889081697		○	●	○	NA	433MHz	Schrader	●	●
혼다	아코드	2013/01-2015/12	433MHz	2GA/2GB/QE	●	●	○	0	433MHz	Continental	●	●
혼다	아코드	2015/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	CR-V	2014/01-2025/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	CR-Z	2011/01-2013/12	315MHz		●	●	○	0	315MHz	TRW	●	●
혼다	씨빅	2013/01-2025/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
혼다	HR-V	2014/09-2025/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
혼다	인사이트	2010/01-2013/12	315MHz		●	●	○	0	315MHz	TRW	●	●
혼다	Legend	2015/01-2016/12	315MHz	Hybrid	●	●	○	0	315MHz	TRW	●	●
혼다	NSX	2016/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	NSX	2016/01-2021/06	433MHz		●	●	○	0	433MHz	Continental	●	●
혼다	오디세이	2014/01-2017/12	315MHz		●	●	○	0	315MHz	TRW	●	●
혼다	오디세이	2021/01-2025/06	433MHz 42753T3RA02		●	●	○	0	433MHz	Continental	●	●
혼다	오디세이	2015/01-2016/12	433MHz		●	●	○	0	433MHz	TRW	●	●
혼다	오디세이	2017/01-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
혼다	파이롯	2009/01-2015/12	315MHz Steel		●	●	○	0	315MHz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
혼다	파이롯	2009/01-2015/12	315MHz Alloy		●	●	○	0/A	315MHz	Pacific	●	●
혼다	파이롯	2016/01-2017/12	433MHz		●	●	○	0	433MHz	Continental	●	●
혼다	파이롯	2018/01-2023/12	433MHz 42753T6NA01		●	●	○	0	433MHz	Continental	●	●
혼다	파이롯	2023/01-2025/06	433MHz 42753T3RA02		●	●	○	0	433MHz	Continental	●	●
홈머	H2	2008/01-2008/12	315MHz 13598771		●	●	●	0/S	315MHz	Schrader	●	●
현대	엑센트	2015/01-2019/12	433MHz Hi Line	RB	●	●	○	0	433MHz	Continental	●	●
현대	엑센트	2015/01-2018/12	433MHz Lo Line	RB	●	●	○	0	433MHz	Continental	●	●
현대	Alsan	2018/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Alsan	2014/01-2017/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Avante	2011/01-2013/12	433MHz	MD	●	●	○	0	433MHz	TRW	●	●
현대	Avante	2021/01-2023/12	433MHz 52933F2000	CN7	●	●	○	0/A	433MHz	Continental	●	●
현대	Avante	2016/01-2020/12	433MHz	AD	●	●	○	0	433MHz	Continental	●	●
현대	Avante	2014/01-2016/12	433MHz	MD	●	●	○	0	433MHz	TRW	●	●
현대	Avante	2012/01-2016/12	433MHz 529333X305	JK	●	●	○	0	433MHz	TRW	●	●
현대	아제라	2011/01-2014/08	433MHz	HG	●	●	○	C	433MHz	TRW	●	●
현대	아제라	2014/09-2017/02	433MHz	HG	●	●	○	C	433MHz	TRW	●	●
현대	아제라	2017/03-2019/12	433MHz	IG	●	●	○	0	433MHz	Continental	●	●
현대	EQ900	2016/01-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	엘란트라	2013/10-2019/12	315MHz Lo Line		●	●	○	0/A	315MHz	TRW	●	●
현대	Elantra GT	2021/01-2021/12	433MHz	PD	●	●	○	0/A	433MHz	Continental	●	●
현대	Elantra GT	2017/06-2020/12	433MHz	PD	●	●	○	0/A	433MHz	Continental	●	●
현대	엘란트라 N	2022/01-2024/12	433MHz 52940CG100		●	●	○	0/A	433MHz	Schrader	●	●
현대	엘란트라 N	2022/01-2024/12	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
현대	에쿠스	2013/01-2019/12	433MHz	VI New	●	●	○	0/A	433MHz	Continental	●	●
현대	에쿠스	2008/01-2013/12	433MHz	VI Old	●	●	○	0	433MHz	TRW	●	●
현대	제네시스	2013/01-2016/12	315MHz Hi Line	BK	●	●	○	0	315MHz	TRW	●	●
현대	제네시스	2013/01-2016/12	433MHz	DH	●	●	○	0/A	433MHz	Continental	●	●
현대	제네시스	2013/01-2016/12	315MHz Lo Line	BK	●	●	○	0	315MHz	TRW	●	●
현대	제네시스	2007/01-2014/12	433MHz	BH	●	●	○	0	433MHz	TRW	●	●
현대	제네시스	2007/01-2007/12	315MHz	BH	●	●	○	0	315MHz	TRW	●	●
현대	Genesis Coupe	2014/01-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Genesis Coupe	2012/01-2013/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Genesis G70	2024/01-2025/06	433MHz 52933J5000		●	●	○	0	433MHz	Schrader	●	●
현대	Genesis G70	2018/01-2025/06	433MHz 52940CG100		●	●	○	0	433MHz	Schrader	●	●
현대	Genesis G70	2018/01-2025/06	433MHz 52940CG100	IK	●	●	○	0	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	Genesis G70	2018/01-2024/12	433MHz 52933J5000	IK	●	●	○	0	433MHz	Schrader	●	●
현대	Genesis G70	2017/01-2017/12	433MHz	IK	●	●	○	0	433MHz	Schrader	●	●
현대	Genesis G80	2016/07-2019/12	433MHz	DH	●	●	○	0	433MHz	Continental	●	●
현대	Genesis G80	2020/01-2022/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G80	2016/07-2019/12	433MHz 529332J100	DH	●	●	○	0	433MHz	Continental	●	●
현대	Genesis G80	2021/07-2025/06	433MHz 52940T6000		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G80	2020/01-2022/12	433MHz	DH	●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G80	2016/07-2019/12	433MHz 52933B1100	DH	●	●	○	0	433MHz	Continental	●	●
현대	Genesis G80	2021/01-2025/06	433MHz 52933D4100		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G80 EV	2020/12-2025/06	433MHz 52933D2100		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G80 EV	2021/12-2025/06	433MHz		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G90	2016/01-2016/12	433MHz	HI	●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis G90	2017/01-2024/12	433MHz	HI	●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis GV60	2021/12-2025/06	433MHz 52933D2100		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis GV60	2021/12-2025/06	433MHz 52940CG100		●	●	○	0/A	433MHz	Schrader	●	●
현대	Genesis GV70	2020/12-2025/06	433MHz		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis GV70	2021/01-2025/06	433MHz 52940T6000		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis GV70 EV	2022/11-2024/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis GV80	2020/01-2022/12	433MHz 52933J5000		●	●	○	0/A	433MHz	Schrader	●	●
현대	Genesis GV80	2021/07-2024/12	433MHz 52940T6000		●	●	○	0/A	433MHz	Continental	●	●
현대	Genesis GV80	2020/01-2021/12	433MHz 52933D4100	JX1	●	●	○	0/A	433MHz	Continental	●	●
현대	Grand Starex	2015/01-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2011/01-2017/12	433MHz	HG/DM	●	●	○	C	433MHz	TRW	●	●
현대	그랜저	2011/06-2015/12	433MHz	HG	●	●	○	C	433MHz	TRW	●	●
현대	그랜저	2015/01-2017/12	433MHz	Hybrid	●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2020/01-2023/12	433MHz 52933D4100	IG LAMBDA	●	●	○	0/A	433MHz	Continental	●	●
현대	그랜저	2018/01-2019/12	433MHz	IG LAMBDA	●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2017/01-2020/12	433MHz	IG/IG HEV	●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2021/07-2023/12	433MHz 52940T6100		●	●	○	0/A	433MHz	Continental	●	●
현대	그랜저	2024/01-2025/06	433MHz	GN7 HEV	●	●	○	0	433MHz	Continental	●	●
현대	그랜저	2014/01-2014/12	433MHz	Hybrid	●	●	○	C	433MHz	TRW	●	●
현대	Grandeur GN7	2023/01-2024/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Ioniq	2016/01-2023/12	433MHz	AE	●	●	○	0	433MHz	Continental	●	●
현대	Ioniq	2022/03-2022/12	433MHz 52940T6100	AE	●	●	○	0	433MHz	Continental	●	●
현대	Ioniq 5	2020/01-2021/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	Ioniq 5	2022/01-2025/06	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
현대	Ioniq 5	2022/01-2025/06	433MHz 52940L1100		●	●	○	0/A	433MHz	Continental	●	●
현대	Ioniq 6	2021/01-2025/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
현대	Kona	2017/01-2024/12	433MHz		●	●	○	A/0	433MHz	Continental	●	●
현대	Kona	2024/01-2025/06	433MHz 52940BE000	SX2	●	●	○	A/0	433MHz	Continental	●	●
현대	Kona	2024/01-2025/06	433MHz	SX2	●	●	○	A/0	433MHz	Continental	●	●
현대	Kona N	2022/01-2025/06	433MHz	OSN	●	●	○	A/0	433MHz	Continental	●	●
현대	Kona electric	2023/07-2025/06	315MHz 529333N000		●	●	○	A/0	315MHz	Continental	●	●
현대	Kona electric	2024/01-2025/06	433MHz 52940BE000		●	●	○	A/0	433MHz	Continental	●	●
현대	Kona electric	2024/01-2025/06	433MHz		●	●	○	A/0	433MHz	Continental	●	●
현대	Maxcruz	2012/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	Nexo	2018/04-2025/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
현대	Palisade	2018/01-2025/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
현대	Porter	2014/01-2023/12	433MHz 52933A5100	HR	●	●	○	0	433MHz	Continental	●	●
현대	Porter	2007/01-2018/12	433MHz 529334H100		●	●	○	0	433MHz	Continental	●	●
현대	싼타페	2018/01-2018/12	433MHz	TM	●	●	○	0/A	433MHz	Schrader	●	●
현대	싼타페	2019/01-2022/12	433MHz	TM	●	●	○	0/A	433MHz	Schrader	●	●
현대	싼타페	2022/01-2024/12	433MHz	TM/TMA	●	●	○	0/A	433MHz	Schrader	●	●
현대	싼타페	2009/01-2012/05	433MHz	CM	●	●	○	0	433MHz	Lear	●	●
현대	싼타페	2006/01-2008/12	433MHz	CM	●	●	○	0	433MHz	Lear	●	●
현대	싼타페	2012/01-2015/12	433MHz	DM	●	●	○	0	433MHz	Continental	●	●
현대	싼타페	2012/06-2014/12	315MHz	NC	●	●	○	0	315MHz	Continental	●	●
현대	Solati	2014/03-2023/12	433MHz		●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2010/01-2010/12	433MHz	YF	●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2010/01-2013/12	433MHz	LF/LFA	●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2019/05-2024/12	433MHz 52940L1100		●	●	○	0/A	433MHz	Continental	●	●
현대	쏘나타	2014/01-2015/12	433MHz 529331J000	VDO	●	●	○	0	433MHz	Continental	●	●
현대	쏘나타	2014/04-2019/12	433MHz Hi Line	LF/LFA	●	●	○	0	433MHz	Schrader	●	●
현대	Sonata Hybrid	2016/01-2019/12	433MHz	YF/LF HEV	●	●	○	0	433MHz	Schrader	●	●
현대	Sonata Hybrid	2020/01-2025/06	433MHz 52940L1100	DN8 HEV	●	●	○	0/A	433MHz	Continental	●	●
현대	Sonata Hybrid	2011/01-2014/12	433MHz 529333N100		●	●	○	0	433MHz	Continental	●	●
현대	Sonata Hybrid	2011/01-2019/12	433MHz 529331J000		●	●	○	0	433MHz	Continental	●	●
현대	Sonata N	2023/01-2025/06	433MHz 52940L1100		●	●	○	0/A	433MHz	Continental	●	●
현대	스타렉스	2007/01-2007/12	315MHz		○	●	○	NA	315MHz	Continental	●	●
현대	스타렉스	2007/01-2015/12	433MHz	TQ	○	●	○	A	433MHz	Continental	●	●
현대	스타렉스	2016/01-2021/12	433MHz		○	●	○	A	433MHz	Continental	●	●
현대	Staria	2021/03-2025/06	433MHz		●	●	○	0	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	투싼	2021/01-2024/12	433MHz	NX	●	●	○	0/A	433MHz	Schrader	●	●
현대	투싼	2021/01-2024/12	433MHz 52940L1100	NX	●	●	○	0/A	433MHz	Continental	●	●
현대	투싼	2021/01-2021/09	433MHz Hi Line	TL	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2016/01-2017/12	433MHz	TL	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2015/05-2020/12	433MHz Hi Line	TL	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2015/01-2018/12	433MHz	LM FCEV	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2012/01-2015/12	433MHz Hi Line	LM	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2012/01-2015/12	433MHz Lo Line	LM	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2009/01-2013/12	433MHz	LM	●	●	○	0	433MHz	TRW	●	●
현대	벨로스터	2011/03-2019/06	433MHz	FS	●	●	○	0	433MHz	Schrader	●	●
현대	벨로스터	2018/01-2025/06	433MHz	JS	●	●	○	0	433MHz	Continental	●	●
현대	Veloster N	2019/01-2024/06	433MHz	JSN	●	●	○	0	433MHz	Continental	●	●
현대	Venue	2019/01-2022/12	433MHz 52933D4100	QX/QXI	●	●	○	0/A	433MHz	Continental	●	●
현대	Venue	2022/01-2025/06	433MHz 52933D4100	QXI	●	●	○	0/A	433MHz	Continental	●	●
현대	Venue	2022/01-2025/06	433MHz 52940T6100	QXI	●	●	○	0/A	433MHz	Continental	●	●
현대	베라크루즈	2007/01-2015/12	433MHz		●	●	○	0	433MHz	Lear	●	●
현대	베라크루즈	2007/01-2012/12	433MHz	EN/CM	●	●	○	0	433MHz	Continental	●	●
현대	i30	2012/01-2016/12	433MHz	GD	●	●	○	0/A	433MHz	Continental	●	●
현대	i30	2016/08-2025/06	433MHz 52933562C6	PD/Pde	●	●	○	0	433MHz	Continental	●	●
현대	i30	2017/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
현대	i30	2007/01-2016/12	433MHz	FD/Fde	●	●	○	0	433MHz	Continental	●	●
현대	i30	2016/08-2025/06	433MHz	PD/Pde	●	●	○	0	433MHz	Continental	●	●
현대	i30 N	2018/01-2024/12	433MHz 52933F2000		●	●	○	0/A	433MHz	Continental	●	●
현대	i30 N	2018/01-2024/12	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
현대	i40	2011/01-2014/03	433MHz	VF	●	●	○	0	433MHz	TRW	●	●
현대	i40	2011/01-2014/03	433MHz Second	VF	●	●	○	0	433MHz	TRW	●	●
현대	i40	2014/04-2020/12	433MHz	VF	●	●	○	0/A	433MHz	TRW	●	●
현대	i40	2017/01-2019/12	433MHz	IF	●	●	○	0	433MHz	Continental	●	●
인피니티	EX Series	2010/03-2015/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
인피니티	EX Series	2008/01-2014/03	433MHz		●	●	○	0	433MHz	Schrader	●	●
인피니티	EX Series	2007/11-2011/03	315MHz 40700JK00C		●	●	○	0	315MHz	Pacific	●	●
인피니티	FX Series	2010/12-2018/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
인피니티	FX Series	2008/07-2010/12	315MHz 40700JA01C		●	●	○	0	315MHz	Schrader	●	●
인피니티	FX Series	2008/05-2011/04	315MHz 40700JK00C		●	●	○	0	315MHz	Pacific	●	●
인피니티	FX Series	2008/05-2010/04	315MHz 40700JY10A		●	●	○	0	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
인피니티	FX Series	2008/03-2013/12	433MHz 407001AY0A		●	●	○	0	433MHz	Schrader	●	●
인피니티	FX Series	2007/07-2008/06	315MHz 40700JA00B		●	●	○	0	315MHz	Schrader	●	●
인피니티	FX Series	2002/11-2007/06	315MHz		●	●	○	0	315MHz	Schrader	●	●
인피니티	FX Series	2010/12-2018/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	G Series	2011/07-2014/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
인피니티	G Series	2010/03-2015/12	315MHz 407001LA0E		●	●	○	0	315MHz	Pacific	●	●
인피니티	G Series	2007/01-2011/06	433MHz		●	●	○	0	433MHz	Schrader	●	●
인피니티	G Series	2006/08-2010/11	315MHz		●	●	○	0	315MHz	Pacific	●	●
인피니티	G Series	2006/08-2007/12	315MHz 40700JA01B		●	●	○	0	315MHz	Schrader	●	●
인피니티	M Series	2010/05-2013/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
인피니티	M Series	2008/05-2010/04	315MHz		●	●	○	0	315MHz	Schrader	●	●
인피니티	M Series	2007/09-2008/08	315MHz 40700JA00C		●	●	○	0	315MHz	Schrader	●	●
인피니티	M Series	2002/07-2007/08	315MHz		●	●	○	0	315MHz	Schrader	●	●
인피니티	M Series	2010/08-2015/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	Q30	2016/04-2020/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
인피니티	Q45	2006/09-2008/12	315MHz		●	●	○	0	315MHz	Schrader	●	●
인피니티	Q45	2002/08-2006/08	315MHz		●	●	○	0	315MHz	Schrader	●	●
인피니티	Q50	2014/01-2022/07	315MHz		●	●	○	0	315MHz	Continental	●	●
인피니티	Q50	2013/11-2021/12	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	Q60	2017/01-2020/12	315MHz		●	●	○	0	315MHz	Continental	●	●
인피니티	Q60	2016/10-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	Q70	2018/10-2021/12	433MHz 407003JA0A		●	●	○	0	433MHz	Continental	●	●
인피니티	Q70	2013/07-2020/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
인피니티	Q70	2013/07-2020/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	Q70	2014/11-2021/12	433MHz 407006WY0B		●	●	○	0	433MHz	Pacific	●	●
인피니티	QX50	2013/09-2018/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
인피니티	QX50	2018/04-2022/05	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	QX50	2016/12-2018/03	433MHz 407001AY0A		●	●	○	0	433MHz	Schrader	●	●
인피니티	QX50	2014/05-2018/03	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	QX60	2018/08-2021/12	433MHz 407009DJ0A		●	●	○	0	433MHz	Continental	●	●
인피니티	QX60	2012/04-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	QX70	2014/05-2019/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	QX80	2014/09-2020/12	433MHz 407006WY0C		●	●	○	0	433MHz	Pacific	●	●
인피니티	QX80	2013/10-2016/09	433MHz		●	●	○	0	433MHz	Pacific	●	●
재규어	E-페이스	2019/01-2022/12	433MHz	X540	●	●	○	0/A	433MHz	Continental	●	●
재규어	E-페이스	2017/01-2018/12	433MHz	X540	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-페이스	2019/01-2022/12	433MHz	X761	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-페이스	2022/01-2025/06	433MHz M8E21A159AA	X761	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-페이스	2015/01-2018/12	433MHz	X761	●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
재규어	F-타요	2012/11-2016/04	433MHz AH521A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타요	2016/05-2018/12	433MHz GX631A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타요	2016/05-2018/12	433MHz FW931A159AB	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타요	2019/01-2021/06	433MHz FW931A159AB	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타요	2021/01-2023/12	433MHz M8E21A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타요	2019/01-2025/06	433MHz GX631A159AA	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타요	2012/11-2016/04	315MHz AH521A159CA	X152	●	●	○	0/A	315MHz	Continental	●	●
재규어	F-타요	2012/11-2016/04	433MHz FW931A159AB	X152	●	●	○	0/A	433MHz	Continental	●	●
재규어	I-페이스	2017/01-2018/12	433MHz	X590	●	●	○	0/A	433MHz	Continental	●	●
재규어	I-페이스	2021/01-2023/12	433MHz M8E21A159AA	X590	●	●	○	0/A	433MHz	Continental	●	●
재규어	I-페이스	2019/01-2023/12	433MHz GX631A159AA	X590	●	●	○	0/A	433MHz	Continental	●	●
재규어	S-타요	1998/10-2011/08	433MHz	X200	●	●	○	0/A	433MHz	Continental	●	●
재규어	S-타요	1998/10-2011/08	315MHz	X200	●	●	○	0/A	315MHz	Continental	●	●
재규어	X-타요	2001/01-2009/12	433MHz	X400	●	●	○	0/A	433MHz	Continental	●	●
재규어	X-타요	2001/01-2009/12	315MHz	X400	●	●	○	0/A	315MHz	Continental	●	●
재규어	XE	2015/01-2018/12	433MHz GX631A159AA	X760	●	●	○	0/A	433MHz	Continental	●	●
재규어	XE	2015/04-2018/12	433MHz FW931A159AB	X760	●	●	○	0/A	433MHz	Continental	●	●
재규어	XE	2019/01-2022/12	433MHz GX631A159AA	X760	●	●	○	0/A	433MHz	Continental	●	●
재규어	XE	2022/01-2023/12	433MHz M8E21A159AA	X760	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2015/09-2018/12	433MHz	X260	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2014/07-2015/05	433MHz	X260	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2009/04-2015/08	315MHz	X250	●	●	○	0/A	315MHz	Continental	●	●
재규어	XF	2007/01-2015/08	433MHz	X250	●	●	○	0/A	433MHz	Continental	●	●
재규어	XF	2019/01-2025/06	433MHz GX631A159AA	X260	●	●	○	0/A	433MHz	Continental	●	●
재규어	XJ	2010/01-2020/04	433MHz AH521A159AA	X351	●	●	○	0/A	433MHz	Continental	●	●
재규어	XJ	2010/01-2020/04	433MHz GX631A159AA	X351	●	●	○	0/A	433MHz	Continental	●	●
재규어	XJ	2002/12-2009/12	433MHz	X350	●	●	○	0/A	433MHz	Continental	●	●
재규어	XK	2006/01-2009/12	315MHz	X150	●	●	○	0/A	315MHz	Continental	●	●
재규어	XK	2006/01-2009/12	433MHz	X150	●	●	○	0/A	433MHz	Continental	●	●
재규어	XK	2010/01-2015/12	315MHz	X150	●	●	○	0/A	315MHz	Continental	●	●
재규어	XK	2010/01-2015/12	433MHz	X150	●	●	○	0/A	433MHz	Continental	●	●
지프	체로키	2019/01-2022/12	315MHz		●	●	○	0/A	315MHz	TRW	●	●
지프	체로키	2018/01-2023/12	433MHz	KL	●	●	○	0/A	433MHz	TRW	●	●
지프	체로키	2018/01-2018/12	315MHz		●	●	○	0/A	315MHz	TRW	●	●
지프	체로키	2017/01-2017/12	433MHz	KL	●	●	●	0/A	433MHz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
지프	체로키	2014/01-2017/12	315MHz		●	●	●	0/A	315MHz	TRW	●	●
지프	체로키	2014/01-2016/12	433MHz	KL	●	●	●	0/A	433MHz	TRW	●	●
지프	컴맨더	2006/01-2007/12	433MHz	XK	●	●	●	0/A	433MHz	Continental	●	●
지프	컴맨더	2008/01-2010/12	433MHz	XK	●	●	●	0/A	433MHz	Schrader	●	●
지프	컴맨더	2006/01-2007/12	315MHz	XK	●	●	●	0/A	315MHz	Continental	●	●
지프	컴파스	2010/01-2012/12	315MHz		●	●	●	0/A	315MHz	Continental	●	●
지프	컴파스	2007/01-2009/12	315MHz	MK49	●	●	●	0/A	315MHz	Continental	●	●
지프	컴파스	2006/05-2017/12	433MHz	MK49	●	●	●	0/A	433MHz	Schrader	●	●
지프	컴파스	2019/01-2025/12	433MHz	MP/MX	●	●	○	0/A	433MHz	Continental	●	●
지프	컴파스	2019/01-2021/12	433MHz	551	●	●	○	0/A	433MHz	Continental	●	●
지프	컴파스	2018/01-2018/12	433MHz	551	●	●	○	0/A	433MHz	Continental	●	●
지프	컴파스	2017/01-2017/12	433MHz	551	●	●	●	0/A	433MHz	Continental	●	●
지프	Gladiator	2019/03-2022/12	433MHz MRXAG4WA5		●	●	○	0/A	433MHz	Schrader	●	●
지프	Gladiator	2021/07-2025/12	433MHz Conti		●	●	○	0/A	433MHz	Continental	●	●
지프	그랜드 체로키	2018/01-2022/12	433MHz 68252493AB	WK	●	●	○	0/A	433MHz	Continental	●	●
지프	그랜드 체로키	2016/01-2017/12	433MHz	WK	●	●	●	0/A	433MHz	Continental	●	●
지프	그랜드 체로키	2012/01-2015/12	433MHz	WK74	●	●	●	0/A	433MHz	Schrader	●	●
지프	그랜드 체로키	2021/01-2023/12	433MHz Conti		●	●	○	0/A	433MHz	Continental	●	●
지프	그랜드 체로키	2011/01-2011/12	433MHz	WK74	●	●	●	0/A	433MHz	Schrader	●	●
지프	그랜드 체로키	2005/01-2006/05	433MHz		●	●	●	0/A	433MHz	Continental	●	●
지프	그랜드 체로키	2016/01-2017/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
지프	그랜드 체로키	2006/06-2010/12	433MHz	WH	●	●	●	0/A	433MHz	Schrader	●	●
지프	그랜드 체로키	2006/01-2007/12	315MHz	WK	●	●	●	0/A	315MHz	Schrader	●	●
지프	그랜드 체로키	2004/05-2005/12	315MHz	WK	●	●	●	0/A	315MHz	Continental	●	●
지프	그랜드 체로키	2024/01-2025/12	433MHz Conti		●	●	○	0/A	433MHz	Continental	●	●
지프	그랜드 체로키	2023/11-2025/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
지프	그랜드 체로키	2021/01-2023/12	433MHz	WL	●	●	○	0/A	433MHz	Continental	●	●
지프	패트리오트	2007/01-2008/12	433MHz	MK	●	●	●	0/A	433MHz	Continental	●	●
지프	패트리오트	2007/01-2008/12	315MHz		●	●	●	0/A	315MHz	Schrader	●	●
지프	패트리오트	2009/01-2014/12	315MHz	MK	●	●	●	0/A	315MHz	Schrader	●	●
지프	패트리오트	2009/01-2014/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
지프	레니게이드	2019/01-2025/06	315MHz		●	●	○	0/A	315MHz	Continental	●	●
지프	레니게이드	2020/01-2022/12	433MHz 53394085		●	●	○	0/A	433MHz	Continental	●	●
지프	레니게이드	2015/01-2016/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
지프	레니게이드	2017/01-2017/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
지프	레니게이드	2018/01-2018/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●
지프	레니게이드	2018/01-2018/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
지프	레니게이드	2018/01-2025/12	433MHz 68193586AC		●	●	○	0/A	433MHz	Continental	●	●
지프	랭글러	2018/01-2019/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
지프	랭글러	2019/01-2020/12	433MHz	JL	●	●	○	0/A	433MHz	Schrader	●	●
지프	랭글러	2021/01-2024/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
지프	랭글러	2010/01-2012/12	315MHz	JK	●	●	●	0/A	315MHz	Schrader	●	●
지프	랭글러	2007/01-2009/12	315MHz	JK	●	●	●	0/A	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
지프	랭글러	2010/01-2012/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
지프	랭글러	2010/01-2013/12	433MHz	JK72	●	●	●	0/A	433MHz	Schrader	●	●
지프	랭글러	2019/01-2019/12	433MHz	J3	●	●	○	0/A	433MHz	Schrader	●	●
지프	랭글러	2021/07-2025/12	433MHz Conti		●	●	○	0/A	433MHz	Continental	●	●
지프	랭글러	2014/01-2017/12	433MHz	JL	●	●	●	0/A	433MHz	Schrader	●	●
기아	Bongo	2020/01-2023/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	Bongo	2017/01-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	Bongo	2014/01-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	카렌스	2017/01-2019/12	433MHz 529332J100	RP	●	●	○	0/A	433MHz	Continental	●	●
기아	카렌스	2006/01-2019/12	433MHz	RP	●	●	○	0/A	433MHz	Continental	●	●
기아	카니발	2005/01-2014/12	315MHz	YP	●	●	○	0	315MHz	Lear	●	●
기아	카니발	2024/01-2025/12	433MHz	KA4	●	●	○	0/A	433MHz	Continental	●	●
기아	카니발	2020/01-2023/12	433MHz	KA4	●	●	○	0/A	433MHz	Continental	●	●
기아	카니발	2019/01-2024/12	433MHz	YP/YPi	●	●	○	0	433MHz	Schrader	●	●
기아	카니발	2018/01-2018/12	433MHz 52933C1100		●	●	○	0	433MHz	Schrader	●	●
기아	카니발	2014/01-2018/12	433MHz	YP/Sedan	●	●	○	0	433MHz	Schrader	●	●
기아	E-Soul	2019/04-2025/06	433MHz	SK3	●	●	○	0/A	433MHz	Continental	●	●
기아	EV6	2025/01-2025/06	433MHz 52940E2100		●	●	○	0	433MHz	Schrader	●	●
기아	EV6	2025/01-2025/06	433MHz 52940BE000		●	●	○	0/A	433MHz	Continental	●	●
기아	EV6	2025/01-2025/06	433MHz 52940L1100		●	●	○	0/A	433MHz	Continental	●	●
기아	EV6	2025/01-2025/06	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
기아	EV6	2025/01-2025/06	433MHz 52940Q3100		●	●	○	0/A	433MHz	Schrader	●	●
기아	EV6	2021/03-2024/12	433MHz 52940BV100		●	●	○	0/A	433MHz	Schrader	●	●
기아	EV6	2021/03-2024/12	433MHz 52940CG100		●	●	○	0/A	433MHz	Schrader	●	●
기아	EV6	2021/03-2024/12	433MHz 52940L8200		●	●	○	0/A	433MHz	Schrader	●	●
기아	EV9	2023/07-2025/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
기아	포르테	2009/01-2013/04	315MHz	TD	●	●	○	0	315MHz	Continental	●	●
기아	K3	2012/01-2016/12	433MHz 529333X305		●	●	○	0	433MHz	TRW	●	●
기아	K3	2019/01-2019/12	433MHz TRW	YDC/YD	●	●	○	0/A	433MHz	TRW	●	●
기아	K3	2012/01-2018/12	433MHz TRW	YDC/YD	●	●	○	0	433MHz	TRW	●	●
기아	K3	2018/01-2021/12	433MHz Pacific	BDC/BD	●	●	○	0/A	433MHz	Pacific	●	●
기아	K3	2022/01-2023/12	433MHz	BD	●	●	○	0/A	433MHz	Pacific	●	●
기아	K5	2011/01-2012/12	433MHz	TF/TF HEV	●	●	○	0	433MHz	Continental	●	●
기아	K5	2013/01-2015/06	433MHz Hybrid	TF/TF HEV	●	●	○	0	433MHz	Continental	●	●
기아	K5	2015/07-2021/12	433MHz Hybrid	JF/JF HEV	●	●	○	0/A	433MHz	Continental	●	●
기아	K5	2020/01-2024/12	433MHz	DL3	●	●	○	0/A	433MHz	Continental	●	●
기아	K7	2008/01-2012/12	433MHz	VG	●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
기아	K7	2013/01-2016/12	433MHz Hybrid	VG	●	●	○	0	433MHz	Continental	●	●
기아	K7	2016/01-2021/12	433MHz	YG	●	●	○	0	433MHz	Continental	●	●
기아	K8	2021/07-2024/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
기아	K8	2024/05-2024/12	433MHz 52940N1000		●	●	○	0/A	433MHz	Schrader	●	●
기아	K9	2019/01-2021/12	433MHz	RJ	●	●	○	0	433MHz	Schrader	●	●
기아	K9	2022/01-2025/06	433MHz	RJ	●	●	○	0	433MHz	Schrader	●	●
기아	K9	2024/10-2025/06	433MHz 52940E2100	RJ	●	●	○	0	433MHz	Schrader	●	●
기아	K9	2011/01-2018/12	433MHz	KH	●	●	○	0	433MHz	Schrader	●	●
기아	모하비	2022/01-2023/12	433MHz 52940T6000	HM PE2	●	●	○	0/A	433MHz	Continental	●	●
기아	모하비	2007/01-2007/12	433MHz 529333V600	HM	●	●	○	0	433MHz	TRW	●	●
기아	모하비	2007/01-2007/12	433MHz 529333M000		●	●	○	0	433MHz	TRW	●	●
기아	모하비	2008/01-2014/08	433MHz		●	●	○	0/A	433MHz	TRW	●	●
기아	모하비	2022/01-2024/12	433MHz	HM PE2	●	●	○	0/A	433MHz	Continental	●	●
기아	모하비	2014/09-2015/12	433MHz	HM	●	●	○	0/A	433MHz	TRW	●	●
기아	모하비	2016/01-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	모하비	2017/01-2020/12	433MHz 529332J100		●	●	○	0/A	433MHz	Continental	●	●
기아	모하비	2020/01-2020/12	433MHz 52933D4100		●	●	○	0/A	433MHz	Continental	●	●
기아	모하비	2020/01-2021/12	433MHz 52933D2100	HM PE2	●	●	○	0/A	433MHz	Continental	●	●
기아	모닝	2014/01-2024/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	모닝	2017/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	Morning 3	2017/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	Niro	2023/01-2025/06	433MHz 52940CG100	SG2	●	●	○	0	433MHz	Schrader	●	●
기아	Niro	2022/01-2025/06	433MHz		●	●	○	0	433MHz	Schrader	●	●
기아	Niro	2016/01-2021/12	433MHz	DE	●	●	○	0	433MHz	Continental	●	●
기아	Opirus	2006/01-2014/12	433MHz		●	●	○	0	433MHz	TRW	●	●
기아	옵티마	2005/12-2010/12	315MHz	MG	●	●	○	0	315MHz	Lear	●	●
기아	Pride	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	Pride	2018/01-2018/12	433MHz Lo Line	YB	●	●	○	0	433MHz	TRW	●	●
기아	Pride	2018/01-2018/12	433MHz Hi Line	YB	●	●	○	0	433MHz	TRW	●	●
기아	Pride	2012/01-2017/12	433MHz	UB	●	●	○	0	433MHz	TRW	●	●
기아	Ray	2018/01-2022/12	433MHz 52933B1100		●	●	○	0	433MHz	Continental	●	●
기아	Ray	2023/01-2023/12	433MHz 52940CG100		●	●	○	0	433MHz	Schrader	●	●
기아	Ray	2011/01-2023/12	433MHz	Elec	●	●	○	0	433MHz	Continental	●	●
기아	Seltos	2019/01-2024/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
기아	Sonet	2021/01-2025/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
기아	Sonet	2024/01-2025/06	433MHz 52940E2100	QYC	●	●	○	0/A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
기아	Sonet	2024/01-2025/06	433MHz 52940CG100	QYC	●	●	○	0/A	433MHz	Schrader	●	●
기아	Sonet	2024/01-2025/06	433MHz	QYC	●	●	○	0/A	433MHz	Schrader	●	●
기아	쏘렌토	2020/01-2024/12	433MHz	MQ4/MQ4 PHEV	●	●	○	0	433MHz	Continental	●	●
기아	쏘렌토	2018/01-2020/09	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	쏘렌토	2014/01-2018/06	433MHz 529333N100	UMA	●	●	○	0	433MHz	Continental	●	●
기아	쏘렌토	2011/01-2015/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	쏘렌토	2009/01-2010/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	쏘렌토	2006/01-2008/12	433MHz	XM	●	●	○	0	433MHz	Continental	●	●
기아	쏘울	2013/11-2016/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
기아	쏘울	2023/01-2025/06	433MHz	SK3	●	●	○	0/A	433MHz	Continental	●	●
기아	쏘울	2023/01-2025/06	433MHz 52940T6100	SK3	●	●	○	0/A	433MHz	Continental	●	●
기아	쏘울	2008/06-2013/10	433MHz	AM	●	●	○	0	433MHz	Continental	●	●
기아	쏘울	2019/01-2022/12	433MHz	SK3	●	●	○	0/A	433MHz	Continental	●	●
기아	쏘울 EV	2013/01-2018/12	433MHz	PS EV	●	●	○	0	433MHz	Schrader	●	●
기아	쏘울 EV	2019/01-2019/12	433MHz	PS EV	●	●	○	0/A	433MHz	Schrader	●	●
기아	스포티지	2013/10-2016/01	433MHz	SL	●	●	○	0/A	433MHz	TRW	●	●
기아	스포티지	2010/01-2014/01	433MHz Hi Line	SL	●	●	○	0	433MHz	TRW	●	●
기아	스포티지	2010/01-2013/12	433MHz Lo Line	SL	●	●	○	0	433MHz	TRW	●	●
기아	스포티지	2009/01-2010/12	315MHz Lo Line	KM/SL	●	●	○	0	315MHz	TRW	●	●
기아	스포티지	2008/01-2008/12	315MHz Lo Line	KM	●	●	○	0	315MHz	TRW	●	●
기아	스포티지	2005/01-2007/12	315MHz Lo Line	KM	●	●	○	0	315MHz	TRW	●	●
기아	스포티지	2021/01-2025/06	433MHz 52940L1100		●	●	○	0/A	433MHz	Continental	●	●
기아	스포티지	2015/11-2021/06	433MHz	QL/QLE	●	●	○	0/A	433MHz	Continental	●	●
기아	스포티지	2023/01-2025/06	433MHz 52940L8200	NQ5	●	●	○	0/A	433MHz	Schrader	●	●
기아	Sportage R	2014/01-2023/12	433MHz		●	●	○	0	433MHz	TRW	●	●
기아	Sportage R	2010/01-2013/12	433MHz		○	●	○	A	433MHz	TRW	●	●
기아	Stinger	2018/01-2025/06	433MHz	CK	●	●	○	0/A	433MHz	Schrader	●	●
기아	Stinger	2017/06-2017/12	433MHz	CK	●	●	○	0	433MHz	Schrader	●	●
기아	Stinger	2017/01-2017/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
기아	Stonic	2017/11-2021/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	Stonic	2017/01-2025/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
람보르기니	아벤타도	2011/01-2023/12	433MHz	LB834	○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	Few Off	2017/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	허라칸	2014/01-2024/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	One Off	2016/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	Urus	2020/01-2024/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	Urus	2017/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
랜드로버	디펜더	2020/01-2025/06	433MHz M8E21A159AA	L663	●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
랜드로버	디펜더	2020/01-2023/12	433MHz GX631A159AA	L663	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디펜더	2020/01-2023/12	433MHz FW931A159AB	L663	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2021/01-2025/06	433MHz M8E21A159AA	L462	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2019/01-2022/12	433MHz GX631A159AA	L462	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2017/01-2018/12	433MHz GX631A159AA	L462	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2009/12-2016/12	315MHz AH521A159CA	L319	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	디스커버리	2009/12-2016/12	433MHz AH521A159AA	L319	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2009/12-2016/12	433MHz FW931A159AB	L319	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2009/12-2016/12	433MHz BH521A159AA	L319	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2009/12-2016/12	433MHz GX631A159AA	L319	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2009/01-2016/12	315MHz BH521A159CA	L319	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	디스커버리	2004/06-2009/11	433MHz	L319	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리	2004/06-2009/11	315MHz	L319	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	디스커버리	2002/01-2004/05	433MHz	L318	●	●	○	0/A	433MHz	Huf/Beru	●	●
랜드로버	디스커버리 스포츠	2021/01-2025/06	433MHz M8E21A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리 스포츠	2019/01-2022/12	433MHz BH521A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리 스포츠	2019/01-2022/12	433MHz GX631A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리 스포츠	2014/06-2018/12	433MHz GX631A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	디스커버리 스포츠	2014/01-2018/12	433MHz BH521A159AA	L550	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2014/12	433MHz BH521A159AA	L359	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2014/12	433MHz FW931A159AB	L359	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2014/12	433MHz GX631A159AA	L359	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2014/12	315MHz BH521A159CA	L359	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2014/12	315MHz 4H231A159CA	L359	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2014/12	315MHz AH521A159CA	L359	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버	2016/01-2018/12	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2013/01-2015/12	433MHz AH521A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2013/01-2015/12	315MHz AH521A159CA	L405	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버	2013/01-2015/12	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
랜드로버	렌지로버	2013/01-2015/12	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2016/01-2018/01	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2005/01-2009/12	433MHz	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2019/01-2021/12	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2020/02-2021/12	433MHz M8E21A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2010/01-2012/12	315MHz BH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버	2005/01-2009/12	315MHz	L322	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버	2010/01-2012/12	433MHz GX631A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2010/01-2012/12	433MHz BH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2022/01-2023/12	433MHz GX631A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2002/01-2004/12	433MHz	L322	●	●	○	0/A	433MHz	Huf/Beru	●	●
랜드로버	렌지로버	2010/01-2012/12	433MHz AH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2022/01-2025/06	433MHz M8E21A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버	2010/01-2012/12	315MHz AH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 에보크	2015/07-2018/12	315MHz BH521A159CA	L538	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 에보크	2015/07-2017/12	433MHz FW931A159AB	L538	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2011/07-2015/06	433MHz BH521A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2011/07-2015/06	315MHz BH521A159CA	L538	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 에보크	2011/07-2015/06	433MHz FW931A159AB	L538	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2011/07-2015/06	315MHz AH521A159CA	L538	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 에보크	2021/07-2025/06	433MHz M8E21A159AA	L551	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2019/01-2023/12	433MHz GX631A159AA	L551	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2011/07-2016/12	433MHz AH521A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2015/07-2018/12	433MHz GX631A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2015/07-2018/12	433MHz BH521A159AA	L538	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2005/01-2009/12	433MHz	L320	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2005/01-2009/12	315MHz	L320	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2010/01-2013/06	433MHz GX631A159AA	L320	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2010/01-2013/06	315MHz AH521A159CA	L320	●	●	○	0/A	315MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
랜드로버	렌지로버 스포츠	2010/01-2013/06	433MHz FW931A159AB	L320	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2010/01-2013/06	433MHz BH521A159AA	L320	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2013/07-2015/12	315MHz AH521A159CA	L494	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2016/01-2018/12	433MHz FW931A159AB	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2016/01-2018/12	433MHz GX631A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2013/07-2015/12	433MHz AH521A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2010/01-2013/06	433MHz AH521A159AA	L320	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2013/07-2015/12	433MHz GX631A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2013/07-2015/12	433MHz FW931A159AB	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2010/01-2013/06	315MHz BH521A159CA	L320	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2022/10-2025/06	433MHz	L461	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2021/01-2022/09	433MHz M8E21A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2019/01-2022/09	433MHz FW931A159AB	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2019/01-2022/09	433MHz GX631A159AA	L494	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 벨라	2017/01-2018/12	433MHz	L560	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 벨라	2019/01-2023/12	433MHz GX631A159AA	L560	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 벨라	2021/01-2025/06	433MHz M8E21A159AA	L560	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2005/01-2009/12	315MHz	L322	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 보그	2010/01-2012/12	315MHz BH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 보그	2010/01-2012/12	315MHz AH521A159CA	L322	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 보그	2010/01-2012/12	433MHz BH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2019/01-2021/12	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2010/01-2012/12	433MHz AH521A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2013/01-2015/12	315MHz AH521A159CA	L405	●	●	○	0/A	315MHz	Continental	●	●
랜드로버	렌지로버 보그	2013/01-2015/12	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2013/01-2015/12	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2016/01-2018/01	433MHz FW931A159AB	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2016/01-2018/12	433MHz GX631A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2020/02-2021/12	433MHz M8E21A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
랜드로버	렌지로버 보그	2022/01-2023/12	433MHz GX631A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2022/01-2025/06	433MHz M8E21A159AA	L460	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2005/01-2009/12	433MHz	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2010/01-2012/12	433MHz GX631A159AA	L322	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2013/01-2015/12	433MHz AH521A159AA	L405	●	●	○	0/A	433MHz	Continental	●	●
랜드로버	렌지로버 보그	2002/01-2004/12	433MHz	L322	●	●	○	0/A	433MHz	Huf/Beru	●	●
렉서스	CT Series	2013/12-2022/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	ES Series	2006/01-2012/05	433MHz PMV-107K/1019		●	●	○	0	433MHz	Pacific	●	●
렉서스	ES Series	2012/06-2021/01	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	ES Series	2018/06-2025/06	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
렉서스	GS Series	2012/01-2022/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	GX Series	2013/09-2019/08	315MHz PMV-C010		●	●	○	0	315MHz	Pacific	●	●
렉서스	IS Series	2005/08-2022/12	315MHz PMV-107J/1017/C11A/1037		●	●	○	0	315MHz	Pacific	●	●
렉서스	IS Series	2013/04-2023/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	LC Series	2017/01-2022/12	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
렉서스	LS Series	2017/10-2025/06	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
렉서스	LS Series	2012/10-2017/09	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	LX Series	2015/10-2021/12	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
렉서스	NX Series	2014/01-2024/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	RC Series	2014/09-2023/01	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	RX Series	2015/09-2025/06	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
렉서스	RX Series	2015/09-2025/06	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
렉서스	RX Series	2009/01-2015/10	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
렉서스	SC Series	2006/08-2010/12	315MHz PMV-107J/1017/C11A/1037		●	●	○	0	315MHz	Pacific	●	●
렉서스	UX Series	2018/01-2024/12	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
링컨	에비에이터	2024/05-2025/12	433MHz PR3Z1A189M		●	●	○	0/S	433MHz	Schrader	●	●
링컨	에비에이터	2019/05-2025/06	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
링컨	에비에이터	2019/05-2025/06	315MHz		●	●	○	0/S	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
링컨	컨티넨탈	2016/07-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	Corsair	2019/05-2025/06	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
링컨	MKC	2014/04-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKS	2017/01-2020/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
링컨	MKS	2011/01-2012/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
링컨	MKS	2013/01-2016/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKS	2008/01-2010/12	315MHz		●	●	●	0/S	315MHz	Lear	●	●
링컨	MKX	2018/01-2019/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
링컨	MKX	2016/01-2017/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKX	2015/01-2015/12	433MHz		●	●	●	S	433MHz	Schrader	●	●
링컨	MKZ	2013/01-2014/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2017/01-2021/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2015/09-2016/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2015/01-2016/12	433MHz DR3V1A180DA		●	●	●	0/S	433MHz	Schrader	●	●
링컨	Nautilus	2023/09-2025/12	433MHz PR3Z1A189M	CDX707	●	●	○	0/S	433MHz	Schrader	●	●
링컨	Nautilus	2023/09-2025/12	433MHz	CDX707	●	●	○	0/S	433MHz	Schrader	●	●
링컨	Nautilus	2018/01-2023/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
링컨	네비게이터	2021/01-2025/06	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
링컨	네비게이터	2024/01-2025/06	433MHz PR3Z1A189M		●	●	○	0/S	433MHz	Schrader	●	●
링컨	네비게이터	2018/01-2023/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
링컨	타운카	2012/01-2013/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
링컨	타운카	2005/07-2011/12	315MHz		●	●	○	S	315MHz	Lear	●	●
Lotus	3-Eleven	2015/01-2021/06	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Elise	2000/09-2021/05	433MHz	Monza	○	●	○	A	433MHz	Schrader	●	●
Lotus	Evora	2010/01-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Exige	2000/09-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
마세라티	지블리	2018/01-2020/12	433MHz	M156/ M157	●	●	○	0/A	433MHz	Schrader	●	●
마세라티	지블리	2018/10-2023/12	433MHz	M156D	●	●	○	0/A	433MHz	Continental	●	●
마세라티	지블리	2013/01-2017/12	433MHz	M156/ M157	●	●	○	0/A	433MHz	Schrader	●	●
마세라티	그란싸브리오	2017/01-2020/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
마세라티	그란 투리스모	2014/01-2022/01	433MHz	M145	●	●	○	0/A	433MHz	Schrader	●	●
마세라티	Grecale	2022/01-2023/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
마세라티	레반테	2019/01-2025/12	433MHz 50554747		●	●	○	0/A	433MHz	Continental	●	●
마세라티	레반테	2018/01-2022/12	433MHz 05154876AA		●	●	○	0/A	433MHz	Schrader	●	●
마세라티	레반테	2015/01-2017/12	433MHz 05154876AA		●	●	○	0/A	433MHz	Schrader	●	●
마세라티	레반테	2015/01-2019/12	433MHz A0009050030		●	●	○	0/A	433MHz	Schrader	●	●
마세라티	MC20	2020/01-2025/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
마세라티	콰트로폴테	2013/01-2017/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
마세라티	콰트로폴테	2018/01-2022/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
마세라티	콰트로폴테	2018/01-2022/12	433MHz 50554747		○	●	○	A	433MHz	Continental	●	●
마세라티	스파이더	2001/07-2008/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	500 Series	2015/01-2022/12	433MHz RDE011		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	600 Series	2014/03-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	700 Series	2017/01-2024/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	GT	2019/01-2024/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	P1	2013/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Senna	2018/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Speedtail	2019/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	A Class	2012/01-2014/03	433MHz	176	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	A Class	2014/04-2018/05	433MHz	176	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	A Class	2018/06-2025/06	433MHz	177	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	A Class	2018/06-2025/06	315MHz A0009054204	177	●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	AMG GT	2014/01-2023/12	433MHz	C190	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	AMG GT	2023/06-2025/06	433MHz A0009058413	192	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	AMG GT	2023/06-2025/06	315MHz A0009058513	192	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	AMG GT	2022/01-2025/06	433MHz	192	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	AMG GT	2018/11-2023/12	433MHz	290	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	AMG GT	2018/11-2023/12	315MHz	290	●	●	○	0/A	315MHz	Schrader	●	●
메르세데스 벤츠	B Class	2019/02-2025/06	433MHz A0009054104	247	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	B Class	2019/02-2025/06	315MHz	247	●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	B Class	2011/11-2019/01	433MHz	246	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	C Class	2007/04-2020/12	433MHz	W205	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	C Class	2022/09-2025/06	315MHz A0009058513	206	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	C Class	2022/09-2025/06	433MHz A0009058413	206	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	C Class	2021/06-2025/06	433MHz	206	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	C Class	2018/01-2018/12	433MHz	C205	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	C Class	2018/06-2023/12	433MHz A0009053907	C205	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CL Class	2007/01-2014/12	433MHz Continental	216	●	●	○	0/A	433MHz	Continental	●	●
메르세데스 벤츠	CL Class	2010/01-2015/12	433MHz	216	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CLA Class	2019/05-2025/06	315MHz A0009054204	118	●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	CLA Class	2012/12-2014/05	433MHz	117	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CLA Class	2014/06-2019/04	433MHz	117	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CLA Class	2019/05-2025/06	433MHz	118	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	CLC Class	2008/01-2018/06	433MHz	216	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CLE Class	2023/06-2025/06	315MHz A0009058513	236	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	CLE Class	2023/06-2025/06	433MHz A0009058413	236	●	●	○	A/0	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
메르세데스 벤츠	CLK Class	2002/01-2018/06	433MHz	209	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CLS Class	2018/01-2025/06	315MHz	257	●	●	○	0/A	315MHz	Schrader	●	●
메르세데스 벤츠	CLS Class	2018/01-2025/06	433MHz	257	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	CLS Class	2012/01-2017/12	433MHz	218	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	E Class	2015/11-2023/12	433MHz	W213/BR238	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	E Class	2023/10-2025/06	315MHz A0009058513	214	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	E Class	2023/10-2025/06	433MHz A0009058413	214	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	E Class	2005/06-2011/10	433MHz	W211	●	●	○	0/A	433MHz	Continental	●	●
메르세데스 벤츠	E Class	2009/07-2014/05	433MHz	W212/C207	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	E Class	2014/06-2018/12	433MHz	W212	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	E Class	2016/01-2023/12	315MHz	213	●	●	○	0/A	315MHz	Schrader	●	●
메르세데스 벤츠	EQA	2020/01-2025/06	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	EQA	2020/01-2025/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	EQB	2021/01-2025/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	EQB	2022/01-2025/06	315MHz		●	●	○	0	315MHz	Huf/Beru	●	●
메르세데스 벤츠	EQC	2019/01-2025/06	433MHz	293	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	EQC	2019/01-2025/06	315MHz	293	●	●	○	0	315MHz	Schrader	●	●
메르세데스 벤츠	EQE	2022/01-2025/06	433MHz	295	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	EQE	2022/01-2025/06	315MHz	295	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	EQE	2022/09-2025/06	315MHz A0009058513	295	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	EQE	2022/09-2025/06	433MHz A0009058413	295	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	EQS	2021/01-2025/06	315MHz	297	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	EQS	2021/01-2025/06	433MHz	297	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	EQS	2022/09-2025/06	315MHz A0009058513	297	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	EQS	2022/09-2025/06	433MHz A0009058413	297	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	EQV	2024/01-2025/06	433MHz A0009057205		●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	G Class	2018/06-2025/06	315MHz	463	●	●	○	0/A	315MHz	Schrader	●	●
메르세데스 벤츠	G Class	2007/04-2018/05	433MHz	G463/461	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	G Class	2018/06-2025/06	433MHz	463	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	GLA Class	2020/01-2025/06	315MHz A0009054204		●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	GLA Class	2020/01-2025/06	433MHz	H247	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	GLA Class	2018/01-2020/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
메르세데스 벤츠	GLB Class	2019/01-2025/06	315MHz	247	●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	GLB Class	2019/01-2025/06	433MHz	247	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	GLC Class	2016/09-2022/12	433MHz A0009053907	C253	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	GLC Class	2022/09-2025/06	315MHz A0009058513	254	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	GLC Class	2022/09-2025/06	433MHz A0009058413	254	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	GLC Class	2022/01-2025/06	315MHz	254	●	●	○	0/A	315MHz	Schrader	●	●
메르세데스 벤츠	GLC Class	2022/06-2025/06	433MHz	254	●	●	○	A/0	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
메르세데스 벤츠	GLC Class	2015/01-2019/07	433MHz	X253	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	GLE Class	2012/01-2020/12	433MHz	X166	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	GLE Class	2018/01-2025/06	315MHz	W167	●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	GLE Class	2018/10-2025/06	433MHz	V167	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	GLK Class	2008/01-2015/09	433MHz	X204	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	GLS Class	2013/01-2019/06	433MHz	X166	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	GLS Class	2019/07-2025/06	433MHz	X167	●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	GLS Class	2020/01-2025/06	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
메르세데스 벤츠	GT	2014/01-2022/12	433MHz	GT	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	ML Class	2011/09-2015/09	433MHz	166	●	●	○	0	433MHz	Schrader	●	●
메르세데스 벤츠	S Class	2022/09-2025/06	315MHz A0009058513	223	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	S Class	2022/09-2025/06	433MHz A0009058413	223	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	S Class	2022/01-2025/06	315MHz	223	●	●	○	0/A	315MHz	Schrader	●	●
메르세데스 벤츠	S Class	2017/01-2017/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	S Class	2009/06-2020/12	433MHz	W222/C217	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	S Class	2021/06-2025/06	433MHz	223	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	S Class 쿠페	2014/01-2022/12	433MHz	217	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	SL Class	2021/09-2025/06	433MHz	232	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	SL Class	2021/09-2025/06	315MHz A0009058513	232	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	SL Class	2021/09-2025/06	315MHz	232	●	●	○	A/0	315MHz	Schrader	●	●
메르세데스 벤츠	SL Class	2021/09-2025/06	433MHz A0009058413	232	●	●	○	A/0	433MHz	Schrader	●	●
메르세데스 벤츠	SL Class	2012/01-2020/12	433MHz	W231	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	SLC Class	2016/01-2020/06	433MHz	R172	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	SLK Class	2004/01-2021/12	433MHz	R171, R172	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	스프린터	2024/06-2025/12	433MHz 6-wheel		○	●	○	A	433MHz	BHSENS	●	●
메르세데스 벤츠	스프린터	2024/06-2025/12	433MHz A0009052816		●	●	○	0/A	433MHz	BHSENS	●	●
메르세데스 벤츠	스프린터	2018/01-2025/06	433MHz A0009054104		●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	V Class	2014/01-2025/06	433MHz	W447	●	●	○	0/A	433MHz	Schrader	●	●
메르세데스 벤츠	V Class	2024/01-2025/06	433MHz A0009057205		●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	비토	2024/01-2025/06	433MHz A0009057205		●	●	○	0/A	433MHz	Huf/Beru	●	●
메르세데스 벤츠	비토	2014/07-2025/06	433MHz	W447	●	●	○	0/A	433MHz	Schrader	●	●
미니	Aceman	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
미니	카브리오	2023/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
미니	카브리오	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
미니	클럽맨	2007/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
미니	클럽맨	2014/07-2014/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	클럽맨	2007/08-2016/12	433MHz 36236781847		●	●	○	A	433MHz	Huf/Beru	●	●
미니	클럽맨	2015/07-2024/06	433MHz		●	●	○	A	433MHz	Continental	●	●
미니	Convertible	2014/07-2015/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
미니	Convertible	2015/01-2023/12	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
미니	Convertible	2009/01-2014/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	Convertible	2009/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
미니	쿠퍼	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
미니	컨트리맨	2023/11-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
미니	컨트리맨	2023/11-2025/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
미니	컨트리맨	2015/07-2024/06	433MHz Continental		●	●	○	A	433MHz	Continental	●	●
미니	컨트리맨	2014/07-2018/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	컨트리맨	2010/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
미니	컨트리맨	2009/01-2014/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	쿠페	2016/01-2017/12	433MHz		●	●	○	A	433MHz	Continental	●	●
미니	쿠페	2014/07-2015/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	쿠페	2012/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
미니	쿠페	2011/07-2014/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	미니	2014/01-2022/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	미니	2009/01-2015/12	433MHz OYGTSSRE4D		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	미니	2006/03-2024/06	433MHz Continental	F55/F56/R56	●	●	○	A	433MHz	Continental	●	●
미니	페이스맨	2009/01-2014/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	페이스맨	2012/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
미니	페이스맨	2014/07-2018/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	로드스터	2014/05-2015/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
미니	로드스터	2012/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
미니	로드스터	2011/01-2014/12	433MHz 36106856227		●	●	○	0/A	433MHz	Huf/Beru	●	●
미츠비시	이클립스	2006/01-2011/08	315MHz		●	●	○	0	315MHz	Schrader	●	●
미츠비시	아웃랜더	2008/01-2011/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
니산	370Z	2008/10-2010/02	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	370Z	2014/09-2022/06	433MHz 407006WYOB		●	●	○	0/A	433MHz	Pacific	●	●
니산	370Z	2011/07-2022/09	433MHz		●	●	○	0	433MHz	Schrader	●	●
니산	370Z	2010/03-2022/06	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	370Z	2009/10-2011/06	433MHz		●	●	○	0	433MHz	Schrader	●	●
니산	알티마	2012/06-2018/10	433MHz		●	●	○	0	433MHz	Continental	●	●
니산	알티마	2012/01-2014/12	315MHz		●	●	○	0	315MHz	Continental	●	●
니산	알티마	2010/09-2011/12	315MHz 407001AA0B		●	●	○	0	315MHz	Schrader	●	●
니산	알티마	2008/05-2009/05	315MHz 40700JA02B		●	●	○	0	315MHz	Schrader	●	●
니산	알티마	2006/01-2011/12	315MHz		●	●	○	0	315MHz	Schrader	●	●
니산	알티마	2018/11-2020/06	433MHz 407004CB0B		●	●	○	0	433MHz	Continental	●	●
니산	큐브	2011/11-2015/12	315MHz 407001LA0E		●	●	○	0	315MHz	Pacific	●	●
니산	큐브	2010/10-2016/12	315MHz 407003AN1A		●	●	○	0	315MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
니산	큐브	2009/07-2009/10	315MHz 40700JA00C		●	●	○	0	315MHz	Schrader	●	●
니산	큐브	2009/10-2012/02	315MHz		●	●	○	0	315MHz	Schrader	●	●
니산	큐브	2009/02-2009/07	315MHz 40700JA01C		●	●	○	0	315MHz	Schrader	●	●
니산	큐브	2013/01-2016/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	큐브	2012/03-2012/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	GT-R	2008/03-2009/12	315MHz 40700JA01C		●	●	○	0	315MHz	Schrader	●	●
니산	GT-R	2008/03-2010/12	315MHz 40700JA00C		●	●	○	0	315MHz	Schrader	●	●
니산	GT-R	2008/12-2011/05	433MHz		●	●	○	0	433MHz	Schrader	●	●
니산	GT-R	2010/11-2020/04	315MHz		●	●	○	0	315MHz	Schrader	●	●
니산	GT-R	2013/11-2022/08	433MHz 4070062B0A		●	●	○	0	433MHz	Pacific	●	●
니산	GT-R	2011/06-2020/04	433MHz		●	●	○	0	433MHz	Schrader	●	●
니산	쥬크	2014/05-2019/09	433MHz		●	●	○	0	433MHz	Pacific	●	●
니산	쥬크	2010/07-2020/12	315MHz 407001LA0E		●	●	○	0	315MHz	Pacific	●	●
니산	쥬크	2010/07-2012/03	315MHz 407001AA0B		●	●	○	0	315MHz	Schrader	●	●
니산	쥬크	2013/01-2014/10	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	쥬크	2012/03-2012/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	쥬크	2011/07-2012/02	315MHz		●	●	○	0	315MHz	Continental	●	●
니산	리프	2014/05-2016/02	433MHz 407006WY0B		●	●	○	0	433MHz	Pacific	●	●
니산	리프	2018/01-2020/01	433MHz		●	●	○	0	433MHz	Continental	●	●
니산	리프	2014/11-2017/12	433MHz		●	●	○	0	433MHz	Continental	●	●
니산	리프	2013/01-2018/12	315MHz		●	●	○	0	315MHz	Continental	●	●
니산	맥시마	2018/11-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
니산	맥시마	2015/04-2018/12	433MHz 407003JA0B		●	●	○	0	433MHz	Continental	●	●
니산	무라노	2015/01-2021/06	433MHz 407006WY0A		●	●	○	0	433MHz	Pacific	●	●
니산	무라노	2014/10-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
니산	무라노	2004/01-2015/12	433MHz 407001AY0A		●	●	○	0	433MHz	Schrader	●	●
니산	무라노	2004/01-2014/09	433MHz		●	●	○	0	433MHz	Schrader	●	●
니산	패스파인더	2012/09-2019/02	433MHz		●	●	○	0	433MHz	Continental	●	●
니산	콰시카이	2013/12-2017/07	433MHz		●	●	○	0/A	433MHz	Continental	●	●
니산	로그	2013/01-2015/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
니산	로그	2011/07-2012/12	315MHz 40700JK00E		●	●	○	0	315MHz	Pacific	●	●
니산	로그	2009/08-2012/12	315MHz		●	●	○	0	315MHz	Schrader	●	●
니산	로그	2007/08-2009/07	315MHz		●	●	○	0	315MHz	Schrader	●	●
니산	엑스트레일	2018/01-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
푸조	1007	2004/01-2011/12	433MHz		●	●	○	0	433MHz	Continental	●	●
푸조	2008	2013/02-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
푸조	207	2005/11-2013/09	433MHz	A7	●	●	○	0	433MHz	Continental	●	●
푸조	208	2012/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
푸조	3008	2016/06-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
푸조	3008	2013/09-2019/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
푸조	3008	2008/11-2013/08	433MHz	T84	●	●	○	0	433MHz	Schrader	●	●
푸조	307	2007/03-2008/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
푸조	307	2001/01-2007/02	433MHz		●	●	○	0	433MHz	Continental	●	●
푸조	308	2020/01-2024/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
푸조	308	2013/06-2019/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
푸조	308	2007/05-2013/05	433MHz		●	●	○	0	433MHz	Schrader	●	●
푸조	407	2003/01-2012/12	433MHz		●	●	○	0	433MHz	Continental	●	●
푸조	5008	2009/09-2013/08	433MHz		●	●	○	0	433MHz	Schrader	●	●
푸조	5008	2017/01-2024/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
푸조	5008	2013/09-2022/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
푸조	508	2010/09-2013/09	433MHz		●	●	○	0	433MHz	Continental	●	●
푸조	508	2013/10-2022/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
푸조	508	2017/07-2024/12	Indirect	R83	○	○	○	S	N/A	N/A	Indirect	●
푸조	607	1999/09-2004/09	433MHz	6042/Z8	○	●	○	NA	433MHz	Schrader	●	●
푸조	607	2004/10-2012/12	433MHz	Z8	●	●	○	0	433MHz	Continental	●	●
푸조	807	2004/10-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
푸조	RCZ	2009/12-2013/09	433MHz	T75	●	●	○	0	433MHz	Schrader	●	●
Polestar	Polestar 2	2020/07-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Polestar	Polestar 3	2023/03-2024/12	433MHz		○	●	○	NA	433MHz	BHSENS	●	●
포르쉐	911	2009/01-2012/12	315MHz	997	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	911	2019/01-2024/12	433MHz	992	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	911	2017/01-2020/12	433MHz	991	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	911	2014/01-2016/12	315MHz	991T	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	911	2014/01-2016/12	433MHz	991T	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	911	2012/02-2016/12	433MHz	991	●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	911	2011/12-2016/12	315MHz	991	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	911	2009/01-2012/12	433MHz	997	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	911	2007/01-2009/12	433MHz	997T	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	911	2007/01-2009/12	315MHz	997T	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	911	2005/01-2008/12	315MHz	997	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	911	2005/01-2008/12	315MHz 99760602500	997	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	911	2004/01-2008/12	433MHz	997	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	918 스파이더	2013/01-2015/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2017/01-2025/12	315MHz	982SP	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2017/01-2025/12	433MHz	982/982SP	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2012/01-2016/12	315MHz	981/981SP	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2009/01-2012/12	315MHz	987	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2004/01-2008/12	315MHz	987	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2004/01-2008/12	433MHz	987	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2012/01-2016/12	433MHz	981	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	Carrera GT	2003/09-2011/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2007/01-2010/12	433MHz	9PA1	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2007/01-2010/12	315MHz	9PA1	●	●	○	0/A	315MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
포르쉐	카이엔	2002/01-2006/12	433MHz	9PA	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2002/01-2006/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2014/11-2017/08	433MHz	92A	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2017/09-2023/12	433MHz	9YA	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2015/01-2023/12	315MHz	9YA	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2011/01-2014/10	433MHz	92A	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2010/01-2014/12	315MHz	92A	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2017/09-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2014/06-2017/08	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2010/01-2014/05	433MHz	4. 8L	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2010/01-2012/12	315MHz	4. 8L	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2008/01-2009/12	315MHz	4. 8L	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2007/01-2009/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2019/10-2025/12	433MHz	CT4-2	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2009/01-2016/12	315MHz	987C/981C/G T4-1	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	케이맨	2009/01-2016/12	433MHz	987C/981C/G T4-1	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2005/01-2008/12	433MHz	987C	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2005/01-2008/12	315MHz	987C	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	GT3	2017/01-2025/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	GT3	2015/01-2015/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
포르쉐	GT3	2010/01-2016/12	433MHz	996/997	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	GT3	2007/01-2009/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	GT3	2006/03-2011/12	433MHz	996	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	마칸	2014/01-2023/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	마칸	2014/01-2023/12	433MHz	P0416/95B	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	파나메라	2009/01-2014/02	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	파나메라	2017/09-2023/12	433MHz	970/971	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	파나메라	2014/01-2016/12	315MHz	970	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	파나메라	2013/09-2017/08	433MHz	970	●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	파나메라	2010/01-2013/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	Panamera S	2009/06-2013/12	315MHz	4. 8L	●	●	○	0/A	315MHz	Huf/Beru	●	●
포르쉐	Panamera S	2009/01-2013/06	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
포르쉐	Taycan	2019/01-2023/12	433MHz 9J1907275		●	●	○	0	433MHz	Huf/Beru	●	●
Renault	Arkana E-TECH	2025/01-2025/06	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Captur	2022/03-2024/06	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Clio III	2005/01-2014/05	433MHz	X85	●	●	●	0	433MHz	Schrader	●	●
Renault	Clio IV	2014/11-2016/02	433MHz 407005642R		●	●	○	0	433MHz	Schrader	●	●
Renault	Clio IV	2018/01-2019/12	433MHz		○	●	○	NA	433MHz	Schrader	●	●
Renault	Grand Koleos	2024/06-2025/06	433MHz		○	●	○	NA	433MHz	Schrader	●	●
Renault	Master	2009/11-2022/08	433MHz	X62	●	●	○	0	433MHz	Schrader	●	●
Renault	QM6	2022/07-2025/06	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	SM6	2022/01-2025/06	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	XM3	2022/01-2024/06	433MHz 407006UA0A		●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Renault	XM3	2022/01-2024/06	433MHz		●	●	○	0	433MHz	Schrader	●	●
Renault	Zoe	2021/01-2023/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Zoe	2019/06-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Renault	Zoe	2018/04-2020/12	433MHz 407004CB0A		●	●	○	0	433MHz	Continental	●	●
르노삼성	QM3	2016/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
르노삼성	QM3	2013/01-2015/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
르노삼성	QM5	2014/01-2016/07	433MHz 407003VU0A		●	●	○	0	433MHz	Continental	●	●
르노삼성	QM5	2011/06-2016/07	315MHz		●	●	○	0	315MHz	Schrader	●	●
르노삼성	QM5	2010/01-2016/07	433MHz		●	●	○	0	433MHz	Schrader	●	●
르노삼성	QM6	2016/08-2022/06	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM3	2018/01-2019/12	433MHz 407004CB0A		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM3	2009/01-2017/12	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM3 ZE	2017/01-2020/12	433MHz 407004CB0A		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM3 ZE	2017/01-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM5	2016/01-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM5	2010/01-2015/12	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM6	2016/01-2021/12	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM7	2016/01-2020/06	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	SM7	2012/01-2015/12	433MHz		●	●	○	0	433MHz	Continental	●	●
르노삼성	XM3	2019/01-2021/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
롤스로이스	컬리넌	2019/01-2023/12	433MHz Huf		○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	컬리넌	2018/01-2024/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
롤스로이스	다운	2016/01-2023/12	433MHz	RR6	○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	고스트	2020/08-2024/06	433MHz 36106887147		○	●	○	A	433MHz	Schrader	●	●
롤스로이스	고스트	2020/01-2024/06	433MHz 36106877937	RR21	○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	고스트	2014/04-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	고스트	2009/12-2014/03	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	팬텀	2017/01-2024/06	433MHz MRXAG5SP4	RR11/RR02	○	●	○	A	433MHz	Schrader	●	●
롤스로이스	팬텀	2012/01-2017/12	433MHz	RR01	○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	팬텀	2003/02-2018/12	433MHz OYGTSSRE4TC		○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	Spectre	2023/08-2024/06	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	Spectre	2023/08-2024/06	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
롤스로이스	레이스	2013/01-2022/12	433MHz	RR5	○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	레이스	2013/05-2023/12	433MHz 36106874830	RR5	○	●	○	A	433MHz	Huf/Beru	●	●
사브	9-3	2006/10-2009/05	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
사브	9-3	2003/01-2006/09	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
사브	9-5	2006/11-2009/09	433MHz	YE3E	○	●	○	A	433MHz	Schrader	●	●
사브	9-5	2002/07-2006/10	433MHz	YE3E	○	●	○	A	433MHz	Schrader	●	●
쌍용	엑티온	2018/07-2025/06	433MHz Q200		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	엑티온	2012/08-2021/12	433MHz QJ		○	●	○	A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
쌍용	체어맨	2014/01-2019/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
쌍용	체어맨	2014/01-2019/12	433MHz 4199034000		●	●	○	A	433MHz	Schrader	●	●
쌍용	체어맨	2005/01-2013/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
쌍용	Chairman W	2008/01-2017/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	코란도	2019/05-2025/06	433MHz 4199037000		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	코란도	2010/11-2023/12	433MHz C200		○	●	○	A	433MHz	Schrader	●	●
쌍용	코란도	2008/01-2013/12	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
쌍용	카이런	2010/01-2016/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	카이런	2006/01-2016/12	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
쌍용	무쏘	2023/01-2025/06	433MHz 4199036100		○	●	○	A	433MHz	BHSENS	●	●
쌍용	무쏘	2016/01-2018/05	433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	무쏘	2018/06-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	Musso Grand	2021/01-2025/06	433MHz 4199036100		○	●	○	NA	433MHz	BHSENS	●	●
쌍용	렉스턴	2006/01-2013/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
쌍용	렉스턴	2020/01-2021/12	433MHz C300		○	●	○	NA	433MHz	Huf/Beru	●	●
쌍용	렉스턴	2017/03-2025/06	433MHz Y400		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	렉스턴	2012/07-2017/12	433MHz Y300		●	●	○	A	433MHz	Schrader	●	●
쌍용	Rodius	2005/05-2021/12	433MHz AJ		○	●	○	A	433MHz	Schrader	●	●
쌍용	Rodius	2005/01-2013/12	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
쌍용	티볼리	2016/01-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	티볼리	2015/01-2020/06	433MHz X100		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	Torres	2023/08-2025/06	433MHz 4199037000		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	Torres EVX	2024/02-2025/06	433MHz 4199037000		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	Turismo	2014/01-2025/06	433MHz AJ		○	●	○	A	433MHz	Schrader	●	●
쌍용	XLV	2016/01-2025/06	433MHz	XK	○	●	○	A	433MHz	Huf/Beru	●	●
Suzuki	Super Carry	2019/06-2023/12	433MHz		○	●	○	NA	433MHz	Continental	●	●
테슬라	Model 3	2021/01-2025/06	2.4GHz		○	●	○	A	2.4GHz	Sysgration	●	●
테슬라	Model 3	2018/01-2021/12	433MHz 107481200B		○	●	○	A	433MHz	Continental	●	●
테슬라	Model 3	2016/01-2020/12	433MHz		○	●	○	A	433MHz	Continental	●	●
테슬라	Model S	2021/01-2022/12	433MHz		○	●	○	A	433MHz	Continental	●	●
테슬라	Model S	2023/01-2023/12	433MHz		○	●	○	A	433MHz	Continental	●	●
테슬라	Model S	2021/01-2025/06	2.4GHz		○	●	○	A	2.4GHz	Sysgration	●	●
테슬라	Model S	2014/09-2020/12	433MHz		○	●	○	A	433MHz	Continental	●	●
테슬라	Model X	2021/01-2025/06	2.4GHz		○	●	○	A	2.4GHz	Sysgration	●	●
테슬라	Model X	2014/10-2023/12	433MHz Continental		○	●	○	A	433MHz	Continental	●	●
테슬라	Model Y	2020/01-2025/06	2.4GHz		○	●	○	A	2.4GHz	Sysgration	●	●
도요타	86	2012/04-2023/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	아발론	2018/04-2022/12	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
도요타	아발론	2016/10-2018/03	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
도요타	캠리	2016/04-2020/07	315MHz PMV-C010		●	●	○	0	315MHz	Pacific	●	●
도요타	캠리	2016/08-2021/01	315MHz PMV-C015/E000		●	●	○	0	315MHz	Pacific	●	●
도요타	캠리	2016/01-2025/06	433MHz PMV-E100		●	●	○	0/A	433MHz	Pacific	●	●
도요타	캠리	2014/01-2021/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	Camry Hybrid	2014/01-2017/09	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	코롤라	2002/01-2013/08	315MHz PMV-107J/1017/C11A/1037		●	●	○	0	315MHz	Pacific	●	●
도요타	FJ 크루저	2014/06-2023/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	포튜나	2016/08-2021/01	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	GR Supra	2019/01-2025/06	433MHz		●	●	○	0	433MHz	Huf/Beru	●	●
도요타	GT86	2012/09-2023/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	랜드크루저	2012/01-2016/01	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	프라도	2009/01-2017/09	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스	2019/01-2025/06	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스	2014/05-2019/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스 C	2014/03-2022/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스 V	2014/11-2017/11	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	RAV4	2018/01-2025/06	433MHz PMV-C215		●	●	○	0	433MHz	Pacific	●	●
도요타	RAV4	2012/01-2023/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	씨에나	2010/06-2022/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
도요타	벤자	2014/06-2015/12	433MHz PMV-C210		●	●	○	0	433MHz	Pacific	●	●
폭스바겐	아테온	2017/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	비틀	2012/12-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	비틀	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	CC	2018/01-2023/06	433MHz MQB		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	CC	2011/06-2017/12	433MHz	VC17	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	EOS	2014/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	골프	2013/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
폭스바겐	골프	2009/01-2012/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
폭스바겐	제타	2010/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	뉴 비틀	2012/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	뉴 비틀	2011/08-2020/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	뉴 비틀	2006/01-2011/12	433MHz	VW314	○	●	○	A	433MHz	Continental	●	●
폭스바겐	뉴 비틀	2006/01-2011/12	315MHz		○	●	○	A	315MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
폭스바겐	파사트	2014/09-2023/12	433MHz	B8	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	파사트	2010/01-2014/12	433MHz		●	●	○	0	433MHz	Huf/Beru	●	●
폭스바겐	파사트	2005/01-2011/12	433MHz	VW451	●	●	○	0/A	433MHz	Continental	●	●
폭스바겐	Passat CC	2009/01-2016/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
폭스바겐	페이톤	2010/06-2019/12	433MHz	Vh67	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	페이톤	2001/12-2007/05	433MHz	VW611	●	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	폴로	2009/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	Santana	2014/09-2023/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	T-ROC	2017/11-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	Teramont	2019/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	Teramont X	2019/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	티구안	2016/01-2023/12	433MHz	VW376/5N2	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	티구안	2011/05-2015/12	433MHz	5N	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	티구안	2008/01-2011/04	433MHz		●	●	○	0/A	433MHz	Continental	●	●
폭스바겐	Tiguan L	2016/01-2023/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	투아렉	2014/08-2023/12	433MHz	7P5/7P6108	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	투아렉	2007/01-2014/07	433MHz 7PP907275F	VW526	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	타우란	2020/06-2025/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
볼보	C30	2011/01-2014/03	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	C30	2006/01-2014/03	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
볼보	C30	2006/01-2010/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	C30 일렉트릭	2011/01-2013/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	C30 일렉트릭	2010/01-2010/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	C40	2022/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	C70	2011/01-2014/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	C70	2008/01-2010/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	C70	2006/01-2014/12	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
볼보	C70	2006/01-2007/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	EX30	2023/06-2024/12	433MHz		○	●	○	NA	433MHz	Schrader	●	●
볼보	S40	2011/01-2014/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	S40	2003/01-2014/12	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
볼보	S40	2003/01-2010/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
볼보	S60	2019/04-2024/12	433MHz 31362304		●	●	○	0/A	433MHz	Schrader	●	●
볼보	S60	2019/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	S60	2010/01-2020/12	433MHz 31302096		●	●	○	0/A	433MHz	Continental	●	●
볼보	S60	2010/01-2019/12	433MHz 31445474		●	●	○	0/A	433MHz	Continental	●	●
볼보	S60	2001/01-2010/12	315MHz 31200923		●	●	○	A	315MHz	Schrader	●	●
볼보	S60	2000/07-2010/02	433MHz 31329981		●	●	○	A	433MHz	Schrader	●	●
볼보	S80	2016/01-2018/02	433MHz		○	●	○	NA	433MHz	Schrader	●	●
볼보	S80	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
볼보	S80	2010/01-2016/12	433MHz 31302096		●	●	○	O/A	433MHz	Continental	●	●
볼보	S80	2007/01-2009/12	433MHz 31302096		●	●	○	O/A	433MHz	Continental	●	●
볼보	S80	2006/01-2017/01	433MHz 31341893		●	●	○	O/A	433MHz	Continental	●	●
볼보	S80	1999/01-2013/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
볼보	S90	2016/05-2024/12	433MHz 31362304		●	●	○	O/A	433MHz	Schrader	●	●
볼보	S90	2016/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V40	2015/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V40	2012/01-2021/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	V50	2011/01-2016/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	V50	2004/01-2014/12	433MHz 31445474		●	●	○	O/A	433MHz	Continental	●	●
볼보	V50	2003/01-2010/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	V60	2019/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V60	2017/11-2024/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
볼보	V60	2011/01-2022/12	433MHz 31341893		●	●	○	O/A	433MHz	Continental	●	●
볼보	V60	2008/01-2014/06	433MHz 31302096		●	●	○	O/A	433MHz	Continental	●	●
볼보	V60 Cross Country	2019/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V70	2007/01-2016/12	433MHz 31445474		●	●	○	O/A	433MHz	Continental	●	●
볼보	V90	2016/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	V90	2015/01-2022/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
볼보	V90 Cross Country	2016/01-2023/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC40	2017/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC60	2015/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC60	2008/01-2017/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	XC70	2010/01-2014/06	433MHz 31302096		●	●	○	O/A	433MHz	Continental	●	●
볼보	XC70	2008/01-2018/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	XC70	2008/01-2009/12	433MHz 31302096		●	●	○	O/A	433MHz	Continental	●	●
볼보	XC90	2016/01-2024/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	XC90	2015/01-2022/12	433MHz 31362304		●	●	○	O/A	433MHz	Schrader	●	●
볼보	XC90	2003/01-2016/12	433MHz 31329981		●	●	○	O/A	433MHz	Schrader	●	●
볼보	XC90	2003/01-2016/12	315MHz 31200923		●	●	○	O/A	315MHz	Schrader	●	●