

MX-Sensor_V6.26 Function List For KR Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Abarth	500C	2010/01-2019/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Aston Martin	DB11	2016/01-2022/12	433MHz	VH500	○	●	○	A	433MHz	Schrader	●	●
Aston Martin	DBS	2007/01-2015/12	433MHz	V12	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	DBS Superleggera	2018/01-2022/12	433MHz	VH500	○	●	○	A	433MHz	Schrader	●	●
Aston Martin	Rapide	2010/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Rapide S	2010/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vanquish	2012/01-2020/12	433MHz	AM310	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vanquish	2010/01-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vantage	2010/01-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	A3	2012/06-2022/12	433MHz	8L	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	A4	2012/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
아우디	A4	2008/08-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A5	2006/12-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A5	2019/01-2022/12	433MHz		●	●	○	O	433MHz	Huf/Beru	●	●
아우디	A6	2017/07-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A6	2005/01-2018/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	A6	2002/01-2017/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	A6	2018/01-2020/12	433MHz	4G	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	A7	2012/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A7	2010/09-2022/12	433MHz 5Q0907275	4G	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	A8	2009/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	A8	2010/11-2016/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	A8	2017/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	Q5	2008/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	Q5	2017/01-2022/12	433MHz	8R	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	Q7	2015/01-2022/12	433MHz	4L/AU726	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	Q7	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	Q7	2005/09-2015/12	433MHz	4L/AU716	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	Q8	2018/01-2022/12	433MHz	4M	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	R9	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	R9	2009/06-2022/12	433MHz 7PP907275F	AU714	●	●	○	A	433MHz	Huf/Beru	●	●
아우디	R9	2015/04-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	RS5	2010/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	RS5	2017/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
아우디	S6	2005/01-2012/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
아우디	S6	2002/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
아우디	S6	2018/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	S7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	S8	2017/10-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	S8	2009/11-2017/10	433MHz	D4	●	●	○	A	433MHz	Huf/Beru	●	●
아우디	S8	2010/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	SQ5	2012/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
아우디	SQ5	2017/01-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
아우디	TT	2014/02-2022/12	433MHz	AU334	●	●	○	O/A	433MHz	Huf/Beru	●	●
아우디	TTS	2016/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
아우디	e-tron	2018/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BAIC	S6	2015/11-2018/06	433MHz		●	●	○	O/A	433MHz	BAIC	●	●
BMW	1 Series	2008/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	1 Series	2010/07-2022/12	433MHz	F20/F21/F52	●	●	○	A	433MHz	Continental	●	●
BMW	2 Series	2019/11-2022/12	433MHz	F44/G42	●	●	○	C	433MHz	Huf/Beru	●	●
BMW	2 Series	2014/01-2022/12	433MHz	F22/F23/F45/F46	●	●	○	A	433MHz	Continental	●	●
BMW	3 Series	2005/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	3 Series	2010/10-2014/03	433MHz	F30	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	3 Series	2009/09-2014/02	433MHz	E9x	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	3 Series	2005/01-2009/08	433MHz	E9x	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	1998/01-2008/06	433MHz	E46	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	2017/10-2022/12	433MHz	G20	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	2014/01-2019/12	433MHz	F30/F31/F35	●	●	○	A	433MHz	Continental	●	●
BMW	3 Series GT	2013/01-2014/02	36106798872 433MHz	F34	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	3 Series GT	2013/01-2021/06	433MHz	F34	●	●	○	A	433MHz	Continental	●	●
BMW	3 Series Sedan	2014/03-2019/12	433MHz	F34	●	●	○	A	433MHz	Continental	●	●
BMW	4 Series	2013/07-2020/12	433MHz	F32/F33/F36	●	●	○	A	433MHz	Continental	●	●
BMW	4 Series	2020/09-2022/12	433MHz	G22/G23/G26	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	2017/01-2022/12	433MHz	G30/G31/G38	●	●	○	A	433MHz	Schrader	●	●
BMW	5 Series	2014/03-2017/12	433MHz	F07/F10/F11	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series	2010/10-2014/02	433MHz	F10/F07/F18	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series GT	2009/01-2010/12	433MHz	E60/E61	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series GT	2014/04-2018/06	433MHz	F07 LCI	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series GT	2017/01-2019/12	433MHz	G32	●	●	○	A	433MHz	Schrader	●	●
BMW	5 Series GT	2009/01-2017/12	433MHz	F10/F07	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series	2011/01-2014/03	433MHz	F06/F12/F13	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series	2014/03-2022/12	433MHz	F12/F13/F06	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series GT	2016/09-2022/12	433MHz	G14/G32	●	●	○	A	433MHz	Schrader	●	●
BMW	7 Series	2010/10-2015/12	433MHz	F01/F02/F04	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	7 Series	2014/03-2015/05	433MHz	F01/F02/F03/F04	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	7 Series	2014/10-2022/12	433MHz	G11/G12	●	●	○	A	433MHz	Schrader	●	●
BMW	8 Series	2018/07-2022/12	433MHz	G14/G15/G16/F91/F92/F93	●	●	○	C	433MHz	Schrader	●	●
BMW	M2	2014/11-2021/12	433MHz	F87	●	●	○	A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	M3	2014/01-2019/12	433MHz	F80	●	●	○	A	433MHz	Continental	●	●
BMW	M4	2014/01-2020/12	433MHz	F82/F83	●	●	○	A	433MHz	Continental	●	●
BMW	M5	2010/09-2014/03	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M5	2014/03-2017/12	433MHz	F10	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M6	2014/03-2018/12	433MHz	F12	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M8	2019/01-2020/12	433MHz		●	●	○	C	433MHz	Continental	●	●
BMW	모터사이클	2010/01-2019/12	433MHz		○	○	○		433MHz	Schrader	Activate Only	●
BMW	X1	2009/01-2013/12	Indirect	E84	○	○	○	A	N/A	N/A	Indirect	●
BMW	X1	2014/03-2016/06	433MHz	E84	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X1	2015/08-2022/12	433MHz	F48	●	●	○	A	433MHz	Continental	●	●
BMW	X2	2016/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	X3	2010/01-2017/12	36106798872 433MHz	F25	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X3	2003/01-2010/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X3	2017/01-2022/12	433MHz	G01/G08/F97	●	●	○	A	433MHz	Schrader	●	●
BMW	X4	2014/01-2019/12	433MHz	F26	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X4	2017/03-2022/12	433MHz	G02/F98	●	●	○	A	433MHz	Schrader	●	●
BMW	X5	2017/09-2022/12	433MHz	F95/G05/G18	●	●	○	A	433MHz	Schrader	●	●
BMW	X5	2013/05-2019/12	433MHz	F15/F85	●	●	○	A	433MHz	Continental	●	●
BMW	X5	2010/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X6	2008/01-2014/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X6	2014/08-2019/12	433MHz	F16/F86	●	●	○	A	433MHz	Continental	●	●
BMW	X6	2018/07-2022/12	433MHz	F96/G06	●	●	○	C	433MHz	Schrader	●	●
BMW	X7	2018/01-2022/12	433MHz	G07	●	●	○	A	433MHz	Schrader	●	●
BMW	Z4	2018/11-2022/12	433MHz	G29	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	Z4	2009/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	Z4	2009/02-2019/02	433MHz	E89	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	i Series	2018/01-2018/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	i3	2013/01-2022/06	433MHz	I01/I12	●	●	○	A	433MHz	Continental	●	●
BMW	i8	2013/01-2020/12	433MHz	I01/I12	●	●	○	A	433MHz	Continental	●	●
BMW	ix3	2020/11-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
벤트리	벤틀가	2016/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
벤트리	Continental GT	2022/01-2022/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
벤트리	Continental GT	2005/06-2021/12	433MHz BY634		●	●	○	A	433MHz	Huf/Beru	●	●
벤트리	플라잉 스퍼	2011/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
벤트리	플라잉 스퍼	2019/01-2022/12	5Q0907275 433MHz		●	●	○	O	433MHz	Huf/Beru	●	●
벤트리	물산	2001/01-2020/12	7PP907275F 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
캐딜락	ATS	2013/01-2013/12	433MHz	A1SL/A1BL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	ATS	2014/01-2014/12	433MHz	A1SL/A1BL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	ATS	2015/01-2015/12	433MHz	A1SL/A1BL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	ATS	2016/01-2020/12	433MHz	A1SL/A1BL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	ATS-V	2016/01-2016/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
캐딜락	ATS-V	2015/01-2015/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
캐딜락	ATS-V	2017/01-2019/12	433MHz		○	●	○	S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
캐딜락	BLS	2006/01-2014/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
캐딜락	CT7	2016/01-2021/12	433MHz 13598773		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	CTS	2014/01-2015/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	CTS	2016/01-2021/06	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	CTS	2013/06-2013/12	433MHz	A1LL	○	●	○	C	433MHz	Schrader	●	●
캐딜락	CTS-V	2016/01-2019/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	CTS-V	2010/01-2015/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	Colorado	2020/01-2020/12	433MHz		●	●	●	O	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2009/01-2011/12	433MHz	GMT926	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2007/01-2008/12	433MHz	GMT926	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2014/01-2014/12	433MHz	GMT900/ GMTK2XL/ K2UL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2021/01-2022/12	433MHz 13533166		●	●	○	C	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2012/01-2012/12	433MHz	GMT900/ GMTK2XL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2015/01-2020/12	433MHz	GMT900/ GMTK2XL/ K2UL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	에스컬레이드	2013/01-2013/12	433MHz	GMT900/ GMTK2XL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	SRX	2014/01-2015/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2013/01-2013/12	433MHz	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	SRX	2012/10-2013/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2012/01-2012/09	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2010/01-2012/12	433MHz	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	SRX	2008/06-2009/12	433MHz 25789964	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	SRX	2016/01-2018/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2010/01-2011/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2009/01-2009/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2016/01-2016/12	433MHz	C1UL	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	SRX	2007/01-2008/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2004/01-2006/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
캐딜락	SRX	2015/01-2016/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	SRX	2014/01-2016/12	433MHz	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	XT4	2018/11-2022/12	433MHz	E2UL	●	●	○	O/S	433MHz	Schrader	●	●
캐딜락	XT5	2018/01-2022/12	433MHz 13516165		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	XT5	2016/01-2021/06	433MHz 13598773		●	●	●	O/S	433MHz	Schrader	●	●
캐딜락	XT6	2019/01-2022/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
쉐보레	Alpheon	2011/01-2015/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
쉐보레	아베오	2019/01-2022/12	433MHz		●	●	●	S	433MHz	Schrader	●	●
쉐보레	아베오	2013/01-2019/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
쉐보레	볼트 EV	2017/01-2020/12	433MHz 13598773		●	●	●	O/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
쉐보레	카마로	2016/01-2016/12	Snap in 433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	카마로	2017/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	캡티바	2011/01-2018/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	콜로라도	2017/01-2022/12	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	크루즈	2012/01-2012/12	433MHz	DISC/ D1JC/ D1WC/ KL1J	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	크루즈	2013/01-2015/12	433MHz	DISC/ D1JC/ D1WC/ KL1J	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	크루즈	2016/01-2019/06	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	에쿠녹스	2017/06-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	임팔라	2006/01-2006/12	Clamp in 315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2007/01-2007/12	Clamp in 315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2008/01-2008/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2009/01-2011/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2012/01-2012/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2013/01-2013/09	315MHz 13598771		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2013/10-2014/12	Limited 315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2015/01-2016/12	Limited 315MHz 13598771		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2016/01-2016/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2017/01-2020/06	315MHz 13598772		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2015/01-2016/12	Limited 315MHz 23445327		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	임팔라	2014/01-2021/06	433MHz 13598773		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	임팔라	2007/01-2007/12	Snap in 315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	말리브	2017/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	말리브	2011/01-2016/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	몬테 카를로	2007/01-2007/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	올랜도	2016/01-2018/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	올랜도	2013/01-2015/12	433MHz	GMT166	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	스파크	2013/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트레일브레이저	2020/01-2022/12	433MHz		●	●	○	0/S	433MHz	Schrader	●	●
쉐보레	트래버스	2018/01-2022/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	트랙스	2012/01-2014/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
쉐보레	트랙스	2015/01-2022/12	433MHz	G1UC	●	●	●	0/S	433MHz	Schrader	●	●
쉐보레	볼트	2016/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
크라이슬러	200	2014/01-2016/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
크라이슬러	300C	2018/01-2021/06	18 inch 433MHz		●	●	○	A	433MHz	Schrader	●	●
크라이슬러	300C	2018/01-2021/06	20 inch 433MHz		●	●	○	A	433MHz	Schrader	●	●
크라이슬러	300C	2009/06-2017/12	18 inch 433MHz		●	●	●	O/A	433MHz	Schrader	●	●
크라이슬러	300C	2009/06-2017/12	20 inch 433MHz		●	●	●	O/A	433MHz	Schrader	●	●
크라이슬러	300C	2005/06-2009/05	433MHz	LE48	●	●	●	O/A	433MHz	Continental	●	●
크라이슬러	그랜드 보예저	2018/01-2020/03	433MHz	RT	●	●	○	S	433MHz	Schrader	●	●
크라이슬러	그랜드 보예저	2011/01-2017/12	433MHz	RT	●	●	●	O/S	433MHz	Schrader	●	●
크라이슬러	퍼시픽카	2004/01-2005/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
크라이슬러	퍼시픽카	2016/01-2017/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
크라이슬러	퍼시픽카	2004/01-2005/12	315MHz		●	●	○	A	315MHz	Continental	●	●
크라이슬러	퍼시픽카	2006/01-2008/12	315MHz	CS	●	●	○	A	315MHz	Continental	●	●
크라이슬러	퍼시픽카	2018/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
크라이슬러	퍼시픽카	2003/01-2003/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Citroen	C4	2013/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	C4 Cactus	2016/01-2021/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Citroen	DS3	2012/01-2019/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Citroen	DS3	2015/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS4	2010/01-2014/01	433MHz	B75	●	●	○	O	433MHz	Schrader	●	●
Citroen	DS4	2014/02-2020/12	433MHz	B81	●	●	○	O/A	433MHz	Schrader	●	●
Citroen	DS4 Crossback	2016/01-2020/06	433MHz		●	●	○	O	433MHz	Schrader	●	●
Citroen	DS5	2011/01-2014/01	433MHz	B81	●	●	○	O	433MHz	Schrader	●	●
Citroen	DS5	2014/02-2019/12	433MHz	X2/50	●	●	○	O	433MHz	Schrader	●	●
Citroen	Space Tourer	2016/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
페라리	296GTB	2022/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	458 이탈리아	2009/01-2020/12	433MHz	F142	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	458 Spider	2009/01-2020/12	433MHz	F142	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	488	2015/01-2021/12	433MHz	F142	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	575M 마라넬로	2002/01-2006/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	595 GTB/GTO	2004/01-2011/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	599 GTB	2004/01-2014/12	433MHz	F141	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	599 GTO	2004/01-2012/12	433MHz	F141	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	612 스카클리에티	2004/01-2011/12	433MHz	F137	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	812 Superfast	2017/01-2018/12	315MHz		○	●	○	C	315MHz	Huf/Beru	●	●
페라리	812 Superfast	2016/01-2021/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
페라리	CTC4 Lusso T	2017/01-2019/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
페라리	캘리포니아	2008/10-2017/12	433MHz	F149	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	엔조	2002/01-2006/12	433MHz	F140	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	F12 벨리네타	2012/10-2022/12	433MHz 282189	F151/F152	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	F12 tdf	2015/01-2021/12	433MHz	F151/F152	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	F430	2004/09-2007/06	433MHz	F131E	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	F430	2007/07-2009/10	433MHz	F131E	●	●	○	O/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
페라리	F8 Tributo	2019/01-2022/12	433MHz 282189	F151/F152	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	FF	2011/01-2020/01	433MHz	F151	●	●	○	O/A	433MHz	Huf/Beru	●	●
페라리	FXX	2005/01-2006/12	433MHz	F140	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	GTC4 루쏘	2016/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	라 페라리	2013/01-2020/12	433MHz	F150	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Monza SP1/SP2	2019/01-2021/12	433MHz	F151/F152	○	●	○	A	433MHz	Huf/Beru	●	●
페라리	Portofino	2017/10-2021/12	F11001648001 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
페라리	Portofino	2016/01-2022/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
페라리	Roma	2020/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
페라리	SF90 Stralade	2020/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Fiat	500	2014/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500C	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500L	2012/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500X	2014/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	Freemont	2014/07-2022/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
포드	에스케이프	2015/01-2018/12	433MHz	C520	●	●	●	O/S	433MHz	Schrader	●	●
포드	에스케이프	2012/05-2014/12	433MHz	C520	●	●	●	S	433MHz	Schrader	●	●
포드	Everest	2015/01-2018/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
포드	엑스피디션	2018/01-2022/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
포드	익스플로러	2011/01-2015/12	315MHz	U502	●	●	●	S	315MHz	Schrader	●	●
포드	익스플로러	2020/01-2020/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
포드	익스플로러	2021/01-2022/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
포드	익스플로러	2015/06-2019/12	433MHz		●	●	○	O/S	433MHz	Schrader	●	●
포드	익스플로러	2011/01-2015/06	433MHz	U502	●	●	●	S	433MHz	Schrader	●	●
포드	익스플로러	2006/01-2010/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
포드	익스플로러	2005/01-2005/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
포드	익스플로러	2004/01-2004/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
포드	쿠가	2014/01-2019/12	433MHz	C520	●	●	●	O/S/A	433MHz	Schrader	●	●
포드	몬데오	2007/01-2012/12	Clamp in 433MHz	CD345	●	●	○	O/A	433MHz	Continental	●	●
포드	몬데오	2017/09-2019/05	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
포드	몬데오	2015/01-2017/08	Snap in 433MHz		●	●	●	O/S	433MHz	Schrader	●	●
포드	몬데오	2013/01-2015/06	Clamp in 433MHz	CD345	●	●	○	O	433MHz	Continental	●	●
포드	무스탕	2014/10-2018/12	433MHz	S550	●	●	●	O/S	433MHz	Schrader	●	●
포드	무스탕	2019/01-2021/12	433MHz	S550	●	●	○	O/S	433MHz	Schrader	●	●
포드	레인저	2015/01-2022/12	Hi Line 433MHz		●	●	○	O/S	433MHz	Schrader	●	●
포드	타우러스	2016/01-2019/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
혼다	아코드	2015/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	아코드	2013/01-2014/12	Direct 433MHz	2GA/2GB/QE	●	●	○	O	433MHz	Continental	●	●
혼다	CR-V	2010/07-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
혼다	CR-Z	2011/01-2013/12	315MHz		●	●	○	C	315MHz	TRW	●	●
혼다	씨빅	2013/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
혼다	HR-V	2014/09-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
혼다	인사이트	2010/01-2013/12	315MHz		●	●	○	C	315MHz	TRW	●	●
혼다	Legend	2015/01-2016/12	315MHz	Hybrid	●	●	○	C	315MHz	TRW	●	●
혼다	오디세이	2017/01-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
혼다	오디세이	2015/01-2016/12	433Mhz		●	●	○	O	433MHz	TRW	●	●
혼다	오디세이	2014/01-2017/12	315MHz		○	●	○	C	315MHz	TRW	●	●
혼다	파이롯	2018/01-2022/12	433MHz		●	●	○	O	433MHz	Continental	●	●
혼다	파이롯	2009/01-2015/12	Steel 315MHz		●	●	○	O	315MHz	Pacific	●	●
혼다	파이롯	2009/01-2015/12	Alloy 315MHz		●	●	○	O/A	315MHz	Pacific	●	●
혼다	파이롯	2016/01-2017/12	433MHz		●	●	○	O	433MHz	Continental	●	●
흠머	H2	2003/01-2007/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
흠머	H2	2008/01-2008/12	315MHz 15922396		●	●	●	O/S	315MHz	Schrader	●	●
흠머	H2	2009/01-2011/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
흠머	H2	2008/01-2008/12	315MHz 13598771		●	●	●	O/S	315MHz	Schrader	●	●
흠머	H3	2005/01-2006/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
흠머	H3	2007/01-2012/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
흠머	H3T	2006/01-2012/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
현대	엑센트	2015/01-2018/12	Hi Line 433MHz	RB	●	●	○	O	433MHz	Continental	●	●
현대	엑센트	2015/01-2018/12	Lo Line 433MHz	RB	●	●	○	O	433MHz	Continental	●	●
현대	Aslan	2014/01-2017/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Aslan	2018/01-2018/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Avante	2016/01-2020/12	AD 433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Avante	2014/01-2016/12	MD 433MHz		●	●	○	O	433MHz	TRW	●	●
현대	Avante	2012/01-2016/12	JK 433MHz		●	●	○	O	433MHz	TRW	●	●
현대	Avante	2011/01-2013/12	MD 433MHz		●	●	○	O	433MHz	TRW	●	●
현대	EQ900	2016/01-2017/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	엘란트라	2013/10-2019/12	Lo Line 315MHz		●	●	○	O/A	315MHz	TRW	●	●
현대	Elantra GT	2021/01-2021/12	433MHz	PD	●	●	○	A	433MHz	Continental	●	●
현대	Elantra GT	2017/06-2020/12	433MHz	PD	●	●	○	O	433MHz	Continental	●	●
현대	에쿠스	2013/01-2016/12	433MHz	VI New	●	●	○	O/A	433MHz	Continental	●	●
현대	에쿠스	2008/01-2013/12	433MHz	VI Old	●	●	○	O	433MHz	TRW	●	●
현대	제네시스	2013/01-2016/12	433MHz	DH	●	●	○	O/A	433MHz	Continental	●	●
현대	제네시스	2013/01-2016/12	315MHz	BK	●	●	○	O	315MHz	TRW	●	●
현대	제네시스	2007/01-2014/12	433MHz	BH	●	●	○	O	433MHz	TRW	●	●
현대	제네시스	2007/01-2007/12	315MHz	BH	●	●	○	O	315MHz	TRW	●	●
현대	Genesis Coupe	2014/01-2016/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Genesis Coupe	2012/01-2013/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Genesis G70	2018/01-2022/12	433MHz	IK	●	●	○	C	433MHz	Schrader	●	●
현대	Genesis G70	2017/01-2017/12	433MHz	IK	●	●	○	O	433MHz	Schrader	●	●
현대	Genesis G80	2020/01-2022/12	433MHz	DH	●	●	○	A	433MHz	Continental	●	●
현대	Genesis G80	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
현대	Genesis G80	2016/07-2019/12	433MHz	DH	●	●	○	O	433MHz	Continental	●	●
현대	Genesis G90	2017/01-2018/12	433MHz	HI	●	●	○	A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	Genesis G90	2019/01-2022/12	433MHz	HI	●	●	○	A	433MHz	Continental	●	●
현대	Genesis G90	2016/01-2016/12	433MHz	HI	●	●	○	O	433MHz	Continental	●	●
현대	Genesis GV70	2020/12-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
현대	Genesis GV80	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
현대	Grand Starex	2015/01-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	그랜저	2018/01-2019/12	433MHz	IG LAMBDA	●	●	○	O	433MHz	Continental	●	●
현대	그랜저	2014/01-2014/12	Hybrid 433MHz		●	●	○	O	433MHz	TRW	●	●
현대	그랜저	2017/01-2020/12	433MHz	IG/IG HEV	●	●	○	O	433MHz	Continental	●	●
현대	그랜저	2015/01-2017/12	Hybrid 433MHz		●	●	○	O	433MHz	Continental	●	●
현대	그랜저	2020/01-2021/12	433MHz	IG LAMBDA	●	●	○	O	433MHz	Continental	●	●
현대	그랜저	2011/06-2015/12	HG 433MHz		●	●	○	O	433MHz	TRW	●	●
현대	그랜저	2011/01-2017/12	DM 433MHz	HG	●	●	○	O	433MHz	TRW	●	●
현대	이오닉	2016/01-2022/12	433MHz	AE	●	●	○	O	433MHz	Continental	●	●
현대	Ioniq 5	2022/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
현대	Ioniq 5	2020/01-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
현대	Kona	2017/01-2022/12	433MHz		●	●	○	A/O	433MHz	Continental	●	●
현대	Maxcruz	2012/01-2018/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Mohave	2020/01-2020/12	433MHz		●	●	○	A	433MHz	Continental	●	●
현대	Nexo	2018/04-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
현대	Palisade	2019/01-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
현대	Porter	2007/01-2018/12	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Porter	2014/01-2020/12	HR 433MHz		●	●	○	O	433MHz	Continental	●	●
현대	싼타페	2006/01-2008/12	433MHz	CM	●	●	○	O	433MHz	Lear	●	●
현대	싼타페	2019/01-2022/12	433MHz	TM	●	●	○	A	433MHz	Schrader	●	●
현대	싼타페	2012/01-2015/12	433MHz	DM	●	●	○	O	433MHz	Continental	●	●
현대	싼타페	2009/01-2012/05	433MHz	CM	●	●	○	O	433MHz	Lear	●	●
현대	싼타페	2012/06-2014/12	315MHz	NC	●	●	○	O	315MHz	Continental	●	●
현대	싼타페	2018/01-2018/12	433MHz	TM	●	●	○	O	433MHz	Schrader	●	●
현대	Solati	2014/03-2019/06	433MHz		●	●	○	O	433MHz	Continental	●	●
현대	쏘나타	2014/04-2019/12	Hi Line 433MHz	LF/LFA	●	●	○	O	433MHz	Schrader	●	●
현대	쏘나타	2010/01-2013/12	433MHz	LF/LFA	●	●	○	O	433MHz	Continental	●	●
현대	쏘나타	2019/05-2022/12	433MHz 52940L1100		●	●	○	A	433MHz	Continental	●	●
현대	쏘나타	2010/01-2010/12	433MHz	YF	●	●	○	O	433MHz	Continental	●	●
현대	쏘나타	2014/01-2015/12	VDO 433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Sonata Hybrid	2011/01-2014/12	529333N100 433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Sonata Hybrid	2011/01-2019/12	529331J000 433MHz		●	●	○	O	433MHz	Continental	●	●
현대	Sonata Hybrid	2016/01-2019/12	433MHz	YF/LF HEV	●	●	○	O	433MHz	Schrader	●	●
현대	스타렉스	2007/01-2007/12	315MHz		○	●	○	C	315MHz	Continental	●	●
현대	스타렉스	2007/01-2015/12	433MHz	TQ	○	●	○	C	433MHz	Continental	●	●
현대	투싼	2012/01-2015/12	Hi line 433MHz	LM	●	●	○	O	433MHz	TRW	●	●
현대	투싼	2012/01-2015/12	Lo Line 433MHz	LM	●	●	○	O	433MHz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
현대	투싼	2009/01-2013/12	433MHz	LM	●	●	○	0	433MHz	TRW	●	●
현대	투싼	2015/01-2018/12	433MHz	LM FCEV	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2015/05-2020/12	433MHz Hi Line	TL	●	●	○	0	433MHz	Schrader	●	●
현대	투싼	2021/01-2021/09	433MHz Hi Line	TL	●	●	○	A	433MHz	Schrader	●	●
현대	투싼	2021/01-2022/12	433MHz	NX	●	●	○	A	433MHz	Schrader	●	●
현대	투싼	2016/01-2017/12	433MHz	TL	●	●	○	0	433MHz	TRW	●	●
현대	벨로스터	2011/03-2019/06	433MHz	FS	●	●	○	0	433MHz	Schrader	●	●
현대	벨로스터	2018/01-2022/12	433MHz	JS	●	●	○	0	433MHz	Continental	●	●
현대	Venue	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
현대	베라크루즈	2007/01-2013/12	433MHz		●	●	○	0	433MHz	Lear	●	●
현대	베라크루즈	2007/01-2012/12	CM 433MHz	EN	●	●	○	0	433MHz	Continental	●	●
현대	i30	2012/01-2016/12	433MHz	GD	●	●	○	0/A	433MHz	Continental	●	●
현대	i30	2016/08-2022/12	433MHz	PD/Pde	●	●	○	0	433MHz	Continental	●	●
현대	i30	2017/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
현대	i40	2017/01-2019/12	433MHz	IF	●	●	○	0	433MHz	Continental	●	●
현대	i40	2014/04-2020/12	433MHz	VF	●	●	○	0/A	433MHz	TRW	●	●
현대	i40	2011/01-2014/03	433MHz	VF	●	●	○	0	433MHz	TRW	●	●
인피니티	EX Series	2007/01-2014/03	433MHz	P53B/J50	●	●	○	0	433MHz	Schrader	●	●
인피니티	FX Series	2015/05-2016/12	315MHz	S51	○	●	○	C	315MHz	Pacific	●	●
인피니티	FX Series	2008/03-2015/04	433MHz	P53C/S51	●	●	○	0	433MHz	Schrader	●	●
인피니티	G Series	2014/03-2015/12	315MHz	V36	○	●	○	C	315MHz	Pacific	●	●
인피니티	G Series	2006/01-2014/02	433MHz	CV36/G312/L53A	●	●	○	0	433MHz	Schrader	●	●
인피니티	M Series	2009/12-2016/04	433MHz	M312/Y51	●	●	○	0	433MHz	Pacific	●	●
인피니티	Q30	2015/01-2021/12	433MHz	GD1A/H15	●	●	○	0/A	433MHz	Schrader	●	●
인피니티	Q50	2013/01-2020/12	433MHz	L53H/D53H/V37	●	●	○	0	433MHz	Continental	●	●
인피니티	Q60	2016/05-2021/12	433MHz	CV37	●	●	○	0	433MHz	Continental	●	●
인피니티	Q70	2018/10-2021/12	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	Q70	2013/01-2021/12	433MHz	L53E	●	●	○	0	433MHz	Pacific	●	●
인피니티	QX50	2017/11-2021/12	433MHz		●	●	○	0	433MHz	Continental	●	●
인피니티	QX50	2014/01-2017/10	315MHz	J50	○	●	○	C	315MHz	Pacific	●	●
인피니티	QX60	2012/02-2022/12	433MHz	L50	●	●	○	0	433MHz	Continental	●	●
인피니티	QX70	2014/01-2020/06	PAC 433MHz	P53C/S51	●	●	○	0	433MHz	Pacific	●	●
인피니티	QX70	2013/01-2019/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
인피니티	QX80	2013/01-2022/12	433MHz	Z62	●	●	○	0	433MHz	Pacific	●	●
인피니티	QX80	2010/01-2016/09	433MHz	JA60	●	●	○	0	433MHz	Pacific	●	●
재규어	E-페이스	2017/01-2022/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	F-페이스	2015/01-2022/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타입	2013/01-2013/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
재규어	F-타입	2017/01-2023/06	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타입	2016/01-2016/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	F-타입	2014/01-2015/06	433MHz		○	●	○	A	433MHz	Continental	●	●
재규어	I-페이스	2017/01-2023/06	433MHz		●	●	○	0/A	433MHz	Continental	●	●
재규어	XE	2014/01-2015/06	433MHz		○	●	○	A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
재규어	XE	2015/01-2022/12	GX631A159AA 433MHz	X760	●	●	○	O/A	433MHz	Continental	●	●
재규어	XF	2014/07-2015/05	433MHz	X260	●	●	○	O/A	433MHz	Continental	●	●
재규어	XF	2015/06-2022/12	433MHz	X260	●	●	○	O/A	433MHz	Continental	●	●
재규어	XF	2008/01-2014/06	433MHz	X250	●	●	○	O/A	433MHz	Continental	●	●
재규어	XJ	2016/01-2022/12	433MHz	X351	●	●	○	O/A	433MHz	Continental	●	●
재규어	XJ	2010/01-2015/12	433MHz	X351	●	●	○	O/A	433MHz	Continental	●	●
재규어	XK	2005/09-2015/12	433MHz	X150	●	●	○	O/A	433MHz	Continental	●	●
재규어	XKR	2006/01-2014/12	433MHz		○	●	○	A	433MHz	Continental	●	●
지프	체로키	2017/01-2017/12	433MHz	KL	●	●	●	O/A	433MHz	TRW	●	●
지프	체로키	2014/01-2016/12	433MHz	KL	●	●	●	O/A	433MHz	TRW	●	●
지프	체로키	2018/01-2021/12	433MHz	KL	●	●	○	A	433MHz	TRW	●	●
지프	컴맨더	2008/01-2010/12	433MHz	XK	●	●	●	O/A	433MHz	Schrader	●	●
지프	컴맨더	2006/01-2007/12	433MHz	XK	●	●	●	O/A	433MHz	Continental	●	●
지프	컴파스	2008/01-2009/12	315MHz	MK49	●	●	●	O/A	315MHz	Continental	●	●
지프	컴파스	2018/01-2019/12	433MHz	551	●	●	○	O/A	433MHz	Continental	●	●
지프	컴파스	2017/01-2017/12	433MHz	551	●	●	●	O/A	433MHz	Continental	●	●
지프	컴파스	2006/05-2014/08	433MHz	MK49	●	●	●	O/A	433MHz	Schrader	●	●
지프	컴파스	2007/01-2007/12	315MHz	MK49	●	●	●	O/A	315MHz	Continental	●	●
지프	컴파스	2014/09-2017/12	433MHz	MK49	●	●	●	O/A	433MHz	Schrader	●	●
지프	컴파스	2019/01-2021/12	433MHz	551	●	●	○	A	433MHz	Continental	●	●
지프	Gladiator	2019/11-2022/12	MRXAG4WA5 433MHz		●	●	○	A	433MHz	Schrader	●	●
지프	그랜드 체로키	2016/01-2018/12	433MHz 68252493AB	WK	●	●	○	O/A	433MHz	Continental	●	●
지프	그랜드 체로키	2011/01-2011/12	433MHz	WK74	●	●	●	O	433MHz	Schrader	●	●
지프	그랜드 체로키	2012/01-2013/12	433MHz	WK74	●	●	●	O	433MHz	Schrader	●	●
지프	그랜드 체로키	2014/01-2015/12	433MHz	WK74	●	●	●	O	433MHz	Schrader	●	●
지프	그랜드 체로키	2016/01-2017/12	433MHz	WK	●	●	●	O/A	433MHz	Continental	●	●
지프	그랜드 체로키	2019/01-2022/12	433MHz 68252493AB	WK	●	●	○	A	433MHz	Continental	●	●
지프	패트리오트	2007/01-2008/12	433MHz	MK	●	●	●	O/A	433MHz	Continental	●	●
지프	패트리오트	2009/01-2014/12	315MHz	MK	●	●	●	O/A	315MHz	Schrader	●	●
지프	레니게이드	2015/01-2016/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
지프	레니게이드	2018/01-2018/12	433MHz		●	●	○	A	433MHz	Continental	●	●
지프	레니게이드	2020/01-2022/12	433MHz 53394085		●	●	○	A	433MHz	Continental	●	●
지프	레니게이드	2017/01-2017/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
지프	랭글러	2018/01-2021/06	433MHz	JL	●	●	○	A	433MHz	Schrader	●	●
지프	랭글러	2014/01-2017/12	433MHz	JL	●	●	●	O/A	433MHz	Schrader	●	●
지프	랭글러	2010/01-2013/12	433MHz	JK72	●	●	●	O/A	433MHz	Schrader	●	●
기아	Bongo	2020/01-2022/12	433MHz		●	●	○	C	433MHz	Continental	●	●
기아	Bongo	2017/01-2019/12	433MHz		●	●	○	C	433MHz	Continental	●	●
기아	Bongo	2014/01-2016/12	433MHz		●	●	○	C	433MHz	Continental	●	●
기아	카렌스	2014/01-2019/12	433MHz	RP	●	●	○	O/A	433MHz	Continental	●	●
기아	카니발	2020/01-2022/12	433MHz	KA4	●	●	○	A	433MHz	Continental	●	●
기아	카니발	2019/01-2019/12	433MHz	YP	●	●	○	O	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
기아	카니발	2018/01-2018/12	52933C1100 433MHz		●	●	○	0	433MHz	Schrader	●	●
기아	카니발	2005/01-2014/12	315MHz	YP	●	●	○	0	315MHz	Lear	●	●
기아	카니발	2014/01-2018/12	Sedan 433MHz	YP	●	●	○	0	433MHz	Schrader	●	●
기아	EV6	2021/03-2027/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
기아	K3	2019/01-2019/12	433MHz TRW	YDC/YD	●	●	○	A	433MHz	TRW	●	●
기아	K3	2012/01-2018/12	433MHz TRW	YDC/YD	●	●	○	0	433MHz	TRW	●	●
기아	K3	2012/01-2016/12	529333X305 433MHz		●	●	○	0	433MHz	TRW	●	●
기아	K3	2019/01-2021/12	433MHz Pacific	BDC/BD	●	●	○	A	433MHz	Pacific	●	●
기아	K5	2020/01-2020/05	433MHz Hybrid	JF/JF HEV	●	●	○	A	433MHz	Continental	●	●
기아	K5	2013/01-2015/06	Hybrid 433MHz	TF/TF HEV	●	●	○	0	433MHz	Continental	●	●
기아	K5	2011/01-2012/12	433MHz	TF/TF HEV	●	●	○	0	433MHz	Continental	●	●
기아	K5	2015/07-2019/12	433MHz Hybrid	JF/JF HEV	●	●	○	O/A	433MHz	Continental	●	●
기아	K5	2020/01-2022/12	433MHz	DL3	●	●	○	A	433MHz	Continental	●	●
기아	K7	2016/01-2021/06	433MHz	YG	●	●	○	0	433MHz	Continental	●	●
기아	K7	2013/01-2016/12	Hybrid 433MHz	VG	●	●	○	0	433MHz	Continental	●	●
기아	K7	2008/01-2012/12	433MHz	VG	●	●	○	0	433MHz	Continental	●	●
기아	K9	2019/01-2022/12	433MHz	RJ	●	●	○	C	433MHz	Schrader	●	●
기아	K9	2011/01-2018/12	433MHz	KH	●	●	○	0	433MHz	Schrader	●	●
기아	모하비	2017/01-2020/12	433MHz		●	●	○	A	433MHz	Continental	●	●
기아	모하비	2016/01-2016/12	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	모하비	2020/01-2021/12	433MHz	HM PE2	●	●	○	A	433MHz	Continental	●	●
기아	모하비	2014/09-2015/12	433MHz		○	●	○	C	433MHz	TRW	●	●
기아	모하비	2008/01-2014/08	433MHz		○	●	○	C	433MHz	TRW	●	●
기아	모하비	2007/01-2007/12	433MHz	HM	●	●	○	0	433MHz	TRW	●	●
기아	모하비	2007/01-2007/12	433MHz		●	●	○	0	433MHz	TRW	●	●
기아	모닝	2017/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	모닝	2014/01-2019/06	433MHz		●	●	○	0	433MHz	Continental	●	●
기아	Morning 3	2017/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	니로	2016/01-2021/12	433MHz	DE	●	●	○	0	433MHz	Continental	●	●
기아	Opirus	2006/01-2014/12	433MHz		●	●	○	0	433MHz	TRW	●	●
기아	Pride	2018/01-2018/12	Lo Line 433MHz	YB	●	●	○	0	433MHz	TRW	●	●
기아	Pride	2018/01-2018/12	Hi Line 433MHz	YB	●	●	○	0	433MHz	TRW	●	●
기아	Pride	2017/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
기아	Pride	2012/01-2017/12	UB 433MHz		●	●	○	0	433MHz	TRW	●	●
기아	Ray	2011/01-2020/12	Elec 433MHz		●	●	○	0	433MHz	Continental	●	●
기아	Seltos	2019/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
기아	Sonet	2021/01-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
기아	쏘렌토	2014/01-2018/06	433MHz 529333N100	UMA	●	●	○	C	433MHz	Continental	●	●
기아	쏘렌토	2018/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
기아	쏘렌토	2020/01-2022/12	433MHz	MQ4	●	●	○	A	433MHz	Continental	●	●
기아	쏘렌토	2006/01-2008/12	433MHz	XM	●	●	○	O	433MHz	Continental	●	●
기아	쏘렌토	2009/01-2010/12	433MHz		●	●	○	O	433MHz	Continental	●	●
기아	쏘렌토	2011/01-2015/12	433MHz		●	●	○	O	433MHz	Continental	●	●
기아	쏘울	2019/01-2022/12	433MHz	SK3	●	●	○	A	433MHz	Continental	●	●
기아	쏘울	2013/11-2016/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
기아	쏘울	2008/06-2013/10	433MHz	AM	●	●	○	O	433MHz	Continental	●	●
기아	스포티지	2013/10-2016/01	433MHz	SL	●	●	○	O/A	433MHz	TRW	●	●
기아	스포티지	2021/01-2023/12	433MHz 52940L1100		●	●	○	A	433MHz	Continental	●	●
기아	스포티지	2015/11-2021/06	433MHz	QL/QLE	●	●	○	O/A	433MHz	Continental	●	●
기아	스포티지	2010/01-2014/01	Hi Line 433MHz	SL	●	●	○	O	433MHz	TRW	●	●
기아	스포티지	2010/01-2013/12	Lo Line 433MHz	SL	●	●	○	O	433MHz	TRW	●	●
기아	Sportage R	2014/01-2015/12	433MHz		●	●	○	O	433MHz	TRW	●	●
기아	Stinger	2018/01-2022/12	433MHz	CK	●	●	○	A	433MHz	Schrader	●	●
기아	Stinger	2017/06-2017/12	433MHz	CK	●	●	○	O	433MHz	Schrader	●	●
기아	Stinger	2017/01-2017/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
기아	Stonic	2017/11-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
기아	Stonic	2017/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
람보르기니	아벤타도	2011/01-2022/12	433MHz	LB834	○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	Few Off	2017/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	허라칸	2014/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	One off	2016/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
람보르기니	Urus	2020/01-2022/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
람보르기니	Urus	2017/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
랜드로버	디펜더	2019/01-2023/06	433MHz LR070840		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	디스커버리	2004/07-2016/12	KR5S18005202 0A 433MHz		○	●	○	A	433MHz	Continental	●	●
랜드로버	디스커버리	2015/10-2016/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	디스커버리	2017/01-2019/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	디스커버리 스포츠	2015/09-2020/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	디스커버리5	2019/01-2020/06	433MHz		○	●	○	A	433MHz	Continental	●	●
랜드로버	프리랜더	2006/01-2022/06	433MHz	Fr132	●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버	2015/06-2022/12	433MHz	D6, Ra5	●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버	2010/01-2015/12	433MHz	L322	●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2015/10-2022/06	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버 에보크	2011/01-2015/09	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2015/06-2022/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버 스포츠	2013/01-2015/05	433MHz		●	●	○	O/A	433MHz	Continental	●	●
랜드로버	렌지로버 벨라	2017/01-2023/06	433MHz		●	●	○	O/A	433MHz	Continental	●	●
렉서스	CT Series	2010/12-2022/12	433MHz	080A	●	●	○	O	433MHz	Pacific	●	●
렉서스	ES Series	2012/06-2018/05	433MHz	980L	●	●	○	O	433MHz	Pacific	●	●
렉서스	ES Series	2006/01-2012/05	433MHz		●	●	○	O	433MHz	Pacific	●	●
렉서스	ES Series	2018/06-2022/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
렉서스	GS Series	2012/01-2022/12	433MHz	920L	●	●	○	O	433MHz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
렉서스	IS Series	2006/01-2022/12	107J 315MHz		●	●	○	0	315MHz	Pacific	●	●
렉서스	IS Series	2013/04-2022/12	C210 433MHz	030L/400A/720A/XE30	●	●	○	0	433MHz	Pacific	●	●
렉서스	LC Series	2017/01-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
렉서스	LS Series	2012/10-2017/09	433MHz		●	●	○	0	433MHz	Pacific	●	●
렉서스	LS Series	2017/10-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
렉서스	LX Series	2015/10-2021/12	C215 433MHz	URJ	●	●	○	0	433MHz	Pacific	●	●
렉서스	NX Series	2014/01-2022/12	433MHz	600A	●	●	○	0	433MHz	Pacific	●	●
렉서스	RC Series	2014/01-2022/12	433MHz	XC1/720A	●	●	○	0	433MHz	Pacific	●	●
렉서스	RX Series	2015/11-2022/12	C215 433MHz	740A	●	●	○	0	433MHz	Pacific	●	●
렉서스	RX Series	2013/01-2015/10	433MHz	640L	●	●	○	0	433MHz	Pacific	●	●
렉서스	RX Series	2015/10-2020/12	C015 315MHz		●	●	○	0	315MHz	Pacific	●	●
렉서스	SC Series	2006/08-2010/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
렉서스	UX Series	2018/01-2023/12	C215 433MHz	URJ	●	●	○	0	433MHz	Pacific	●	●
링컨	에비에이터	2020/01-2020/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
링컨	컨티넨탈	2017/01-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	Corsair	2020/08-2022/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
링컨	Corsair	2019/08-2020/07	433MHz		○	●	○	S	433MHz	Schrader	●	●
링컨	MKC	2015/06-2019/12	433MHz	2. OF SEL	●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKX	2015/01-2015/12	433MHz		●	●	●	S	433MHz	Schrader	●	●
링컨	MKX	2016/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2021/01-2021/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2017/01-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2015/09-2016/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
링컨	MKZ	2013/01-2016/12	433MHz DR3V1A180DA		●	●	●	0/S	433MHz	Schrader	●	●
링컨	Nautilus	2019/01-2021/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Lotus	3 Eleven	2015/01-2021/06	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Elise	2000/09-2021/05	433MHz	Monza	○	●	○	A	433MHz	Schrader	●	●
Lotus	Evora	2010/01-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Exige	2000/09-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
마세라티	지블리	2013/01-2020/12	433MHz	M156/ M157	●	●	○	0/A	433MHz	Schrader	●	●
마세라티	그란싸브리오	2017/01-2020/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
마세라티	그란 투리스모	2014/01-2022/01	433MHz	M145	●	●	○	0/A	433MHz	Schrader	●	●
마세라티	레반테	2020/01-2021/12	433MHz	M161	○	●	○	C	433MHz	Continental	●	●
마세라티	레반테	2015/01-2019/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
마세라티	MC20	2020/01-2021/12	433MHz		○	●	○	C	433MHz	Continental	●	●
마세라티	콰트로폴테	2013/01-2018/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
McLaren	500 Series	2015/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	600 Series	2014/03-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	700 Series	2017/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	GT	2019/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	P1	2013/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Senna	2018/01-2020/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
McLaren	Speedtail	2019/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
메르세데스-벤츠	A Class	2014/04-2018/05	433MHz	W176	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	A Class	2012/01-2014/03	433MHz	W176	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	A Class	2018/06-2022/06	433MHz	W177	●	●	○	O/A	433MHz	Huf/Beru	●	●
메르세데스-벤츠	AMG GT	2014/01-2022/06	433MHz	C190	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	B Class	2011/11-2019/01	433MHz	W246/W242	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	C Class	2021/06-2023/12	433MHz	206	○	●	○	A	433MHz	Schrader	●	●
메르세데스-벤츠	C Class	2018/06-2020/12	433MHz	W205	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	C Class	2018/01-2018/12	433MHz	C205	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	C Class	2014/03-2018/05	433MHz	W205	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	C Class	2007/04-2014/02	433MHz	W204/W203	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	CL Class	2007/01-2014/12	433MHz	C216	●	●	○	O	433MHz	Continental	●	●
메르세데스-벤츠	CLA Class	2019/05-2022/12	433MHz	C118	●	●	○	O/A	433MHz	Huf/Beru	●	●
메르세데스-벤츠	CLA Class	2014/06-2019/04	433MHz	C117	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	CLA Class	2012/12-2014/05	433MHz	C117	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	CLS	2021/01-2022/12	433MHz	206	○	●	○	C	433MHz	Schrader	●	●
메르세데스-벤츠	CLS	2021/01-2022/12	315MHz	206	○	●	○	C	315MHz	Schrader	●	●
메르세데스-벤츠	CLS Class	2012/01-2017/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	CLS Class	2017/01-2022/12	433MHz	C257	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	E Class	2015/11-2022/12	433MHz	W213/BR238	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	E Class	2014/06-2018/12	433MHz	W212	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	E Class	2009/07-2014/05	433MHz	W212/C207	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	E Class	2005/06-2011/10	433MHz	W211	●	●	○	O/A	433MHz	Continental	●	●
메르세데스-벤츠	EQB	2021/01-2022/12	433MHz	243	●	●	○	O	433MHz	Huf/Beru	●	●
메르세데스-벤츠	EQC	2019/05-2022/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	EQE	2022/01-2022/12	433MHz	295	○	●	○	A	433MHz	Schrader	●	●
메르세데스-벤츠	EQE	2022/01-2022/12	315MHz	295	○	●	○	C	315MHz	Schrader	●	●
메르세데스-벤츠	EQS	2021/01-2022/12	315MHz	297	○	●	○	C	315MHz	Schrader	●	●
메르세데스-벤츠	G Class	2018/06-2022/12	433MHz	G463	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	G Class	2007/04-2018/05	433MHz	G463/461	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	GLA Class	2018/01-2020/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
메르세데스-벤츠	GLA Class	2020/02-2022/12	433MHz	H247	●	●	○	O/A	433MHz	Huf/Beru	●	●
메르세데스-벤츠	GLB Class	2019/01-2022/12	433MHz	X247	●	●	○	O/A	433MHz	Huf/Beru	●	●
메르세데스-벤츠	GLC Class	2015/01-2019/07	433MHz	X253	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	GLC Class	2016/09-2022/12	433MHz	C253	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	GLE Class	2018/10-2022/12	433MHz	V167	●	●	○	O/A	433MHz	Huf/Beru	●	●
메르세데스-벤츠	GLE Class	2015/07-2020/12	433MHz	X166	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	GLK Class	2008/01-2015/09	433MHz	X204	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	GLS Class	2013/01-2019/06	433MHz	X166	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	GT	2014/01-2022/12	433MHz	GT	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	ML Class	2011/09-2015/09	433MHz	166	●	●	○	O	433MHz	Schrader	●	●
메르세데스-벤츠	S Class	2021/06-2023/12	433MHz	223	○	●	○	A	433MHz	Schrader	●	●
메르세데스-벤츠	S Class	2017/01-2017/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	S Class	2013/07-2020/12	433MHz	W222/C217	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	S Class	2009/06-2013/06	433MHz	W221	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	S Class 쿠페	2014/01-2022/12	433MHz	217	●	●	○	O	433MHz	Schrader	●	●
메르세데스-벤츠	SL Class	2012/01-2020/12	433MHz	W231	●	●	○	O/A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
메르세데스-벤츠	SLC Class	2016/01-2020/06	433MHz	R172	●	●	○	O/A	433MHz	Schrader	●	●
메르세데스-벤츠	SLK Class	2004/01-2021/12	433MHz	R171, R172	●	●	○	O/A	433MHz	Schrader	●	●
미니	3-5 Doors Hatch	2014/01-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
미니	클럽맨	2013/11-2022/12	433MHz	F54	●	●	○	A	433MHz	Continental	●	●
미니	클럽맨	2008/01-2013/12	Indirect	R55	○	○	○	A	N/A	N/A	Indirect	●
미니	Convertible	2017/01-2021/12	433MHz	R57	●	●	○	A	433MHz	Continental	●	●
미니	Convertible	2014/01-2016/12	433MHz	R57	●	●	○	O/A	433MHz	Huf/Beru	●	●
미니	Convertible	2010/01-2013/12	Indirect	R57	○	○	○	A	N/A	N/A	Indirect	●
미니	쿠퍼	2014/03-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
미니	컨트리맨	2010/01-2013/12	Indirect	R60	○	○	○	A	N/A	N/A	Indirect	●
미니	컨트리맨	2011/01-2018/12	433MHz	R60	●	●	○	O/A	433MHz	Huf/Beru	●	●
미니	컨트리맨	2015/07-2022/12	433MHz	F60	●	●	○	A	433MHz	Continental	●	●
미니	쿠페	2012/01-2013/12	Indirect	R58	○	○	○	A	N/A	N/A	Indirect	●
미니	쿠페	2016/01-2017/12	433MHz		●	●	○	A	433MHz	Continental	●	●
미니	쿠페	2011/07-2015/12	433MHz	R58	●	●	○	O/A	433MHz	Huf/Beru	●	●
미니	해치백	2013/11-2019/12	433MHz	F56	●	●	○	A	433MHz	Continental	●	●
미니	페이스맨	2013/01-2014/06	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
미니	페이스맨	2014/07-2018/06	433MHz	R61	●	●	○	O/A	433MHz	Huf/Beru	●	●
미니	페이스맨	2012/01-2013/12	Indirect	R61	○	○	○	A	N/A	N/A	Indirect	●
미니	로드스터	2011/11-2014/06	433MHz	R55	○	●	○	C	433MHz	Huf/Beru	●	●
미니	로드스터	2014/01-2015/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
미니	로드스터	2012/01-2013/12	Indirect	R59	○	○	○	A	N/A	N/A	Indirect	●
미츠비시	아웃랜더	2008/01-2011/12	Indirect		○	○	○	C	N/A	N/A	Indirect	●
니산	370Z	2013/07-2021/06	PAC 433MHz	RC53D(2)/Z34	●	●	○	O/A	433MHz	Pacific	●	●
니산	370Z	2008/01-2014/07	433MHz	C53D/Z34	●	●	○	O	433MHz	Schrader	●	●
니산	알티마	2009/01-2012/06	315MHz	L32	○	●	○	C	315MHz	Schrader	●	●
니산	알티마	2012/05-2019/09	407003JA0B 433MHz	L33	●	●	○	O	433MHz	Continental	●	●
니산	알티마	2015/01-2022/12	433MHz	L33	●	●	○	O	433MHz	Continental	●	●
니산	Altima Sedan	2006/01-2012/12	315MHz	L33	●	●	○	O	315MHz	Schrader	●	●
니산	큐브	2011/01-2015/12	Smart key 315MHz	Z12	●	●	○	O	315MHz	Pacific	●	●
니산	GT-R	2007/01-2022/12	315MHz	R35	●	●	○	O	315MHz	Schrader	●	●
니산	쥬크	2012/01-2014/02	Smart key 315MHz	F15	○	●	○	C	315MHz	Pacific	●	●
니산	쥬크	2014/03-2019/12	407005ZHOA 433MHz		●	●	○	O	433MHz	Pacific	●	●
니산	리프	2017/01-2022/12	433MHz		●	●	○	O	433MHz	Continental	●	●
니산	리프	2010/10-2019/12	433MHz	ZE0/B12G	●	●	○	O	433MHz	Pacific	●	●
니산	Leaf Korea	2015/01-2019/12	433MHz		●	●	○	O	433MHz	Continental	●	●
니산	맥시마	2015/01-2021/12	Clamp in 433MHz	A36	●	●	○	O	433MHz	Continental	●	●
니산	맥시마	2019/01-2022/12	433MHz		●	●	○	O	433MHz	Continental	●	●
니산	무라노	2008/01-2015/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
니산	무라노	2014/01-2014/12	433MHz	Z51/Z52/P42 M	●	●	○	O	433MHz	Pacific	●	●
니산	무라노	2013/10-2022/12	Clamp in 433MHz	Z52	●	●	○	O	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
니산	패스파인더	2014/01-2015/10	433MHz	P61B	○	●	○	C	433MHz	Continental	●	●
니산	패스파인더	2015/11-2020/12	433MHz	R52/P61B	●	●	○	O	433MHz	Continental	●	●
니산	콰시카이	2014/01-2016/12	433MHz	J10/J11/P32 S	○	●	○	C	433MHz	Continental	●	●
니산	엑스트레일	2022/01-2022/12	433MHz		●	●	○	O	433MHz	Continental	●	●
니산	엑스트레일	2018/01-2019/12	433MHz		●	●	○	O	433MHz	Continental	●	●
푸조	1007	2004/01-2011/12	433MHz	A08/PF1	●	●	○	O	433MHz	Continental	●	●
푸조	2008	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
푸조	207	2007/01-2013/09	433MHz	A7	○	●	○	C	433MHz	Continental	●	●
푸조	208	2012/05-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
푸조	208	2002/01-2002/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
푸조	3008	2013/09-2019/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
푸조	3008	2008/11-2013/08	433MHz	T84	●	●	○	O	433MHz	Schrader	●	●
푸조	308	2013/09-2019/12	9802003680 433MHz	T7	●	●	○	O	433MHz	Schrader	●	●
푸조	308	2014/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
푸조	308	2007/04-2015/08	5430W0 433MHz	T7	●	●	○	O	433MHz	Schrader	●	●
푸조	407	2003/01-2012/12	433MHz	D2	●	●	○	O	433MHz	Continental	●	●
푸조	5008	2017/01-2022/12	433MHz	T87	○	●	○	C	433MHz	Schrader	●	●
푸조	5008	2009/01-2013/08	433MHz	T87	●	●	○	O	433MHz	Schrader	●	●
푸조	508	2013/10-2022/12	433MHz	W2	●	●	○	O/A	433MHz	Schrader	●	●
푸조	508	2010/01-2014/09	433MHz		●	●	○	O	433MHz	Schrader	●	●
푸조	607	2004/10-2012/12	433MHz	Z8	●	●	○	O	433MHz	Continental	●	●
푸조	807	2004/10-2016/12	433MHz	V2/80092	●	●	○	O	433MHz	Continental	●	●
포르쉐	718(982)	2016/01-2021/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911	2015/01-2020/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	911	2012/02-2016/12	433MHz	991	●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	911	2011/01-2017/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911	2005/01-2012/12	315MHz	997	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911	2004/07-2012/01	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911(991)	2011/12-2016/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911(991)	2011/01-2016/12	433MHz	991	●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	911(992)	2017/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911(997)	2015/09-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911(997)	2009/01-2015/08	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911(997)	2008/04-2015/08	433MHz	997	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911(997)	2005/02-2008/03	433MHz	997	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911(997)	2005/01-2008/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911(터보)	2010/01-2016/12	433MHz	991T	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	911(터보)	2010/01-2016/12	315MHz	991T	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911(터보)	2007/01-2009/12	315MHz	997T	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	911(터보)	2007/01-2009/12	433MHz	997T	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	918 스파이더	2013/01-2015/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2017/01-2022/12	315MHz	982/982SP	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2016/03-2022/12	433MHz	982/982SP	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2012/01-2016/12	315MHz	981/981SP	●	●	○	O/A	315MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
포르쉐	박스터	2012/01-2016/12	433MHz	981	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2009/01-2013/12	433MHz	987	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	박스터	2009/01-2012/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2004/01-2008/12	315MHz	987	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	박스터	2004/01-2008/12	433MHz	987	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Carrera GT	2003/09-2011/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2010/01-2014/12	315MHz	92A	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2017/09-2022/12	433MHz	9YA	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2015/01-2021/12	315MHz	9YA	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2014/11-2017/08	433MHz	92A	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2011/01-2014/10	433MHz	92A	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2007/01-2010/12	315MHz	9PA1	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2007/01-2010/12	433MHz	9PA1	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	카이엔	2002/01-2006/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	카이엔	2002/01-2006/12	433MHz	9PA	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2010/01-2012/12	315MHz	4. 8L	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2007/01-2009/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2017/09-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2014/06-2017/08	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2010/01-2014/05	433MHz	4. 8L	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Cayenne S	2008/01-2009/12	315MHz	4. 8L	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	케이맨	2013/01-2016/12	315MHz	2. 7L	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	케이맨	2017/01-2020/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2016/10-2022/12	433MHz	982/982C/CT 4-2	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2012/01-2016/12	433MHz	981	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2005/01-2008/12	433MHz	987/987C	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2005/01-2008/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	케이맨	2009/01-2011/12	433MHz	987	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	케이맨	2009/01-2012/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	GT3	2006/03-2011/12	433MHz	996	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	GT3	2015/01-2015/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
포르쉐	GT3	2010/01-2016/12	433MHz	996/997	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	GT3	2017/01-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
포르쉐	GT3	2007/01-2009/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	마칸	2018/01-2022/12	315MHz	95B	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	마칸	2014/01-2022/12	433MHz	P0416/95B	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	마칸	2014/01-2018/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	파나마라	2017/09-2022/12	433MHz	970/971	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	파나마라	2014/01-2016/12	315MHz	970	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	파나마라	2013/09-2017/08	433MHz	970	●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	파나마라	2009/01-2014/02	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	파나마라	2010/01-2013/12	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	Panamera S	2009/06-2013/12	315MHz	4. 8L	●	●	○	O/A	315MHz	Huf/Beru	●	●
포르쉐	Panamera S	2009/01-2013/06	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
포르쉐	Taycan	2019/01-2022/12	433MHz 9J1907275		○	●	○	C	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Renault	Clio	2013/01-2015/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Renault	Clio III	2004/04-2014/05	433MHz	X85	●	●	●	O	433MHz	Schrader	●	●
Renault	Clio IV	2014/06-2019/12	433MHz	X85/X98	●	●	○	O	433MHz	Schrader	●	●
Renault	Kangoo	2022/01-2022/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Renault	Master	2009/11-2022/12	433MHz	X62	●	●	○	O	433MHz	Schrader	●	●
Renault	Zoe	2019/07-2022/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	QM3	2016/01-2018/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
르노삼성	QM3	2013/01-2015/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
르노삼성	QM5	2014/01-2016/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	QM5	2009/01-2013/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
르노삼성	QM5	2007/01-2013/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
르노삼성	QM6	2016/01-2016/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	QM6	2017/01-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM3	2017/01-2020/12	407004CBOA 433MHz		○	●	○	C	433MHz	Continental	●	●
르노삼성	SM3	2009/01-2018/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM3 ZE	2015/01-2018/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM5	2010/01-2015/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM5	2016/01-2019/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM6	2015/01-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM7	2016/01-2020/06	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	SM7	2012/01-2015/12	433MHz		●	●	○	O	433MHz	Continental	●	●
르노삼성	XM3	2019/01-2020/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
롤스로이스	컬리넨	2019/01-2022/12	YGOTSSRE4A 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
롤스로이스	컬리넨	2018/01-2021/12	433MHz	R31	○	●	○	A	433MHz	Schrader	●	●
롤스로이스	다운	2016/01-2022/12	433MHz	RR6	○	●	○	C	433MHz	Huf/Beru	●	●
롤스로이스	고스트	2020/08-2022/08	433MHz		○	●	○	C	433MHz	Schrader	●	●
롤스로이스	고스트	2020/01-2021/06	433MHz	RR21	○	●	○	C	433MHz	Huf/Beru	●	●
롤스로이스	고스트	2010/01-2020/12	433MHz	RR04	○	●	○	C	433MHz	Huf/Beru	●	●
롤스로이스	팬텀	2017/01-2022/12	MRXAG5SP4 433MHz	RR11	○	●	○	A	433MHz	Schrader	●	●
롤스로이스	팬텀	2012/01-2017/12	433MHz	RR01	○	●	○	A	433MHz	Huf/Beru	●	●
롤스로이스	레이스	2013/01-2022/12	433MHz	RR5	○	●	○	C	433MHz	Huf/Beru	●	●
쌍용	엑티온	2012/08-2021/12	QJ 433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	엑티온	2018/07-2019/12	Q200 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	체어맨	2014/01-2019/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
쌍용	체어맨	2014/01-2019/12	4199034000 433MHz		●	●	○	A	433MHz	Schrader	●	●
쌍용	체어맨	2005/01-2013/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
쌍용	코란도	2010/11-2022/12	C200 433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	코란도	2019/05-2022/06	4199037000 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	코란도	2008/01-2013/12	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
쌍용	카이런	2010/01-2016/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	카이런	2006/01-2014/05	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
쌍용	무쏘	2018/06-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	무쏘	2016/01-2018/05	433MHz		○	●	○	A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
쌍용	렉스턴	2012/07-2017/12	Y300 433MHz		●	●	○	A	433MHz	Schrader	●	●
쌍용	렉스턴	2020/01-2021/12	C300 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
쌍용	렉스턴	2017/03-2022/12	Y400 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	렉스턴	2006/01-2013/12	315MHz		●	●	○	A	315MHz	Huf/Beru	●	●
쌍용	Rodius	2005/05-2021/12	AJ 433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	Rodius	2005/01-2013/12	315MHz		○	●	○	A	315MHz	Huf/Beru	●	●
쌍용	티볼리	2016/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	티볼리	2015/01-2020/06	X100 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
쌍용	Turismo	2014/01-2022/12	AJ 433MHz		○	●	○	A	433MHz	Schrader	●	●
쌍용	XLV	2016/01-2021/12	XK 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
테슬라	Model 3	2016/01-2020/08	433MHz		○	●	○	A	433MHz	Continental	●	●
테슬라	Model 3	2018/01-2021/12	433MHz (10748 1200B)		○	●	○	A	433MHz	Continental	●	●
테슬라	Model S	2014/09-2022/12	433MHz		○	●	○	A	433MHz	Continental	●	●
테슬라	Model X	2014/10-2022/12	Continental 433MHz		○	●	○	A	433MHz	Continental	●	●
도요타	86	2012/04-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
도요타	아발론	2013/01-2018/04	433MHz		●	●	○	0	433MHz	Pacific	●	●
도요타	아발론	2018/04-2022/12	433MHz	740A	●	●	○	0	433MHz	Pacific	●	●
도요타	캠리	2014/01-2017/12	433MHz	XV50	●	●	○	0	433MHz	Pacific	●	●
도요타	캠리	2016/01-2022/12	C215 433MHz	045L	●	●	○	0/A	433MHz	Pacific	●	●
도요타	Camry Hybrid	2014/01-2017/09	433MHz	XV50/XV70	●	●	○	0	433MHz	Pacific	●	●
도요타	코롤라	2002/01-2013/08	Japan/USA 315MHz		●	●	○	0	315MHz	Pacific	●	●
도요타	FJ 크루저	2014/06-2022/12	433MHz	155L	●	●	○	0	433MHz	Pacific	●	●
도요타	GR Supra	2019/01-2022/12	433MHz		●	●	○	0	433MHz	Huf/Beru	●	●
도요타	GT86	2012/09-2022/12	433MHz	E88	●	●	○	0	433MHz	Pacific	●	●
도요타	랜드크루저	2014/01-2021/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
도요타	Land Cruiser Prado	2009/01-2017/09	433MHz	611L	●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스	2019/01-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스	2014/01-2018/12	433MHz	590L/030A/XW30/XW50/690A/277N	●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스 C	2014/03-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
도요타	프리우스 V	2014/11-2017/11	433MHz		●	●	○	0	433MHz	Pacific	●	●
도요타	RAV4	2012/01-2019/09	433MHz	410A/XA40/120L	●	●	○	0	433MHz	Pacific	●	●
도요타	RAV4	2018/01-2022/12	433MHz	XA50	●	●	○	0	433MHz	Pacific	●	●
도요타	씨에나	2010/06-2022/12	433MHz	500N/500L	●	●	○	0	433MHz	Pacific	●	●
도요타	벤자	2014/06-2015/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
폭스바겐	아테온	2017/01-2022/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	비틀	2012/12-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	비틀	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	CC	2018/01-2022/12	MQB 433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	CC	2011/06-2017/12	433MHz	VC17	●	●	○	0/A	433MHz	Huf/Beru	●	●
폭스바겐	EOS	2014/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	골프	2013/01-2022/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
폭스바겐	골프	2009/01-2012/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
폭스바겐	ID. 3	2020/01-2022/12	Indirect		○	○	○	C	N/A	N/A	Indirect	●
폭스바겐	ID. 4	2021/01-2022/12	Indirect		○	○	○	C	N/A	N/A	Indirect	●
폭스바겐	제타	2010/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	뉴 비틀	2011/08-2020/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	뉴 비틀	2012/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	뉴 비틀	2008/01-2011/07	433MHz	VW314	○	●	○	C	433MHz	Continental	●	●
폭스바겐	뉴 비틀	2006/01-2011/12	315MHz		○	●	○	C	315MHz	Continental	●	●
폭스바겐	뉴 비틀	2006/01-2011/12	433MHz	VW314	○	●	○	C	433MHz	Continental	●	●
폭스바겐	파사트	2014/09-2022/12	433MHz	B8	●	●	○	O/A	433MHz	Huf/Beru	●	●
폭스바겐	파사트	2005/01-2011/12	433MHz	VW451	●	●	○	O/A	433MHz	Continental	●	●
폭스바겐	파사트	2010/01-2014/12	433MHz		●	●	○	O	433MHz	Huf/Beru	●	●
폭스바겐	Passat CC	2009/01-2011/12	433MHz		○	●	○	C	433MHz	Continental	●	●
폭스바겐	페이톤	2001/12-2007/05	433MHz	VW611	●	●	○	A	433MHz	Huf/Beru	●	●
폭스바겐	페이톤	2010/06-2019/12	433MHz	Vh67	●	●	○	O/A	433MHz	Huf/Beru	●	●
폭스바겐	폴로	2009/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
폭스바겐	씨로코	2012/01-2016/12	Indirect		○	○	○	C	N/A	N/A	Indirect	●
폭스바겐	T-Cross	2019/01-2022/12	Indirect		○	○	○	C	N/A	N/A	Indirect	●
폭스바겐	T-ROC	2021/01-2022/12	Indirect		○	○	○	C	N/A	N/A	Indirect	●
폭스바겐	Teramont	2019/01-2022/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
폭스바겐	티구안	2011/05-2015/12	433MHz	5N	●	●	○	O/A	433MHz	Huf/Beru	●	●
폭스바겐	티구안	2016/01-2022/12	433MHz	VW376/5N2	●	●	○	O/A	433MHz	Huf/Beru	●	●
폭스바겐	티구안	2008/01-2011/04	433MHz		●	●	○	A	433MHz	Continental	●	●
폭스바겐	Tiguan L	2016/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
폭스바겐	투아렉	2014/08-2022/12	433MHz	7P5/7P6108	●	●	○	O/A	433MHz	Huf/Beru	●	●
폭스바겐	투아렉	2010/01-2014/07	433MHz	VW526	●	●	○	O/A	433MHz	Huf/Beru	●	●
볼보	C30	2011/01-2014/03	433MHz	Y279	●	●	○	O/A	433MHz	Continental	●	●
볼보	C30	2006/01-2010/12	433MHz	Y279	●	●	○	O/A	433MHz	Continental	●	●
볼보	C30 일렉트릭	2011/01-2013/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	C30 일렉트릭	2010/01-2010/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	C70	2006/01-2007/12	433MHz	V70064	●	●	○	O/A	433MHz	Continental	●	●
볼보	C70	2011/01-2014/12	433MHz	V70064	●	●	○	O/A	433MHz	Continental	●	●
볼보	C70	2008/01-2010/12	433MHz	V70064	●	●	○	O/A	433MHz	Continental	●	●
볼보	S40	2003/01-2010/12	433MHz	V40044	●	●	○	O/A	433MHz	Continental	●	●
볼보	S40	2011/01-2014/12	433MHz	V40044	●	●	○	O/A	433MHz	Continental	●	●
볼보	S60	2010/01-2013/01	433MHz	Y283	●	●	○	O/A	433MHz	Continental	●	●
볼보	S60	2010/01-2013/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
볼보	S60	2013/02-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	S60	2014/07-2020/12	433MHz	Y283	●	●	○	O/A	433MHz	Continental	●	●
볼보	S60	2018/01-2021/06	433MHz	V431	●	●	○	O/A	433MHz	Schrader	●	●
볼보	S80	2006/01-2013/02	433MHz		●	●	○	O/A	433MHz	Continental	●	●
볼보	S80	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
볼보	S80	2006/01-2013/12	315MHz		●	●	○	A	315MHz	Schrader	●	●
볼보	S80	2016/01-2018/02	433MHz	V541	○	●	○	C	433MHz	Schrader	●	●
볼보	S90	2016/01-2021/06	433MHz	V541	●	●	○	O/A	433MHz	Schrader	●	●
볼보	S90	2016/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
불보	V40	2015/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
불보	V40	2012/01-2020/12	433MHz	Y555, Y556	●	●	○	O/A	433MHz	Continental	●	●
불보	V50	2011/01-2016/12	433MHz	V5004-124	●	●	○	O/A	433MHz	Continental	●	●
불보	V50	2003/01-2010/12	433MHz	V5004-124	●	●	○	O/A	433MHz	Continental	●	●
불보	V60	2012/01-2022/12	433MHz 31341893		●	●	○	O/A	433MHz	Continental	●	●
불보	V60	2015/09-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
불보	V60	2017/11-2022/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
불보	V60	2008/01-2014/06	433MHz	Y352	●	●	○	O/A	433MHz	Continental	●	●
불보	V70	2007/01-2016/12	433MHz	Y285	●	●	○	O/A	433MHz	Continental	●	●
불보	V90	2016/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
불보	V90	2015/01-2022/12	433MHz	V542	●	●	○	O/A	433MHz	Schrader	●	●
불보	XC40	2017/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
불보	XC60	2015/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
불보	XC60	2008/01-2022/06	433MHz	Y413	●	●	○	O/A	433MHz	Continental	●	●
불보	XC70	2014/07-2018/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
불보	XC70	2010/01-2014/06	433MHz	Y381	●	●	○	O/A	433MHz	Continental	●	●
불보	XC70	2008/01-2009/12	433MHz	Y381	●	●	○	O/A	433Mhz	Continental	●	●
불보	XC90	2016/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
불보	XC90	2015/01-2022/12	433MHz	V526	●	●	○	O/A	433MHz	Schrader	●	●
불보	XC90	2005/01-2014/12	433MHz	Y289	●	●	○	O/A	433MHz	Schrader	●	●