



MX-Sensor_V1.60 Function List For EU Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| AION | Hyper GT | 07/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| AION | Hyper HT | 11/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| AION | Hyper SSR | 10/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| AION | IA5 | 09/2019-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | LX | 10/2019-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | LX PLUS | 01/2022-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | S | 04/2019-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | S PLUS | 06/2021-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | V | 06/2020-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | V PLUS | 06/2020-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AION | Y PLUS | 09/2022-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| AIWAYS | U5 | 12/2019-04/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| AIWAYS | U6 | 10/2022-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| Abarth | 124 Spider | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 10/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 4A Grande Punto | 01/2007-12/2010 | 433MHz | 199 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Abarth | 4B Punto EVO | 01/2010-12/2013 | 433MHz | 199 | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Abarth | 500 | 01/2008-12/2022 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Abarth | 500 | 01/2008-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500C | 01/2010-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 500C | 08/2011-11/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | 595 | 01/2014-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | 595 | 01/2014-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 595 C | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | 695 Biposto | 01/2015-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Abarth | 695 Biposto | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | 81 Nuova Punto | 01/2012-12/2013 | 433MHz | 199 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Abarth | Punto Evo | 01/2008-12/2013 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Abarth | Punto Evo | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Acura | ILX | 06/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | NSX | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | RDX | 01/2021-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | RDX | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | RDX | 01/2018-12/2023 | 433MHz 42753T6NA01 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Acura | TLX | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | TLX | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | TLX | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Alfa Romeo | 159 | 07/2005-12/2016 | 433MHz | 939 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | 4C | 01/2013-12/2021 | 433MHz | 960/961 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 8C | 12/2006-12/2010 | 433MHz | 920 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Alfa Romeo | Brera | 01/2005-07/2012 | 433MHz | 939/946 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | Executive | 11/2018-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | GTA | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2020-12/2024 | 433MHz | 952 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2016-12/2017 | 433MHz 50547691 | 952 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 04/2014-12/2016 | 433MHz | UT | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2018-12/2021 | 433MHz 50547691 | 952 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 01/2018-12/2023 | 433MHz | 940 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Giulietta | 01/2014-12/2017 | 433MHz | 940 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Kamal | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 08/2013-12/2020 | 433MHz | 955 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 01/2008-07/2013 | 433MHz | 955 | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Alfa Romeo | Quadrifoglio | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Quadrifoglio | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Spider | 01/2006-12/2010 | 433MHz | 939 | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Alfa Romeo | Spider | 06/2006-12/2017 | 433MHz | 946 | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Alfa Romeo | Stelvio | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 01/2019-12/2024 | 433MHz | 949 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Tonale | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Tonale | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B10 | 01/1999-12/2004 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | B12 | 01/1999-12/2001 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 03/2014-06/2019 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B3 | 07/2022-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 07/2022-06/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B3 | 09/2009-03/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 03/2006-08/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B3 | 01/1999-12/2002 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | B3 | 05/1998-01/2006 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B4 | 09/2020-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B4 | 02/2022-03/2023 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B4 | 03/2014-07/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B5 | 02/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B5 | 01/2007-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Alpina | B5 | 01/2005-12/2014 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B5 | 01/2017-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B5 | 03/2014-12/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B6 | 03/2014-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B6 | 12/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B6 | 03/2006-11/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 07/2015-07/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B7 | 08/2022-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 01/2006-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B8 | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D10 | 01/1999-12/2004 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | D3 | 01/1999-12/2002 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | D3 | 06/2005-08/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 09/2009-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D3 | 01/2014-12/2022 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D3 | 07/2022-06/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D3 | 07/2022-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D4 | 03/2014-07/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | D4 | 09/2020-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D4 | 02/2022-03/2023 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D5 | 01/2017-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | D5 | 03/2014-12/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D5 | 09/2011-12/2014 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | D5 | 02/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | Roadster | 01/2003-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alpina | XB7 | 07/2022-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XB7 | 01/2020-06/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XD3 | 08/2017-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XD3 | 04/2014-06/2017 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 09/2010-03/2014 | 433MHz | F25 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD3 | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XD4 | 09/2018-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | Cygnat | 01/2011-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| Aston Martin | DB11 | 01/2016-12/2024 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DB9 | 01/2009-12/2018 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DB9 | 01/2005-12/2011 | 433MHz Smartire | | ○ | ● | ○ | NA | 433MHz | Smartire | ● | ● |
| Aston Martin | DBS | 01/2018-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2007-12/2015 | 433MHz | V12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 09/2012-12/2015 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2018-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | 433MHz HY53SE360671 AA | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 10/2018-12/2021 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 10/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 04/2020-12/2024 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Lagonda | 01/2015-12/2019 | 433MHz | COMET | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | One-77 | 01/2011-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 03/2010-06/2021 | 433MHz | VH400 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 01/2010-12/2020 | 433MHz | F149 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2010-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 01/2012-12/2020 | 433MHz | AM310 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 07/2005-12/2024 | 433MHz | AM305 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2005-12/2011 | 433MHz Smartire | | ○ | ● | ○ | NA | 433MHz | Smartire | ● | ● |
| Aston Martin | Vantage | 01/2019-12/2023 | 433MHz RDE036 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | Virage | 01/2010-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 01/2011-08/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 09/2012-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A1 | 06/2010-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A3 | 06/2012-12/2023 | 433MHz | 8L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A3 | 01/2005-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2012-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2001-12/2011 | 433MHz 4F0907275B | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 08/2008-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A4 | 01/2004-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 11/1996-12/2010 | 433MHz | B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A5 | 12/2006-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A5 | 09/2006-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2000-12/2005 | 433MHz 4D0907275 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2000-12/2007 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 03/2004-12/2019 | 433MHz 7PP907275F | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 07/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 01/2011-12/2023 | 433MHz | 4G | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2009-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 05/2004-05/2011 | 433MHz 4F0907275D | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 03/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 Allroad | 07/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 Allroad | 01/2013-06/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | A6 Avant | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 09/2010-12/2023 | 433MHz 5Q0907275 | 4G | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2009-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 03/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/1999-09/2002 | 433MHz | 4D | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2010-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2009-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 11/2009-10/2017 | 433MHz | 4H/4L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 10/2002-12/2012 | 433MHz | 4E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A9 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Allroad | 01/2000-12/2005 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | C-MPV | 03/2009-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q2 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q2 | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q3 | 07/2011-12/2023 | 433MHz | 8U | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q3 | 06/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q4 | 09/2019-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 01/2008-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q5 | 09/2008-12/2023 | 433MHz | 8R | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q6 | 06/2022-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 09/2005-12/2015 | 433MHz | 4L/AU716 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 01/2015-12/2023 | 433MHz MLB | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2018-12/2023 | 433MHz | 4M | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | R8 | 06/2009-12/2024 | 433MHz 7PP907275F | AU714 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 04/2015-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2006-12/2022 | 433MHz 4F0907275D | AU714 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS Q3 | 01/2018-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q8 | 12/2019-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2013-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS3 | 07/2016-12/2023 | 433MHz | 8V | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 06/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | RS4 | 01/2008-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS4 | 04/2006-12/2018 | 433MHz | 8E/B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 03/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 06/2020-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2015-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 06/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2017-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 01/2000-12/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS6 | 01/2019-12/2023 | 433MHz 5Q0907275 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2008-12/2010 | 433MHz | C6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 04/2000-09/2005 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6/RS6 Plus | 01/2020-03/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2010-06/2021 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS7 | 03/2018-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S1 | 01/2015-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S10 | 09/1999-10/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 01/2015-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S4 | 01/2003-12/2009 | 433MHz | B7 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S5 | 01/2018-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 06/2018-12/2023 | 433MHz 5Q0907275 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 07/2009-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 03/2020-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2004-06/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2000-12/2005 | 433MHz 4D0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S7 | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2017-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-10/2009 | 433MHz | D3 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 09/1999-09/2002 | 433MHz | D2 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 11/2009-10/2017 | 433MHz | D4 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Audi | S9 | 11/2009-10/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ2 | 01/2019-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ5 | 01/2014-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ5 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ7 | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ7 | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | SQ8 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 02/2014-12/2023 | 433MHz | AU334 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 03/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 04/2006-02/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT RS | 10/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 11/2016-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TTS | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TTS | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | e-tron | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | e-tron GT | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | e-tron GT | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Avatr | Avatr 11 | 08/2022-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Avatr | Avatr 12 | 11/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| BAIC BJEV | EC3 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC BJEV | EH Series | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC BJEV | EU Series | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC BJEV | EU260 | 11/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC BJEV | EU5 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC BJEV | EV300 | 04/2018-12/2018 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BAIC | ● | ● |
| BAIC BJEV | EX3 | 06/2018-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BAIC BJEV | EX5 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC HUANSU | H3 | 09/2015-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC HUANSU | H3F | 09/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC HUANSU | S3L | 09/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC HUANSU | S5 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC HUANSU | S6 | 11/2015-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BAIC | ● | ● |
| BAIC HUANSU | S7 | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | BJ40 | 01/2017-12/2022 | 433MHz TP3040002 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ40 | 01/2018-12/2024 | 433MHz B00019849 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | BJ40 | 01/2020-12/2024 | 433MHz B00011299 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ40 Plus | 01/2018-12/2021 | 433MHz B00011299 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ40 Plus | 01/2020-12/2021 | 433MHz B00019849 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | BJ40L | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ40L | 01/2016-12/2020 | 433MHz TP3040002 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|--------------|-----------------|--------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BAIC MOTOR | BJ40L Golden | 06/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ60 | 10/2020-12/2024 | 433MHZ | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | BJ80 | 01/2020-12/2024 | 433MHz B00019849 | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | BJ80 | 01/2018-12/2024 | 433MHz B00011299 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ80 | 01/2016-06/2018 | 433MHz TP3040002 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ80 | 01/2017-06/2019 | 433MHz 36380100B01000 | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | X6 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHZ | Baolong | ● | ● |
| BAIC SENOVA | CC | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | D50 | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | D70 | 01/2013-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X25 | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X35 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X55 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X65 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC WEIWANG | S50 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BESTUNE | B30 | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | B50 | 01/2016-12/2021 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | B50 | 01/2012-12/2016 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | B50 | 01/2011-12/2016 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | B50F | 01/2015-06/2018 | 433MHz | | ○ | ● | ○ | NA | 433MHz | FAW | ● | ● |
| BESTUNE | B50F | 01/2015-06/2018 | 433MHz FS43XOL5 | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| BESTUNE | B70 | 10/2017-12/2019 | 433MHz FS43XOL5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | B70 | 06/2014-10/2017 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | B70 | 01/2011-05/2014 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | B90 | 01/2012-12/2017 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | B90 | 01/2012-12/2017 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | B90 | 01/2012-12/2017 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | T33 | 08/2019-12/2023 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | T33 | 08/2019-12/2023 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | T77 | 01/2017-12/2024 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | T77 | 01/2018-12/2024 | 433MHz 5GA037973C | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BESTUNE | X40 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | X80 | 07/2016-12/2022 | 433MHz FS43XOL5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BESTUNE | X80 | 01/2013-06/2016 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | X80 | 01/2013-06/2016 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BMW | 1 Series | 03/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 1 Series | 09/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 1 Series | 01/2007-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 01/2014-12/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 2 Series | 03/2014-12/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 2 Series | 11/2012-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 11/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 09/2009-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/2005-08/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/1999-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 3 Series | 01/1998-12/2003 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2014-12/2022 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 10/2010-03/2014 | 433MHz | F30/F31/F34 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2019-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 4 Series | 07/2020-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 4 Series | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 07/2013-12/2021 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 4 Series | 01/2013-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 05/2003-12/2013 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/1999-12/2004 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 5 Series | 11/2016-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 07/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 08/1998-05/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 5 Series | 03/2014-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 04/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 01/2011-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 01/2004-12/2007 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | 6 Series | 08/2003-10/2012 | 433MHz | E63/E64 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 07/2017-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 01/2002-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 07/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 06/2015-12/2022 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 7 Series | 09/1998-12/2005 | 433MHz | E38 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/2006-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 03/2014-05/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 8 Series | 07/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M2 | 12/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M2 | 11/2014-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 11/2020-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M3 | 01/2014-12/2019 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M3 | 01/1999-12/2006 | 433MHz 36112360420 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 07/2021-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M4 | 10/2014-12/2017 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 03/2014-12/2021 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M5 | 01/1999-12/2003 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M5 | 01/2016-12/2022 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M5 | 03/2014-12/2017 | 433MHz 36106874830 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 09/2010-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/2003-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/2005-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M6 | 01/2005-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | M6 | 06/2011-12/2015 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 03/2014-12/2018 | 433MHz | F12 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M7 | 03/2014-12/2017 | 433MHz | F01 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M8 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Motorcycle | 01/2010-12/2019 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |
| BMW | X1 | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 09/2008-02/2014 | 433MHz | E84 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 03/2014-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 08/2015-12/2023 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X2 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X2 | 01/2016-12/2023 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 03/2003-07/2011 | 433MHz | E83 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 11/2010-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 04/2014-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 01/2003-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X3 | 01/2017-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | X4 | 01/2014-12/2018 | 433MHz 36106790054 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 05/2013-03/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 04/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 11/2006-09/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2015-07/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X5 | 10/2010-06/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2005-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X5 | 08/2018-03/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 01/2007-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X5 | 10/1999-09/2007 | 433MHz | E53 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 04/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 12/2007-09/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 10/2010-07/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 08/2014-07/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 | 08/2019-12/2023 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X6 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X7 | 12/2018-07/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X7 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | XM | 12/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 01/2003-12/2008 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | Z4 | 01/2006-02/2014 | 433MHz 36106790054 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 03/2014-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 11/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 10/2002-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i3 | 01/2013-06/2022 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i3 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i4 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i5 | 07/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i7 | 07/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i8 | 01/2013-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | iX | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX2 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX3 | 08/2017-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BORGWARD | BX5 | 01/2016-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| BORGWARD | BX7 | 01/2016-06/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| BORGWARD | BXi7 | 05/2018-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| BYD | ATTO 3 | 02/2022-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| BYD | ATTO 3 | 12/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | Destroyer 05 | 03/2022-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| BYD | Destroyer 05 | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Dolphin | 12/2022-12/2024 | 433MHz Right-hand drive | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Dolphin | 08/2021-12/2024 | 433MHz SC3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Dolphin | 08/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Dolphin | 08/2021-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | E2 | 09/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | E3 | 10/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | E5 | 04/2018-12/2022 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | E5 | 04/2017-04/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | E5 | 01/2016-03/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | E5 | 04/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | E6 | 10/2011-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | E6 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | E9 | 11/2022-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | E9 | 11/2022-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | E9 | 11/2022-12/2024 | 433MHz SC3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | E9 | 03/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | F3 | 01/2020-12/2022 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | F3 | 01/2020-12/2022 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | F3 | 09/2019-06/2021 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | FangChengBao Bao 5 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Frigate 07 | 09/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Frigate 07 | 09/2022-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | G5 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | G5 | 09/2014-12/2015 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | G6 | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | G6 | 09/2011-12/2017 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Han DM | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Han DM-i | 04/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Han DM-i | 04/2022-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Han DM-p | 05/2023-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Han DM-p | 05/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Han EV | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Han EV | 07/2020-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | Han EV | 04/2022-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Qin | 01/2014-10/2019 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin | 01/2014-10/2019 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Qin | 11/2019-12/2022 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin | 11/2019-12/2020 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Qin DM | 12/2013-01/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Qin DM | 02/2017-10/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin EV | 03/2016-04/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Qin EV | 03/2016-10/2019 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin EV | 11/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin L | 05/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| BYD | Qin L | 05/2024-12/2024 | 433MHz SC3609200 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BYD | Qin PLUS DM-i | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin PLUS DM-i | 01/2022-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | Qin PLUS EV | 04/2021-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Qin PLUS EV | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin PLUS EV | 04/2021-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | Qin Pro | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin Pro DM | 09/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Qin Pro EV | 09/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | S2 | 06/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | S7 | 10/2014-06/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | S7 | 10/2014-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Sea Lion 07 EV | 05/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Sea Lion 07 EV | 05/2024-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Seal | 07/2022-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Seal | 07/2022-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | Seal 06 DM-i | 05/2024-12/2024 | 433MHz SA3HE3609200 C | | ○ | ● | ○ | NA | 433MHz | YunLing | ● | ● |
| BYD | Seal 06 DM-i | 05/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Seal DM-i | 09/2023-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Seal DM-i | 09/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Sirui | 04/2013-12/2016 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Sirui | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song | 01/2016-12/2017 | 433MHz 6B3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song | 04/2017-12/2022 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song | 08/2018-12/2022 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song | 03/2020-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song | 10/2015-08/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song DM | 08/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song DM | 08/2018-12/2019 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song DM | 04/2017-08/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song EV | 01/2017-12/2019 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song EV | 01/2017-12/2019 | 433MHz 4WD | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song EV | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song EV | 04/2017-08/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Song EV | 01/2017-12/2019 | 433MHz 2WD | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song L | 12/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Song L | 12/2023-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song MAX | 09/2017-12/2021 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song MAX | 03/2019-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song MAX | 09/2017-12/2021 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song MAX DM | 03/2019-12/2022 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song MAX DM-i | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song MAX EV | 03/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song PLUS | 09/2020-12/2022 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song PLUS DM-i | 06/2023-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Song PLUS DM-i | 06/2023-12/2024 | 433MHz SA3HE3609200 C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Song PLUS DM-i | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song PLUS EV | 06/2023-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Song PLUS EV | 06/2023-12/2024 | 433MHz SA3HE3609200 C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Song PLUS EV | 03/2021-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song PLUS EV | 09/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro | 07/2019-02/2021 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro | 07/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro | 07/2019-12/2021 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | Song Pro DM | 07/2019-12/2020 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro DM | 07/2019-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song Pro DM | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro DM-i | 12/2019-12/2024 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song Pro DM-i | 07/2019-12/2024 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro DM-i | 05/2023-12/2024 | 433MHz SA3HE3609200 C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Song Pro DM-i | 05/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Song Pro DM-i | 12/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Song Pro EV | 07/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Song Pro EV | 07/2019-12/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Surui | 08/2012-12/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Surui | 03/2015-12/2016 | 433MHz 6B3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Surui | 03/2015-12/2016 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | T3 | 11/2020-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BYD | Tang | 02/2017-06/2019 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang | 02/2017-06/2019 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Tang | 01/2018-07/2020 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Tang | 08/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang | 08/2020-12/2022 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Tang | 01/2018-07/2020 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang DM | 06/2015-01/2017 | 433MHz 6B3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Tang DM | 02/2017-05/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang DM | 06/2018-12/2022 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang DM | 06/2018-12/2022 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Tang DM | 06/2015-01/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Tang DM-i | 01/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang DM-i | 06/2018-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | Tang DM-i | 03/2023-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | Tang DM-p | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang EV | 01/2017-12/2021 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang EV | 01/2018-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Tang EV | 06/2018-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | YangWang U8 | 09/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Yuan | 01/2017-12/2017 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan | 01/2016-12/2017 | 433MHz 6B3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Yuan | 04/2016-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Yuan EV | 09/2018-12/2019 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan EV | 05/2018-12/2020 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Yuan EV | 05/2018-12/2019 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan EV | 04/2016-05/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | Yuan Pro | 01/2021-12/2024 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Yuan Pro | 01/2021-12/2024 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | Yuan UP | 03/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Baojun | 530 | 01/2017-12/2024 | 433MHz 23576928 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Baojun | 530 | 01/2017-12/2024 | 433MHz 23548419 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Bentley | Arnage | 01/2008-09/2011 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2006-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2016-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands | 01/2008-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands Coupe | 01/2008-06/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 03/2014-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2019-12/2024 | 433MHz 5Q0907275B | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2005-03/2013 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2019-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2003-12/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------------|-------------------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Bentley | Continental Flying Spur | 03/2005-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 09/2003-05/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 01/2018-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 04/2018-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 06/2005-12/2023 | 433MHz BY634 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2018-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2006-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | E-CUV | 11/2014-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2019-12/2024 | 433MHz 5Q0907275 | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | GTC | 07/2006-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulliner | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2001-12/2020 | 433MHz 7PP907275F | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BlueSG | Car Share | 01/2011-12/2011 | 433MHz | | ○ | ● | ○ | NA | 433MHz | LDL Technology | ● | ● |
| BrillianceZhonghua | V3 | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BrillianceZhonghua | V5 | 01/2012-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| BrillianceZhonghua | V6 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Bugatti | Chiron | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Royale | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2005-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Vitesse | 01/2016-12/2016 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Buick | Nexia R3 | 11/2017-12/2020 | 433MHz | T-CAR | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Buick | Park Avenue | 01/1997-12/2005 | 433MHz | G-CAR | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| CMC | A180 | 01/2019-12/2023 | 433MHz T23030041 | | ● | ● | ○ | O | 433MHz | Oragne | ● | ● |
| CMC | A180 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| CMC | A190 | 01/2019-12/2023 | 433MHz T23030041 | | ● | ● | ○ | O | 433MHz | Oragne | ● | ● |
| CMC | A190 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| CMC | VERYCA | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| CMC | ZINGER | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2013-12/2013 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2014-12/2014 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2015 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-12/2020 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2012-12/2012 | 433MHz | A1SL/A1BL | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2020-12/2020 | 433MHz 13529770 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2015-12/2015 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|--------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | ATS-V | 01/2017-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | BLS | 01/2006-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S/A | 433MHz | BHSENS | ● | ● |
| Cadillac | CT4 | 01/2023-12/2023 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2022-12/2023 | 433MHz 13593957 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2023 | 433MHz 13530661 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2023-12/2024 | 433MHz 13549707 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | CT5 | 01/2023-12/2023 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2019-12/2023 | 433MHz 13530661 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2023-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2021-12/2022 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2015-12/2015 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2019 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2017-12/2019 | 433MHz | GMX322 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2008-12/2008 | 433MHz | GMX206/ GMX226 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2006-12/2007 | 433MHz | GMX322 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-06/2021 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2010-12/2013 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 06/2013-12/2013 | 433MHz | A1LL | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 06/2013-12/2013 | 433MHz | GMX322 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2016 | 433MHz | GMX322 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2016-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2017-06/2018 | 433MHz | D1BLI | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2016-12/2016 | 433MHz | D1BLI | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2014-12/2014 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2020-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|--------------------|-----------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | Escalade | 01/2021-12/2023 | 433MHz 13530661 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2020 | 433MHz | GMT900/ GMTK2XL/ K2UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2013-12/2013 | 433MHz | GMT900/ GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 12/2005-12/2006 | 433MHz | GMT926 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2008 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2009-12/2011 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2012-12/2012 | 433MHz | GMT900/ GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2024 | 433MHz 13538761 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2018-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2021-12/2024 | 433MHz 13538761 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Lyriq | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Cadillac | Lyriq | 06/2022-12/2023 | 433MHz 13530661 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Cadillac | Lyriq | 06/2022-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Cadillac | SRX | 01/2010-12/2012 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2013-12/2013 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2005-12/2006 | 433MHz | GMT265 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2016-12/2016 | 433MHz | C1UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2014-12/2016 | 433MHz | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2009-12/2009 | 433MHz | GMT265 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2007-12/2008 | 433MHz | GMT265 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 06/2008-12/2009 | 433MHz 25789964 | GMT166 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2011 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2009 | 433MHz 20925925 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2005-12/2007 | 433MHz | GMX295 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2008-09/2012 | 433MHz | GMX295 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XLR | 08/2003-02/2011 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2024-12/2024 | 433MHz 13538566 | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| Cadillac | XT4 | 01/2024-12/2024 | 433MHz 13549707 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | XT4 | 11/2018-12/2022 | 433MHz | E2UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2022-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2016-06/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Cadillac | XT5 | 01/2022-12/2024 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2020-12/2024 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2012-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| ChangAn | Alsvin | 08/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS15 | 01/2016-11/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS15 | 03/2019-06/2024 | 433MHz 3601010W10AB | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS35 | 01/2016-12/2023 | 433MHz FS43X1 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 | 01/2016-12/2023 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS35 | 01/2015-12/2015 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS35 | 01/2015-12/2015 | 433MHz FS43X1 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 PLUS | 03/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 PLUS | 01/2018-05/2019 | 433MHz Hi Confi | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS55 | 01/2017-12/2023 | 433MHz Lo Confi | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 | 01/2017-12/2023 | 433MHz Hi Confi | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 PLUS | 07/2021-12/2024 | 433MHz | The Second | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 PLUS | 09/2023-12/2024 | 433MHz | The Third | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 433MHz 2WD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 433MHz 2WD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 433MHz 4WD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 PLUS | 03/2022-12/2024 | 433MHz | The Second | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 PLUS | 06/2021-02/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 PLUS | 04/2023-12/2024 | 433MHz | The Third | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| ChangAn | CS75 PLUS | 09/2019-05/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS85 | 03/2019-11/2020 | 433MHz 3601010BS01A A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS85 | 03/2019-11/2020 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS85 | 09/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS85 | 12/2020-08/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS95 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS95 | 04/2021-01/2023 | 433MHz 3601010BS01A A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|-----------------------------------|--|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| ChangAn | CS95 | 04/2021-01/2023 | 433MHz 3601010MK01A A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS95 | 01/2019-03/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CX70 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | EADO | 01/2018-02/2020 | 433MHz Hi Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | EADO | 05/2019-12/2020 | 433MHz 3601010W10 Hi Conf i | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | EADO | 03/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | EADO EV460 | 03/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | EADO PLUS | 03/2020-04/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | Hunter | 01/2020-12/2023 | 433MHz | DEV-D20TCIE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Hunter | 01/2020-12/2023 | 433MHz Hi Conf i | DEV- D20TCIE/4D2 OM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Hunter | 01/2020-12/2023 | 433MHz Lo Conf i | DEV- D20TCIE/JE4 D25/4K22D4T /4D2OM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | LINMAX | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Lamore | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | Oshan | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Oshan X70A | 03/2018-12/2020 | 433MHz 3601010MK01 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Oshan X70A | 03/2018-12/2022 | 433MHz 3601010MK51 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Raeton | 01/2013-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Raeton | 01/2017-12/2019 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Raeton CC | 01/2017-07/2021 | 433MHz Lo Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Raeton CC | 01/2017-07/2021 | 433MHz Hi Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | UNI-K | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | UNI-T | 08/2021-01/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | UNI-V | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Chery | ARRIZO 5 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | ARRIZO 5 | 03/2017-12/2018 | 433MHz T113114011 | | ● | ● | ○ | 0 | 433MHz | Chery | ● | ● |
| Chery | ARRIZO 5 | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | ARRIZO 5 | 07/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 5 Plus | 12/2020-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 5 Plus | 12/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 5e | 01/2019-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 5e | 06/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 6 | 06/2019-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chery | ARRIZO GX | 09/2019-12/2023 | 433MHz 802000247AA | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chery | ARRIZO GX | 06/2019-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | ARRIZO GX | 10/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Arrizo | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | E3 | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Chery | ● | ● |
| Chery | E3 | 01/2013-12/2015 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | EQ1 | 10/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | EQ1 | 03/2017-09/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | EQ5 | 09/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown | ● | ● |
| Chery | Fulwin | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | OMODA 5 | 07/2022-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Chery | QQ | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | Tiggo | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | Tiggo 2 | 01/2017-12/2023 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 2 | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3 | 05/2016-12/2023 | 433MHz T113114011 | | ● | ● | ○ | 0 | 433MHz | Chery | ● | ● |
| Chery | Tiggo 3 | 01/2021-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3 | 07/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3 | 01/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3X | 11/2016-12/2020 | 433MHz 802000021AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3X | 11/2016-12/2022 | 433MHz J523114013 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3X | 12/2021-12/2023 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3X | 06/2020-06/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3xe | 01/2018-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 3xe | 07/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 4 | 06/2019-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 4 Pro | 01/2022-12/2023 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5 | 01/2013-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 5 | 07/2018-12/2022 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 5X | 12/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 5X | 06/2020-12/2024 | 433MHz 802000126AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5X | 10/2018-12/2020 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5X | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 5e | 01/2017-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5e | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------------|-----------------|------------------------|-------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chery | Tiggo 7 | 01/2018-06/2020 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 7 | 06/2016-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 | 12/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 7 | 07/2018-12/2022 | 433MHz 802000021AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 PLUS | 09/2021-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 7 PLUS | 09/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 PRO | 01/2020-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 | 01/2018-06/2018 | 433MHz 11652AWARDKS | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 | 04/2018-12/2023 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 | 01/2018-06/2021 | 433MHz 802000021AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 8 | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PLUS | 01/2020-06/2024 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 PLUS | 10/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 PLUS | 10/2020-06/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PLUS PHEV | 01/2022-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PLUS PHEV | 01/2022-12/2024 | 433MHz 802000126AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 PRO | 05/2022-06/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 Pro Max | 05/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 9 | 05/2023-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo e | 04/2020-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Wujie Pro | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Avalanche | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 06/2012-12/2012 | 433MHz | G1SC/ G1JC/ T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2011-05/2012 | 433MHz | G1SC/ G1JC/ T300 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2006-12/2010 | 433MHz | G1SC/ G1JC/ T300 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2015-06/2020 | 433MHz | G1SC/G1JC/T 250/T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2013-12/2014 | 433MHz | G1SC/G1JC/T 250/T300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------------|-----------------|--------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Blazer | 01/2022-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer EV | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2021-06/2024 | 433MHz 13516165 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2017-12/2020 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2023 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-06/2022 | 433MHz | 1AG37/ A1BC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 433MHz | 1AG37/ A1BC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2013-12/2013 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2012 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-12/2020 | 433MHz Snap in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 433MHz Snap in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2010-12/2011 | 433MHz | GMX521 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2019 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2020-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Captiva | 06/2006-12/2008 | 433MHz | C100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2012-12/2019 | 433MHz 25789964 | C100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2009-12/2011 | 433MHz | C100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2022-12/2023 | 433MHz 23576928 | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Cheyenne | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 07/2019-12/2023 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne Trailer | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2015-12/2019 | 433MHz | G1LC | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2012-12/2014 | 433MHz | G1LC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2023-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2017-12/2022 | 433MHz 13522629 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 07/2004-12/2012 | 433MHz | GMI700 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2013-12/2017 | 433MHz | GMI700 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado (LCV) | 01/2003-06/2006 | 433MHz | GMT355 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------------|-----------------|---------------------|---------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Colorado (LCV) | 07/2006-12/2012 | 433MHz | GMT355 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2022-12/2024 | 433MHz 13554170 | | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 02/2020-12/2022 | 433MHz | Y2XC | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2015-12/2019 | 433MHz | GMX245 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2019 | 433MHz | Y1BC | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 06/2000-12/2009 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2019-06/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-12/2018 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2013-12/2015 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2012-12/2012 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2011-12/2011 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 10/2008-12/2010 | 433MHz | DISC/ D1JC/ D1WC/ KL1J | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Epica | 01/2006-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2018-12/2023 | 433MHz MRXAG6SP4 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2022-12/2024 | 433MHz 13540606 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Escalade | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Escalade ESV Trailer | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Escalade Trailer | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2014-12/2024 | 433MHz | GMT610 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2013 | 433MHz | GMT610 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 07/2007-12/2008 | 433MHz | GMT610 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 07/2002-06/2007 | 433MHz | GMT610 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Groove | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Baolong | ● | ● |
| Chevrolet | Impala | 01/2020-12/2020 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2017-12/2019 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Lacetti | 06/2003-12/2014 | 433MHz Snap in | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Lacetti | 06/2003-12/2016 | 433MHz Clamp in | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------------|-----------------|--------------------|----------------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Malibu | 01/2022-12/2024 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 433MHz | V300/ GMX351/ GMX386 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2014-12/2015 | 433MHz | V300/ GMX351/ GMX386 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-06/2014 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 06/2010-06/2011 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2022 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 06/2014-12/2018 | 433MHz | M100 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 04/2005-06/2014 | 433MHz | M200 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 01/1998-03/2005 | 433MHz | M100 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Matiz | 01/2019-06/2021 | 433MHz | M100 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Nexia | 11/2017-12/2022 | 433MHz | T-CAR | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Niva | 01/2003-12/2022 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Onix | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Dias | ● | ● |
| Chevrolet | Onix | 01/2024-12/2024 | 433MHz | CANFD | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Orlando | 01/2017-06/2021 | 433MHz | J309 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2015-12/2016 | 433MHz | J309/D1NC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2013-12/2014 | 433MHz | J309 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2012-12/2012 | 433MHz | J309 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 09/2010-12/2011 | 433MHz | J309 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Sail | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | S | 433MHz | Baolong | ● | ● |
| Chevrolet | Silverado | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-12/2020 | 433MHz | K2XC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 07/2010-12/2014 | 433MHz | K2XC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 07/2019-12/2023 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado Trailer | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2013-12/2014 | 433MHz | M1JC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 07/2009-12/2012 | 433MHz | M1JC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2005-06/2009 | 433MHz | M200 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2016-12/2023 | 433MHz | M1JC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2015-12/2015 | 433MHz | M1JC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2023 | 433MHz 13516165 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Suburban | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2016-12/2018 | 433MHz | GMT931 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2015-12/2015 | 433MHz | GMT931 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2014-12/2014 | 433MHz | GMT931 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | 433MHz | GMT931 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2008 | 433MHz | GMT931 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2006-12/2006 | 433MHz | GMT931 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2018-12/2020 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2016-06/2020 | 433MHz | GMT921 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2015-12/2015 | 433MHz | GMT921 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2000-12/2014 | 433MHz | GMT921 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 07/2020-12/2020 | 433MHz | TIUC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2023 | 433MHz | TIUC | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz 26253785 | WMI:3GN | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2015-12/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2021-12/2022 | 433MHz 26253785 | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz | WMI:3GN | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz 22853740 | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz 26253785 | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2013-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2009-12/2012 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2006-12/2008 | 433MHz | GMT360 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2001-12/2005 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2020-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2017-12/2020 | 433MHz 13598773 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2010-12/2012 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2020-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2013-12/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2012-12/2012 | 433MHz | G1UC | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chevrolet | Trax | 01/2015-12/2023 | 433MHz | G1UC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2013-12/2014 | 433MHz | G1UC | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 06/2010-12/2012 | 433MHz | D1JCI | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2019-12/2019 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2017-12/2018 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2016-12/2018 | 433MHz | D1JCI | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 06/2015-08/2020 | 433MHz | D2JCI | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2013-12/2015 | 433MHz | D1JCI | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chrysler | 200 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2015-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2011-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2014-12/2017 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2011-12/2013 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2009-12/2010 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 06/2004-06/2011 | 433MHz | LE48 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2014-12/2017 | 433MHz | LE48 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2022-12/2023 | 433MHz BHSENS | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Chrysler | 300 | 01/2018-12/2021 | 433MHz | LE48 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2018-06/2021 | 433MHz 20 inch | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2018-06/2021 | 433MHz 18 inch | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 06/2009-12/2017 | 433MHz 18 inch | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 06/2005-05/2009 | 433MHz | LE48 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300C | 06/2009-12/2017 | 433MHz 20 inch | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Concorde | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 10/2003-01/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Delta | 01/2013-12/2017 | 433MHz | 844 | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Chrysler | Delta | 01/2008-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Chrysler | Grand Voyager | 01/2023-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2018-03/2020 | 433MHz | RT | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 01/2018-12/2019 | 433MHz | RU | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2016-12/2017 | 433MHz | RU | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Voyager | 01/2011-12/2017 | 433MHz | RT | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Intrepid | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Sebring | 06/2006-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2007-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chrysler | Town & Country | 01/2008-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2011-12/2013 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2014-12/2016 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Viper | 09/2012-12/2017 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Voyager | 01/2011-12/2017 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Chrysler | Voyager | 01/2018-12/2019 | 433MHz | RT | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Ypsilon | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | Ypsilon | 01/2018-06/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Chrysler | Ypsilon | 01/2008-03/2011 | 433MHz | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Chrysler | Ypsilon | 01/2011-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Chrysler | Ypsilon | 04/2011-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 01/2008-09/2013 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 10/2013-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 07/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C-Cactus | 07/2014-12/2016 | 433MHz | B71 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | C-Elysee | 09/2012-12/2021 | 433MHz | M3/M4 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | C-ZERO | 01/2010-06/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Citroen | C1 | 04/2005-03/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C1 | 06/2014-03/2022 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Pacific | ● | ● |
| Citroen | C3 | 09/2009-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C3 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | C3 | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 08/2008-07/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 09/2004-07/2008 | 433MHz | B5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C4 | 10/2014-10/2018 | 433MHz | B58 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 08/2010-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C4 Aircross | 04/2012-06/2018 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Citroen | C4 Cactus | 05/2014-04/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 Picasso | 05/2006-02/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 12/2000-07/2004 | 433MHz | X40 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 08/2004-08/2013 | 433MHz | X3/X40 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C5 | 09/2013-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | C5 Aircross | 09/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C6 | 01/2005-12/2013 | 433MHz | X6 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C8 | 01/2002-09/2005 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C8 | 10/2005-12/2015 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | DS3 | 01/2009-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS3 | 01/2015-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS4 | 12/2010-01/2014 | 433MHz | B75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 02/2014-07/2020 | 433MHz | B81 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | DS4 Crossback | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 02/2014-11/2018 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 06/2011-01/2014 | 433MHz | B81 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS6 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Citroen | DS7 | 01/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS7 | 03/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Dispatch | 10/2006-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Dispatch | 06/2014-04/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Dispatch | 05/2016-06/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | E-Mehari | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Jumper | 10/2022-12/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Citroen | Jumper | 02/2006-11/2013 | 433MHz | B9 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper | 12/2013-09/2022 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Jumper | 05/2006-04/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumper | 02/2006-11/2013 | 433MHz 1612474480 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper Combi | 06/2014-08/2022 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Jumper Combi | 02/2006-05/2014 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper Combi | 09/2022-12/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Citroen | Jumpy | 06/2014-04/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumpy | 05/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy | 10/2006-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumpy Combi | 09/2006-06/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumpy Combi | 10/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy Combi | 07/2014-09/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 01/2016-08/2018 | 433MHz | B53/B7 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 11/2007-12/2015 | 433MHz | B53/B7 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Nemo Multispace | 01/2016-07/2018 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Citroen | Nemo Multispace | 10/2007-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Relay | 10/2022-12/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Citroen | Relay | 02/2006-11/2013 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Relay | 12/2013-09/2022 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Citroen | Relay | 05/2006-05/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Space Tourer | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Cowin | E5 | 03/2023-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Cowin | X7 | 06/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DENZA | D9 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DENZA | D9 | 08/2023-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| DENZA | DENZA X | 11/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DENZA | N7 | 07/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| DENZA | N7 | 07/2023-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DENZA | N8 | 08/2023-12/2024 | 433MHz SA3HE3609200 B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| DENZA | N8 | 08/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFPV | A30 | 01/2017-12/2017 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DFPV | A9 | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DFPV | AX3 | 11/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| DFPV | AX4 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFPV | AX5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFPV | AX7 | 01/2017-12/2024 | 433MHz E340020JD0201 | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| DFPV | AX7 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| DFPV | E70 | 01/2022-12/2024 | 433MHz E300019160 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| DFPV | E70 | 10/2017-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| DFPV | Hao Ji | 01/2022-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| DFSK | C32 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | C35 | 01/2018-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DFSK | EC31 | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DFSK | EC35 | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DFSK | Fengguang 330/Glory 330 | 01/2019-12/2024 | 433MHz 3641050FA01 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengguang 330/Glory 330 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengguang 500/Glory 500 | 10/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengguang 500/Glory 500 | 01/2021-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengguang 560/Glory 560 | 06/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2016-06/2018 | 433MHz 3641050SA01 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2017-12/2019 | 433MHz 3641050SA04 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Lan dian E3 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Lan dian E5 | 03/2023-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Lan dian E5 | 03/2023-06/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DR Auto | DR 3 Coupe | 01/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DR Auto | DR 3 Coupe | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Chery | ● | ● |
| DR Auto | DR 4 | 01/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DR Auto | DR 5 | 01/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DR Auto | DR 5 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Chery | ● | ● |
| DR Auto | DR 6 | 01/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DR Auto | DR 6 | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Chery | ● | ● |
| DR Auto | DR EVO | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DR Auto | DR F35 | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Chery | ● | ● |
| Dacia | Dokker | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Dokker | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Dacia | Dokker | 01/2012-12/2021 | 433MHz 407001628R | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dacia | Duster | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dacia | Duster | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Duster | 01/2010-06/2021 | 433MHz 407001628R | H79 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dacia | Kwid | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Dacia | Lodgy | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Lodgy | 01/2012-12/2022 | 433MHz 407001628R | J92 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Logan | 02/2010-12/2021 | 433MHz 407001628R | L52/K52 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Logan | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Oroch Pickup | 01/2016-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Dacia | Oroch Pickup | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Sandero | 01/2014-12/2021 | 433MHz 407005642R | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Dacia | Sandero | 06/2014-12/2021 | 433MHz 407001628R | B52 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dacia | Sandero | 01/2016-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Dacia | Sandero II | 01/2022-06/2024 | 433MHz 407004CB0B | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Dacia | Spring | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Dacia | Stepway II | 01/2013-12/2018 | 433MHz 407001628R | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Daewoo | Genra | 04/2004-12/2020 | 433MHz | J200 | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Daewoo | Matiz Kasten | 09/1998-06/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Daewoo | Nexia | 11/1995-12/2016 | 433MHz | T-CAR | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Dodge | Avenger | 01/2014-12/2014 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Avenger | 01/2006-12/2013 | 433MHz | JS41D | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 01/2006-12/2012 | 433MHz | PM49 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Caravan | 06/2011-12/2017 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Caravan | 01/2010-12/2010 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Dodge | Challenger | 01/2011-12/2013 | 433MHz | LC22 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2008-12/2010 | 433MHz | LC22 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2018-12/2018 | 433MHz | LC22 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2014-12/2017 | 433MHz | LC22 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2019-12/2022 | 433MHz | LC22 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Dodge | Challenger SRT | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Dodge | Challenger SRT | 01/2018-12/2021 | 433MHz | LD | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2015-12/2017 | 433MHz | LD | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2022-12/2023 | 433MHz BHSENS | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Dodge | Charger | 08/2017-12/2017 | 433MHz | LX48D/LD | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2009-12/2009 | 433MHz | LX48D/LD | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2018-12/2022 | 433MHz | LX48D/LD | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2011-12/2013 | 433MHz | LX48D/LD | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2014-09/2014 | 433MHz | LX48D/LD | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 10/2014-07/2017 | 433MHz | LX48D/LD | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2010-12/2010 | 433MHz | LX48D/LD | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2022-12/2023 | 433MHz BHSENS | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Dodge | Charger SRT | 01/2015-12/2015 | 433MHz | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Dodge | Charger SRT | 01/2011-12/2014 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2012-12/2015 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2009-12/2011 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Dart | 10/2012-12/2019 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 01/2010-12/2017 | 433MHz Continental | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 01/2011-12/2013 | 433MHz | WD75 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2014-12/2017 | 433MHz | WD75 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2018-12/2022 | 433MHz | WD75 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Durango SRT | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2008-12/2010 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Intrepid | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2018-12/2021 | 433MHz | JC49 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2011-12/2017 | 433MHz | JC49 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2008-12/2011 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Nitro | 06/2006-04/2013 | 433MHz | KA | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1200 | 01/2016-12/2019 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dodge | Ram 1200 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dodge | Ram 1500 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 01/2019-12/2024 | 433MHz DT | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2018-12/2019 | 433MHz | DS | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 01/2010-12/2013 | 433MHz | D2 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2009-12/2009 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 10/2013-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 2500 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram ProMaster | 01/2022-12/2024 | 433MHz Continental | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Ram Series | 01/2006-12/2009 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Ram Series | 01/2014-12/2017 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 01/2018-12/2021 | 433MHz | DS/DJ | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 01/2020-12/2023 | 433MHz | DX | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Series | 01/2010-12/2013 | 433MHz | DS/DJ | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | SRT Viper | 01/2010-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Viper | 01/2013-12/2016 | 433MHz | ZD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Viper | 01/2003-12/2011 | 433MHz | ZB | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| EVOLUTE | i-JET | 04/2021-06/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| EVOLUTE | i-JET | 01/2020-12/2022 | 433MHz 3641050RA01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| EVOLUTE | i-JOY | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EVOLUTE | i-JOY | 01/2019-12/2023 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| EVOLUTE | i-PRO | 01/2022-12/2024 | 433MHz E300019160 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| EVOLUTE | i-PRO | 10/2017-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| EVOLUTE | i-SKY | 03/2023-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| EVOLUTE | i-SPACE | 03/2023-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EVOLUTE | i-SPACE | 03/2023-06/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| EVOLUTE | i-VAN | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EXEED | LX | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| EXEED | LX | 08/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| EXEED | RX | 02/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| EXEED | TX | 04/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EXEED | TXL | 07/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EXEED | VX | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAWDAIHATSU | SENIA R7 | 01/2016-06/2019 | 433MHz Lo Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAWDAIHATSU | SENIA R7 | 01/2016-06/2019 | 433MHz Hi Conf i | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAWDAIHATSU | SENIA R8 | 01/2020-12/2021 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAWDAIHATSU | SENIA R9 | 01/2016-06/2019 | 433MHz Hi Conf i | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| FAWDAIHATSU | SENIA R9 | 01/2018-12/2019 | 433MHz Lo Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fawmc | V80 | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Fengon | 330 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | 370 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | 560 | 06/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | 580 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fengon | 580 | 01/2017-12/2019 | 433MHz 3641050SA04 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | 580 | 01/2016-06/2018 | 433MHz 3641050SA01 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | E3 | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fengon | E3 | 01/2019-12/2023 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | S560 | 01/2017-06/2019 | 433MHz 3641050SA01 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | S560 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fengon | S560 | 01/2018-06/2021 | 433MHz 3641050SA04 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | ix5 | 01/2018-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | ix7 | 11/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Ferrari | 296GTB | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|------------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ferrari | 458 Italia | 01/2014-12/2015 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 09/2007-12/2013 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Speciale | 01/2013-12/2016 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Spider | 01/2009-12/2020 | 433MHz | F142 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 488 | 01/2015-12/2021 | 433MHz | F142 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/1997-12/2001 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/2002-12/2006 | 433MHz | F133e | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 01/2004-12/2014 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTO | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 612 Scaglietti | 01/2004-12/2011 | 433MHz | F137 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | CTC4 Lusso T | 01/2017-12/2019 | 433MHz F11001495001 | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Ferrari | CTC4 Lusso T | 01/2017-12/2019 | 433MHz F11001648001 | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 01/2011-12/2011 | 433MHz 224549 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 10/2008-12/2017 | 433MHz | F149 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Daytona SP3 | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 01/2002-12/2006 | 433MHz | F140 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 01/2015-12/2020 | 433MHz | F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 01/2012-12/2022 | 433MHz | F151/ F152 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 01/2015-12/2021 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 07/2007-10/2009 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 09/2004-06/2007 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2007-12/2009 | 433MHz | F131EVO | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 Scuderia | 07/2007-04/2013 | 433MHz | F131E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F550/575 | 01/1996-11/2009 | 433MHz | F133 | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F588 Dino | 01/2019-12/2022 | 433MHz Huf/Beru | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 01/2019-12/2023 | 433MHz 282189 | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-01/2020 | 433MHz | F151 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FXX | 01/2005-12/2006 | 433MHz | F140 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 01/2013-12/2020 | 433MHz | F150 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Monza SP1/SP2 | 01/2019-12/2021 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 10/2017-12/2023 | 433MHz F11001648001 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Roma | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Roma | 01/2020-12/2023 | 433MHz 314818 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | SF90 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Fiat | 124 Spider | 01/2017-12/2021 | 433MHz | NF/J12F | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Fiat | 124 Spider | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Fiat | 124 Spider | 08/2015-12/2016 | 433MHz | NF/J12F | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | 500 | 01/2007-12/2013 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500 | 01/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2014-12/2022 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500C | 01/2013-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500C | 01/2014-06/2019 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 01/2007-12/2013 | 433MHz | 312 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 01/2018-12/2022 | 433MHz | 330 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 01/2012-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500L | 01/2007-12/2017 | 433MHz | 330 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | 500X | 01/2020-12/2024 | 433MHz | 334 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Fiat | 500X | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500X | 01/2015-12/2019 | 433MHz | 334 | ● | ● | ● | O | 433MHz | Continental | ● | ● |
| Fiat | Albea | 10/2013-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Bravo | 01/2013-12/2014 | 433MHz Clamp in | 198 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Bravo | 01/2013-12/2014 | 433MHz Snap in | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Bravo | 01/2007-10/2016 | 433MHz | 198 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Croma | 01/2005-06/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Doblo | 01/2020-12/2022 | 433MHz | X2/50 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Doblo | 01/2010-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Doblo | 01/2009-12/2021 | 433MHz | 223/263 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Ducato | 06/2014-06/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Ducato | 01/2006-05/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Egea | 01/2015-12/2023 | 433MHz Snap in | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Egea | 01/2015-12/2023 | 433MHz Clamp in | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Fiorino | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Fiorino | 01/2014-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Fiorino | 10/2007-12/2014 | 433MHz | 225 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Freemont | 07/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Freemont | 01/2011-06/2014 | 433MHz | JF | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Fullback | 01/2016-12/2021 | 433MHz | 4P00/ KTOT | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Fiat | Grande Punto | 01/2006-05/2014 | 433MHz 53104671 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Fiat | Grande Punto | 01/2012-12/2015 | 433MHz | 199 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Idea | 01/2003-12/2012 | 433MHz | 350 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Fiat | Linea | 01/2007-12/2018 | 433MHz | 200 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Fiat | Palio | 01/2007-12/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Palio | 01/2011-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Panda | 01/2012-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Panda | 11/2011-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Punto | 01/2005-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Punto | 09/2005-12/2018 | 433MHz | 199 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|--------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Fiat | Punto Evo | 01/2009-12/2012 | 433MHz | 199 | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Fiat | Punto Evo | 01/2009-12/2012 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Qubo | 01/2007-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | Qubo | 01/2007-12/2021 | 433MHz | 225 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Scudo | 11/2013-06/2019 | 433MHz | 3H/G9 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Scudo | 01/2016-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Scudo | 01/2006-10/2013 | 433MHz | G9 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Sedici | 01/2014-12/2016 | 433MHz | YY2 | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | Strada | 01/2012-09/2021 | 433MHz | 178/326 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Talento | 01/2016-12/2022 | 433MHz | FJL/X82 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Tipo | 01/2015-12/2022 | 433MHz Snap in | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | Tipo | 01/2015-12/2022 | 433MHz Clamp in | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Fiat | Tipo | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Fiat | Toro Pickup | 01/2016-12/2022 | 433MHz | 334 | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | Ulysse | 10/2005-06/2011 | 433MHz | UL0102/179/V1 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Fiat | Ulysse | 01/2002-09/2005 | 433MHz | FL166/179/V1 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Fisker | Karma | 01/2011-01/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Lear | ● | ● |
| Ford | B-MAX | 05/2012-12/2019 | 433MHz | B232 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | B-MAX | 05/2012-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Bronco | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 10/2020-12/2023 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 10/2020-12/2023 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 01/2024-12/2024 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2014-12/2016 | 315MHz | C344N | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2012-12/2012 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 08/2010-12/2020 | 433MHz | C344 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | C-Max | 08/2010-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | C-Max | 01/2017-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2014-12/2019 | 433MHz | CB7/CEU/C344 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2013-12/2013 | 315MHz | C344N | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | E-Series | 01/2006-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 01/2013-06/2019 | 433MHz EV6T1A180CB | CBW | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 06/2013-09/2014 | 433MHz | B515 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 10/2014-12/2017 | 433MHz | B515 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 11/2017-12/2023 | 433MHz | CR6 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2016-12/2019 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2015-12/2015 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 06/2014-12/2014 | 433MHz | CD389/CD539 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|-------------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Edge | 01/2013-12/2014 | 315MHz | U387 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2012-12/2012 | 315MHz | U387 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2011-12/2011 | 315MHz | U387 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2007-12/2010 | 315MHz no Chrome rims | U387 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Edge | 01/2007-12/2014 | 433MHz | U387 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2007-12/2007 | 315MHz with Chrome rims | U387 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Edge | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2023-12/2023 | 433MHz | CD389/CD539 | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2021-12/2022 | 433MHz | CD389/CD539 | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2020-12/2020 | 433MHz | CD389/CD539 | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Escape | 05/2012-12/2014 | 433MHz | C520 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2014-12/2019 | 433MHz | C520 (2) | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2015-12/2018 | 433MHz | C520 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Everest | 01/2006-05/2009 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Everest | 06/2009-05/2015 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 06/2015-12/2017 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 06/2016-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Everest | 01/2018-12/2019 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Everest | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2022-12/2023 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2017 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2011-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2007-12/2008 | 433MHz | U222 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 06/2003-12/2006 | 433MHz | U222 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 09/2015-12/2017 | 433MHz | U502 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2013-09/2015 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2012-12/2012 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 09/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-08/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2009-06/2015 | 433MHz | U502 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2011-12/2011 | 315MHz | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-03/2019 | 315MHz BB5T1A180DA | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 10/2015-12/2017 | 315MHz BB5T1A180DA | U502 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 10/2015-12/2017 | 315MHz | U502 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2021-12/2022 | 433MHz | P702 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2021-12/2024 | 433MHz | P552 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-05/2020 | 433MHz | P552 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2018 | 433MHz | P415 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2011-12/2014 | 433MHz | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | F-150 | 09/2008-12/2010 | 433MHz | P415 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 06/2020-12/2020 | 433MHz | P552 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series | 09/2008-12/2009 | 433MHz | P415 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2010-12/2020 | 433MHz | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2017-06/2023 | 433MHz | CE1 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Fiesta | 05/2014-06/2019 | 433MHz | CCN | ● | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Flex | 01/2012-12/2012 | 315MHz | D471 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 02/2012-12/2012 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Flex | 01/2016-12/2019 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2016-12/2019 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Flex | 01/2020-12/2021 | 315MHz | D471 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2013-12/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Flex | 01/2009-12/2010 | 315MHz | D471 | ● | ● | ● | O/S | 315MHz | Lear | ● | ● |
| Ford | Flex | 01/2011-12/2011 | 315MHz | D471 | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2011-12/2013 | 433MHz EV6T1A180DB | CEW/CB8 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 12/2010-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Focus | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 01/2014-06/2019 | 433MHz EV6T1A180DB | CEW/CB8 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 05/2018-12/2019 | 433MHz | CGE | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Focus C-Max | 01/2014-06/2016 | 433MHz | CB7 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Focus IV | 09/2018-05/2019 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus IV | 06/2019-12/2022 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus RS | 06/2015-12/2018 | 433MHz | P3T/600A | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus ST | 05/2014-02/2018 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus ST | 03/2018-12/2023 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Focus (LCV) | 12/2010-12/2018 | 433MHz | C346 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | GT | 08/2017-12/2023 | 433MHz | CGX | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Galaxy | 01/2006-04/2015 | 433MHz | CD340 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | Galaxy | 05/2015-12/2020 | 315MHz | | ● | ● | ○ | O/S/A | 315MHz | Schrader | ● | ● |
| Ford | Galaxy | 05/2015-12/2020 | 433MHz | CD390 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Galaxy | 01/2021-12/2021 | 315MHz | | ● | ● | ○ | O/S/A | 315MHz | Schrader | ● | ● |
| Ford | Galaxy | 01/2021-12/2021 | 433MHz | CD390 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Galaxy | 01/2022-12/2023 | 433MHz | CD390 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Galaxy | 01/2022-12/2023 | 315MHz | | ● | ● | ○ | O/S/A | 315MHz | Schrader | ● | ● |
| Ford | Grand C-MAX | 01/2014-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | KA | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Ford | KA | 01/2008-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ford | KA III | 01/2016-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | KA+ | 01/2016-06/2021 | 433MHz | KAF | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Ford | Kuga | 11/2012-12/2013 | 433MHz | C520 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2014-12/2019 | 433MHz | C520 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Mondeo | 06/2019-12/2023 | 433MHz JX7T1A180CA | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 06/2019-12/2022 | 433MHz F2GZ1A189B | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 01/2007-12/2012 | 433MHz Clamp in | CD345 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Ford | Mondeo | 09/2017-05/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 10/2014-12/2017 | 433MHz Snap in | CD391 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mondeo | 01/2013-06/2015 | 433MHz Clamp in | CD345 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | Mustang | 01/2007-12/2009 | 433MHz | S197 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 09/2004-12/2006 | 433MHz | S197 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2010-12/2014 | 433MHz | S197 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2020-12/2023 | 433MHz | S550 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2015-12/2019 | 433MHz | S550 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2015-12/2015 | 433MHz | S197 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | PUMA | 11/2019-12/2024 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2015-12/2018 | 433MHz Hi Line | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 09/2015-12/2017 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2015-12/2015 | 433MHz Lo Line | P375 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2016-12/2018 | 433MHz Lo Line | P375 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2018-12/2018 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2019-12/2021 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2019-12/2023 | 433MHz Hi Line | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2019-12/2023 | 433MHz Lo Line | P375 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2024-12/2024 | 433MHz Hi Line | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2024-12/2024 | 433MHz Lo Line | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2022-12/2023 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 05/2014-12/2014 | 433MHz | P375 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 05/2015-12/2018 | 315MHz | | ● | ● | ○ | O/S/A | 315MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2021-12/2021 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2022-12/2023 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2006-04/2015 | 433MHz | CD340 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Ford | S-Max | 06/2019-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2019-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | S-Max | 01/2019-05/2019 | 433MHz | CD539/CD389 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | S-Max | 05/2015-12/2018 | 433MHz | CD539/CD389 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Taurus | 04/2007-04/2010 | 315MHz Banded | | ● | ● | ● | O/S | 315MHz | Lear | ● | ● |
| Ford | Taurus | 05/2010-12/2010 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2011-12/2011 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2012-10/2012 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2012-12/2012 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2012-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2015-12/2019 | 433MHz BB5Z1A189A | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2017-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2016-12/2016 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2015-12/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2013-10/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2019-12/2021 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Ford | Territory | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Ford | Tourneo Connect | 01/2013-05/2018 | 433MHz DR3V1A180DA | V408 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Connect | 05/2018-12/2023 | 433MHz F2GZ1A189B | V408 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Connect | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Courier | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Courier | 01/2014-12/2023 | 433MHz | B460 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Custom | 06/2019-12/2024 | 433MHz | TTF | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Tourneo Custom | 09/2013-05/2019 | 433MHz | V362 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2019-12/2019 | 433MHz | V363 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2015-12/2018 | 433MHz | V363 | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 06/2013-12/2014 | 433MHz | V363 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 06/2019-12/2024 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Ford | Transit Chassis | 06/2013-05/2019 | 433MHz | V363 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Combi | 01/2013-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Combi | 01/2019-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2013 | 433MHz EV6T1A180CB | V363 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2016-05/2018 | 433MHz EV6T1A180CB | V363 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2019-12/2023 | 433MHz F2GZ1A189B | V408 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 05/2018-12/2018 | 433MHz F2GZ1A189B | V408 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2018 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Transit Connect | 01/2014-12/2015 | 433MHz EV6T1A180CB | V363 | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2014-12/2023 | 433MHz EV6T1A180CB | B460 | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Transit Courier | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Transit Custom | 06/2019-12/2024 | 433MHz | TTS | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit Custom | 09/2013-05/2019 | 433MHz | V363 | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ford | Transit LCV | 01/2013-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Vignale Mondeo | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Vignale S-Max | 01/2015-12/2020 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Forthing | CM7 | 01/2014-12/2016 | 433MHz B123685020 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Forthing | CM7 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | F600 | 01/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Friday | 03/2023-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Forthing | Joyear S50 | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Joyear X5 | 06/2017-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | Joyear X5 | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Joyear X5 | 01/2014-06/2019 | 433MHz B123685020 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Forthing | M6 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | M6 | 01/2018-12/2020 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | M7 | 01/2018-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | M7 | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | S50 EV | 01/2018-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | S50 EV | 01/2018-12/2023 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | S500 | 11/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | SX6 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | SX6 | 01/2018-12/2019 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | T5 | 01/2018-12/2019 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | T5 | 01/2018-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | T5 EVO | 03/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | U-Tour V9 | 09/2023-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Forthing | X6 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | yacht/V-Tour | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Forthing | yacht/V-Tour | 01/2022-12/2023 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Foton | Sauvana | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| Foton | Toano | 03/2022-06/2024 | 433MHz V13110000059 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| Foton | Toano | 01/2017-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Foton | Toano | 01/2017-06/2024 | 433MHz 6 Wheel | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Foton | Tunland | 01/2011-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | TTE | ● | ● |
| GMC | Acadia | 11/2016-08/2018 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 09/2018-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2022-12/2024 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2006-12/2009 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------------|-----------------|--------------------|----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GMC | Savana | 01/2002-06/2007 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2009-12/2012 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2017-12/2024 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 07/2007-12/2008 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2024 | 433MHz 13542523 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2021-12/2023 | 433MHz 13530661 | | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2015-12/2022 | 433MHz | K2XG2 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 07/2009-12/2013 | 433MHz | GMT902 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2024 | 433MHz 13538761 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2016 | 433MHz | GMT902 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2014 | 433MHz | K2XG2 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2024 | 433MHz 13545366 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2013-12/2013 | 433MHz | K2XG2 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 06/2006-06/2009 | 433MHz | GMT902 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2017-12/2017 | 433MHz | GMT902 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2018-12/2023 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 07/2019-12/2023 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra Trailer | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2015-12/2016 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2018-12/2021 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2012-12/2014 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2022-12/2024 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2014-12/2014 | 433MHz | K2UG/ GMT922 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2005-12/2006 | 433MHz | GMT922 (2) | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2007-12/2008 | 433MHz | GMT922 (2) | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2021-12/2023 | 433MHz 13542523 | | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2020-12/2021 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2009-12/2013 | 433MHz | GMT922 (2) | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon All | 01/2015-12/2019 | 433MHz | K2UG (2) / GMT922 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Geely | Atlas | 01/2015-12/2023 | 433MHz QY1031 | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Geely | Atlas | 09/2019-12/2020 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas | 01/2022-12/2023 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas L | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Geely | Atlas L | 05/2023-12/2024 | 433MHz 6608064280 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| Geely | Atlas Pro | 09/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Atlas Pro | 09/2019-12/2023 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas X | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | Azkarra | 01/2020-12/2023 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Azkarra | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Binray | 01/2018-03/2019 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Binray | 01/2018-12/2023 | 433MHz 01741388 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | Binray | 04/2019-12/2022 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Binyue | 07/2018-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Binyue | 01/2020-12/2024 | 433MHz 6600129664 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Binyue | 01/2019-12/2024 | 433MHz 01741388 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | Binyue MHEV | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Binyue MHEV | 01/2019-12/2019 | 433MHz 01734809 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Binyue Pro | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Binyue Pro | 01/2020-12/2022 | 433MHz 01734809 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Borui | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Borui | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | Borui GE | 07/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | Borui GE | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | Coolray | 09/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EC7 | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2012-12/2020 | 433MHz 06703309 | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | EC7 | 01/2009-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC8 | 01/2010-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Whetron | ● | ● |
| Geely | EMGRAND | 01/2017-05/2019 | 433MHz 01734809 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND | 01/2017-05/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND | 06/2019-12/2020 | 433MHz 01741388 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | EMGRAND | 01/2023-12/2024 | 433MHz 6600273895 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | EMGRAND | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND EV | 01/2015-06/2019 | 433MHz 06703309 | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | EMGRAND EV | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Geely | EMGRAND EV Pro | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND EV Pro | 01/2021-12/2021 | 433MHz 01734809 | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND EV450 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND EV500 | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND GL | 09/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GL | 01/2017-06/2019 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GL | 01/2021-12/2021 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 07/2019-12/2020 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GS | 06/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 01/2016-12/2023 | 433MHz 1067030201 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 01/2015-05/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GT | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND HEV | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | EMGRAND PHEV | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | TTE | ● | ● |
| Geely | EMGRAND PHEV | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EMGRAND RS | 08/2010-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | EMGRAND S | 01/2021-12/2024 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND X7 | 01/2013-12/2023 | 433MHz 6703202 | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EMGRAND X7 | 01/2013-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | EMGRAND X7 Sport | 01/2022-12/2023 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND X7 Sport | 09/2019-12/2020 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND X7 Sport | 01/2019-12/2023 | 433MHz QY1031 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | Englon King Kong | 01/2006-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | GC 6 | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | GE11 A | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GE11 C | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GE11 EX3 | 11/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | GE11 G6 | 10/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GSE | 01/2018-12/2019 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | GX7 | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | GX7 | 01/2014-12/2015 | 433MHz 6703202 | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | GX9 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | ICON | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Monjaro | 01/2022-12/2023 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Geely | Monjaro | 01/2022-12/2023 | 433MHz 01732445 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Geely | New Coolray | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|-------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Geely | SC6 | 01/2014-12/2017 | 433MHz 06703309 | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | SX7 | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | SX7 | 01/2013-12/2014 | 433MHz 06703309 | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | Tugella | 01/2019-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Tugella | 07/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Tugella L | 01/2021-12/2024 | 433MHz 01732445 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Geely | Tugella L | 01/2021-12/2024 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Geely | Tugella S | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | VF11 | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | VF11 | 01/2019-12/2023 | 433MHz G5 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | VX11 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | VX11 | 01/2020-12/2023 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | VX11 | 01/2020-12/2023 | 433MHz 6600129664 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | VX11 L | 12/2022-12/2024 | 433MHz 6608064280 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | Vision | 07/2019-12/2020 | 433MHz New | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision | 01/2018-06/2019 | 433MHz New | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision S1 | 01/2017-12/2019 | 433MHz 01734809 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision S1 | 06/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | Vision X3 | 01/2017-11/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | Vision X3 | 06/2019-12/2023 | 433MHz G6 MT | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X3 | 06/2019-12/2023 | 433MHz G6 CVT | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | Vision X3 | 12/2017-12/2023 | 433MHz G5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X6 | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | Vision X6 | 01/2020-12/2020 | 433MHz CVT | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X6 | 01/2016-12/2020 | 433MHz QY1031A0- 190930 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X6 AT | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X6 Pro | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | X7 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | M2 | 04/2014-12/2017 | 433MHz 3641110K80 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| GreatWall | M4 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| GreatWall | M4 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641100AKR02 A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Funky Cat | 11/2020-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | ORA Funky Cat | 11/2020-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Funky Cat | 11/2020-12/2024 | 433MHz 3641100AKR02 A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| GreatWall | ORA Funky Cat | 11/2020-12/2024 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Good Cat | 11/2020-12/2024 | 433MHz 3641100AKR02 A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| GreatWall | ORA Good Cat | 11/2020-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | ORA Good Cat | 11/2020-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Good Cat | 11/2020-12/2024 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Grand Cat | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| GreatWall | POER | 09/2019-12/2022 | 433MHz Snap in | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER | 09/2019-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER | 06/2021-12/2024 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | POER EV | 09/2020-12/2023 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER EV | 09/2020-12/2023 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Steed | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Steed | 06/2014-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | TanKe 300 | 01/2023-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | TanKe 300 | 08/2023-12/2024 | 433MHz 3641100XKV3A A | | ● | ● | ○ | 0/A | 433MHZ | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GreatWall | TanKe 300 | 01/2023-12/2024 | 433MHz 3641101AKN01 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | TanKe 300 | 12/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | TanKe 400 Hi4-T | 09/2023-12/2024 | 433MHz Clamp in | | ● | ● | ○ | 0/A | 433MHz | Dias | ● | ● |
| GreatWall | TanKe 500 | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| GreatWall | Tracker | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Tracker | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C20 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| GreatWall | Voleex C20R | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C20R | 09/2011-12/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2014-12/2015 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C30 | 01/2014-12/2017 | 433MHz 3641110AK80X A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 EV | 01/2018-12/2020 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C30 EV | 01/2018-12/2020 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C50 | 01/2015-12/2021 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C50 | 01/2011-12/2014 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | WEY Coffee 01 | 03/2022-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | WEY Coffee 01 | 01/2022-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | WEY Coffee 02 | 01/2023-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | WEY Coffee 02 | 01/2022-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | WEY Macchiato PHEV | 11/2021-06/2023 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | WEY Macchiato PHEV | 11/2021-06/2023 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | WEY P8 | 08/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | WEY VV5 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | WEY VV6 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | WEY VV7 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| GreatWall | WEY VV7 | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 01/2016-12/2024 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 01/2011-12/2016 | 433MHz 3641110AK80X A | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 6 | 04/2014-11/2018 | 433MHz 3641100XSZ08 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 6 | 01/2014-12/2015 | 433MHz 3641110K80 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 6 | 01/2012-12/2015 | 433MHz 3641110AK80X A | | ● | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 7 | 06/2018-12/2024 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 7 | 06/2018-12/2024 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| HSV | ClubSport GXP | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | GTS | 01/2007-12/2012 | 433MHz | HT0078 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | Grange | 01/2007-12/2012 | 433MHz | HR0078 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | Maloo GXP | 01/2010-12/2010 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | R8 | 01/2007-12/2012 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HSV | Senator | 01/2007-12/2012 | 433MHz | HE0078 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| HaiMa | 6P | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | 7X | 08/2020-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Baolong | ● | ● |
| HaiMa | 7X-E | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Baolong | ● | ● |
| HaiMa | 8S | 01/2019-12/2024 | 433MHz PA1055440M1A | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| HaiMa | 8S | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | Family | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | Freema | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | Haima 7 | 01/2012-12/2013 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | M3 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | M6 | 06/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | QISHI | 01/2010-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | S5 | 01/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| HaiMa | S7 | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| Haval | Dargo | 08/2020-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0/A | 433MHz | SAT | ● | ● |
| Haval | Dargo | 08/2020-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 08/2020-12/2024 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Haval | Dargo II | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHZ | Schrader | ● | ● |
| Haval | F5 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | F7 | 11/2018-12/2023 | 433MHz 3641100BKRO2 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | F7 | 11/2018-12/2023 | 433MHz 3641100XKRO2 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | F7 | 11/2018-12/2023 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | F7X | 04/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H1 | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2 | 07/2017-12/2023 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2 | 01/2014-12/2023 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2s | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H3 | 04/2009-12/2016 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| Haval | H4 | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H5 | 06/2010-12/2015 | 433MHz 3641110AK80X A | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| Haval | H5 | 06/2010-12/2015 | 433MHz 3641110K80 | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| Haval | H5 | 01/2016-06/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H5 Classics | 01/2015-12/2020 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H5 Classics | 01/2014-12/2020 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 | 01/2016-12/2021 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 | 01/2016-12/2019 | 433MHz 3641100XKZ16 B | CC6461RM | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Haval | H6 | 01/2011-12/2015 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 Coupe | 01/2023-12/2023 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 Coupe | 06/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 Coupe | 01/2015-05/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 Coupe | 01/2023-12/2023 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|---------|-----------------|-----------------------------|----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Haval | H6 II | 01/2021-12/2021 | 433MHz 3641100BKR02 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | H6 II | 01/2020-12/2021 | 433MHz 3641100AKU00 B | CC6464RM | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | H6 II | 01/2020-01/2021 | 433MHz 3641100AKZ16 A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Haval | H6 II | 07/2019-12/2022 | 433MHz 3641100AKZ16 A | CC6461RM CC6472RM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Haval | H6 II | 01/2017-12/2021 | 433MHz 3641100XKR02 A | CC6472RM CC6464RM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 III | 08/2020-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 III | 08/2020-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 III | 08/2020-12/2024 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 PHEV | 01/2022-12/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 PHEV | 01/2022-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6S | 10/2021-06/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6S | 10/2021-06/2024 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H7 | 01/2016-12/2022 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7 | 01/2022-12/2023 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0/A | 433MHz | SAT | ● | ● |
| Haval | H7 | 01/2022-12/2023 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7L | 01/2017-12/2020 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7L | 01/2017-12/2020 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H8 | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 01/2017-07/2019 | 433MHz 3641100XKU00 B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Haval | H9 | 01/2014-12/2019 | 433MHz 3641100XKU00 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 08/2019-12/2024 | 433MHz 3641100XKR02 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 08/2019-12/2024 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641100BKR02 A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641101XKN01 A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641100AKR02 A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641101BKN01 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | M2 | 01/2014-12/2015 | 433MHz 3641100XKU00 A | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Haval | M6 | 01/2017-06/2019 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | M6 | 07/2019-12/2023 | 433MHz 3641100XKZ16 A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| HiPhi | HiPhi X | 09/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | HiPhi | ● | ● |
| HiPhi | HiPhi Y | 07/2023-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | HiPhi | ● | ● |
| Holden | Colorado | 01/2013-12/2017 | 433MHz | GMI700 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Holden | WM Caprice | 01/2007-12/2012 | 433MHz | WM | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Honda | Accord | 01/2009-12/2013 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Accord | 01/2015-12/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Accord | 01/2013-12/2015 | 433MHz | 2GA/2GB/QE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | CR-V | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | CR-V | 01/2010-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-Z | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2009-12/2012 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2013-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Civic | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Clarity | 01/2016-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Crosstour | 01/2010-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | HR-V | 11/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | HR-V | 09/2014-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Honda e | 01/2019-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Insight | 06/2009-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Jazz | 01/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------|-----------------|------------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Honda | NSX | 01/2016-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | NSX | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Odyssey | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Honda | Odyssey | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 01/2021-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Passport | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2018-12/2023 | 433MHz 42753T6NA01 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2023-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| HongQi | E-HS3 | 01/2019-12/2023 | 433MHz FS43XOL2 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | E-HS3 | 10/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | E-HS9 | 12/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H5 | 01/2019-12/2023 | 433MHz QY1218A0 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H5 | 07/2022-06/2024 | 433MHz 3778080DB01A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H5 | 01/2017-12/2018 | 433MHz FS43XOL5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H5 | 08/2023-12/2024 | 433MHz 3778080DB01B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H6 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H7 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| HongQi | H7 | 01/2013-09/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| HongQi | H7 | 09/2017-06/2024 | 433MHz 3778080MD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | H9 | 08/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | HS5 | 05/2023-12/2024 | 433MHz 3778080DB01A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | HS5 | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | HS7 | 01/2019-12/2023 | 433MHz FS43XOL2 | 3.0T | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| HongQi | HS7 | 01/2019-12/2023 | 433MHz FS43XOL2 | 2.0T | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Hummer | H2 | 01/2002-06/2006 | 433MHz | H28 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Hummer | H2 | 07/2006-12/2007 | 433MHz | H28 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2008-12/2008 | 433MHz | H28 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2005-12/2006 | 433MHz | H38/ GMT345 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2007-12/2013 | 433MHz | H38/ GMT345 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Hyundai | Accent | 04/2019-12/2024 | 433MHz Lo Line | HC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2019-12/2024 | 433MHz Hi Line | HC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2011-12/2021 | 433MHz Hi Line | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 01/2014-06/2020 | 433MHz Lo Line | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Alcazar | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Aura | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Avante | 01/2016-12/2020 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Avante | 01/2021-12/2023 | 433MHz 52933F2000 | CN7 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Avante | 01/2012-12/2016 | 433MHz 529333X305 | JK | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Azera | 01/2011-08/2014 | 433MHz | HG | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Hyundai | Azera | 03/2017-12/2019 | 433MHz | IG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 09/2014-02/2017 | 433MHz | HG | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Hyundai | Azera | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Bayon | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | C-Green | 01/2016-06/2019 | 433MHz | AE | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Hyundai | Centennial | 01/2013-12/2018 | 433MHz | VI New | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Centennial | 07/2009-12/2013 | 433MHz | VI Old | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Creta | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2022-12/2024 | 433MHz 52940BV100 | SU2r | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2022-12/2022 | 433MHz | SU2r | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 11/2015-12/2023 | 433MHz | GSB/GSR | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2016-12/2023 | 433MHz Russia | GSB/GSR | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2016-12/2019 | 433MHz 529333N100 | GS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Creta | 01/2022-12/2024 | 433MHz | SU2id | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Custin | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Baolong | ● | ● |
| Hyundai | Elantra | 01/2015-12/2020 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2014-12/2018 | 433MHz | MD/UD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Elantra | 01/2008-12/2012 | 433MHz | FD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2012-12/2013 | 433MHz | MD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Elantra | 07/2020-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra N | 01/2022-12/2024 | 433MHz 52940L8200 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 01/2022-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Equus | 01/2008-12/2013 | 433MHz | VI Old | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Equus | 01/2013-12/2019 | 433MHz | VI New | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis | 01/2007-12/2014 | 433MHz | BH | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2013-12/2019 | 433MHz | DH | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G70 | 01/2018-12/2024 | 433MHz 52933J5000 | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2018-12/2024 | 433MHz 52940CG100 | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2017-12/2017 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G80 | 07/2016-12/2019 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 07/2021-12/2024 | 433MHz 52940T6000 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Genesis G80 | 01/2020-12/2022 | 433MHz | DH | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 01/2021-12/2024 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 EV | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2016-12/2016 | 433MHz | HI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2022-12/2024 | 433MHz 52940CG100 | RS4 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G90 | 01/2022-12/2024 | 433MHz 52933D4100 | RS4 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2017-12/2024 | 433MHz | HI | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV60 | 12/2021-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV60 | 12/2021-12/2024 | 433MHz 52933D2100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 01/2022-12/2022 | 433MHz | IK | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV70 | 07/2021-12/2022 | 433MHz 52940T6000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 01/2022-12/2022 | 433MHz 52940T6000 | IK | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 07/2021-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV70 | 01/2021-12/2024 | 433MHz 52933D2100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 12/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 EV | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 07/2021-12/2024 | 433MHz 52940T6000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 01/2020-12/2024 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Grand I10 | 01/2014-12/2020 | 433MHz 52933B2100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Grand I10 | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grand I10 | 01/2020-12/2024 | 433MHz 52940BV100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Grand SantaFe | 01/2019-12/2020 | 433MHz 52933C1100 | DM | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Grand SantaFe | 04/2013-12/2018 | 433MHz | NC/DM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grand SantaFe | 01/2019-12/2019 | 433MHz | NC/DM | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 01/2011-12/2017 | 433MHz | HG/DM | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Hyundai | Grandeur | 06/2011-12/2015 | 433MHz | HG | ● | ● | ○ | C | 433MHz | TRW | ● | ● |
| Hyundai | Grandeur | 01/2015-12/2017 | 433MHz | Hybrid | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 01/2017-12/2020 | 433MHz | IG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 01/2018-12/2019 | 433MHz | IG LAMBDA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 07/2021-12/2023 | 433MHz 52940T6100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur GN7 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H-1 | 01/2011-12/2023 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H-1 | 07/2021-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | H-350 | 01/2014-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | H-350 | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | H100 | 01/2010-12/2024 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H300 | 01/2014-12/2022 | 433MHz | LU/AU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H300 | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | HB20 | 01/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq | 01/2016-12/2023 | 433MHz | AE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2022-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2022-12/2024 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Ioniq 6 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Kauai | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Kona | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Hyundai | Kona N | 01/2022-12/2024 | 433MHz | OSN | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Hyundai | Nexo | 04/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2023-12/2024 | 433MHz | LX2 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Porter | 01/2006-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Cruz | 01/2022-12/2024 | 433MHz 52933C1100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Cruz | 01/2022-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Santa Cruz | 01/2019-12/2021 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2023-12/2024 | 433MHz 52940CG100 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 04/2017-12/2018 | 433MHz 52933B1100 | DM/DMI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 03/2018-12/2024 | 433MHz 52940Q3100 | TM/TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 03/2018-12/2024 | 433MHz | TM/TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 04/2013-12/2017 | 433MHz 529333N100 | DM/DMI | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2021-12/2024 | 433MHz | TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2006-12/2008 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 01/2009-05/2012 | 433MHz | CM | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 06/2012-03/2013 | 433MHz | DM/NC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Solaris | 01/2014-12/2023 | 433MHz | HC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Solaris | 01/2011-03/2017 | 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2020-12/2024 | 433MHz 52940T6000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 04/2014-04/2019 | 433MHz Hi Line | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 05/2019-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2010-12/2013 | 433MHz | LF/LFA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2011-12/2016 | 433MHz 529333N100 | YFC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2014-02/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 04/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Sonata Hybrid | 01/2024-12/2024 | 433MHz 52940L1100 | DN8 HEV | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 01/2020-12/2023 | 433MHz 52940L1100 | DN8 HEV | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 08/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata Hybrid | 01/2020-06/2020 | 433MHz Hi Line | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata Hybrid | 08/2017-12/2019 | 433MHz Hi Line | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata N | 01/2023-12/2024 | 433MHz 52940L1100 | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Starex | 02/2021-12/2023 | 433MHz 52940Q3100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Starex | 01/2021-12/2023 | 433MHz 52940CG100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Starex | 03/2011-03/2021 | 433MHz | TQ | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Stargazer | 01/2022-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Staria | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sub-Compact SUV | 01/2015-06/2019 | 433MHz | IB | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Hyundai | Tucson | 07/2013-06/2015 | 433MHz Hi line | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Tucson | 11/2013-09/2015 | 433MHz Lo line | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2016-09/2020 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2006-05/2015 | 433MHz | LM | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Tucson | 06/2015-08/2018 | 433MHz | LM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2015-12/2015 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2021-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Tucson | 10/2020-12/2024 | 433MHz | NX4 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2021-12/2024 | 433MHz 52940Q3100 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 03/2011-06/2019 | 433MHz | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 01/2019-12/2020 | 433MHz 529332V100 | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 01/2021-12/2022 | 433MHz 52933D4100 | JS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Veloster N | 01/2019-06/2024 | 433MHz | JSN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 01/2023-12/2024 | 433MHz 52933D4100 | QX | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 01/2022-12/2024 | 433MHz 52933D4100 | QXI | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 01/2019-12/2022 | 433MHz 52933D4100 | QX/QXI | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Hyundai | Veracruz | 01/2009-12/2015 | 433MHz | EN | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | Verna | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Verna | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i10 | 11/2013-06/2020 | 433MHz 52933B2100 | IA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | i10 | 01/2020-12/2023 | Indirect | LA | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Hyundai | i10 | 10/2007-10/2013 | 433MHz | IA/PA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|--------------|-----------------|----------------------|------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | i20 | 01/2008-05/2014 | 433MHz 529331J000 | PB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 01/2013-12/2016 | 433MHz | PB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 01/2020-12/2020 | 433MHz | BC | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 | 01/2022-12/2024 | 433MHz | BI3 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 | 01/2021-12/2024 | 433MHz 52933C1100 | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 | 10/2014-12/2020 | 433MHz | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 N | 10/2021-07/2023 | 433MHz | BC | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 N | 01/2021-12/2024 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 01/2017-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Hyundai | i30 | 01/2007-12/2016 | 433MHz | FD/Fde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 12/2011-12/2017 | 433MHz | Gde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 04/2014-12/2018 | 433MHz | GD | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 08/2016-12/2024 | 433MHz | PD/Pde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 | 08/2016-12/2024 | 433MHz 52933562C6 | PD/Pde | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i30 Fastback | 01/2017-06/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | i30 N | 01/2018-12/2024 | 433MHz 52933F2000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 N | 01/2018-12/2024 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i40 | 01/2011-03/2014 | 433MHz | VF | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 01/2011-03/2014 | 433MHz Second | VF | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 04/2014-12/2020 | 433MHz | VF | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 01/2017-12/2019 | 433MHz | IF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i800 | 07/2021-12/2024 | 433MHz 52940CG100 | US4 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | i800 | 03/2014-12/2021 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i800 | 01/2013-02/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | i800 | 01/2007-01/2014 | 433MHz | TQ | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | iLoad | 01/2009-12/2022 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | iMax | 01/2014-12/2022 | 433MHz 529334H100 | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix20 | 10/2013-03/2017 | 433MHz | JC/IX5 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | ix20 | 04/2017-12/2021 | 433MHz | JC/IX5 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | ix20 | 01/2010-09/2013 | 433MHz | JC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix25 | 01/2017-12/2018 | 433MHz | OS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix25 | 01/2017-12/2020 | 433MHz 52933C1100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | ix25 | 01/2019-12/2019 | 433MHz | OS | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | ix25 | 01/2021-12/2022 | 433MHz 52940BV100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | ix35 | 07/2020-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | ix35 | 01/2019-12/2021 | 433MHz Lo Line | LMC/EL/ELH/ LM FCEV | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 01/2017-12/2020 | 433MHz FUEL CELL | EL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | ix35 | 10/2015-12/2016 | 433MHz | TL/TLE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | ix35 | 01/2017-09/2017 | 433MHz FUEL CELL | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 01/2013-12/2016 | 433MHz FUEL CELL | EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 09/2013-12/2018 | 433MHz Lo Line | LMC/EL/ELH/LM FCEV | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 09/2013-12/2016 | 433MHz | LM | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 09/2013-12/2015 | 433MHz Hi Line | EL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 01/2010-08/2013 | 433MHz | LM/EL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | ix35 | 01/2017-06/2020 | 433MHz | TL/TLE | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | ix55 | 01/2007-12/2013 | 433MHz 529333J000 | EN | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Hyundai | ix55 | 10/2008-12/2019 | 433MHz 529333N100 | EN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| INEOS | Grenadier | 01/2022-12/2024 | 433MHz 407005663R | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| INEOS | Grenadier | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Infiniti | EX Series | 01/2008-03/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | FX Series | 12/2010-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | FX Series | 03/2008-12/2013 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2007-06/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2010-12/2014 | 433MHz 407001LL0D | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | G Series | 07/2011-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | JX35 | 04/2012-01/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | M Series | 08/2010-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q30 | 04/2016-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | Q50 | 11/2013-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 07/2013-09/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q60 | 10/2016-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 07/2013-09/2016 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | Q70 | 10/2018-12/2021 | 433MHz 407003JA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q70 | 07/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q70 | 11/2014-12/2021 | 433MHz 407006WY0B | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX30 | 04/2016-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | QX40 | 04/2017-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX50 | 04/2018-05/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX50 | 06/2020-12/2024 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX50 | 01/2018-12/2023 | 433MHz 4070062B0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX50 | 05/2014-03/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX50 | 12/2016-03/2018 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | QX55 | 04/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|--------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Infiniti | QX55 | 08/2021-03/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX56 | 01/2010-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX60 | 08/2018-12/2021 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX60 | 11/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX60 | 04/2012-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX70 | 07/2013-12/2015 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | QX70 | 10/2013-04/2014 | 433MHz 407001LL0D | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX70 | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 10/2013-09/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 09/2014-12/2023 | 433MHz 407006WY0C | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Isuzu | D-Max | 01/2007-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Isuzu | D-Max | 09/2020-06/2024 | 433MHz 8974993680 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Isuzu | D-Max | 06/2016-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Unknown | ● | ● |
| Isuzu | MU-X | 11/2016-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| Isuzu | Rodeo | 01/2004-12/2004 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Iveco | Daily | 02/2019-12/2024 | 433MHz Schrader 6 Wheels | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| JAC | J4 | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 | 01/2011-12/2017 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 A30 | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 A30 | 01/2012-12/2012 | 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | J6 B15 | 01/2012-12/2016 | 433MHz | | ○ | ● | ○ | NA | 433MHz | JAC | ● | ● |
| JAC | J7 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | J7 | 01/2020-12/2023 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | JS4 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Jiayue X4 | 06/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| JAC | Jiayue X7 | 04/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Jiayue X7 | 04/2020-12/2021 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | Refine A60 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine M2 | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine M4 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| JAC | Refine M5 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| JAC | Refine M6 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| JAC | Refine R3 | 01/2018-06/2020 | 433MHz SAT | | ● | ● | ○ | S | 433MHz | SAT | ● | ● |
| JAC | Refine R3 | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | JAC | ● | ● |
| JAC | Refine S2 | 01/2018-12/2022 | 433MHz Steel | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S2 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S2 | 09/2017-12/2022 | 433MHz 3666200V5000 | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S3 | 01/2015-12/2023 | 433MHz TP3040001 | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| JAC | Refine S3 | 01/2015-12/2023 | 433MHz 3666200V5000 | | ● | ● | ○ | S | 433MHz | JAC | ● | ● |
| JAC | Refine S4 | 08/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| JAC | Refine S5 | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S7 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| JAC | SUNRAY | 06/2019-12/2024 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | SUNRAY | 01/2021-12/2024 | 433MHz 3666200R0542 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| JAC | Sehol E10X | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Sehol E40X | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| JAC | T6 | 01/2020-12/2024 | 433MHz 3666200P3331 | | ● | ● | ○ | C | 433MHz | Dias | ● | ● |
| JAC | T6 | 01/2020-12/2024 | 433MHz 3666200V5000 | | ● | ● | ○ | S | 433MHz | JAC | ● | ● |
| JAC | T6 | 01/2015-12/2020 | 433MHz SCH | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | T8 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| JAC | T8 | 01/2022-12/2024 | 433MHz 3666200P3331 | | ● | ● | ○ | C | 433MHz | Dias | ● | ● |
| JAC | e-JS4 | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | iEV6E | 04/2019-12/2021 | 433MHz 3666200V5000 | | ● | ● | ○ | O/S | 433MHz | JAC | ● | ● |
| JAC | iEV6E | 04/2019-12/2021 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | iEV7S | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | JAC | ● | ● |
| JAC | iEVA50 | 04/2018-05/2021 | 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | iEVA50 | 06/2021-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | JAC | ● | ● |
| JAC | iEVA60 | 04/2019-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| JAC | iEVS4 | 09/2019-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | JAC | ● | ● |
| JETOUR | DASHING | 09/2022-06/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | DASHING i-DM | 09/2022-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | T2 | 09/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | X70 | 06/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70 PLUS | 10/2020-12/2023 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70 PLUS | 10/2020-12/2023 | 433MHz QY1051 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70M | 03/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X90 | 09/2020-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X90 | 06/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC | Limo | 09/2021-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Unknown | ● | ● |
| JMC Ford | Ranger | 06/2023-12/2024 | 433MHz MC191A180AB | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC Ford | Territory | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC Ford | Territory EV | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC Ford | Tourneo | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Jaguar | E-Pace | 01/2019-12/2022 | 433MHz | X540 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 01/2017-12/2018 | 433MHz | X540 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jaguar | E-Pace | 01/2022-12/2024 | 433MHz M8E21A159AA | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2022-12/2024 | 433MHz M8E21A159AA | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2019-12/2022 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2015-12/2018 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2021-12/2023 | 433MHz M8E21A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 05/2016-12/2018 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 05/2016-12/2018 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 11/2012-04/2016 | 433MHz AH521A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 11/2012-04/2016 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2019-12/2024 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2019-06/2021 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2019-12/2023 | 433MHz GX631A159AA | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2017-12/2018 | 433MHz | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2021-12/2024 | 433MHz M8E21A159AA | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | RD-7 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 10/1998-08/2011 | 433MHz | X200 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | X-Type | 01/2001-12/2009 | 433MHz | X400 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2019-12/2022 | 433MHz GX631A159AA | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 04/2015-12/2018 | 433MHz FW931A159AB | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2015-12/2018 | 433MHz GX631A159AA | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2022-12/2024 | 433MHz M8E21A159AA | X760 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 09/2015-12/2018 | 433MHz | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 07/2014-05/2015 | 433MHz | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2007-08/2015 | 433MHz | X250 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2019-12/2024 | 433MHz GX631A159AA | X260 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 433MHz AH521A159AA | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 433MHz GX631A159AA | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 12/2002-12/2009 | 433MHz | X350 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 433MHz FW931A159AB | X351 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 01/2010-12/2015 | 433MHz | X150 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 01/2006-12/2009 | 433MHz | X150 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | XKR | 01/2006-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | B-CUV | 10/2014-12/2016 | 433MHz | 520 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | C-CUV | 01/2016-06/2019 | 433MHz | MP | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Jeep | Cherokee | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2023 | 433MHz | KL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2018 | 433MHz 68324960AA | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2017-12/2017 | 433MHz | KL | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2014-12/2016 | 433MHz | KL | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2005-12/2013 | 433MHz 56029359AC | KK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Cherokee | 01/2002-12/2004 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2006-12/2010 | 433MHz | XK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2019-12/2022 | 433MHz | 551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2018-12/2018 | 433MHz | 551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2018-12/2018 | 433MHz | MP/MX | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 433MHz | MP/MX | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 433MHz | 551 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 05/2006-12/2017 | 433MHz | MK49 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2019-12/2024 | 433MHz | MP/MX | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | D-CUV | 05/2013-12/2016 | 433MHz | KL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 07/2021-12/2024 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 11/2019-12/2022 | 433MHz MRXAG4WA5 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2024-12/2024 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2021-12/2023 | 433MHz | WL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2021-12/2023 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2018-12/2022 | 433MHz 68252493AB | WK | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 06/2006-12/2010 | 433MHz | WH | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2005-05/2006 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2001-12/2004 | 433MHz | WK/WJ | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2012-12/2015 | 433MHz | WK74 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | WK | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2011-12/2011 | 433MHz | WK74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Jeep | Grand Wagoneer | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Wagoneer | 09/2023-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Wagoneer | 01/2022-12/2023 | 433MHz 68339096AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Liberty | 01/2010-12/2015 | 433MHz | Li0103 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jeep | Meridian | 01/2022-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Meridian | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Patriot | 12/2006-12/2017 | 433MHz | MK74 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Renegade | 01/2018-12/2024 | 433MHz 68193586AC | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2018-12/2021 | 433MHz | BU/520 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2016-12/2017 | 433MHz 68252493AB | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2015-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2014-12/2017 | 433MHz | BU/520 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 08/2023-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 01/2022-12/2022 | 433MHz 68339096AB | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 01/2023-12/2023 | 433MHz | WS | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 06/2006-08/2010 | 433MHz | JK72 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 09/2010-12/2017 | 433MHz | JK72 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2014-12/2017 | 433MHz | JL | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2019-12/2019 | 433MHz | J3 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2019-12/2020 | 433MHz | JL | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 07/2021-12/2024 | 433MHz Conti | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KAWAI | W150 | 06/2019-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| KIA | Bongo | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Bongo | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Bongo | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | C-CUV EV | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Cadenza | 01/2017-12/2023 | 433MHz 529333N100 | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2011-07/2016 | 433MHz | VG | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2016-12/2023 | 433MHz 52933D9100 | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carens | 01/2006-12/2020 | 433MHz | RP/UN | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Carens | 01/2023-12/2024 | 433MHz | KY | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carens | 01/2022-12/2022 | 433MHz | KY | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carnival | 01/2014-12/2018 | 433MHz | YP/Sedan | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carnival | 01/2016-12/2018 | 433MHz | YP/VQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2019-12/2024 | 433MHz | YP/YPi | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carnival | 01/2020-12/2024 | 433MHz | KA4 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 03/2021-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| KIA | Ceed | 01/2018-12/2021 | 433MHz | CD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed | 03/2012-06/2018 | 433MHz | JD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed | 01/2006-09/2012 | 433MHz | ED | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed | 01/2022-12/2024 | 433MHz | CD | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed SW | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed SW | 01/2006-08/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed SW | 09/2012-04/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Ceed SW | 05/2018-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------|-----------------|----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Cerato | 01/2016-12/2018 | 433MHz 529333X305 | YD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Cerato | 01/2015-12/2016 | 433MHz | BD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cerato | 02/2009-12/2014 | 433MHz 529333X305 | TD | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Cerato | 01/2016-12/2018 | 433MHz 52933A7100 | YD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Cerato | 01/2019-12/2020 | 433MHz | YD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Cerato | 01/2021-12/2023 | 433MHz | BD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | E-Niro | 01/2023-12/2024 | 433MHz | SG2 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | E-Niro | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | E-Niro | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | E-Soul | 04/2019-12/2024 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | EV6 | 03/2021-12/2024 | 433MHz 52940BV100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV6 | 03/2021-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV9 | 07/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | EV9 | 07/2023-12/2024 | 433MHz 52940CG100 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| KIA | Forte | 01/2022-12/2024 | 433MHz | BD/BDm | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Forte | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Forte | 01/2019-12/2021 | 433MHz | BD/BDm | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | K2500 | 06/2014-06/2024 | 433MHz | PU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K2700 | 06/2014-06/2024 | 433MHz | PU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K3 | 01/2022-12/2024 | 433MHz 52940Q3100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K3 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | K3 | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | K3000 | 06/2014-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2023-12/2024 | 433MHz | Snap In OE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2020-12/2024 | 433MHz 52933D4100 | Clamp In OE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2020-12/2024 | 433MHz | DL3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K8 | 07/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | K9 | 01/2011-12/2018 | 433MHz | KH | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K9 | 01/2019-12/2021 | 433MHz | RJ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K9 | 01/2022-12/2024 | 433MHz | RJ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K900 | 09/2018-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | K900 | 01/2022-06/2024 | 433MHz | RJ | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Magentis | 10/2010-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Mohave | 09/2014-12/2016 | 433MHz Lo line | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Mohave | 01/2022-12/2023 | 433MHz 52933D2100 | HM PE2 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2020-12/2021 | 433MHz 52933D2100 | HM PE2 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2008-08/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|-------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Mohave | 01/2017-12/2019 | 433MHz Hi line | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Mohave | 09/2014-12/2016 | 433MHz Hi line | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Mohave | 01/2019-12/2020 | 433MHz 529332J100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2017-12/2019 | 433MHz Lo line | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Morning | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Morning | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Niro | 01/2023-12/2024 | 433MHz 52940CG100 | SG2 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Niro | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Niro | 01/2016-12/2021 | 433MHz | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Opirus | 01/2006-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Optima | 08/2013-12/2016 | 433MHz | TF/TF HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 06/2010-07/2013 | 433MHz | TF/TF HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima | 01/2020-12/2024 | 433MHz | DK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 09/2015-12/2022 | 433MHz | JF/JFA | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 06/2012-12/2013 | 433MHz | TF HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2014-12/2015 | 433MHz | TF HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2016-12/2020 | 433MHz | JF HEV/PHEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| KIA | Picanto | 01/2016-12/2023 | 433MHz 52933D9100 | TA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2011-12/2017 | 433MHz 529333N100 | TA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 01/2008-08/2012 | 433MHz | ED | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 01/2023-12/2024 | 433MHz | CD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 03/2012-06/2018 | 433MHz | JD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Pro Ceed | 01/2022-12/2022 | 433MHz | CD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 01/2020-06/2021 | 433MHz | CD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Pro Ceed | 05/2018-12/2019 | 433MHz | CD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Quoris | 06/2012-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Rio | 01/2017-12/2024 | 433MHz | SC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Rio | 06/2014-12/2020 | 433MHz Lo line | UB | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Rio | 01/2011-06/2014 | 433MHz | UB | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Rio | 05/2014-06/2020 | 433MHz Hi line | UB | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Rio | 12/2016-06/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Rondo | 01/2014-12/2021 | 433MHz 529332J100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sedona | 01/2021-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sedona | 01/2015-12/2020 | 433MHz | YP | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 01/2021-12/2022 | 433MHz | YP | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Seltos | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sonet | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sorento | 01/2020-12/2024 | 433MHz | MQ4 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Sorento | 01/2018-09/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2017-12/2020 | 433MHz 52933D4100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2016-06/2020 | 433MHz | UM/XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2021-12/2023 | 433MHz 52933D4100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2020-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 07/2012-12/2015 | 433MHz | UM/XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2009-07/2012 | 433MHz | XM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 01/2019-12/2019 | 433MHz | PS | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Soul | 10/2013-12/2018 | 433MHz | PS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul | 01/2023-12/2024 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Soul | 01/2019-12/2022 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Soul | 06/2008-10/2013 | 433MHz | AM | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul EV | 01/2019-12/2019 | 433MHz | PS EV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Soul EV | 01/2013-12/2018 | 433MHz | PS EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul Electric | 01/2019-12/2019 | 433MHz | SK3 EV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Soul Electric | 06/2014-12/2018 | 433MHz | SK3 EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sportage | 11/2015-06/2021 | 433MHz | QL/QLE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sportage | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sportage | 01/2021-06/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sportage | 01/2010-12/2013 | 433MHz Lo Line | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Sportage | 01/2010-01/2014 | 433MHz Hi Line | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Sportage | 10/2013-01/2016 | 433MHz | SL | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| KIA | Sportage | 01/2014-12/2015 | 433MHz Hi Line | SL | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Sportage | 01/2022-06/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Stinger | 06/2017-12/2017 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Stinger | 01/2018-12/2024 | 433MHz | CK | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Stonic | 11/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Stonic | 01/2017-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Telluride | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Venga | 05/2014-12/2022 | 433MHz | YN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Venga | 06/2009-04/2014 | 433MHz | YN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | XCeed | 01/2020-06/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | XCeed | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | XCeed | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Karma | Revero | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| LEAPMOTOR | C01 | 09/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| LEAPMOTOR | C11 | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| LEAPMOTOR | C11 | 12/2020-02/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | LEAPMOTOR | ● | ● |
| LEAPMOTOR | T03 | 05/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | LEAPMOTOR | ● | ● |
| LYNK_CO | 01 | 01/2020-12/2021 | 433MHz 8889198315 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|--------------|-----------------|----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| LYNK_CO | 01 | 08/2022-12/2024 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 01 PHEV | 09/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 01 PHEV | 12/2020-08/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 02 | 01/2020-12/2021 | 433MHz 8889198315 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 02 Hatchback | 06/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 03 | 08/2020-12/2023 | 433MHz 8889198315 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| LYNK_CO | 03 | 01/2021-06/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| LYNK_CO | 03 | 01/2022-06/2024 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 03 PHEV | 07/2021-09/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 05 | 03/2020-06/2024 | 433MHz 8889198315 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| LYNK_CO | 05 | 03/2020-12/2024 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 05 EM-P | 05/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 06 EM-P | 06/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| LYNK_CO | 07 EM-P | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| LYNK_CO | 08 EM-P | 09/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| LYNK_CO | 09 | 01/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| LYNK_CO | 09 EM-P | 10/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Lada | 4x4 | 01/2014-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lada | Granta | 04/2014-12/2024 | 433MHz 407004CBOA | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Lada | Granta | 09/2012-06/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lada | Kalina | 05/2013-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lada | Largus | 01/2015-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lada | Priora | 01/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lada | Vesta | 01/2015-12/2024 | 433MHz VDO | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Lada | Vesta | 02/2017-12/2024 | 433MHz Schrader | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lada | Xray | 01/2015-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lamborghini | Aventador | 01/2011-12/2023 | 433MHz | LB834 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Centenario | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Few Off | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Gallardo | 01/2003-06/2018 | 433MHz | LB714/LB724 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 01/2014-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | LP640 | 06/2007-01/2010 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Murcielago | 01/2002-12/2015 | 433MHz | LB824 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | One Off | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Reventon | 01/2007-12/2010 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Sian | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 01/2018-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lancia | Delta | 06/2014-12/2020 | 433MHz | PK | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lancia | Delta | 01/2008-05/2014 | 433MHz | 844 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Lancia | Flavia | 01/2014-12/2016 | 433MHz | UF | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Lancia | Flavia | 01/2012-12/2014 | 433MHz | JS27 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lancia | Flavia | 01/2010-12/2011 | 433MHz | JS27 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Lancia | Musa | 01/2004-12/2014 | 433MHz | 848 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Lancia | Phedra | 01/2002-09/2005 | 433MHz Schrader | 179 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lancia | Phedra | 01/2002-12/2012 | 433MHz Continental | 179 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lancia | Thema | 01/2011-12/2018 | 433MHz | LX | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lancia | Voyager | 01/2007-12/2010 | 433MHz | RT | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lancia | Voyager | 01/2011-10/2015 | 433MHz | RT/RU | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lancia | Voyager | 11/2015-12/2017 | 433MHz | RU/RA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lancia | Ypsilon | 01/2011-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lancia | Ypsilon | 01/2011-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Land Rover | Defender | 01/2020-12/2024 | 433MHz M8E21A159AA | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/1997-12/2019 | 433MHz BH521A159AA | L316 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 06/2014-12/2018 | 433MHz | L316 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2020-12/2023 | 433MHz GX631A159AA | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2020-12/2023 | 433MHz FW931A159AB | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 12/2009-12/2016 | 433MHz AH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 06/2004-11/2009 | 433MHz | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2002-05/2004 | 433MHz | L318 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Discovery | 12/2009-12/2016 | 433MHz BH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2017-12/2018 | 433MHz GX631A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2019-12/2022 | 433MHz GX631A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2021-12/2024 | 433MHz M8E21A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 12/2009-12/2016 | 433MHz FW931A159AB | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 12/2009-12/2016 | 433MHz GX631A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2019-12/2022 | 433MHz GX631A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2019-12/2022 | 433MHz BH521A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 06/2014-12/2018 | 433MHz GX631A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2014-12/2018 | 433MHz BH521A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2021-12/2024 | 433MHz M8E21A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 01/2006-12/2014 | 433MHz BH521A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 01/2006-12/2014 | 433MHz FW931A159AB | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | FreeLander | 01/2006-12/2014 | 433MHz GX631A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | LR2 | 01/2006-12/2014 | 433MHz GX631A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 433MHz BH521A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 433MHz FW931A159AB | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR3 | 06/2004-11/2009 | 433MHz | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz BH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz GX631A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz AH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz FW931A159AB | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2005-12/2009 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2016-01/2018 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2016-12/2018 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2019-12/2021 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 02/2020-12/2021 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2022-12/2023 | 433MHz GX631A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2002-12/2004 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 01/2022-12/2024 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2015-12/2018 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2015-12/2017 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 433MHz AH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2019-12/2023 | 433MHz GX631A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2019-12/2022 | 433MHz FW931A159AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Evoque | 07/2015-12/2018 | 433MHz GX631A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2021-12/2024 | 433MHz M8E21A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2021-09/2022 | 433MHz M8E21A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2019-09/2022 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2016-12/2018 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2016-12/2018 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 433MHz AH521A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2005-12/2009 | 433MHz | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz FW931A159AB | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2019-09/2022 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz AH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz GX631A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz BH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 10/2022-12/2024 | 433MHz | L461 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2017-12/2018 | 433MHz | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2019-12/2023 | 433MHz GX631A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2021-12/2024 | 433MHz M8E21A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2022-12/2023 | 433MHz GX631A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 02/2020-12/2021 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2019-12/2021 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2016-12/2018 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2022-12/2024 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2016-01/2018 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|-------------------|-----------------|--------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Vogue | 01/2002-12/2004 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover Vogue | 01/2005-12/2009 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| LandWind | X5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| LeadingIdeal | L7 | 09/2022-06/2024 | 433MHz X0137000023 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| LeadingIdeal | L7 | 09/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| LeadingIdeal | L8 | 09/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| LeadingIdeal | L9 | 06/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Lexus | C-CUV | 11/2014-12/2016 | 433MHz | 600A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | CT Series | 12/2013-12/2022 | 433MHz | 080A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 08/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 06/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 06/2012-01/2021 | 433MHz C210 | 980L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 01/2006-05/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2012-12/2022 | 433MHz | 920L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2005-12/2011 | 433MHz | GS32 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS430 | 01/2006-12/2006 | 433MHz 1019 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 08/2021-12/2023 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 09/2019-12/2022 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 01/2006-12/2009 | 433MHz | J120 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 06/2009-08/2019 | 433MHz | J150 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 01/2006-01/2021 | 433MHz | XE20 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 09/2020-10/2023 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 04/2013-12/2023 | 433MHz C210 | 030L/400A/720A/XE30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LBX | 10/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 05/2017-12/2021 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 11/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | LFA | 06/2014-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LFA | 01/2010-12/2012 | 433MHz | LFA | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 08/2006-09/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2012-09/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 05/2014-08/2017 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2020-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2005-12/2010 | 433MHz 107K | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 06/2012-12/2024 | 433MHz C210 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|--------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lexus | LX Series | 11/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 10/2015-12/2021 | 433MHz C215 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2014-12/2024 | 433MHz | 600A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 11/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RC Series | 09/2014-01/2023 | 433MHz | XC1/720A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2009-10/2015 | 433MHz | 640L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 09/2015-12/2024 | 433MHz C215 | 740A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 07/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | RZ Series | 01/2023-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | SC Series | 08/2009-01/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | SC Series | 01/2001-12/2011 | 433MHz | UZZ40 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2018-12/2024 | 433MHz C215 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2020-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lifan | 820 | 01/2015-12/2016 | 433MHz | | ○ | ● | ○ | S | 433MHz | LiFan | ● | ● |
| Lifan | Maiwei | 01/2016-12/2022 | 433MHz 151219100353 0059 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Maiwei | 01/2018-12/2021 | 433MHz Z71036 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Murman | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | LiFan | ● | ● |
| Lifan | Myway | 01/2018-12/2021 | 433MHz Z71036 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Myway | 01/2016-12/2022 | 433MHz 151219100353 0059 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Solano 2 | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | LiFan | ● | ● |
| Lifan | X50 | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | CheWan | ● | ● |
| Lifan | X60 | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | LiFan | ● | ● |
| Lifan | X70 | 01/2017-12/2023 | 433MHz SCA3638200 | | ○ | ● | ○ | NA | 433MHz | LiFan | ● | ● |
| Lifan | X70 | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | LiFan | ● | ● |
| Lincoln | Aviator | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2020-12/2024 | 433MHz D6A5FA180BB | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Continental | 07/2016-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Corsair | 05/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2016-12/2019 | 433MHz | 2.0F SEL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 04/2014-12/2015 | 433MHz | 2.0F SEL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKX | 02/2012-06/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2017-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2013-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2018-12/2023 | 433MHz F2GZ1A189B | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2016-12/2017 | 433MHz | FA0114 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2018-12/2023 | 433MHz | FA0114 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lincoln | Navigator | 01/2011-12/2014 | 433MHz | FA0114 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2017-12/2017 | 433MHz F2GZ1A189B | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lotus | 3-Eleven | 01/2015-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | 3-Eleven | 06/2017-12/2021 | 433MHz A132G6017F | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Elan | 01/2018-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Elise | 09/2000-05/2021 | 433MHz | Monza | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evija | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Evora | 07/2015-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Evora | 06/2009-12/2021 | 433MHz | Eagle | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Exige | 02/2017-12/2021 | 433MHz A132G6017F | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | Exige | 09/2000-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Luxgen | 5 | 07/2013-12/2018 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Luxgen | M7 | 01/2009-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Luxgen | S3 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Luxgen | S5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Luxgen | U5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | C | 433MHz | SAT | ● | ● |
| Luxgen | U6 | 01/2014-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Luxgen | U6 | 01/2018-12/2023 | 433MHz 28451LB900 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| Luxgen | U7 | 01/2010-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Luxgen | V7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| MAN | TGE | 01/2014-12/2016 | 433MHz Continental | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| MAN | TGE | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| MAXUS | D90 | 06/2019-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | E-Deliver 3 | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | E-Deliver 9 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ5 | 07/2019-12/2023 | 433MHz C00047579 | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ5 | 07/2019-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ6 | 05/2020-12/2023 | 433MHz C00047579 | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ6 | 05/2020-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | EV80 | 01/2021-12/2024 | 433MHz TP3040001 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| MAXUS | G10 | 01/2014-12/2024 | 433MHz GC91B50 | LTR | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 01/2014-12/2024 | 433MHz GC91B50 | PCR | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | G20 | 04/2019-12/2024 | 433MHz C00047579 | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | G20 | 04/2019-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | G20 ES | 01/2023-12/2024 | 433MHz C00104713 | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | MIFA5 | 06/2022-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| MAXUS | MIFA7 | 11/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| MAXUS | MIFA9 | 06/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | MIFA9 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T60 | 01/2017-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T60 | 01/2017-12/2024 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T60 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T70 | 01/2017-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T70 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 | 01/2021-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 EV | 03/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2015-12/2022 | 433MHz TP3040001 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| MAXUS | V80 | 01/2015-12/2022 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2023-12/2024 | 433MHz C00406825 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V90 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Dias | ● | ● |
| MAXUS | V90 | 01/2020-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MG | Astor | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | EXTENDER | 01/2017-12/2023 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MG | EXTENDER | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MG | EZS | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | GS | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | GS | 09/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | HS | 01/2018-12/2018 | 433MHz 10290600 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | HS | 07/2020-12/2023 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | HS | 01/2019-12/2021 | 433MHz 10290600 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | Hector | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MARVEL R | 10/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | MG3 | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | MG3 | 09/2013-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG4 EV | 09/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MG | MG5 | 01/2020-12/2024 | 433MHz 10290600 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG5 | 01/2020-12/2024 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG5 EV | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG6 | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG6 | 11/2017-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | MG6 | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG7 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| MG | One | 12/2021-12/2024 | 433MHz 10290600 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | One | 12/2021-12/2024 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | Pilot | 10/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | ZS | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | eHS | 11/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MHERO | MHERO 917/MHERO I | 08/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Mahindra | Alturas G4 | 01/2018-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | B-CUV | 01/2016-01/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Bolero | 09/2003-12/2024 | 433MHz 1805BA0131NA | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Bolero | 06/2014-12/2023 | 433MHz 1805BA0131N | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Genio | 01/2014-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Goa | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Goa | 01/2014-12/2022 | 433MHz | W105 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | KUV100 | 01/2016-12/2023 | 433MHz 1805BA0131NA | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | NC | 06/2014-12/2017 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Mahindra | NC | 01/2011-12/2021 | 433MHz | CL/MM | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | NUVOSPORT | 01/2017-01/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Pick-Up Dual Cab | 06/2014-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mahindra | Quanto | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 01/2015-12/2023 | 433MHz 1805BA0131N | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 06/2014-12/2023 | 433MHz | U202 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 12/2017-12/2023 | 433MHz 1805BAA00791 N | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | Scorpio-N | 09/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | Thar | 08/2020-12/2024 | 433MHz 1805BAA00791 N | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mahindra | Thar | 01/2014-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XUV300 | 02/2019-12/2024 | 433MHz 1805BW600221 N | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | XUV300 | 02/2019-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | XUV3X0 | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | XUV500 | 10/2011-12/2023 | 433MHz 1805BA0131N | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mahindra | XUV500 | 01/2014-12/2023 | 433MHz 1805BAA00791 N | | ○ | ● | ○ | S | 433MHz | Huf/Beru | ● | ● |
| Mahindra | XUV500 | 01/2013-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XUV700 | 08/2021-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | XYLO | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | e20 | 01/2014-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | 4200 | 01/2001-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------|-----------------|-----------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Maserati | 4200 GT/Coupe | 01/2002-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Alfieri | 01/2016-12/2021 | 433MHz | M165 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Coupe | 01/2002-06/2009 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Coupe | 07/2009-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Coupe | 01/2001-12/2007 | 433MHz | M138 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GT Coupe | 03/2014-12/2020 | 433MHz | M138 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GT Coupe | 01/2014-12/2020 | 433MHz | M145 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GT Coupe | 01/2002-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Ghibli | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Ghibli | 10/2018-12/2023 | 433MHz | M156D | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Ghibli | 01/2018-12/2020 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 01/2013-12/2017 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GrabSport Cabrio | 01/2007-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranCabrio | 09/2009-12/2022 | 433MHz Huf/Beru | M147 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranCabrio | 07/2015-12/2017 | 433MHz Schrader | M147 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranCabrio | 01/2008-08/2009 | 433MHz | M147 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2014-01/2022 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 09/2010-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2007-08/2010 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 08/2017-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 01/2013-07/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Grecale | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Grecale | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2016-12/2019 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 04/2015-12/2018 | 433MHz | WM | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2020-12/2023 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2019-12/2022 | 433MHz | WM | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | MC20 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Quattroporte | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 10/2018-12/2023 | 433MHz Continental | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Quattroporte | 01/2018-12/2022 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2013-12/2017 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2011-12/2015 | 433MHz | M139 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2010-12/2010 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 04/2003-12/2009 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Spyder | 07/2001-12/2008 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maybach | GLS SUV | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 10/2008-12/2014 | 433MHz | Ma009-127 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Landulet | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|--------------|-----------------|-----------------------|-----------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Maybach | Maybach 57 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | S Series | 01/2021-12/2024 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 01/2021-12/2024 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Mazda | B Series LCV | 05/2011-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | B-Hatch Xev | 09/2020-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | BT Pickup | 05/2011-12/2019 | 433MHz | J26E | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | BT-50 | 01/2012-12/2020 | 433MHz | J26E | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mazda | CX-3 | 08/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-3 | 08/2014-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-3 | 01/2020-12/2023 | 433MHz BDEL37140 | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-30 | 07/2021-12/2024 | 433MHz BDMC37140 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-30 | 01/2019-12/2024 | 433MHz BDEL37140 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 11/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 11/2011-12/2023 | 433MHz | J53C/J72A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 06/2017-12/2024 | 433MHz BDMC37140 | J53C/J72A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-60 | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-7 | 01/2009-12/2018 | 433MHz | J31H | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-9 | 03/2020-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2016-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-9 | 01/2013-12/2019 | 433MHz | J50C | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-9 | 10/2006-12/2012 | 433MHz | J50C | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-30 | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-5 | 03/2010-12/2024 | 433MHz | NC/J04C/J12 A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-5 | 03/2015-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 2 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| Mazda | Mazda 2 | 01/2015-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 2 | 12/2009-06/2021 | 433MHz | DY/DE/DJ/ J03/J64F | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 12/2007-12/2008 | 433MHz | DY/DE/DJ/ J03/J64F | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 06/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 06/2014-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 06/2009-05/2014 | 433MHz | BL/BM | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2011-12/2018 | 433MHz | J74G | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2010-12/2010 | 433MHz | J74G | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2011-12/2024 | 433MHz | GH/GJ/J61A/ J71E | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2008-12/2010 | 433MHz | GH/GJ | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2022-12/2023 | 433MHz BDMC37140 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|---------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | Mazda 6 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Premacy | 03/2014-12/2018 | 433MHz | J54L | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| McLaren | 500 Series | 01/2015-12/2022 | 433MHz RDE011 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 500 Series | 01/2015-12/2024 | 433MHz RDE018 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 01/2014-12/2024 | 433MHz F11001648001 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 03/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 04/2014-12/2015 | 315MHz F11001223002 | | ○ | ● | ○ | NA | 315MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 01/2017-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Artura | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| McLaren | Elva | 01/2020-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | GT | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 01/2011-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 01/2013-12/2015 | 433MHz 11B0015CP.01 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2020-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Speedtail | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Sports Series | 01/2015-06/2022 | 433MHz F11001648001 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Sports Series | 01/2015-06/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Super Series | 01/2017-12/2023 | 433MHz F11001648001 | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| McLaren | Super Series | 03/2011-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 06/2018-12/2024 | 433MHz | 177 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 04/2014-05/2018 | 433MHz | 176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 01/2012-03/2014 | 433MHz | 176 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG | 01/2010-12/2020 | 433MHz | W197 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG | 07/1999-03/2002 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | AMG GT | 06/2023-12/2024 | 433MHz A0009058413 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 06/2023-12/2024 | 433MHz A0009058706 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 08/2019-12/2021 | 433MHz | C190 (A0009053907) | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-12/2023 | 433MHz | 290 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 01/2014-12/2023 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 02/2019-12/2024 | 433MHz A0009054104 | 247 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 11/2011-01/2019 | 433MHz | 246 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 01/2000-12/2006 | 433MHz | W203 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | C Class | 04/2007-12/2020 | 433MHz | W205 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 09/2022-12/2024 | 433MHz A0009058413 | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 06/2021-12/2024 | 433MHz | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | C Class | 06/2018-12/2023 | 433MHz A0009053907 | C205 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 01/2010-12/2015 | 433MHz | 216 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 07/2006-06/2019 | 433MHz A0009054100 | 216 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CL Class | 01/1998-12/2006 | 433MHz | 215 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 01/2006-06/2015 | 433MHz Continental | 216 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | CLA Class | 12/2012-05/2014 | 433MHz | 117 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 06/2014-04/2019 | 433MHz | 117 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 05/2019-12/2024 | 433MHz | 118 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLC Class | 01/2008-06/2018 | 433MHz | 216 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 01/2022-12/2024 | 433MHz | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 06/2023-12/2024 | 433MHz A0009058413 | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 01/2002-06/2018 | 433MHz | 209 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2011-12/2017 | 433MHz A0009050030 | 218 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 07/2009-12/2017 | 433MHz | 218 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 10/2004-12/2004 | 433MHz A0055422318 | 219 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 09/2004-12/2011 | 433MHz A0025408017 | 219 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | CLS Class | 01/2018-12/2024 | 433MHz | 257 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Citan | 01/2012-12/2023 | 433MHz | 415 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | Citan | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | Citan | 09/2021-12/2022 | 433MHz A4204012400 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mercedes | E Class | 07/2009-05/2014 | 433MHz | W212/C207 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 06/2005-10/2011 | 433MHz | W211 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | E Class | 01/2002-05/2005 | 433MHz | W211 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 10/2023-12/2024 | 433MHz A0009058413 | 214 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 11/2015-12/2023 | 433MHz | W213/BR238 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 06/2014-12/2018 | 433MHz | W212 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 01/2014-10/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercedes | E Class AMG | 01/1999-12/2002 | 433MHz | W210 | ● | ● | ○ | 0/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQA | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQC | 01/2019-12/2024 | 433MHz | 293 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 09/2022-12/2024 | 433MHz A0009058413 | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 01/2022-12/2024 | 433MHz | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQG | 06/2024-12/2024 | 433MHz A0009054104 | 465 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQS | 01/2021-12/2024 | 433MHz | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 09/2022-12/2024 | 433MHz A0009058413 | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQV | 01/2020-12/2022 | 433MHz | 447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-12/2024 | 433MHz | 463 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | G Class | 06/2024-12/2024 | 433MHz A0009054104 | 465 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | G Class | 06/2018-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 05/2007-06/2009 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mercedes | G Class | 04/2007-05/2018 | 433MHz | G463/461 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 04/2006-09/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 01/2013-06/2019 | 433MHz | X166 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 06/2009-12/2012 | 433MHz | X164 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 01/2020-12/2024 | 433MHz | H247 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 12/2013-06/2020 | 433MHz | X156 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLB Class | 01/2019-12/2024 | 433MHz | 247 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 09/2016-12/2022 | 433MHz A0009053907 | C253 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 06/2022-12/2024 | 433MHz | 254 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 09/2022-12/2024 | 433MHz A0009058413 | 254 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 01/2015-07/2019 | 433MHz | X253 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 10/2018-12/2023 | 433MHz | V167 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 04/2015-11/2019 | 433MHz | X166/C292 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 10/2015-06/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 01/2008-09/2015 | 433MHz | X204 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 07/2019-12/2024 | 433MHz | X167 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLS Class | 01/2013-06/2019 | 433MHz | X166 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT | 09/2018-06/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT | 01/2014-12/2022 | 433MHz | GT | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2014-12/2019 | 433MHz | C190 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2005-05/2011 | 433MHz | W164 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | M Class | 01/2010-12/2014 | 433MHz | W166 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 08/2009-05/2011 | 433MHz | W164 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 06/2011-12/2019 | 433MHz | W166 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 12/2004-07/2009 | 433MHz | W164 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Marco Polo | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Metris | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 06/2005-12/2014 | 433MHz Continental | W251 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | R Class | 08/2009-06/2018 | 433MHz | W251 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 09/2022-12/2024 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 06/2021-12/2024 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 07/2020-06/2021 | 433MHz | C217 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 06/2009-12/2020 | 433MHz | W222/C217 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 10/2005-05/2009 | 433MHz | W221 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 07/1999-09/2005 | 433MHz | W220 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 01/2013-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class coupe | 07/1999-12/2002 | 433MHz | C215 | ● | ● | ○ | 0/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class coupe | 01/2003-09/2005 | 433MHz | C215 | ● | ● | ○ | 0/S | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 09/2021-12/2024 | 433MHz A0009058413 | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | SL Class | 01/2012-12/2020 | 433MHz | W231 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 01/2005-06/2012 | 433MHz | W230 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | SL Class | 09/2021-12/2024 | 433MHz | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Roadster | 08/2001-06/2005 | 433MHz | R230 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLC Class | 01/2016-06/2020 | 433MHz | R172 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 07/2020-12/2021 | 433MHz | R172 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 05/2004-11/2009 | 433MHz | 171 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | SLK Class | 01/2004-12/2021 | 433MHz | R171, R172 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLR Class | 04/2004-12/2015 | 433MHz | R199 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2011 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 01/2010-06/2019 | 433MHz | 197 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 11/2011-06/2020 | 433MHz | 906 (NVC3) | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2018-12/2024 | 433MHz A0009054104 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter | 01/2006-12/2014 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter | 06/2006-10/2011 | 433MHz | W906 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Sprinter Combi | 10/2018-06/2021 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter Combi | 11/2011-09/2018 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter Combi | 01/2006-10/2011 | 433MHz | 906 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | T Class | 08/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mercedes | V Class | 01/2014-12/2024 | 433MHz | W447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vario | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vario | 01/2012-12/2013 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Mercedes | Viano | 01/2015-12/2022 | 433MHz A0025409517 | W447 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mercedes | Viano | 07/2003-05/2014 | 433MHz A0025409517 | W639 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Viano | 06/2014-12/2021 | 433MHz A4479050500 | W639 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Vito | 10/2014-12/2020 | 433MHz | VS20 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | Vito | 05/2003-06/2014 | 433MHz | W639 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | Vito | 07/2014-12/2024 | 433MHz | W447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | X Class | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Mini | Cabrio | 12/2008-06/2014 | 433MHz 36106856227 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 07/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 11/2015-06/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 08/2007-12/2016 | 433MHz 36236781847 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 01/2007-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Clubman | 10/2006-06/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 07/2015-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 07/2014-12/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubvan | 01/2012-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Clubvan | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mini | Clubvan | 07/2012-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2015-12/2023 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Convertible | 01/2009-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Convertible | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 07/2014-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 01/2010-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Countryman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2015-06/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Coupe | 07/2014-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 01/2012-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Coupe | 07/2011-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 03/2006-06/2024 | 433MHz Continental | F55/F56/R56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 01/2009-12/2015 | 433MHz OYGTSSRE4D | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 07/2014-06/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Paceman | 01/2012-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Paceman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 01/2011-12/2014 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 01/2012-12/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Roadster | 05/2014-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mitsubishi | ASX | 01/2014-12/2023 | 433MHz | GA0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | ASX | 03/2018-03/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Attrage | 08/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Attrage | 09/2014-08/2021 | 433MHz | A10 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Colt Plus | 07/2016-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Delica | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Mitsubishi | Eclipse Cross | 10/2017-06/2022 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 01/2018-12/2018 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross PHEV | 12/2021-12/2024 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross PHEV | 12/2020-11/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Galant | 01/2003-12/2006 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | L200 | 01/2014-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | L200 | 01/2014-12/2024 | 433MHz | KA0T/KJ0T | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 01/2014-12/2020 | 433MHz | CY0 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer Sportback | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 08/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|----------------|-----------------|-----------------------|------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | Mirage | 01/2014-12/2023 | 433MHz | A00 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 08/2021-12/2024 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 09/2019-08/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero | 01/2014-12/2021 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 11/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 05/2021-06/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 01/2014-12/2024 | 433MHz 4250C477 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 12/2020-12/2024 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 09/2021-12/2024 | 433MHz 4250G123 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 03/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 04/2014-02/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 01/2022-12/2023 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 11/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 01/2016-12/2022 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 11/2022-12/2024 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 10/2016-10/2022 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Shogun | 01/2014-12/2020 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Shogun Sport | 01/2018-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mitsubishi | Space Star | 01/2014-12/2020 | 433MHz | A00 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Space Star | 08/2021-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Strada | 12/2016-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Triton | 08/2014-12/2024 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Xpander | 09/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 06/2009-12/2022 | 433MHz | HA0/HAV/HA3 W | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| NETA | GT | 04/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| NETA | L | 04/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| NETA | S | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Softec | ● | ● |
| NETA | U | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| NETA | U | 03/2020-12/2024 | 433MHz S003114010 | | ● | ● | ○ | 0 | 433MHz | Softec | ● | ● |
| NETA | X | 10/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| NIO | EC6 | 01/2020-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| NIO | EC7 | 12/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| NIO | ES6 | 01/2020-12/2024 | 433MHz A2C82481801 | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| NIO | ES6 | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| NIO | ES7 | 06/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| NIO | ES8 | 01/2018-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| NIO | ET5 | 12/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| NIO | ET7 | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Nissan | 370Z | 09/2014-06/2022 | 433MHz 407006WYOB | | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| Nissan | 370Z | 07/2011-09/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | 370Z | 10/2009-06/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | 370Z | 10/2020-09/2022 | 433MHz 407006GNOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Almera | 01/2013-01/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 11/2018-06/2020 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 06/2012-10/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Ariya | 02/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Armada | 01/2004-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Armada | 08/2012-12/2018 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Atleon | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | B-EV | 01/2014-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Cabstar | 06/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Cube | 01/2008-09/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Cube | 10/2014-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | E-NV200 | 02/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | E-NV200 | 01/2017-12/2022 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | E-NV200 | 05/2014-01/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Nissan | Evalia | 01/2012-09/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Frontier | 01/2005-12/2014 | 433MHz 40700JY00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Frontier | 10/2002-08/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Frontier | 09/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | GT-R | 12/2008-05/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 06/2011-04/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 05/2020-03/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 09/2022-12/2024 | 433MHz 407006GP1A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 11/2013-08/2022 | 433MHz 4070062B0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 11/2013-12/2023 | 433MHz 407006WY0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Interstar | 02/2024-12/2024 | 433MHz 4070000Q0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Interstar | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Interstar | 06/2014-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Juke | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Nissan | Juke | 05/2014-09/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 10/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Kicks | 11/2016-03/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Kicks | 09/2019-12/2024 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Kubistar | 01/2003-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Nissan | Leaf | 02/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 01/2018-01/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 01/2017-09/2018 | 433MHz 407005ZH0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Leaf | 11/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 05/2014-02/2016 | 433MHz 407006WY0B | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Livina | 04/2016-02/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Livina | 03/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Magnite | 02/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | March | 04/2016-12/2020 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | March | 04/2016-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Maxima | 08/2012-03/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Maxima | 11/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Maxima | 04/2015-12/2018 | 433MHz 407003JA0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 03/2017-12/2024 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 06/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Murano | 01/2015-06/2021 | 433MHz 407006WY0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Murano | 01/2004-12/2015 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Murano | 01/2004-09/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Murano | 10/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 11/2018-12/2023 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NP300 | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NP300 | 01/2008-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NP300 Navara | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NP300 Navara | 01/2017-10/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NT500 | 03/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NV200 | 01/2016-06/2017 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Nissan | NV200 | 09/2009-12/2021 | 433MHz 407004CB0B | | ● | ● | ○ | O/S | 433MHz | Continental | ● | ● |
| Nissan | NV200 | 09/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV200 | 02/2014-08/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV250 | 01/2019-03/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NV300 | 09/2014-12/2022 | 433MHz 407001628R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NV300 | 03/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NV300 | 06/2021-12/2023 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | NV350 | 02/2017-10/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV400 | 01/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NV400 Combi | 03/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Navara | 10/2004-05/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Navara | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Navara | 06/2016-10/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Note | 08/2013-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2004-12/2013 | 433MHz 40700JY00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2004-08/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 09/2012-02/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 08/2018-06/2021 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Patrol | 11/2015-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 01/2010-06/2016 | 433MHz 407001LLOD | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 01/2019-12/2019 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Pixo | 01/2009-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Primastar | 01/2021-12/2024 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Primastar | 03/2022-12/2024 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Primastar | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Primera | 01/2002-12/2009 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Pulsar | 01/2014-12/2018 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pulsar | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 05/2021-12/2024 | 433MHz 40700E1B6A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 11/2016-12/2021 | 433MHz 407004CB0B | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 05/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 12/2013-07/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 08/2018-09/2019 | 433MHz 4070000Q0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 10/2015-12/2020 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 10/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 10/2019-12/2024 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Sentra | 01/2013-12/2022 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 04/2016-09/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Sentra | 01/2016-07/2016 | 433MHz 407003AR1A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sunny | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sylphy | 05/2019-12/2022 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Sylphy | 07/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sylphy | 10/2017-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sylphy | 12/2015-09/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | TERRANO | 01/2021-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Nissan | TERRANO | 06/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Teana | 01/2014-12/2019 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Teana | 02/2013-04/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Teana | 01/2018-12/2020 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Teana | 04/2016-12/2022 | 433MHz 407006WY0B | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Terra | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Tiida | 11/2017-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Tiida | 01/2016-10/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Tiida | 07/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Nissan | Tiida | 07/2020-06/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Tiida | 04/2016-09/2019 | 433MHz 407005ZH0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Tiida | 10/2019-12/2024 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 10/2003-08/2004 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Townstar | 02/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Terra | 05/2018-06/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | X-Trail | 02/2014-04/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 05/2017-04/2022 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 06/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Z | 01/2022-12/2023 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Z | 05/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Opel/Vauxhall | Adam | 01/2013-07/2014 | 433MHz | GM 4403 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam | 08/2014-11/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam | 08/2014-11/2019 | 433MHz S/Rocks | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera | 01/2015-12/2019 | 433MHz | D2JCI | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera | 09/2011-04/2016 | 433MHz | D1JOI | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Ampera-e | 01/2017-12/2021 | 433MHz | G2KCZ | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2016-12/2020 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2006-10/2010 | 433MHz | C105 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 11/2010-05/2014 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 06/2014-12/2015 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra H | 01/2004-10/2009 | 433MHz 13354312 | GM A3300 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra H | 01/2004-10/2009 | 433MHz 13172567 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 06/2014-08/2015 | 433MHz 13598787 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 06/2014-08/2015 | 433MHz 13581560 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 10/2011-05/2014 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 11/2009-09/2011 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra K | 08/2019-07/2022 | 433MHz | | ● | ● | ● | 0/S/A | 433MHz | Huf | ● | ● |
| Opel/Vauxhall | Astra K | 09/2015-07/2019 | 433MHz | D2J0 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|--------------|-----------------|--------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Astra Van | 08/2019-03/2022 | 433MHz | | ● | ● | ● | O/S/A | 433MHz | Huf | ● | ● |
| Opel/Vauxhall | Astra Van | 06/2014-06/2016 | 433MHz | D2J0/ GM P3400 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 07/2004-05/2014 | 433MHz | GM A3300 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra Van | 07/2016-07/2019 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cabrio | 06/2014-12/2019 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cabrio | 01/2013-05/2014 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 01/2013-05/2014 | 433MHz | D1A0 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 06/2014-12/2020 | 433MHz | D1A0 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Combo | 01/2012-07/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Combo Life | 08/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Combo Life | 11/2011-07/2018 | 433MHz 16 inch | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Combo Life | 11/2011-07/2018 | 433MHz 15 inch | 263 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2006-12/2014 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Corsa | 05/2006-05/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 06/2014-11/2014 | 433MHz | GM S4400 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 12/2014-12/2019 | 433MHz 13581560 | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2020-12/2024 | Indirect | F/Mk5 | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Corsa | 12/2014-12/2019 | 433MHz 13581561 | C0145 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Van | 11/2014-12/2019 | 433MHz 13581560 | C0145 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Van | 11/2014-12/2019 | 433MHz 13581561 | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Van | 06/2014-10/2014 | 433MHz | GM S4400 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa Van | 05/2006-05/2014 | 433MHz | GM 4530 | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Crossland | 01/2017-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Equinox | 01/2011-12/2019 | 433MHz | D2UC | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | GTC | 10/2015-06/2021 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Grandland | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Insignia | 10/2015-02/2017 | 433MHz | GM G3700 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 05/2014-09/2015 | 433MHz | GM G3700 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 09/2011-04/2014 | 433MHz | GM G3700 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 03/2017-07/2019 | 433MHz | | ● | ● | ● | O/S/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 01/2008-08/2011 | 433MHz | GM G3700 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 08/2019-08/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf | ● | ● |
| Opel/Vauxhall | Karl | 01/2015-06/2021 | 433MHz | M2J0 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Maloo | 06/2016-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Maloo R8 LSA | 01/2014-12/2018 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Meriva | 04/2010-12/2018 | 433MHz 13581561 | GM S4470 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Meriva | 04/2010-12/2018 | 433MHz 13581562 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 07/2012-08/2015 | 433MHz | G1U0 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 09/2015-12/2019 | 433MHz | G1U0 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka X | 09/2015-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|---------------|-----------------|----------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Movano | 06/2010-08/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Movano | 03/2022-12/2024 | 433MHz X2/50 | X2/50 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Movano | 03/2010-02/2022 | 433MHz 407009322R | X62 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Movano Combi | 06/2009-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Movano Combi | 03/2022-12/2024 | 433MHz X2/50 | X2/50 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Opel/Vauxhall | Movano Combi | 03/2010-02/2022 | 433MHz 407009322R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Signum | 01/2002-12/2011 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | VXR8 | 01/2008-12/2019 | 433MHz | Z2 | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra | 01/2002-10/2012 | 433MHz | 0e86/ GM Z3200 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vectra Estate | 06/2002-06/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Viva | 01/2015-12/2020 | 433MHz | M2J0 | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro | 01/2015-06/2024 | 433MHz | X82/X83 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro | 01/2014-12/2014 | 433MHz | X82/X83 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro Combi | 10/2014-06/2024 | 433MHz 407009322R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro Combi | 07/2019-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Vivaro Combi | 07/2019-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira | 05/2005-06/2011 | 433MHz 13172567 | GM A3370 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira | 05/2005-06/2011 | 433MHz 13354312 | B | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira | 02/2015-09/2019 | 433MHz | B | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira | 07/2011-01/2015 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira Life | 01/2019-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Zafira Tourer | 06/2014-01/2020 | 433MHz | C/ GM P3470 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Zafira Tourer | 11/2011-05/2014 | 433MHz | C/ GM P3470 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Pagani | Huayra | 01/2011-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Pagani | Zonda | 01/2011-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Peugeot | 1007 | 01/2004-12/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 107 | 03/2005-07/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 107 Van | 03/2005-07/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 01/2014-12/2022 | 433MHz | B3 | ● | ● | ○ | 0/S | 433MHz | Pacific | ● | ● |
| Peugeot | 108 Van | 01/2014-12/2022 | 433MHz | B3 | ● | ● | ○ | 0/S | 433MHz | Pacific | ● | ● |
| Peugeot | 2008 | 02/2013-04/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 2008 | 05/2014-12/2021 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Peugeot | 2008 | 02/2013-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 207 | 10/2013-12/2016 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 207 | 11/2005-09/2013 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 207 Van | 11/2005-09/2014 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 208 | 01/2012-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 208 | 01/2012-12/2019 | 433MHz | A9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 09/2013-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 11/2008-08/2013 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Peugeot | 3008 | 06/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 301 | 01/2012-12/2022 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Peugeot | 307 | 03/2007-12/2008 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 307 | 01/2001-02/2007 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 308 | 06/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 01/2020-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 308 | 05/2007-05/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 4008 | 04/2012-01/2018 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Peugeot | 407 | 01/2003-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 408 | 07/2012-03/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 5008 | 09/2013-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 09/2009-08/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 10/2013-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 09/2010-09/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 508 | 07/2017-12/2024 | Indirect | R83 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 607 | 09/1999-09/2004 | 433MHz | 6042/Z8 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 607 | 10/2004-12/2012 | 433MHz | Z8 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 807 | 02/2002-09/2004 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 807 | 10/2004-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | Bipper | 12/2007-09/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Bipper | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Bipper Tepee | 10/2007-09/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 12/2013-12/2022 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer | 02/2006-11/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 01/2023-12/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Peugeot | Boxer | 01/2006-11/2013 | 433MHz 1612474480 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer Combi | 01/2023-12/2024 | 433MHz | X2/50 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Peugeot | Boxer Combi | 01/2006-11/2013 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer Combi | 12/2013-12/2022 | 433MHz | X2/50 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer Combi | 02/2006-11/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Expert | 10/2006-12/2013 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 03/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Expert | 01/2014-02/2016 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert Tepee | 06/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Expert Tepee | 10/2006-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert Tepee | 06/2014-05/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | ION | 12/2010-06/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Peugeot | KP1 | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Landtrek | 01/2019-12/2024 | 433MHz | KP1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 01/2008-05/2014 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 07/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Partner | 06/2014-06/2018 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner Tepee | 06/2014-09/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner Tepee | 01/2008-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|----------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Peugeot | Partner Tepee | 10/2019-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | RCZ | 10/2013-06/2017 | 433MHz | T75 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 12/2009-09/2013 | 433MHz | T75 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Peugeot | Rifter | 07/2018-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Traveller | 03/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Polestar | Polestar 1 | 07/2018-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Polestar | Polestar 2 | 07/2020-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Polestar | Polestar 4 | 11/2023-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Porsche | 718(982) | 01/2016-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 07/2004-01/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 01/2011-12/2016 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(991) | 01/2017-12/2020 | 433MHz | 991 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(992) | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(997) | 01/2004-06/2008 | 433MHz OYGTSSRE4B | 997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(997) | 09/2015-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(997) | 04/2008-08/2015 | 433MHz | 997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(Turbo) | 01/2007-12/2009 | 433MHz | 997T | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(Turbo) | 01/2017-12/2021 | 433MHz | 991T/992T | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911(Turbo) | 01/2010-12/2016 | 433MHz | 991T | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 03/2012-06/2018 | 433MHz | 918 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2004-12/2008 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2012-12/2016 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2013 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 03/2016-12/2024 | 433MHz | 982/982SP | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2017-12/2024 | 315MHz | 982/982SP | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 01/2003-12/2011 | 433MHz | GT | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 12/2006-12/2010 | 433MHz | 9PA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2011-07/2014 | 433MHz | 92A | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 09/2017-12/2023 | 433MHz | 9YA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 08/2014-08/2017 | 433MHz | 92A | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 433MHz | 9PA | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 433MHz 7L0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 09/2017-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 06/2014-08/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2015 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2017-12/2024 | 315MHz | CT4-2 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 04/2013-12/2016 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 10/2016-12/2024 | 433MHz | 982/982C/CT4-2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 05/2014-12/2016 | 433MHz GTS | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2009 | 433MHz | 987/987C | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Porsche | GT3 | 01/2010-12/2016 | 433MHz | 997 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 03/2006-12/2011 | 433MHz | 996 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 07/2013-12/2023 | 433MHz | P0416/95B | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Mission E | 01/2019-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2009-08/2013 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2021-12/2022 | 433MHz | 971-2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2017-12/2023 | 433MHz | 970/971 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2013-08/2017 | 433MHz | 970 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2009-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2019-12/2023 | 433MHz 9J1907275 | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 11/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| QOROS | 2 | 01/2016-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| QOROS | 3 | 01/2014-12/2022 | 433MHz J523114013 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| QOROS | 3 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| QOROS | 5 | 01/2016-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | AUSTRAL | 01/2020-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Alaskan | 01/2017-12/2023 | 433MHz 40700EZ00A | | ○ | ● | ○ | NA | 433MHz | Pacific | ● | ● |
| Renault | Alpine A110 | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Alpine A110 | 01/2018-12/2022 | 433MHz 407003VU0A | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Arkana | 04/2021-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Arkana | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Arkana | 01/2019-12/2021 | 433MHz 407001628R | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Renault | Arkana E-TECH | 01/2024-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Austral E-TECH | 07/2022-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Avantime | 01/2001-12/2003 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Captur | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Captur | 01/2013-12/2019 | 433MHz | J87 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Captur | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Clio E-TECH | 06/2023-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Clio III | 04/2008-05/2014 | 433MHz | X85 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 01/2012-12/2018 | 433MHz | X85/X98 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 06/2014-06/2016 | 433MHz 407005642R | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Clio IV | 03/2022-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Clio IV | 01/2012-12/2014 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Clio V | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Dokker | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Dokker Stepway | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Dokker Stepway | 01/2014-12/2018 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Duster I | 12/2018-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Duster II | 01/2018-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Espace IV | 01/2002-02/2015 | 433MHz | J81 | ● | ● | ● | O | 433MHz | Schrader | ● | ● |
| Renault | Espace V | 01/2015-12/2023 | 433MHz | JFC | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Espace V | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Express | 05/2019-06/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Express | 01/2021-12/2023 | 433MHz 407009322R | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Fluence | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Fluence | 01/2009-06/2021 | 433MHz | L38 | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Initiale Paris | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | K-Ze | 01/2019-06/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | KOLEOS II/QM6 | 06/2016-12/2022 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Kadjar | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Kadjar | 05/2021-12/2023 | 433MHz 407006UA0A | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Kangoo | 10/2007-01/2021 | 433MHz | X61 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Kangoo II | 06/2017-12/2019 | 433MHz 407005642R | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Kangoo II | 01/2014-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Kangoo III | 01/2020-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Kangoo Passenger | 03/2021-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Kangoo Passenger | 10/2007-03/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Kangoo Van | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Kangoo Z. E. | 01/2017-12/2020 | 433MHz | XFG | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Kaptur | 01/2016-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Kiger | 12/2021-06/2024 | 433MHz 407005642R | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Kiger | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2010-12/2024 | 433MHz 407001AY0A | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 06/2010-12/2024 | 315MHz 40700JA00C | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2012-12/2013 | 315MHz 407001AA0D | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2013-07/2016 | 433MHz 407003VU0A | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Koleos | 06/2013-12/2024 | 433MHz 407005663R | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Koleos | 06/2010-05/2012 | 315MHz 407001AA0B | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2008-12/2013 | 433MHz | H45 | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |
| Renault | Kwid | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Renault | Laguna Grandtour | 06/2007-12/2016 | 433MHz | | ● | ● | ○ | O | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Laguna I | 01/1998-12/2001 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Laguna II | 12/2000-03/2010 | 433MHz | X74 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna III | 01/2007-12/2016 | 433MHz | X91 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Laguna III | 01/2009-12/2016 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Latitude | 05/2009-12/2017 | 433MHz | L43 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Latitude | 01/2016-06/2018 | 433MHz | LFD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Lodgy | 01/2012-12/2022 | SD 433MHz | J92 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Renault | Lodgy | 01/2022-12/2023 | 433MHz 407004CB0B | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Lodgy | 06/2014-12/2023 | 433MHz 407005642R | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Logan Stepway | 01/2014-12/2017 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Logan Stepway | 01/2018-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Master | 01/2014-08/2022 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Master | 11/2009-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Master | 09/2022-06/2024 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Master III | 03/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Master III | 06/2017-12/2023 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Megane | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane E-TECH | 05/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Megane I | 01/1997-12/2003 | 433MHz | B32/X95/X64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Megane II | 01/2005-12/2009 | 433MHz | B32/X84 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane III | 10/2008-12/2016 | 433MHz | X95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 02/2021-06/2024 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 01/2020-12/2024 | 433MHz 407704CB1B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 02/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 06/2017-06/2024 | 433MHz 407005663R | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Modus | 01/2004-12/2014 | 433MHz | J77 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Oroch Pickup | 01/2015-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Sandero | 10/2012-12/2021 | SD 433MHz | B52 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Renault | Scenic E-TECH | 01/2024-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Scenic I | 01/1997-12/2003 | 433MHz | J64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Scenic II | 01/2003-07/2010 | 433MHz | J95 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic III | 01/2009-12/2018 | 433MHz | J95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic IV | 01/2016-12/2023 | 433MHz | JFA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic RX4 | 01/2001-12/2003 | 433MHz 407002138R | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Spider | 03/2010-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Symbol | 01/2013-12/2023 | 433MHz | L52 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Symbol/Thalia | 01/2019-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Renault | Talisman | 01/2015-12/2023 | 433MHz 407004CB0A | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Renault | Talisman | 01/2015-12/2023 | 433MHz 407000435R | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Talisman | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Trafic | 01/2021-06/2024 | 433MHz 407006UA0A | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Trafic | 01/2014-12/2021 | 433MHz | X82 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Trafic | 03/2022-06/2024 | 433MHz 407004CB0B | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Trafic Passenger | 06/2021-12/2024 | 433MHz 407006UA0A | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Trafic Passenger | 03/2014-05/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Twingo | 03/2022-06/2024 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Twingo | 06/2014-06/2024 | 433MHz | X44 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Twingo | 01/2018-12/2024 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Twingo | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Renault | Vel Satis | 01/2001-12/2009 | 433MHz | X73 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Wind | 06/2010-12/2016 | 433MHz | X33 | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Renault | Zoe | 01/2021-12/2024 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 06/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 04/2018-12/2024 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe E-TECH | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Retrofit | CARMAXP425TX | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | CARMAX | ● | ● |
| Retrofit | E-LEAD | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | Honda-CRV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | ORO W401 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410/W403 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W417 | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W417-A | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W418-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Rivian | EDV | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rivian | R1S | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rivian | R1T | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Roewe | CLEVER | 03/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | Ei5 | 06/2020-12/2024 | 433MHz 10718213 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | IMAX8 | 01/2023-12/2024 | 433MHz 10290600 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | IMAX8 | 01/2023-12/2024 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | IMAX8 | 01/2020-12/2022 | 433MHz 10290600 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | IMAX8 | 01/2020-12/2022 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | RX3 PRO | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | RX5 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | RX5 | 01/2019-06/2020 | 433MHz 10290600 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|------------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Roewe | RX5 | 06/2020-12/2022 | 433MHz 10718213 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | RX5 PLUS | 06/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | RX5 eMAX PHEV | 11/2021-06/2024 | 433MHz 10290600 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | RX5 eMAX PHEV | 11/2021-06/2024 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | RX8 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | eRX5 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | eRX5 | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | ei6 | 06/2020-12/2023 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Roewe | i5 | 06/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Rolls Royce | Black Badge | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Cabrio | 06/2009-12/2011 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Cullinan | 01/2018-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Cullinan | 02/2018-12/2023 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 01/2016-12/2023 | 433MHz | RR6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 04/2014-12/2023 | 433MHz 36106790054 | RR6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 08/2020-06/2024 | 433MHz 36106887147 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Ghost | 01/2020-06/2024 | 433MHz 36106877937 | RR21 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 04/2014-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 12/2009-03/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2017-06/2024 | 433MHz MRXAG5SP4 | RR11/RR02 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Phantom | 01/2012-12/2017 | 433MHz | RR01 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 02/2003-12/2018 | 433MHz OYGTSSRE4TC | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom Drophead Coupe | 01/2007-12/2018 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Spectre | 08/2023-06/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 02/2021-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 05/2013-12/2023 | 433MHz 36106874830 | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 01/2013-12/2022 | 433MHz | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| SGMW | Almaz | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| SGMW | Asta | 09/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Saab | 09-maggio | 01/2006-12/2012 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Saab | 09-maggio | 01/2002-12/2005 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Saab | 09-mar | 09/2002-12/2006 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Saab | 09-mar | 01/2007-12/2015 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2003-09/2006 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2013-12/2014 | 433MHz 12825085 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 06/2009-12/2012 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 10/2006-05/2009 | 433MHz | YS3F | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2013-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Saab | 9-3X | 07/2007-04/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-4X | 01/2011-06/2014 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 10/2009-12/2013 | 433MHz | YS3G | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 11/2006-09/2009 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 07/2002-10/2006 | 433MHz | YE3E | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-7X | 01/2007-12/2011 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Scion | FR-S | 01/2013-12/2016 | 433MHz | | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Scion | TC | 01/2010-12/2014 | 433MHz | | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Scion | TC | 01/2015-12/2018 | 433MHz | 745L | ● | ● | ○ | O | 433MHz | Pacific | ● | ● |
| Seat | Alhambra | 05/2010-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Altea | 01/2010-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Arona | 03/2017-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Ateca | 09/2016-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Exeo | 01/2009-02/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Exeo | 06/2013-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Seat | Ibiza | 01/2010-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Leon | 01/2010-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Mii | 06/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Tarraco | 01/2018-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seat | Toledo | 01/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Seres | AITO M5 | 04/2024-12/2024 | 433MHz 3641050FS01 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Seres | AITO M5 | 01/2022-06/2024 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Seres | AITO M7 | 09/2023-12/2024 | 433MHz 3641050FS01 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Seres | AITO M7 | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Seres | AITO M9 | 12/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Seres | F5 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Seres | SF5 | 04/2021-06/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Seres | SF5 | 01/2020-12/2022 | 433MHz 3641050RA01 | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| Seres | Seres 3 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| Seres | Seres 5 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| Skoda | Citigo | 05/2014-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Citigo | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Citigo | 01/2011-04/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 01/2015-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 10/2013-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Fabia | 01/2013-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Kamiq | 09/2019-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Karoq | 01/2017-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Karoq | 05/2017-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Kodiaq | 01/2016-06/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Kodiaq | 11/2016-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Octavia | 10/2012-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Octavia | 01/2013-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Skoda | Octavia | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Praktik | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Rapid | 05/2015-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Rapid | 01/2012-04/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Rapid | 01/2013-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Roomster | 01/2013-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Roomster | 01/2006-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Scala | 01/2019-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 03/2008-04/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Superb | 01/2013-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skoda | Superb | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Yeti | 06/2009-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Yeti | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Skyworth | ET5 | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Softec | ● | ● |
| Skyworth | EV6 | 04/2022-06/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Softec | ● | ● |
| Skyworth | HT-I | 09/2022-06/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Softec | ● | ● |
| Smart | #1 | 01/2021-12/2023 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Smart | #3 | 01/2023-06/2024 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Smart | EQ Forfour | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | EQ Fortwo | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 01/2005-12/2023 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 01/2004-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 01/2007-02/2014 | 433MHz | A451 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 03/2014-12/2023 | 433MHz | A453 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Soueast | A5 | 11/2018-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Steel Mate | ● | ● |
| Soueast | DX3 | 01/2016-12/2023 | 433MHz 25M01C031 | | ● | ● | ○ | O | 433MHz | TTE | ● | ● |
| Soueast | DX3 | 01/2016-12/2023 | 433MHz 25M01A031 | | ● | ● | ○ | O | 433MHz | Whetron | ● | ● |
| Ssangyong | Actyon | 08/2012-12/2021 | 433MHz QJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Actyon | 07/2018-12/2019 | 433MHz Q200 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Actyon Sport | 10/2012-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | C-CUV | 05/2015-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Chairman | 01/2014-12/2019 | 433MHz 4199034000 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Korando | 11/2010-12/2023 | 433MHz C200 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Korando | 01/2018-12/2023 | 433MHz C300 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Korando | 05/2019-06/2024 | 433MHz 4199037000 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Korando | 01/2023-12/2023 | 433MHz 4199036100 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Ssangyong | Kyron | 01/2010-12/2016 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | LUVi | 01/2015-12/2019 | 433MHz X100 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 01/2016-05/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Musso | 06/2018-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 01/2023-06/2024 | 433MHz 4199036100 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------------|-----------------|-------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Ssangyong | New Actyon | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Nomad | 07/2013-10/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Rexton | 07/2012-12/2017 | 433MHz Y300 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Rexton | 03/2017-12/2023 | 433MHz Y400 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Rexton | 01/2023-12/2023 | 433MHz 4199036100 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Ssangyong | Rodius | 05/2005-12/2021 | 433MHz AJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Tivoli | 05/2014-12/2014 | 433MHz X100 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Tivoli | 01/2015-06/2020 | 433MHz X100 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Tivoli | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Tivoli | 07/2021-06/2024 | 433MHz 4199036100 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Ssangyong | Turismo | 01/2014-12/2022 | 433MHz AJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | XLV | 01/2016-12/2022 | 433MHz | XK | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Subaru | Ascent | 01/2018-12/2024 | 433MHz | HR3 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | BRZ | 01/2014-12/2024 | 433MHz ZC | ZC | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Subaru | C-Concept | 01/2014-06/2018 | 433MHz | VL9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Crosstrek | 01/2018-12/2024 | 433MHz | HR3 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | FORESTER E-BOXER | 09/2019-12/2024 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2019-12/2024 | 433MHz | S5/SK | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2014-12/2018 | 433MHz | SJ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2019-12/2019 | 433MHz | SJ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 09/2016-12/2024 | 433MHz | HR3 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 01/2014-09/2017 | 433MHz | 55A/MF1/ZR1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Justy | 01/2014-12/2020 | 433MHz | D71A | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 01/2014-12/2017 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 05/2017-12/2024 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 01/2018-12/2019 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 01/2015-06/2021 | 433MHz VM | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Levorg | 03/2021-12/2022 | 433MHz | VN | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2018-12/2019 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 12/2017-12/2024 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2014-11/2017 | 433MHz | EZ5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Solterra | 06/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Subaru | Trezia | 01/2014-12/2020 | 433MHz | 217A | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | Tribeca | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | Tribeca | 01/2014-12/2016 | 433MHz | 00X | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2019-12/2023 | 433MHz MRXSHR3 | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2014-12/2018 | 433MHz XK | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | XV | 01/2012-12/2017 | 433MHz | MF1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | XV | 03/2017-12/2023 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 12/2014-02/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | XV E-BOXER | 01/2020-12/2024 | 433MHz | G5 | ● | ● | ○ | A/O | 433MHz | Schrader | ● | ● |
| Suzuki | APV | 01/2014-12/2024 | 433MHz | YC5/YRA | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------------|-----------------|-------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Suzuki | Across | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Suzuki | Alivio | 09/2018-12/2019 | 433MHz | YLA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Alivio | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Hamaton | ● | ● |
| Suzuki | Alivio (Dual fuel) | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | Hamaton | ● | ● |
| Suzuki | Alto | 01/2014-06/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Alto | 06/2014-12/2017 | 433MHz | YC5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Baleno | 01/2016-12/2024 | 433MHz | YR | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | C-SUV | 08/2020-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Pacific | ● | ● |
| Suzuki | C-Wagon | 09/2020-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Pacific | ● | ● |
| Suzuki | Carry Van | 04/2015-12/2018 | 433MHz | YV7 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Celerio | 01/2014-12/2024 | 433MHz | YLA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Celerio | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Ciaz | 01/2015-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Cultus | 09/2014-12/2023 | 433MHz | YLA | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Suzuki | Grand Vitara | 01/2014-12/2024 | 433MHz | YT4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 01/2016-01/2021 | 433MHz | YJ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 02/2021-12/2024 | 433MHz | MF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 01/2014-01/2021 | 433MHz | YR7/YW5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 02/2021-12/2024 | 433MHz | | ● | ● | ○ | A/O | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 01/2009-12/2019 | 433MHz | YW1 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | S-Cross | 09/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | S-Cross | 01/2013-08/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 | 01/2013-12/2023 | 433MHz | YY1, YY3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 01/2013-08/2021 | 433MHz | YAA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 09/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Splash | 09/2013-12/2019 | 433MHz | YV1/YV4/YV5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Super Carry | 06/2019-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Suzuki | Swace | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Suzuki | Swift | 08/2013-01/2021 | 433MHz | YP6/YP7/YS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 02/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift Sport | 01/2017-01/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift Sport | 02/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 09/2013-01/2021 | 433MHz | YFA/YG4/YH4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 02/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara Brezza | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Suzuki | Vitara Hybrid | 01/2020-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara Hybrid | 07/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Wagon R | 09/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown | ● | ● |
| TJFAW | Junpai A50 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | NA | 433MHz | Xiali | ● | ● |
| TJFAW | Junpai A70 | 01/2016-12/2019 | 433MHz FS43XOL2 | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| TJFAW | Junpai A70E | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| TJFAW | Junpai D60 | 10/2014-12/2020 | 433MHz 42621TFA00 | | ● | ● | ○ | S | 433MHz | Xiali | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|---------------|-----------------|--------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| TJFAW | Junpai D60 | 07/2016-12/2017 | 433MHz QY1036 | | ● | ● | ○ | S | 433MHz | Xiali | ● | ● |
| TJFAW | Junpai D60 | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| TJFAW | Junpai D80 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| TRAUM | SEEK5 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | TTE | ● | ● |
| Tata | Aria | 01/2016-12/2017 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Bolt | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | GenX Nano | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Harrier | 01/2018-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Hexa | 01/2017-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Indica | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Indigo | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Nexon | 01/2017-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Safari | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Safari Dicor | 01/2016-12/2017 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Safari Storme | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Sumo Gold | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Tiago | 01/2017-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tata | Tigor | 01/2017-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Xenon XT | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Tata | Zest | 01/2016-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Tesla | Model 3 | 01/2018-12/2021 | 433MHz 107481200B | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model 3 | 01/2021-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model 3 | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 09/2014-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 01/2010-09/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Model S | 01/2021-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model S | 01/2023-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model X | 01/2021-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model X | 10/2014-12/2023 | 433MHz Continental | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model Y | 01/2020-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Roadster | 01/2010-12/2012 | 433MHz Baolong | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Roadster | 01/2008-12/2010 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | 4 Runner | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | 86 | 04/2012-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Allion | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 02/2012-12/2022 | 433MHz | 480L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 01/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 01/2020-12/2024 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Auris | 05/2014-07/2020 | 433MHz | 130A/130L/142L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avalon | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avanza | 08/2022-12/2024 | 433MHz E100 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avanza | 09/2016-12/2024 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------------|-----------------|-------------------|---|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Avensis | 01/2005-12/2005 | 433MHz 107K | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avensis | 10/2008-12/2019 | 433MHz C210 | 312N/445L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aygo | 01/2014-06/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aygo | 01/2016-06/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Aygo X | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 01/2016-12/2024 | 433MHz | 560A | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 10/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2016-12/2024 | 433MHz C215 | 045L | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 10/2016-01/2021 | 433MHz 60010 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2014-12/2017 | 433MHz | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2007-12/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 09/2017-12/2024 | 433MHz 60010 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Coaster | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 10/2007-12/2018 | 433MHz | 366A/140A/150A/681N/079L/140N/340N/252L/150L/466A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2019-12/2024 | 433MHz C215 | 740A | ● | ● | ○ | O/A | 433MHz | Pacific | ● | ● |
| Toyota | Corolla Cross | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla Cross | 01/2022-12/2024 | 433MHz 4260702090 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Dyna | 01/2012-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 05/2006-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 06/2014-12/2023 | 433MHz | 155L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FR-S | 04/2014-06/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Fortuner | 05/2020-03/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Fortuner | 12/2005-12/2023 | 433MHz | 669L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | GR 86 | 03/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | GR Supra | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Toyota | GT86 | 09/2012-12/2023 | 433MHz | E88 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Granvia | 01/2023-12/2024 | 433MHz E100 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Granvia | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Harrier | 11/2021-12/2024 | 433MHz 4260702090 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Harrier | 09/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hiace | 08/2004-12/2022 | 433MHz | 550N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hiace | 06/2014-12/2024 | 433MHz E100 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2014-11/2019 | 433MHz | 397L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander hybrids | 01/2021-12/2022 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hilux | 01/2015-12/2022 | 433MHz | 669L/640A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hilux | 08/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | IQ | 01/2008-12/2016 | 433MHz | 630L/630X | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | IZOA | 05/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | IZOA | 05/2020-12/2024 | 433MHz 4260702090 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------------|-----------------|-------------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | IZOA | 01/2018-05/2021 | 433MHz C215 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Innova | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 11/2016-11/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 01/2020-10/2022 | 433MHz | XU70 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Kluger | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 10/2015-12/2024 | 433MHz | 215L/611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2005-08/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2012-01/2016 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2017-01/2021 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 06/2021-12/2023 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 10/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 01/2009-08/2017 | 433MHz | 611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 08/2016-08/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Levin | 06/2019-12/2024 | 433MHz 4260702090 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Levin | 06/2019-12/2024 | 433MHz | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Matrix | 01/2007-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2015-12/2020 | 433MHz C210 | 470A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2019-12/2024 | 433MHz C215 | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Previa | 01/2007-12/2020 | 433MHz | 085X/085L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 05/2014-12/2019 | 433MHz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius Alpha | 05/2014-08/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius C | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 12/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 09/2016-11/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius V | 05/2015-08/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Proace | 06/2014-12/2023 | 433MHz | G9/K0 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Toyota | Proace | 01/2011-05/2014 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Toyota | Proace II | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Proace II | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Toyota | Proace Verso | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | RAV4 | 01/2012-12/2023 | 433MHz | 410A/XA40/120L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 09/2006-08/2010 | 433MHz 107K | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 11/2005-12/2011 | 433MHz | 120L/XA30 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 11/2005-08/2006 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 04/2021-12/2024 | 433MHz 426076673F | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2018-12/2024 | 433MHz | XA50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 04/2021-12/2024 | 433MHz 4260702090 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Raize | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|------------------------------|--------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Rush | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sequoia | 01/2008-12/2022 | 433MHz | 200L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienna | 06/2010-12/2022 | 433MHz | 500N/500L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienna | 01/2021-12/2024 | 433MHz 426070E040 | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Toyota | Sienta | 01/2014-12/2019 | 433MHz | 433L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Solara | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Supra | 03/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | Tundra | 04/2007-12/2022 | 433MHz | 480A/180L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Urban Cruiser | 06/2007-12/2020 | 433MHz | 260L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Vellfire | 01/2020-05/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Vellfire | 05/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 01/2008-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Verso | 01/2014-12/2023 | 433MHz | 770L/151L/ 595L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Verso-S | 10/2010-12/2017 | 433MHz | 770L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Vios | 08/2022-12/2024 | 433MHz E100 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Vios | 12/2019-12/2022 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Wildlander | 05/2021-12/2024 | 433MHz 4260702090 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 07/2020-12/2024 | 433MHz C215 | 020L/850L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 01/2011-12/2023 | 433MHz C210 | 020L/850L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris (P9) | 01/2007-12/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris Cross | 07/2021-12/2024 | 433MHz | XPB1F | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris GR | 08/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | bZ4X | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Trumpchi | EMK00 | 09/2022-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | EMPOW | 08/2021-06/2024 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Trumpchi | ES9 | 10/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Trumpchi | GA3 S | 01/2015-12/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GA4 | 03/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GA4 | 01/2018-02/2021 | 433MHz | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GA5 | 01/2013-12/2017 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Trumpchi | GA6 | 01/2021-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GA6 | 06/2019-12/2022 | 433MHz 8060004BAD00 00 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GA6 | 12/2014-05/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GA8 | 01/2016-03/2020 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GA8 | 01/2023-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GA8 | 04/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GE3 530 | 09/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GM8/M8 | 01/2018-08/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GM8/M8 | 09/2019-05/2021 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GM8/M8 | 06/2021-12/2024 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------|-----------------|--------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Trumpchi | GM8/M8 | 01/2018-08/2019 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GN8 | 06/2021-12/2023 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Trumpchi | GN8 | 01/2018-12/2022 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 10/2020-02/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 07/2019-09/2020 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 08/2017-06/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 09/2018-06/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 07/2019-12/2022 | 433MHz 8060004BAD0000 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 04/2015-08/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 09/2018-06/2019 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 MAX | 04/2024-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS5 | 10/2018-12/2023 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS5 | 08/2018-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS7 | 08/2017-12/2020 | 433MHz 8060004CAD0000 | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GS7 | 01/2018-12/2018 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS8 | 09/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS8 | 07/2019-08/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GS8 | 07/2019-08/2020 | 433MHz 8060004ARX0000 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS8 | 01/2018-06/2019 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS8 | 01/2016-06/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| VOYAH | Dreamer | 05/2022-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| VOYAH | FREE | 06/2021-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| VOYAH | Zhuiguang | 04/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| VinFast | VF8 | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| VinFast | VF9 | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Volkswagen | Amarok | 11/2009-02/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 03/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 01/2023-12/2024 | 433MHz 2HJ919331G | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Amarok | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Amarok | 01/2023-12/2023 | 433MHz F2GZ1A189B | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Arteon | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 06/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Atlas | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Beetle | 12/2012-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Beetle | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Bora | 01/2005-12/2010 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Volkswagen | CC | 01/2009-12/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | CC | 06/2011-12/2017 | 433MHz | VC17 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2018-06/2023 | 433MHz MQB | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 06/2011-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | CC | 01/2009-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Caddy | 01/2014-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caddy | 12/2003-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | California | 11/2019-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volkswagen | Caravelle | 11/2019-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Caravelle | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Caravelle | 01/2003-12/2018 | 433MHz | VN750 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 03/2018-12/2024 | 433MHz 2N0907275A | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 07/2014-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Crafter | 04/2006-06/2014 | 433MHz | VN830 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 01/2006-12/2016 | 433MHz Continental | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Cross Blue | 04/2016-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | EOS | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | EOS | 02/2006-06/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Golf | 03/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2009-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Golf | 10/2008-02/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Jetta | 07/2010-12/2023 | 433MHz | VW361 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 01/2010-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Magotan | 01/2015-12/2016 | 433MHz 1K0907255B | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Magotan | 01/2008-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Magotan | 01/2016-06/2023 | 433MHz 5Q0907275B | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Magotan | 01/2007-12/2013 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Multivan | 10/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volkswagen | Multivan | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Multivan | 03/2004-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | New Beetle | 02/1998-07/2011 | 433MHz | VW314 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | New Beetle | 01/2006-12/2011 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 08/2011-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Passat | 09/2014-12/2023 | 433MHz | B8 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2005-12/2011 | 433MHz | VW451 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Passat | 01/2010-12/2015 | 433MHz | B6/VW471 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2010-12/2014 | 433MHz | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2015-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 03/2005-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Passat CC | 03/2008-12/2022 | 433MHz 3AA907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat CC | 09/2014-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2007-05/2010 | 433MHz | 3D/VW611 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 12/2001-05/2007 | 433MHz | VW611 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 03/2001-12/2007 | 433MHz | 996 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2010-12/2019 | 433MHz | Vh67 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 01/2009-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Polo | 09/2017-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Santana | 09/2014-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Scirocco | 06/2008-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Scirocco | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Sharan | 01/2008-06/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Sharan | 03/2010-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | T-Cross | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-ROC | 11/2017-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Talagon | 01/2022-12/2024 | 433MHz 30D907251 | | ● | ● | ○ | O | 433MHz | Topsystem | ● | ● |
| Volkswagen | Tayron | 05/2022-12/2024 | 433MHz 30D907251 | | ● | ● | ○ | O | 433MHz | Topsystem | ● | ● |
| Volkswagen | Tayron X | 05/2022-12/2024 | 433MHz 30D907251 | | ● | ● | ○ | O | 433MHz | Topsystem | ● | ● |
| Volkswagen | Teramont | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Teramont | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Teramont X | 07/2022-12/2024 | 433MHz 30D907251 | | ● | ● | ○ | O | 433MHz | Topsystem | ● | ● |
| Volkswagen | Tiguan | 01/2008-02/2010 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2007-12/2015 | 433MHz | B6/VW471 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2016-12/2023 | 433MHz | VW376/5N2 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 06/2020-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2008-04/2011 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Tiguan | 01/2011-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2012-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan L | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Touareg | 02/2002-12/2007 | 433MHz | 7L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2007-07/2014 | 433MHz 7PP907275F | VW526 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2006-12/2009 | 433MHz | VW526 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Touareg | 08/2014-12/2023 | 433MHz | 7P5/7P6108 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 06/2020-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 01/2015-12/2023 | 433MHz | VW378 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran | 07/2010-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Touran L | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touran (LCV) | 07/2010-06/2018 | 433MHz | VW368 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 04/2003-02/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Transporter | 03/2018-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Up! | 08/2011-12/2018 | 433MHz | VW120 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Up! | 11/2014-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Variant | 01/2024-06/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | XL1 | 07/2013-09/2018 | 433MHz | | ● | ● | ○ | C | 433MHz | Huf/Beru | ● | ● |
| Volvo | C30 | 01/2011-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2006-03/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 Electric | 01/2010-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C30 Electric | 01/2011-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C40 | 01/2021-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | C70 | 01/2006-12/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2006-12/2007 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2008-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | EX30 | 06/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Volvo | S40 | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2003-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2003-12/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 07/2000-02/2010 | 433MHz 31329981 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | S60 | 01/2019-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 01/2010-12/2019 | 433MHz 31302096 | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 04/2019-12/2023 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | S60 | 01/2010-12/2019 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 Cross Country | 01/2015-12/2019 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60L | 01/2014-12/2020 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2010-12/2016 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S80 | 01/2007-12/2009 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | S80 | 01/2006-01/2017 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80L | 03/2006-12/2016 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Volvo | S90 | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S90 | 05/2016-12/2023 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | S90L | 01/2017-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 01/2015-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 01/2012-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V40 Cross Country | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 Cross Country | 01/2012-12/2017 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2004-12/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2003-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 01/2019-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 | 11/2017-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V60 | 01/2011-12/2019 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 01/2008-06/2014 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 Cross Country | 01/2019-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 Cross Country | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 Cross Country | 01/2018-12/2020 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V70 | 01/2000-12/2007 | 433MHz 31329981 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | V70 | 01/2007-12/2017 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2007-06/2014 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V90 | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V90 | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 Cross Country | 01/2016-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 Cross Country | 06/2016-06/2022 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC40 | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2008-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2010-06/2014 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2009 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | XC90 | 01/2015-12/2022 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2002-05/2018 | 433MHz 31329981 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 (LCV) | 06/2015-06/2017 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 (LCV) | 06/2015-06/2017 | 433MHz 31329981 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| WeltMeister | EX5 | 06/2018-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| WeltMeister | W6 | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| XPENG | G3 | 09/2021-12/2023 | 433MHz | | ● | ● | ○ | A/O | 433MHz | BHSENS | ● | ● |
| XPENG | G6 | 06/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| XPENG | G9 | 09/2022-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| XPENG | P5 | 09/2021-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| XPENG | P7 | 04/2020-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| XPENG | P7 | 09/2021-12/2024 | 433MHz 8040002DF1 | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| XPENG | X9 | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| ZEEKR | 001 | 02/2024-12/2024 | 433MHz 8894215959 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| ZEEKR | 001 | 01/2021-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| ZEEKR | 007 | 12/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| ZEEKR | 009 | 11/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| ZEEKR | X | 04/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| ZOTYE | Coupa | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Orange | ● | ● |
| ZOTYE | Domy SR7 | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | Domy SR9 | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O | 433MHz | Orange | ● | ● |
| ZOTYE | Domy X5 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Zotye | ● | ● |
| ZOTYE | Domy X7 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Zotye | ● | ● |
| ZOTYE | E Series | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| ZOTYE | Meet5 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | TTE | ● | ● |
| ZOTYE | T Series | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| ZOTYE | T300 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | T500 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Zotye | ● | ● |
| ZOTYE | T600 | 01/2013-12/2021 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| ZOTYE | T600 Coupe | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | T600 NEW | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | T700 | 01/2017-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| ZOTYE | T800 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Dias | ● | ● |
| ZOTYE | Z Series | 01/2016-06/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| ZOTYE | Z360 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | Z560 | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | O | 433MHz | Orange | ● | ● |
| ZOTYE | Z700 | 01/2013-06/2019 | 433MHz | | ● | ● | ○ | O | 433MHz | Schrader | ● | ● |
| ZzNissan | MX5 | 01/2016-12/2018 | 433MHz | | ● | ● | ○ | O | 433MHz | Baolong | ● | ● |
| ZzNissan | MX6 | 07/2015-12/2019 | 433MHz E340020JD020 1 | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| ZzNissan | MX6 | 01/2015-12/2016 | 433MHz QY1036 | | ○ | ● | ○ | NA | 433MHz | Xiali | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| ZzNissan | rich | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown | ● | ● |
| ZzNissan | rich | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | HSAE | ● | ● |
| ZzNissan | rich6 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown | ● | ● |
| ZzNissan | rich6 | 10/2018-12/2022 | 433MHz HSE6150F | | ● | ● | ○ | 0 | 433MHz | HSAE | ● | ● |
| ZzNissan | rich6 | 10/2018-12/2020 | 433MHz HTP1831 | | ● | ● | ○ | 0 | 433MHz | HSAE | ● | ● |
| ZzNissan | rich6 EV | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown | ● | ● |
| ZzNissan | rich7 | 01/2022-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown | ● | ● |