



MX-Sensor_V2.00 Function List For US Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining (Red:New, Yellow: Modify)

Special Declaration:

- 1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.
- 2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Abarth | 124 Spider | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 10/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Abarth | 124 Spider | 09/2016-12/2020 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Acura | CSX | 06/2005-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | ILX | 01/2016-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | ILX | 01/2012-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | ILX | 06/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | ILX | 06/2022-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | Integra | 01/2022-12/2024 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | Integra | 01/2022-12/2024 | 433MHz Snap in | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | MDX | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | MDX | 01/2016-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | MDX | 06/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | MDX | 01/2007-05/2013 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Acura | MDX | 01/2004-12/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | MDX | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | NSX | 06/2016-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | NSX | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | RDX | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | RDX | 01/2016-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | RDX | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Acura | RDX | 01/2021-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | RDX | 01/2019-12/2024 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | RL | 01/2004-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | RL | 01/2009-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | RLX | 01/2016-12/2020 | 315MHz 42753TZ3A51 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | RLX | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | RLX | 01/2016-12/2020 | 315MHz 42753TX4A51 | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Acura | TL | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | TL | 01/2009-10/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Acura | TL | 11/2012-12/2014 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Acura | TLX | 01/2018-12/2021 | 433MHz 42753T6NA01 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | TLX | 01/2020-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Acura | TLX | 01/2014-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Acura | TSX | 01/2007-12/2008 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Acura | TSX | 01/2009-12/2014 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Acura | ZDX | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Acura | ZDX | 01/2009-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Alfa Romeo | 159 | 07/2005-12/2016 | 433MHz | 939 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | 4C | 01/2012-12/2016 | 433MHz | 4C | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 4C | 01/2017-12/2022 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | 8C | 12/2006-12/2010 | 433MHz | 920 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Alfa Romeo | Brera | 01/2005-07/2012 | 433MHz | 939/946 | ● | ● | ○ | A | 433MHz | TRW | ● | ● |
| Alfa Romeo | Castello | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | GTV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulia | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Giulietta | 01/2010-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Alfa Romeo | Kamal | 01/2020-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 08/2013-12/2020 | 433MHz | 955 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Alfa Romeo | MiTo | 01/2008-07/2013 | 433MHz | 955 | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Alfa Romeo | Spider | 01/2006-12/2010 | 433MHz | 939 | ○ | ● | ○ | NA | 433MHz | TRW | ● | ● |
| Alfa Romeo | Stelvio | 01/2019-12/2024 | 433MHz | 949 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 01/2017-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Stelvio | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Tonale | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alfa Romeo | Tonale | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Alpina | B6 | 03/2014-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 01/2006-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B7 | 07/2015-07/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | B7 | 07/2015-07/2022 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | B7 | 03/2014-06/2015 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | B8 | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XB7 | 07/2022-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Alpina | XB7 | 07/2022-06/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Alpina | XB7 | 01/2020-06/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Alpina | XB7 | 01/2020-06/2022 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | XD3 | 08/2017-06/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Alpina | XD4 | 01/2018-06/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Aston Martin | Cygnat | 01/2011-06/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Pacific | ● | ● |
| Aston Martin | DB11 | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Aston Martin | DB11 | 01/2016-12/2023 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DB11 | 01/2016-12/2024 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------|------------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Aston Martin | DB9 | 01/2009-12/2018 | 433MHz | AM803 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DB9 | 01/2005-12/2011 | 433MHz Smartire | | ○ | ● | ○ | NA | 433MHz | Smartire | ● | ● |
| Aston Martin | DB9 | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2007-12/2015 | 433MHz | V12 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBS | 01/2018-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | 433MHz HY53SE360671A A | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBS Superleggera | 01/2018-12/2022 | 433MHz | VH500 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | DBX | 01/2022-12/2024 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | DBX | 10/2018-12/2021 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Aston Martin | One-77 | 01/2011-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 01/2010-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide | 01/2009-12/2019 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2014-12/2016 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Rapide S | 01/2010-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 01/2013-12/2018 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Aston Martin | Vanquish | 01/2005-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2010-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Vantage | 01/2005-12/2011 | 433MHz Smartire | | ○ | ● | ○ | NA | 433MHz | Smartire | ● | ● |
| Aston Martin | Virage | 01/2010-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Aston Martin | Zagato | 01/2011-08/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A3 | 06/2012-12/2023 | 433MHz | 8L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A3 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A3 | 01/2005-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2011-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | A4 | 01/2007-12/2012 | 315MHz Continental | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A4 | 01/2004-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A4 | 01/2001-12/2011 | 433MHz 4F0907275B | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A5 | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | A5 | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A5 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A6 | 01/2011-12/2012 | 433MHz OYGTSSRE4B | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2010-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 05/2004-05/2009 | 433MHz 7PP907275F | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2019-12/2022 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Audi | A6 | 03/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2004-12/2011 | 315MHz 7PP907275G | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2002-12/2005 | 315MHz 4D0907275D | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2019-12/2023 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2000-12/2007 | 433MHz | 4B | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A6 | 01/2002-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A7 | 01/2019-12/2023 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A7 | 03/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2009-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 | 01/2018-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A7 Quattro | 01/2012-12/2016 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | A8 | 01/1999-09/2002 | 433MHz | 4D | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 10/2002-12/2012 | 433MHz | 4E | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 11/2009-10/2017 | 433MHz | 4H/4L | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/1999-12/2009 | 315MHz | 4E/4D | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2010-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | A8 | 01/2003-12/2023 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | A9 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Allroad Quattro | 01/2001-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | Alltrack | 01/2017-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q2 | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q2 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q3 | 01/2015-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q3 | 07/2011-12/2023 | 433MHz | 8U | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q4 | 09/2019-12/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q5 | 01/2008-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | Q5 | 01/2017-12/2023 | 433MHz | 8R | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q5 | 01/2017-12/2019 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Audi | Q7 | 01/2015-12/2023 | 433MHz MLB | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2016-12/2023 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2005-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q7 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | Q7 | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Audi | Q7 | 01/2005-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q8 | 01/2018-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | Q8 | 01/2018-12/2023 | 433MHz | 4M | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | Q9 | 01/2021-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 06/2009-12/2024 | 433MHz 7PP907275F | AU714 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2010-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | R8 | 01/2007-12/2020 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | R8 Race Car | 01/2013-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS Q3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS Q8 | 12/2019-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 06/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS3 | 07/2016-12/2023 | 433MHz | 8V | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 06/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 03/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2015-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS4 | 01/2005-12/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | RS5 | 06/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2018-12/2020 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS5 | 01/2017-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2000-12/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2008-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2000-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2013-12/2018 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS6 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2013-12/2018 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | RS7 | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S3 | 01/2015-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Audi | S4 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S4 | 01/2004-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S4 | 01/2001-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S4 | 01/2002-12/2003 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S4 | 01/2010-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | S5 | 01/2008-12/2014 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Audi | S5 | 01/2018-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S5 | 01/2010-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S6 | 03/2020-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2005-12/2011 | 315MHz 7PP907275G | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2004-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2010-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2002-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S6 | 01/2010-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | S7 | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S7 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-10/2009 | 433MHz | D3 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/1999-09/2002 | 433MHz | D2 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | S8 | 11/2009-12/2018 | 433MHz | D4 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/1999-09/2002 | 315MHz | D2 | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 10/2002-12/2010 | 315MHz | D3 | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2010-12/2017 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | S8 | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Audi | SQ2 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ5 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | SQ5 | 01/2014-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ7 | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | SQ7 | 01/2016-12/2017 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | SQ8 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 02/2014-12/2023 | 433MHz | AU334 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT | 01/2010-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TT | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Audi | TT RS | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 11/2016-06/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | TT RS | 10/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Audi | TTS | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Audi | TTS | 01/2009-12/2009 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Audi | e-tron | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Audi | e-tron GT | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Audi | e-tron GT | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| BAIC MOTOR | BJ40 | 01/2018-12/2024 | 433MHz B00019849 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | BJ40 | 01/2020-12/2024 | 433MHz B00011299 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | BJ40 | 01/2018-12/2022 | 433MHz TP3040002 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | New BJ40 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | U7 | 11/2018-06/2024 | 433MHz A00076481 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | U7 | 11/2018-06/2024 | 433MHz TP3040050 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC MOTOR | X55 II | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | X6 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BAIC MOTOR | X75 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BAIC SENOVA | D50 | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X25 | 01/2018-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X55 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAIC SENOVA | X65 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BAW | 212 T01 | 08/2024-12/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | Unknown Manufacturer | ● | ● |
| BESTUNE | B50 | 01/2011-12/2016 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | B50 | 01/2016-12/2021 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | B50 | 01/2012-12/2016 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | B70 | 06/2014-10/2017 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | B70 | 01/2011-05/2014 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | B70 | 10/2017-12/2019 | 433MHz FS43X0L5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | T33 | 08/2019-12/2023 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | T33 | 08/2019-12/2023 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | T77 | 01/2017-12/2024 | 433MHz 5GA037973A | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BESTUNE | T77 | 01/2018-12/2024 | 433MHz 5GA037973C | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BESTUNE | X40 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | X80 | 01/2013-06/2016 | 433MHz BM133714XA | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| BESTUNE | X80 | 01/2013-06/2016 | 433MHz 5BA037973 | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| BESTUNE | X80 | 07/2016-12/2022 | 433MHz FS43X0L5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BMW | 1 Series | 09/2010-12/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 1 Series | 07/2019-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------|-----------------|--------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BMW | 1 Series | 01/2014-12/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 1 Series | 01/2007-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 11/2012-02/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 03/2014-12/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 2 Series | 11/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 2 Series | 11/2019-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2019-12/2024 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 3 Series | 01/2005-08/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 09/2009-12/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 10/2010-03/2014 | 433MHz | F30/F31/F34 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2019-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/1998-12/2003 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 01/1999-12/2002 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2014-12/2022 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 3 Series | 03/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 3 Series | 03/2019-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 4 Series | 07/2020-12/2024 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 4 Series | 07/2013-12/2021 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | 4 Series | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 07/2020-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 4 Series | 07/2020-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 4 Series | 01/2013-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 07/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 07/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 11/2016-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 5 Series | 11/2016-12/2024 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 5 Series | 05/2003-12/2013 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 03/2014-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 01/1997-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 5 Series | 08/1998-05/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 04/2014-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 01/2011-03/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series | 01/2003-12/2012 | 433MHz | E63/E64 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 6 Series GT | 07/2017-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | 6 Series GT | 07/2017-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 06/2015-12/2022 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| BMW | 7 Series | 07/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/1999-12/2002 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/2002-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 09/2010-02/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 03/2014-05/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 06/2015-12/2022 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 7 Series | 01/2006-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 07/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | 7 Series | 01/1994-12/2001 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | 8 Series | 07/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | 8 Series | 07/2018-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M1 | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M2 | 12/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M2 | 12/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M2 | 11/2014-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M3 | 02/2002-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 11/2020-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M3 | 01/2008-12/2013 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 01/2002-12/2003 | 433MHz 36112360420 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M3 | 11/2020-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M3 | 01/2014-12/2019 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M4 | 10/2014-12/2017 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 07/2021-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M4 | 07/2021-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M4 | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M4 | 03/2014-12/2021 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | M5 | 01/2006-08/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 09/2010-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 04/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M5 | 01/2016-12/2022 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M5 | 01/2017-06/2020 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | M5 | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 06/2011-12/2015 | 433MHz 36106856227 | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| BMW | M6 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M6 | 01/2006-05/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | M7 | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | M8 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | Motorcycle | 01/2010-12/2019 | 433MHz | | ○ | ○ | ○ | | 433MHz | Schrader | Activate Only | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| BMW | X1 | 11/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X1 | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 08/2015-12/2023 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X1 | 09/2008-02/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X1 | 03/2014-12/2016 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X2 | 11/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X2 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X2 | 01/2016-12/2023 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X3 | 01/2004-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| BMW | X3 | 03/2003-07/2011 | 433MHz | E83 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 01/2017-12/2024 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X3 | 01/2017-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X3 | 11/2010-03/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X3 | 04/2014-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 01/2014-12/2018 | 433MHz 36106790054 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X4 | 04/2018-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X4 | 04/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X4 | 05/2013-03/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 10/1999-09/2007 | 433MHz | E53 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2006-09/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 10/2010-12/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 01/2015-07/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X5 | 08/2018-03/2023 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X5 | 04/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X5 | 08/2018-03/2023 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X5 | 04/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X6 | 01/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X6 | 01/2008-04/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | X6 | 08/2014-07/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | X6 | 12/2007-09/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 10/2010-07/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 08/2019-12/2023 | 315MHz Schrader | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X6 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X6 | 08/2019-12/2023 | 433MHz Schrader | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X7 | 12/2018-07/2022 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | X7 | 12/2018-07/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BMW | X7 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | X7 | 08/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | XM | 12/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | XM | 12/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| BMW | Z4 | 01/2006-02/2014 | 433MHz 36106790054 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 03/2014-12/2016 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 10/2002-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 11/2018-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | Z4 | 11/2018-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | Z8 | 01/2003-12/2006 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i3 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i3 | 01/2013-06/2022 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | i4 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i4 | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i5 | 07/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i5 | 07/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i7 | 07/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | i7 | 07/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | i8 | 01/2013-12/2022 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| BMW | iX | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 11/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX1 | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX2 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| BMW | iX2 | 11/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| BMW | iX3 | 08/2017-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| BMW | iX3 | 08/2017-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BORGWARD | BX6 | 06/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| BYD | ATTO 3 | 02/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | ATTO 3 | 12/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | ATTO 3 | 12/2021-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | BHSENS | ● | ● |
| BYD | DOLPHIN | 12/2022-12/2024 | 433MHz SC3609200H | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | DOLPHIN | 08/2021-06/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | DOLPHIN | 08/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | DOLPHIN | 08/2021-12/2024 | 433MHz SC3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | DOLPHIN | 12/2022-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | BHSENS | ● | ● |
| BYD | Destroyer 05 | 03/2022-12/2024 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Destroyer 05 | 03/2022-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Destroyer 05 | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | E2 | 09/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | E3 | 10/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | F3 | 09/2019-06/2021 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|--------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| BYD | F3 | 01/2020-12/2022 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | F3 | 01/2020-12/2022 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | FangChengBao Bao 5 | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | HAN DM | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | HAN DM-i | 04/2022-12/2024 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | HAN DM-i | 04/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | HAN DM-p | 05/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | HAN DM-p | 05/2023-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | HAN EV | 07/2020-12/2024 | 433MHz SC3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | HAN EV | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | HAN EV | 07/2020-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | HAN EV | 04/2022-12/2024 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | KING DM-i | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | KING DM-i | 03/2022-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | KING DM-i | 03/2022-12/2024 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | QIN L DM-i | 05/2024-06/2025 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | QIN L DM-i | 05/2024-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | QIN PLUS DM-i | 01/2022-12/2024 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | QIN PLUS DM-i | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | QIN PLUS EV | 04/2021-12/2024 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | QIN PLUS EV | 04/2021-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | QIN PLUS EV | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | QIN PLUS EV | 02/2023-12/2024 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | SEAL DM-i | 09/2023-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SEAL DM-i | 09/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | SEAL EV | 07/2022-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | SEAL EV | 07/2022-06/2025 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | SEAL U EV | 07/2022-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | SEAL U EV | 07/2022-06/2025 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SEALION 6 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SEALION 6 | 06/2023-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | SEALION 6 | 06/2023-06/2025 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | SEALION 7 EV | 05/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | SEALION 7 EV | 05/2024-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SONG DM | 04/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SONG DM | 04/2017-08/2018 | 433MHz HA3609200 | | ● | ● | ○ | 0 | 433MHz | BYD | ● | ● |
| BYD | SONG DM | 08/2018-12/2019 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | SONG L DM-i | 07/2024-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | SONG L DM-i | 07/2024-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | SONG L DM-i | 07/2024-06/2025 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SONG L EV | 08/2024-06/2025 | 433MHz SA3HE3609200B | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| BYD | SONG PLUS | 09/2020-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | SONG PLUS DM-i | 06/2023-06/2025 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | SONG PLUS DM-i | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SONG PLUS DM-i | 06/2023-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | SONG PLUS EV | 09/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | SONG PLUS EV | 03/2021-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | SONG PLUS EV | 06/2023-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | SONG PLUS EV | 06/2023-06/2025 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | SONG Pro DM-i | 09/2024-06/2025 | 433MHz SA3HE3609200C | | ○ | ● | ○ | NA | 433MHz | YunLing | ● | ● |
| BYD | Sea Lion 05 DM-i | 09/2024-06/2025 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| BYD | Sea Lion 05 DM-i | 09/2024-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Sea Lion 05 DM-i | 09/2024-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Sea Lion 07 EV | 05/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Sea Lion 07 EV | 05/2024-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | Seal 06 DM-i | 05/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Seal 06 DM-i | 05/2024-12/2024 | 433MHz SA3HE3609200C | | ● | ● | ○ | 0 | 433MHz | YunLing | ● | ● |
| BYD | Seal 06 GT | 10/2024-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Seal 07 DM-i | 08/2024-06/2025 | 433MHz SA3HE3609200B | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | Seal 07 DM-i | 08/2024-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | TANG EV | 01/2018-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | TANG EV | 06/2018-12/2024 | 433MHz SC3609200B | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| BYD | YUAN PLUS | 02/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| BYD | YUAN PLUS | 12/2021-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | BHSENS | ● | ● |
| BYD | YUAN PLUS | 12/2021-12/2024 | 433MHz SC3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | YUAN Pro | 01/2021-12/2024 | 433MHz SA3609200B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| BYD | YUAN Pro | 01/2021-12/2024 | 433MHz S6DM3609200 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| BYD | YangWang U8 | 09/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | YangWang U9 | 02/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| BYD | eMAX 7 | 03/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Bentley | Arnage | 01/2008-09/2011 | 433MHz 7PP907275F | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Arnage | 01/2008-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Azure | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2016-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Bentayga | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands | 01/2008-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Brooklands Coupe | 01/2008-06/2016 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 06/2005-12/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2003-12/2004 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2005-05/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2012-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental | 01/2006-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental Flying Spur | 03/2005-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------------------|-----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Bentley | Continental GT | 09/2003-05/2005 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 01/2010-01/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 04/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 01/2005-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Continental GT | 06/2005-12/2023 | 433MHz BY634 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2006-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Continental GTC | 01/2018-12/2023 | 433MHz 5Q0907275 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2005-12/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2019-12/2024 | 433MHz 5Q0907275 | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2005-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Flying Spur | 01/2011-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | GTC | 07/2006-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2011-12/2020 | 433MHz 95560602100 | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2012-12/2012 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2009-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Bentley | Mulsanne | 01/2001-12/2020 | 433MHz 7PP907275F | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| BrightDrop | Zevo 400 | 01/2022-12/2025 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BrightDrop | Zevo 600 | 01/2022-12/2025 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| BrillianceZhonghua | V3 | 01/2017-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| BrillianceZhonghua | V5 | 01/2012-12/2021 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| BrillianceZhonghua | V6 | 01/2019-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Bugatti | Chiron | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Royale | 01/2016-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2013-12/2015 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Huf/Beru | ● | ● |
| Bugatti | Veyron | 01/2005-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Buick | Allure | 01/2006-12/2007 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Buick | Allure | 01/2006-12/2006 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Allure | 01/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Buick | Allure | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2008-12/2009 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Allure | 01/2011-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Cascada | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Buick | Cascada | 01/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Cascada | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Buick | Century | 01/1999-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Enclave | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 06/2014-12/2016 | 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 09/2013-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 09/2013-12/2015 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2013-08/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave | 01/2009-08/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Enclave | 05/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Buick | Enclave | 01/2018-12/2018 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave I | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave I | 01/2022-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave I | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Enclave I | 01/2025-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Encore | 01/2018-12/2022 | 315MHz 13522628 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2017-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2013-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Encore | 01/2019-12/2025 | 433MHz 13540603 | GX | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Envision | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Buick | Envision | 01/2016-12/2017 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Envision | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Buick | Envision | 01/2023-12/2023 | 433MHz 13549707 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Buick | Envision | 01/2021-12/2023 | 433MHz 13538566 | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| Buick | Envision | 01/2020-12/2020 | 433MHz 13538566 | | ● | ● | ● | 0/S | 433MHz | Baolong | ● | ● |
| Buick | Envision | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Envision | 01/2021-12/2022 | 433MHz 13593957 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Envision | 01/2021-12/2022 | 315MHz 13516164 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Envision | 01/2016-12/2020 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Envista | 01/2024-12/2025 | 433MHz 13538566 | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Buick | Envista | 01/2024-12/2025 | 433MHz 13549707 | | ● | ● | ● | 0 | 433MHz | BHSENS | ● | ● |
| Buick | Envista | 04/2023-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Buick | LaCrosse | 01/2008-12/2008 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | LaCrosse | 01/2008-07/2009 | 315MHz 13898771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Buick | LaCrosse | 01/2009-07/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 08/2009-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2016-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2004-12/2006 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Buick | LaCrosse | 01/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Buick | LeSabre | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Buick | LeSabre | 01/1998-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Lucerne | 01/2009-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Lucerne | 01/2006-12/2006 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Lucerne | 01/2007-12/2007 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Lucerne | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Park Avenue | 01/1997-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Park Avenue | 01/2006-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Park Avenue | 01/2009-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Rainier | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Buick | Rainier | 01/2003-12/2009 | 315MHz Clamp in | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Buick | Rainier | 01/2006-12/2007 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Buick | Regal | 01/2013-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 08/2017-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Buick | Regal | 05/2009-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Regal | 01/1997-12/2004 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Regal | 01/2025-12/2025 | 433MHz 13549707 | | ● | ● | ● | 0/S | 433MHz | BHSENS | ● | ● |
| Buick | Rendezvous | 01/2003-12/2007 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Buick | Verano | 01/2011-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Verano | 01/2016-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Buick | Verano Pro | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Dias | ● | ● |
| CMC | A180 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| CMC | A180 | 01/2019-12/2023 | 433MHz T23030041 | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| CMC | A190 | 07/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| CMC | A190 | 01/2019-12/2023 | 433MHz T23030041 | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| CMC | VERYCA | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| CMC | ZINGER | 07/2016-06/2019 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2020-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2013-12/2014 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | ATS | 01/2013-12/2020 | 315MHz 13581558 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2014-12/2014 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2015 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2017 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2015-12/2020 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-12/2017 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2016-06/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2018-12/2019 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2018-12/2020 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2020-12/2020 | 433MHz 13529770 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Cadillac | ATS | 01/2013-12/2013 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS | 01/2012-12/2012 | 433MHz | A1SL/A1BL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS Sport | 01/2013-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS Sport | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-L | 01/2014-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2018-12/2019 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2013-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2017-12/2017 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2017-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | ATS-V | 01/2018-12/2019 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2025-12/2025 | 433MHz 13556202 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2023 | 433MHz 13593957 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2021-12/2025 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2025 | 433MHz 13530661 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT4 | 01/2020-12/2023 | 433MHz Snap in | | ● | ● | ○ | 0/S/A | 433MHz | Baolong | ● | ● |
| Cadillac | CT4 | 01/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S/A | 433MHz | BHSENS | ● | ● |
| Cadillac | CT4 | 01/2024-12/2024 | 433MHz 13538566 | | ● | ● | ○ | 0/S/A | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------|-----------------|--------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | CT5 | 01/2023-12/2023 | 433MHz 13549707 | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | CT5 | 01/2024-12/2025 | 433MHz 13554170 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2024-12/2025 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2024-12/2025 | 433MHz 13556202 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2024-12/2025 | 433MHz 13538565 | | ● | ● | ○ | 0/S/A | 433MHz | Baolong | ● | ● |
| Cadillac | CT5 | 01/2023-12/2023 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2022-12/2023 | 433MHz Snap in | | ● | ● | ○ | 0/S/A | 433MHz | Baolong | ● | ● |
| Cadillac | CT5 | 01/2020-12/2023 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2020-12/2022 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT5 | 01/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | CT5 | 01/2019-12/2023 | 433MHz 13530661 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2016-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CT6 | 01/2019-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2012 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2010-12/2011 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2015 | 315MHz 13581558 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 10/2007-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2007-09/2007 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2006-12/2007 | 433MHz | GMX322 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2021 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2006-12/2006 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2013-12/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2013-12/2013 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2012-12/2012 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2012-12/2012 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|--------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | CTS | 01/2010-12/2013 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2010-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2019 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2008-12/2008 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2009-12/2009 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2014 | 433MHz | GMX206/ GMX226 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2014-12/2015 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS | 01/2016-12/2019 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2017-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2017-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2014-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V | 01/2009-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V (Sport) | 01/2014-12/2015 | 315MHz 15268606 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V (Sport) | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | CTS-V (Sport) | 01/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Celestiq | 07/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2009-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2007-12/2007 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2006-12/2006 | 315MHz 25920615 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | DTS | 01/2005-12/2006 | 315MHz 15268606 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 01/2004-12/2004 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Deville | 01/2000-12/2003 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2017-12/2018 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2013-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | ELR | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2025-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2025-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2013-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|--------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | Escalade | 01/2013-12/2013 | 433MHz | GMT900/GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2014-12/2014 | 433MHz | GMT900/GMTK2XL/K2UL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2023 | 433MHz 13540603 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2023 | 433MHz 13530661 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2024 | 433MHz 13538761 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2024-12/2024 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2025-12/2025 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2021-12/2021 | 433MHz 13528563 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2020-12/2020 | 433MHz 13528563 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2017-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2015-12/2018 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2009-12/2011 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Cadillac | Escalade | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2009-12/2011 | 433MHz | GMT926 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2010-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade | 01/2012-12/2012 | 433MHz | GMT900/GMTK2XL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade DRW | 01/2024-12/2024 | 433MHz 13538760 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade DRW | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade DRW | 01/2024-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2021-12/2025 | 433MHz 13538761 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | Escalade ESV | 01/2021-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2021-12/2025 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2018-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV | 01/2016-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV DRW | 01/2024-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV DRW | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV DRW | 01/2024-12/2024 | 433MHz 13538760 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade ESV Trailer | 01/2022-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade IQ | 07/2024-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade IQ | 07/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade IQ | 07/2024-12/2025 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Escalade IQ Trailer | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Escalade Trailer | 01/2022-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Cadillac | Hearse | 01/2001-12/2005 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Limousine | 01/2001-12/2005 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Lyriq | 06/2022-12/2023 | 433MHz | | ● | ● | ○ | A/0/S | 433MHz | Baolong | ● | ● |
| Cadillac | Lyriq | 06/2022-12/2024 | 433MHz 13530661 | | ● | ● | ○ | A/0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Lyriq | 01/2024-12/2025 | 433MHz | | ● | ● | ○ | A/0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | Lyriq | 01/2024-12/2025 | 315MHz | | ● | ● | ○ | A/0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Optiq | 01/2025-12/2025 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Optiq | 01/2025-12/2025 | 433MHz 13545364 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | Optiq | 01/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | SLS | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SLS | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2010-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2012-09/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2016-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2015-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2004-12/2006 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | SRX | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | SRX | 10/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2005-12/2007 | 433MHz | GMX295 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2008-09/2012 | 433MHz | GMX295 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2009 | 433MHz 20925925 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2011 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2009-12/2011 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | STS | 01/2011-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | Seville | 01/2001-12/2003 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | Seville | 01/2004-12/2006 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 01/2010-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 01/2004-12/2005 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR | 08/2003-02/2011 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XLR | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XLR-V | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2020-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | BHSENS | ● | ● |
| Cadillac | XT4 | 01/2024-12/2025 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2022-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2024-12/2025 | 433MHz 13538761 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 06/2018-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT4 | 01/2024-12/2024 | 433MHz 13538566 | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| Cadillac | XT4 | 01/2022-12/2023 | 315MHz 13512346 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2025-12/2025 | 433MHz 13540606 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-06/2020 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2018-12/2022 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2016-06/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2017-12/2019 | 315MHz 13589597 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XT5 | 01/2025-12/2025 | 433MHz 13554187 | | ● | ● | ● | 0/S | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|------------------------|---------------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Cadillac | XT5 | 01/2022-12/2024 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2020-12/2025 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2022-12/2025 | 433MHz 13554187 | | ● | ● | ● | 0/S | 433MHz | Baolong | ● | ● |
| Cadillac | XT6 | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Cadillac | XT6 | 01/2019-12/2023 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2013-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2017-12/2019 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Cadillac | XTS | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| ChangAn | Alsvin | 08/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS15 | 03/2019-06/2024 | 433MHz 3601010W10AB | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS15 | 01/2016-11/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 | 01/2016-12/2023 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS35 | 01/2016-12/2023 | 433MHz FS43X1 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 | 01/2015-12/2015 | 433MHz FS43X1 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 | 01/2015-12/2015 | 433MHz 3601010W10 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS35 PLUS | 03/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS35 PLUS | 01/2018-05/2019 | 433MHz Hi Conf i | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | CS35 PLUS | 04/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 | 01/2017-12/2023 | 433MHz Lo Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 | 01/2017-12/2023 | 433MHz Hi Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 PLUS | 07/2021-12/2024 | 433MHz The Second | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | CS55 PLUS | 09/2023-12/2024 | 433MHz The Third | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 433MHz 2WD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 433MHz 4WD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CS75 | 01/2014-12/2016 | 433MHz 2WD | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | CX70 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | E-STAR | 04/2020-06/2024 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | E-STAR | 05/2023-12/2024 | 433MHz Snap in | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | Hunter | 01/2020-12/2023 | 433MHz Hi Conf i | DEV- D20TCIE/4D2 OM | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|-----------------------|------------------------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| ChangAn | Hunter | 01/2020-12/2023 | 433MHz Lo Confi | DEV-D20TCIE/JE4 D25/4K22D4T /4D20M | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Hunter | 01/2020-12/2023 | 433MHz | DEV-D20TCIE | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Oshan | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ChangAn | Oshan X7 | 11/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| ChangAn | UNI-T | 08/2021-01/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| ChangAn | UNI-T | 06/2020-07/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Chery | ARRIZO 5 | 08/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 5 | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | ARRIZO 6 | 06/2019-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | ARRIZO 7 | 07/2013-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | ARRIZO 8 | 09/2022-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | EQ1 | 10/2020-09/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Softec | ● | ● |
| Chery | EQ1 | 03/2017-09/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | EQ1 | 10/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Softec | ● | ● |
| Chery | Fulwin T10 | 06/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Chery | Fulwin T6 | 05/2024-12/2024 | 433MHz 802000277AA | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Chery | Fulwin T6 | 05/2024-12/2024 | 433MHz 802000121AA | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Chery | OMODA 5 | 07/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Chery | QQ | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chery | Tiggo 2 | 01/2017-12/2023 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 2 | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3 | 05/2016-12/2023 | 433MHz T113114011 | | ● | ● | ○ | 0 | 433MHz | Chery | ● | ● |
| Chery | Tiggo 3 | 01/2021-12/2023 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3X | 11/2016-12/2020 | 433MHz 802000021AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3X | 12/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 3X | 06/2020-06/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 3X | 11/2016-12/2022 | 433MHz J523114013 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 4 Pro | 01/2022-12/2024 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5 | 07/2018-12/2022 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 5X | 12/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 5X | 06/2020-12/2024 | 433MHz 802000126AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-----------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chery | Tiggo 5X | 10/2018-12/2020 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 5X | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 5X | 01/2022-12/2024 | 433MHz 802000277AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 7 | 12/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Chery | Tiggo 7 | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 7 | 01/2022-12/2024 | 433MHz 802000277AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 | 06/2019-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PLUS | 10/2020-12/2024 | 433MHz 802000277AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PLUS | 01/2020-06/2024 | 433MHz 802000012AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 PLUS | 10/2020-06/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PLUS PHEV | 01/2022-12/2024 | 433MHz 802000126AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Chery | Tiggo 8 PLUS PHEV | 01/2022-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8 PRO(DPI/PHEV) | 08/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Chery | Tiggo 8L | 08/2024-06/2025 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Chevrolet | Avalanche | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2009-12/2011 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Chevrolet | Avalanche | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2004-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Avalanche | 01/2010-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2021-12/2023 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0 | 315MHz | TRW | ● | ● |
| Chevrolet | Aveo | 01/2011-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Aveo | 01/2002-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2017-12/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2024-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2024-12/2024 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------|-----------------|-----------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Blazer | 01/2022-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer | 01/2022-12/2025 | 433MHz 13554187 | | ● | ● | ● | 0/S | 433MHz | Baolong | ● | ● |
| Chevrolet | Blazer EV | 01/2024-12/2024 | 433MHz 13533166 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Blazer EV | 01/2024-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2022-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2021-06/2024 | 433MHz 13516165 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2019-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2016-12/2020 | 433MHz 13516165 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Bolt | 01/2017-12/2020 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2023 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2023 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2020-12/2020 | 433MHz Clamp in | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2018-12/2019 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-12/2022 | 433MHz Clamp in 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2019 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2017-12/2020 | 433MHz Snap in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2014-12/2015 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2013-12/2013 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2013 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2013 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2012-12/2012 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2010-12/2011 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2009-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 433MHz Snap in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro | 01/2016-12/2016 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Camaro ZL1 | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2017-12/2021 | 433MHz 13598787 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Camaro ZL1 | 01/2017-12/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2016-12/2017 | 315MHz 13598786 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2017-12/2019 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2014-12/2017 | 315MHz 13581559 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2011-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2007-12/2009 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2010-12/2013 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Caprice | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2022-12/2023 | 433MHz 23576928 | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Captiva | 01/2012-12/2015 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 12/2008-12/2019 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Captiva | 01/2020-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Baolong | ● | ● |
| Chevrolet | Captiva sport | 01/2008-12/2015 | 315MHz 13598771 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cavalier | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Cavalier | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Cavalier | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Cavalier | 01/2016-12/2020 | 433MHz Lo Line | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Chevrolet | Cavalier | 01/2016-12/2020 | 433MHz Hi Line | | ● | ● | ○ | 0/S | 433MHz | Dias | ● | ● |
| Chevrolet | Cheyenne | 11/2016-12/2019 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2016-12/2018 | 433MHz 13598773 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2015-10/2016 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2014-12/2015 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2011-12/2013 | 433MHz 13598773 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2010-12/2011 | 315MHz Clamp in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2007-12/2013 | 315MHz Snap in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2007-12/2012 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2022-12/2023 | 433MHz 13542523 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Cheyenne | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2021-12/2024 | 315MHz 13538759 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2020-12/2021 | 433MHz 13512347 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne | 01/2018-12/2021 | 433MHz 13516165 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 07/2019-12/2023 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne DRW | 01/2024-12/2024 | 433MHz 13538760 | Y2XC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cheyenne Trailer | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | City Express | 01/2015-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2010-12/2010 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2010-12/2010 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2009-12/2009 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | Cobalt | 01/2009-12/2009 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cobalt | 01/2008-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | Cobalt | 01/2008-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2012-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2011-12/2011 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2003-12/2010 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2025-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2020-12/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2023-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2020-12/2022 | 433MHz 13512347 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Colorado | 01/2023-12/2025 | 433MHz 13554170 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 02/2020-12/2022 | 433MHz | Y2XC | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2016-12/2019 | 315MHz 13581559 | C7 | ● | ● | ● | 0/S/A | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2015-12/2019 | 433MHz 13581560 | C7 | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Corvette | 01/1997-12/2000 | 315MHz | C5 | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2014 | 433MHz | C6 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2012-12/2012 | 315MHz | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2013-12/2013 | 315MHz | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2021-12/2025 | 315MHz 13538759 | | ● | ● | ○ | 0/S/A | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2024-12/2025 | 433MHz 84977020 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2001-12/2004 | 315MHz | C5 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2005-12/2009 | 315MHz 25758220 | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2020-12/2022 | 433MHz 13593957 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2014-12/2014 | 433MHz | C7 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 06/2000-12/2009 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2009-12/2009 | 315MHz 13598771 | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2010-12/2011 | 315MHz | C6 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Corvette | 01/2022-12/2025 | 433MHz 13554170 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Corvette Grand | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2009-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2022-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2020-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2019-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-06/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Cruze | 01/2013-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Damas | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2009-12/2009 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2010-12/2012 | 315MHz 15921013 | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Chevrolet | Equinox | 01/2008-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2007-12/2007 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 06/2017-12/2023 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2025-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2017-05/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2013-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 06/2012-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2011-12/2012 | 315MHz 12768826 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2008-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Equinox | 01/2022-12/2023 | 315MHz 13512346 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2009-12/2009 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Equinox | 01/2022-12/2024 | 433MHz 13540606 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox EV | 01/2024-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Equinox EV | 01/2024-12/2025 | 433MHz 13556202 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2016-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2014-12/2024 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2016-12/2024 | 433MHz 13556202 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2025-12/2025 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2025-12/2025 | 433MHz 13556202 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2013 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Express Series | 01/2009-12/2009 | 315MHz 15921013 | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | Express Series | 06/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | G Series | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Groove | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Baolong | ● | ● |
| Chevrolet | HHR | 01/2008-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 06/2007-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2009-12/2009 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2010-12/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | HHR | 01/2009-12/2010 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2006-12/2006 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2006-12/2006 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2000-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Chevrolet | Impala | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2020-12/2020 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2020-12/2020 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2017-06/2020 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2017-12/2018 | 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Impala | 01/2015-12/2016 | 315MHz Limited 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2015-12/2016 | 315MHz Limited 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2014-06/2021 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Impala | 10/2013-12/2014 | 315MHz Limited | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 10/2013-12/2014 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2013-09/2013 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2013-09/2013 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2009-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Impala | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Labo | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2010-06/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2013-12/2013 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2003-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Chevrolet | Malibu | 01/2013-06/2014 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2022-12/2025 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2022-12/2025 | 433MHz 13554187 | | ● | ● | ● | 0/S | 433MHz | Baolong | ● | ● |
| Chevrolet | Malibu | 01/2013-12/2014 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2014-12/2015 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 07/2011-06/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2016-12/2016 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2018 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2019 | 315MHz 22854866 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2017-12/2022 | 433MHz | V300 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2019-12/2022 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu | 01/2019-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Malibu | 01/2008-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu Fleet | 01/2016-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Malibu Fleet | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2000-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Chevrolet | Monte Carlo | 01/2006-12/2006 | 315MHz Clamp in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2006-12/2006 | 315MHz Snap in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Monte Carlo | 01/2007-12/2009 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Onix | 01/2019-12/2023 | 433MHz 26689967 | | ● | ● | ● | 0/S | 433MHz | Dias | ● | ● |
| Chevrolet | Onix | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Dias | ● | ● |
| Chevrolet | Onix | 08/2012-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Onix | 01/2024-12/2024 | 433MHz | CANFD | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Optra | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Chevrolet | Optra | 01/2019-12/2022 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2016-12/2018 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2013-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2011-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Orlando | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Prisma | 08/2014-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Prisma | 08/2020-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | S10 | 01/2017-12/2024 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2017-12/2018 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2017-12/2017 | 315MHz 13581559 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2014-12/2016 | 315MHz 20964159 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SS Sedan | 01/2013-12/2016 | 315MHz 13581559 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | SSR | 01/2006-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | SSR | 01/2006-12/2007 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Sail | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Sail | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Seeker | 01/2022-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Baolong | ● | ● |
| Chevrolet | Silverado | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2000-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2023 | 433MHz 13530661 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2023 | 315MHz 13538759 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2009-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Silverado | 01/2009-09/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 10/2013-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-10/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2015-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 07/2010-12/2014 | 433MHz | K2XC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2017-12/2018 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2017-12/2023 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2021-12/2022 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2011-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Chevrolet | Silverado | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2024-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2024-12/2025 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 11/2016-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2024-12/2025 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado | 01/2022-12/2023 | 433MHz 13542523 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 07/2019-12/2023 | 433MHz Clamp in | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2017-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2024-12/2025 | 433MHz 13554170 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado EV | 01/2024-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado EV | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado EV | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Silverado Trailer | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado Trailer | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Silverado Trailer | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2017-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Sonic | 01/2013-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2016-12/2023 | 315MHz 13598772 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Spark | 01/2016-12/2023 | 433MHz | M1JC | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2017-12/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spark | 01/2002-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Spin | 08/2014-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2024 | 433MHz 13530661 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2016-08/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2024 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2000-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2024 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2023 | 433MHz 13516165 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Chevrolet | Suburban | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2018-12/2020 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 09/2016-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2009-12/2013 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2011-12/2018 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2025-12/2025 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Suburban | 01/2025-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban DRW | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban DRW | 01/2024-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Suburban Trailer | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2021 | 433MHz 13540603 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2021 | 433MHz 13528563 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2020-12/2020 | 433MHz 13528563 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|---------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Tahoe | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2017-12/2020 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2016-12/2018 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2000-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Chevrolet | Tahoe | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2009-12/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2010-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2011-12/2013 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2025 | 433MHz 13530661 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2025 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe | 01/2014-12/2015 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe DRW | 01/2024-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe DRW | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tahoe Trailer | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz 22853740 | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2015-12/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz 26253785 | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz | WMI:3GN | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Tracker | 01/2019-12/2020 | 433MHz 26253785 | WMI:3GN | ● | ● | ● | 0/S | 433MHz | Dias | ● | ● |
| Chevrolet | Tracker | 01/2021-12/2024 | 433MHz 26253785 | | ● | ● | ○ | S | 433MHz | Dias | ● | ● |
| Chevrolet | Tracker | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Chevrolet | Tracker | 01/2023-12/2025 | 433MHz 22853740 | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2007-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2006-12/2008 | 433MHz | GMT360 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2001-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2017-12/2020 | 433MHz 13598773 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2020-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trailblazer | 01/2009-12/2012 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2024-12/2024 | 433MHz 13549707 | | ● | ● | ● | 0/S | 433MHz | BHSENS | ● | ● |
| Chevrolet | Traverse | 01/2008-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2025-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2024-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2020-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2016-12/2017 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2016-12/2016 | 315MHz 13581558 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 06/2014-12/2016 | 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2014-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Traverse | 01/2013-12/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2023-12/2024 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2019-12/2022 | 315MHz 13516164 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2017-06/2022 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2012-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Trax | 01/2024-12/2025 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Uplander | 01/2008-12/2009 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Uplander | 01/2008-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Van | 01/2008-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Chevrolet | Volt | 01/2019-12/2019 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2017-06/2020 | 433MHz 13598773 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2016-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2013-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2011-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chevrolet | Volt | 01/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Chrysler | 200 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chrysler | 200 | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2014-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2011-12/2013 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 200 | 01/2008-12/2014 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2022-12/2023 | 433MHz BHSSENS | | ● | ● | ○ | O/A | 433MHz | BHSSENS | ● | ● |
| Chrysler | 300 | 01/2017-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2016-12/2016 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2014-12/2015 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2011-12/2013 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2010-12/2010 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2009-12/2009 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 | 01/2008-12/2008 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2007-12/2007 | 315MHz | LX | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2006-12/2007 | 433MHz | LX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300 | 01/2005-12/2006 | 315MHz | LX | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300 SRT | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 01/2013-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300 SRT | 01/2010-12/2012 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2014-12/2015 | 433MHz 56029400AE | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Chrysler | 300C | 01/2006-12/2006 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | 300C | 06/2005-05/2009 | 433MHz | LE48 | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Chrysler | 300M | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Aspen | 01/2008-12/2011 | 315MHz | HG | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Chrysler | Aspen | 01/2007-12/2007 | 315MHz | HG | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Aspen | 01/2012-12/2015 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Concorde | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 01/2003-12/2008 | 433MHz | ZH | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 01/2009-12/2011 | 433MHz | ZH | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire | 01/2009-12/2011 | 315MHz | ZH | ● | ● | ○ | O | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire | 01/2005-12/2006 | 315MHz | ZH | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire (International) | 01/2007-12/2008 | 433MHz | ZH | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Crossfire (International) | 01/2007-12/2008 | 315MHz | ZH | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire (NAFTA) | 01/2007-12/2008 | 315MHz | ZH | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Crossfire (NAFTA) | 01/2007-12/2008 | 433MHz | ZH | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Grand Caravan | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chrysler | Grand Caravan | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Chrysler | Intrepid | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | PT Cruiser | 11/2007-12/2010 | 315MHz | PT | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------------|-----------------|----------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Chrysler | Pacifica | 01/2006-12/2008 | 315MHz | CS | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Pacifica | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Pacifica | 01/2018-12/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Prowler | 01/2001-12/2002 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Chrysler | Sebring | 01/2006-12/2010 | 433MHz | JS | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Sebring | 01/2008-12/2011 | 315MHz | JS | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Chrysler | Sebring | 01/2007-12/2007 | 315MHz | JS | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2006-12/2006 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2008-12/2010 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2007-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2008-12/2010 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | Town & Country | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Chrysler | Town & Country | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Chrysler | Voyager | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Citroen | Berlingo | 01/2008-09/2013 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 10/2013-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Berlingo | 07/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C-Elysee | 09/2012-12/2021 | 433MHz | M3/M4 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Citroen | C1 | 04/2005-03/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C3 | 09/2009-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C4 | 09/2004-07/2008 | 433MHz | B5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C4 | 10/2014-10/2018 | 433MHz | B58 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 | 08/2010-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | C4 | 08/2008-07/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C4 Aircross | 04/2012-06/2018 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Citroen | C4 Cactus | 05/2014-04/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C4 Picasso | 05/2006-02/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 09/2013-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | C5 | 08/2004-08/2013 | 433MHz | X3/X40 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C5 | 12/2000-07/2004 | 433MHz | X40 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | C5 Aircross | 09/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | C6 | 01/2005-12/2013 | 433MHz | X6 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Citroen | C8 | 01/2002-09/2005 | 433MHz | V3 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS3 | 01/2009-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS3 | 01/2015-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | DS4 | 02/2014-07/2020 | 433MHz | B81 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | DS4 | 12/2010-01/2014 | 433MHz | B75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Citroen | DS4 | 02/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 02/2014-11/2018 | 433MHz | X2/50 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS5 | 06/2011-01/2014 | 433MHz | B81 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS7 | 03/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | DS7 | 01/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Citroen | Jumper | 12/2013-09/2022 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | Jumper | 02/2006-11/2013 | 433MHz | B9 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper | 02/2006-11/2013 | 433MHz 1612474480 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumper | 10/2022-12/2024 | 433MHz | X2/50 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Citroen | Jumpy | 05/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Jumpy | 10/2006-05/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Jumpy | 06/2014-04/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 01/2016-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Citroen | Nemo | 01/2016-08/2018 | 433MHz | B53/B7 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Citroen | Nemo | 11/2007-12/2015 | 433MHz | B53/B7 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Citroen | Space Tourer | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Cowin | X3 | 06/2016-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFEV | EX1 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| DFEV | NAMMI 01 | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| DFEV | NAMMI BOX | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| DFFuKang | E-Elysee | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DFFuKang | ES600 | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DFPV | A30 | 01/2017-12/2017 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| DFPV | AX3 | 11/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFPV | AX4 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFPV | AX5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFPV | AX7 | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| DFPV | AX7 | 01/2017-12/2024 | 433MHz E340020JD0201 | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| DFPV | E70 | 10/2017-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Baolong | ● | ● |
| DFPV | HUGE | 01/2022-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| DFPV | L7 | 05/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| DFPV | SHINE | 01/2020-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Baolong | ● | ● |
| DFPV | SHINE | 01/2019-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| DFPV | SHINE GS | 01/2020-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| DFPV | SHINE MAX | 09/2021-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Baolong | ● | ● |
| DFSK | D1 | 03/2024-12/2024 | 433MHz 403112ZG1A | | ○ | ● | ○ | NA | 433MHz | Unknown Manufacturer | ● | ● |
| DFSK | D1 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| DFSK | D1 EV | 12/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| DFSK | E3/500 EV | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | E5/S580 DMI | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| DFSK | E5/S580 DMI | 03/2023-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | EC35 | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| DFSK | EC36 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | EC36 II | 07/2023-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengguang 330/Glory 330 | 01/2019-12/2024 | 433MHz 3641050FA01 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengguang 330/Glory 330 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengguang 500/Glory 500 | 10/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengguang 500/Glory 500 | 01/2021-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengguang 560/Glory 560 | 06/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2016-06/2018 | 433MHz 3641050SA01 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2017-12/2019 | 433MHz 3641050SA04 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengguang 580/Glory 580 | 01/2019-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengon 600/Glory 600 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengon 600/Glory 600 | 01/2019-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengon ix5/Glory Ix5 | 01/2018-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| DFSK | Fengon ix5/Glory Ix5 | 10/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| DFSK | Fengon ix7/Glory Ix7 | 11/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Dacia | Sandero | 01/2014-12/2021 | 433MHZ 407005642R | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dacia | Sandero | 01/2012-12/2017 | 433MHz 407001628R | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Daewoo | Nexia | 01/2000-12/2001 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Dodge | Attitude | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dodge | Attitude | 01/2015-12/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Dodge | Attitude | 07/2024-06/2025 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Dodge | Attitude | 08/2021-12/2024 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dodge | Avenger | 01/2007-12/2014 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Avenger | 01/2007-12/2016 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | C/V | 01/2012-12/2012 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | C/V | 01/2015-12/2016 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | C/V | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 01/2008-12/2009 | 315MHz | PM | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Caliber | 01/2007-12/2012 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Dodge | Caliber | 01/2007-12/2007 | 315MHz | PM | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Dodge | Caliber | 01/2011-12/2012 | 315MHz | PM | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Caliber | 01/2010-12/2010 | 315MHz | PM | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Caravan | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Dodge | Caravan | 01/2010-12/2010 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Caravan | 01/2006-06/2010 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Caravan | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Challenger | 01/2009-12/2009 | 433MHz | LC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2011-12/2013 | 433MHz | LC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2010-12/2010 | 433MHz | LC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2014-12/2015 | 433MHz | LC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2022-12/2023 | 433Mhz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Dodge | Challenger | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger | 01/2008-12/2008 | 433MHz | LC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2018-12/2021 | 433MHz | LD | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2015-12/2017 | 433MHz | LD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Challenger SRT | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Dodge | Charger | 01/2009-12/2009 | 433MHz | LX | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2008-12/2008 | 433MHz | LX | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Charger | 01/2007-12/2007 | 315MHz | LX | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Charger | 01/2005-12/2006 | 315MHz | LX | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Charger | 01/2014-12/2015 | 433MHz | LD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2022-12/2023 | 433MHz BHSENS | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Dodge | Charger | 01/2011-12/2013 | 433MHz | LD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2010-12/2010 | 433MHz | LX | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 08/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2017-07/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2022-12/2023 | 433MHz BHSENS | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Dodge | Charger SRT | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2011-12/2014 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2009-12/2009 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2010-12/2010 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Charger SRT | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2008-12/2010 | 315MHz Snap in | ND | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2008-12/2010 | 315MHz Clamp in | ND | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Dakota | 01/2011-12/2011 | 315MHz | ND | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Dart | 10/2012-12/2019 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Durango | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|---------------|-----------------|--------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Dodge | Durango | 01/2009-12/2010 | 315MHz | HB | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2007-12/2008 | 315MHz | HB | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Durango | 01/2014-12/2016 | 433MHz | WD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2011-12/2013 | 433MHz | WD | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Durango | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Durango SRT | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2004-12/2005 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2001-12/2003 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2018-12/2022 | 433MHz SCH | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Grand Caravan | 01/2008-12/2010 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Dodge | Grand Caravan | 01/2006-12/2006 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Hornet | 01/2023-06/2025 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Dodge | Intrepid | 01/2002-12/2004 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2009-12/2009 | 433MHz | JC | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2021-12/2023 | 433MHz 8060004BAD0000 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2010-12/2010 | 433MHz Lo Line | JC | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 11/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 10/2016-10/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2014-09/2016 | 433MHz | JC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2011-12/2013 | 433MHz | JC | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Journey | 01/2010-12/2010 | 433MHz | JC | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Journey | 01/2010-12/2010 | 433MHz Hi line | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 01/2011-12/2011 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 01/2007-12/2007 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Magnum | 01/2005-12/2006 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Magnum | 01/2008-12/2008 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Magnum | 01/2009-12/2009 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Magnum | 01/2010-12/2010 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Nitro | 06/2006-04/2013 | 433MHz | KA | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Nitro | 11/2006-12/2008 | 315MHz | KA | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Nitro | 01/2009-12/2012 | 315MHz | KA | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Ram 1000 | 01/2016-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Dodge | Ram 1500 | 01/2010-12/2013 | 433MHz | D2 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|--------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Dodge | Ram 1500 | 01/2019-12/2025 | 433MHz DT | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2018-12/2019 | 433MHz | DS | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 10/2013-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 1500 | 01/2009-12/2009 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 1500 | 01/2008-12/2009 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Ram 2500 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 2500 | 01/2008-12/2009 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Dodge | Ram 2500 | 01/2010-12/2013 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 2500 | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0 | 433MHz | TRW | ● | ● |
| Dodge | Ram 2500 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 01/2010-12/2013 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 3500 | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2018-12/2018 | 433MHz Alloy wheel | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2014-12/2017 | 433MHz Steel wheel | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2014-12/2017 | 433MHz Alloy wheel | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 3500 DRW | 01/2018-12/2018 | 433MHz Steel wheel | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4000 | 01/2018-12/2019 | 433MHz | DS | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4000 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4000 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4000 | 01/2019-12/2024 | 433MHz DT | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram 4500/5500 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4500/5500 | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram 4500/5500 | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Cargo | 01/2015-12/2015 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram ProMaster | 01/2022-12/2024 | 433MHz Continental | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Dodge | Ram ProMaster | 01/2018-12/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram ProMaster | 01/2014-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram ProMaster City | 01/2018-12/2023 | 433MHz 05154876AA | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram ProMaster City | 01/2015-12/2017 | 433MHz 05154876AA | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram ProMaster City | 01/2015-12/2022 | 433MHz 56029400AE | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Ram Series | 01/2020-12/2023 | 433MHz | DX | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Dodge | Ram Trailer | 01/2019-12/2024 | 433MHz | | ○ | ● | ● | S | 433MHz | Schrader | ● | ● |
| Dodge | SRT Viper | 01/2013-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Sprinter | 01/2007-12/2020 | 315MHz | VB | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Stratus | 01/2007-12/2007 | 315MHz | JR | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Dodge | Viper | 01/2013-12/2016 | 433MHz | VX | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Dodge | Viper | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Dodge | Viper | 01/2003-12/2011 | 433MHz | ZB | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Dodge | Viper | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| EXEED | LX | 08/2021-12/2024 | 433MHz 802000247AA | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| EXEED | LX | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| EXEED | LX C-DM | 03/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| EXEED | LX C-DM | 03/2022-12/2024 | 433MHz 802000277AA | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| EXEED | RX | 02/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| EXEED | RX C-DM | 03/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| EXEED | STERRA ES | 11/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| EXEED | STERRA ET | 04/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| EXEED | TX | 04/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EXEED | TXL | 01/2023-12/2024 | 433MHz 802000121AA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| EXEED | TXL | 04/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| EXEED | VX | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Epai | epai 007 | 02/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Epai | epai 008 | 06/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| FAWDAIHATSU | SENIA R7 | 01/2016-06/2019 | 433MHz Lo Conf i | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| FAWDAIHATSU | SENIA R7 | 01/2016-06/2019 | 433MHz Hi Conf i | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Fengon | 330 | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | 500 | 10/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fengon | 500 | 01/2021-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | 560 | 06/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | 580 | 01/2017-12/2019 | 433MHz 3641050SA04 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | 580 | 01/2019-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | 580 | 01/2016-06/2018 | 433MHz 3641050SA01 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | 580 | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fengon | S560 | 01/2017-06/2019 | 433MHz 3641050SA01 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | S560 | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Fengon | S560 | 01/2018-06/2021 | 433MHz 3641050SA04 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Fengon | ix5 | 01/2018-12/2024 | 433MHz 3641050FS01 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Fengon | ix7 | 11/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Ferrari | 296GTB | 06/2021-12/2024 | 315MHz BHSENS | | ○ | ● | ○ | A | 315MHz | BHSENS | ● | ● |
| Ferrari | 296GTB | 06/2021-12/2024 | 433MHz BHSENS | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Ferrari | 296GTB | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 01/2009-12/2013 | 433MHz | F142 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Italia | 01/2014-12/2016 | 433MHz | F142 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|--------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ferrari | 458 Speciale | 01/2013-12/2016 | 433MHz | F142 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 458 Spider | 01/2009-12/2020 | 433MHz | F142 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 488 | 01/2015-12/2021 | 433MHz | F142 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/1998-12/2002 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 550 Maranello | 01/2010-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 575M Maranello | 01/2002-12/2006 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTB | 01/2004-12/2014 | 433MHz | F141 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 GTO | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 599 SA Aperta | 01/2004-12/2012 | 433MHz | F141 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 612 Scaglietti | 01/2004-12/2012 | 433MHz | F137 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | 812 Superfast | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 01/2015-06/2019 | 433MHz | F149 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | California | 01/2008-12/2014 | 433MHz | F149 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Daytona SP3 | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Enzo | 01/2002-12/2009 | 433MHz | F140 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 10/2012-12/2023 | 433MHz 282189 | F151/ F152 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F12 Berlinetta | 10/2012-12/2014 | 315MHz | F151/ F152 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | F12 tdf | 01/2015-12/2021 | 433MHz | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2004-12/2007 | 433MHz | F131E | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F430 | 01/2008-12/2011 | 433MHz | F131E | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F488 | 01/2021-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F588 Dino | 01/2019-12/2022 | 433MHz Huf/Beru | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Spider | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 01/2019-12/2023 | 433MHz 282189 | F151/ F152 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | F8 Tributo | 01/2022-12/2023 | 433MHz 314818 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-06/2019 | 433MHz | F151 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | FF | 01/2011-06/2019 | 315MHz | F151 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | FXX | 01/2003-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | GTC4 Lusso | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 01/2014-12/2019 | 433MHz | F150 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | La Ferrari | 01/2013-12/2020 | 315MHz | F150 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ferrari | Portofino | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Roma | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | SF90 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ferrari | Spider | 01/2002-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Fiat | 124 Spider | 08/2015-12/2016 | 433MHz | NF/J12F | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Fiat | 124 Spider | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 124 Spider | 01/2017-12/2021 | 433MHz | NF/J12F | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Fiat | 500 | 01/2023-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2014-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Fiat | 500 | 01/2011-12/2013 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Fiat | 500 | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fiat | 500 | 01/2017-12/2022 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Fiat | 500C | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | 500E | 01/2015-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 03/2013-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Fiat | 500L | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Fiat | 500X | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Fiat | 500X | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Fiat | 500X | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Fiat | 500X | 01/2014-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Fiat | Ducato | 06/2014-06/2024 | 433MHz | X2/50 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Fiat | Tipo | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Fisker | Karma | 01/2012-12/2012 | 433MHz | | ○ | ● | ○ | S | 433MHz | Lear | ● | ● |
| Ford | Bronco | 01/2020-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2021-12/2024 | 315MHz 81C3A8189CA | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2021-12/2024 | 315MHz ML3T1A180BA | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Bronco | 10/2024-12/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2021-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Bronco | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 11/2024-12/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 10/2020-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Bronco Sport | 10/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2013-12/2013 | 315MHz | C344N | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2012-12/2012 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | C-Max | 01/2014-12/2020 | 315MHz | C344N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Crown Victoria | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | E-Series | 01/2023-12/2025 | 433MHz PC3Z1A189D | | ○ | ● | ○ | S | 433MHz | Sensata Technologies | ● | ● |
| Ford | E-Series | 01/2020-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | E-Series | 10/2024-12/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | E-Series | 08/2009-12/2019 | 315MHz Schrader | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | E-Series | 01/2009-12/2010 | 315MHz Band | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | E-Series | 01/2009-12/2009 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Lear | ● | ● |
| Ford | E-Series | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | E-Series | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Lear | ● | ● |
| Ford | E-Series SD | 01/2023-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | E-Series SD | 01/2020-12/2023 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | E-Series SD DRW | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | E-Series SD DRW | 01/2020-12/2023 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 06/2019-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Ecosport | 07/2017-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ecosport | 06/2015-06/2017 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2015-12/2020 | 433MHz F2GZ1A189B | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2015-12/2020 | 315MHz | CD539N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2012-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 01/2011-12/2014 | 315MHz | U387 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Edge | 07/2010-12/2010 | 315MHz | U387 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 11/2006-12/2010 | 315MHz no Chrome rims | U387 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Edge | 01/2007-12/2007 | 315MHz with Chrome rims | U387 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Edge | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Edge | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2008-12/2008 | 315MHz | U377 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Escape | 01/2025-06/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2025-06/2025 | 315MHz | | ○ | ● | ○ | A/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 06/2008-12/2011 | 315MHz Schrader | U377 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 08/2019-12/2024 | 433MHz JX7Z1A189A | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 08/2019-12/2024 | 315MHz JX7Z1A189C | | ● | ● | ○ | 0/A/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2017-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2014-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 10/2013-12/2017 | 315MHz | C520 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2013-12/2013 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2013-09/2013 | 315MHz | C520 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2012-12/2012 | 315MHz | U377 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Escape | 01/2012-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Escape | 01/2005-12/2005 | 315MHz | U204 | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Escape | 01/2006-12/2007 | 315MHz | U204 | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Exp Sport Trac | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Expedition | 09/2017-12/2017 | 315MHz HC3Z1A189A | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2007-12/2010 | 315MHz no Chrome rims | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Expedition | 01/2007-12/2010 | 315MHz with Chrome rims | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Expedition | 03/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2018-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Expedition | 01/2018-12/2022 | 315MHz GL3Z1A189A | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 09/2017-12/2017 | 433MHz F2GZ1A189F | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2017 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 01/2015-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Expedition | 08/2012-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Expedition | 08/2010-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 05/2019-12/2024 | 433MHz JX7Z1A189A | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2005-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Explorer | 11/2010-05/2015 | 433MHz BB5Z1A189A | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 11/2010-09/2015 | 315MHz Schrader | U502 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 05/2015-12/2017 | 315MHz F2GZ1A189A | U502 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 06/2015-12/2019 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 06/2024-12/2025 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Explorer | 05/2019-12/2024 | 315MHz JX7Z1A189C | | ● | ● | ○ | 0/S/A | 315MHz | Schrader | ● | ● |
| Ford | Explorer | 01/2018-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 10/2014-12/2014 | 315MHz F2GZ1A189A | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 07/2014-12/2014 | 433MHz P415 | P415 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 08/2012-06/2014 | 433MHz EV6T1A180CB | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 08/2008-12/2010 | 315MHz P415 | P415 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2011-12/2014 | 315MHz P415 | P415 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2021-12/2024 | 433MHz P702 | P702 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2006-12/2008 | 315MHz P221 | P221 | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | F-150 | 01/2023-12/2024 | 433MHz PC3Z1A189K | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2025-12/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2023-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 10/2020-12/2024 | 315MHz ML3Z1A189B | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2020 | 433MHz P415 | P415 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-150 | 01/2015-12/2017 | 315MHz P552 | P552 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-150 | 10/2014-12/2014 | 433MHz F2GZ1A189B | P415 | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | F-150 HD | 08/2007-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Ford | F-150 HD | 10/2014-12/2014 | 315MHz F2GZ1A189A | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 HD | 01/2011-12/2014 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-150 HD | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2021-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | F-Series | 01/2019-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series | 01/2009-12/2014 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2017-12/2017 | 433MHz Trailer | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2018-12/2019 | 433MHz Trailer | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 07/2016-12/2016 | 315MHz HC3Z1A189A | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2024-12/2024 | 433MHz PC3Z1A189D | | ● | ● | ○ | 0/S | 433MHz | Sensata Technologies | ● | ● |
| Ford | F-Series SD | 01/2007-05/2010 | 315MHz Banded | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | F-Series SD | 06/2010-12/2010 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2011-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2020-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2024-12/2024 | 433MHz FR3Z1A189B | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 02/2023-12/2023 | 433MHz FR3Z1A189B | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2023-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2017-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2023-12/2023 | 433MHz PC3Z1A189D | | ● | ● | ○ | 0/S | 433MHz | Sensata Technologies | ● | ● |
| Ford | F-Series SD | 10/2020-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2015-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2018-12/2019 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD | 01/2017-12/2017 | 315MHz HC3Z1A189A | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 02/2023-12/2024 | 433MHz FR3Z1A189B | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Ford | F-Series SD DRW | 01/2023-12/2024 | 433MHz PC3Z1A189D | | ● | ● | ○ | S | 433MHz | Sensata Technologies | ● | ● |
| Ford | F-Series SD DRW | 01/2023-12/2023 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2018-12/2023 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2016-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 06/2010-12/2016 | 315MHz Snap in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | F-Series SD DRW | 01/2006-05/2010 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Fiesta | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2014-12/2017 | 315MHz | B299N | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta | 04/2010-12/2010 | 315MHz | B299N | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta | 01/2011-12/2013 | 315MHz | B299N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fiesta ST | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Fiesta ST | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Five Hundred | 01/2006-12/2007 | 315MHz | D258 | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Flex | 05/2010-12/2012 | 315MHz Schrader | D471 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2020-12/2021 | 315MHz | D471 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2016-12/2019 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2013-12/2019 | 315MHz | D471 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Flex | 01/2013-12/2019 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Flex | 05/2008-12/2010 | 315MHz | D471 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Flex | 02/2012-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Focus | 01/2019-12/2020 | 315MHz | C346N | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2014-12/2018 | 315MHz | C346N | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2013-12/2013 | 315MHz | C346N | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2012-12/2012 | 315MHz | C170 | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Focus | 01/2008-12/2009 | 315MHz | C170 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Focus | 01/2007-12/2007 | 315MHz | C170 | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Focus | 07/2009-12/2011 | 315MHz Schrader | C170 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Focus RS | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Focus RS | 01/2016-12/2017 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Focus ST | 01/2018-12/2018 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Freestar | 01/2006-12/2010 | 315MHz | V229 | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Freestar | 01/2005-12/2005 | 315MHz | V229 | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Freestar | 01/2004-12/2004 | 315MHz | V229 | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Freestyle | 01/2005-12/2010 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Fusion | 04/2016-12/2019 | 433MHz | CD389 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2021-12/2021 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2020-07/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 07/2012-06/2013 | 315MHz | CD391 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 04/2016-12/2017 | 315MHz | CD539N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 07/2013-03/2016 | 315MHz | CD391 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Fusion | 08/2012-03/2016 | 433MHz | CD391 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2008-01/2009 | 315MHz | CD338 | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Fusion | 02/2009-06/2012 | 315MHz | CD338 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Fusion | 01/2006-12/2007 | 315MHz | CD338 | ● | ● | ○ | 0/S | 315MHz | Lear | ● | ● |
| Ford | GT | 10/2016-06/2024 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Grand Marquis | 01/2007-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Interceptor Crown Vic | 01/2006-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Interceptor Explorer | 09/2015-12/2019 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Interceptor Explorer | 01/2020-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Interceptor Explorer | 01/2011-08/2015 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Interceptor Taurus | 01/2011-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2014-12/2019 | 433MHz | C520 | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Kuga | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Maverick | 11/2024-06/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Maverick | 08/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Maverick | 08/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2005-06/2006 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Mustang | 03/2009-12/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2020-12/2023 | 315MHz | | ● | ● | ○ | 0/S/A | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2020-12/2023 | 433MHz | S550 | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2025-06/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 05/2023-12/2023 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 02/2012-09/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 07/2006-02/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Mustang | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 10/2014-12/2019 | 433MHz | S550 | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang | 10/2014-12/2019 | 315MHz | S550 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2010-09/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang | 01/2025-06/2025 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 10/2020-12/2024 | 315MHz FR3Z1A189A | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2025-06/2025 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Mustang Mach-E | 01/2025-06/2025 | 433MHz | | ○ | ● | ○ | S/A | 433MHz | Schrader | ● | ● |
| Ford | PUMA | 11/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | PUMA | 01/2020-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Police Responder Hybrid | 01/2019-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Ranger | 01/2019-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Ford | Ranger | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Ford | Ranger | 01/2018-12/2018 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2012-12/2017 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 11/2018-12/2020 | 315MHz HC3Z1A189A | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2019-12/2021 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2022-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Ranger | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | SSV Plug-In Hybrid | 01/2019-12/2020 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Shelby GT500 | 01/2013-12/2015 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Shelby GT500 | 01/2012-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Shelby GT500 | 01/2015-12/2023 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Special Service Police Sedan | 01/2014-12/2017 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 04/2007-04/2010 | 315MHz Banded | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Taurus | 11/2015-12/2019 | 433MHz BB5Z1A189A | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2011-10/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 05/2010-12/2010 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2017-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2018-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2015-12/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2019-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2013-12/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2013-10/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Ford | Taurus | 11/2012-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Ford | Taurus | 01/2012-12/2012 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Taurus X | 01/2008-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Taurus X | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Ford | Territory | 01/2021-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Ford | Transit | 01/2019-12/2019 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2014-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2010-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2025-12/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2015-12/2018 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Transit | 01/2023-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 01/2021-12/2022 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Ford | Transit | 01/2020-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit | 10/2019-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Transit Cargo & Wagon | 01/2020-12/2020 | 315MHz | | ○ | ● | ○ | A/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2010-12/2010 | 315MHz | V227N | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2013-12/2013 | 315MHz | V408N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2014-12/2015 | 315MHz | V408N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 05/2018-12/2018 | 315MHz F2GZ1A189A | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2019-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2016-12/2018 | 315MHz | V408N | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit Connect | 01/2011-12/2012 | 315MHz | V227N | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Ford | Transit DRW | 10/2019-12/2024 | 315MHz F2GZ1A189A | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit DRW | 01/2020-12/2023 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Transit DRW | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Ford | Transit LCV | 01/2014-12/2019 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Ford | Windstar | 01/2001-12/2003 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Forthing | Friday | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Joyear S50 | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Joyear S50 | 08/2019-12/2024 | 433MHz E340020JD0201 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Joyear S50 | 01/2018-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Joyear X5 | 01/2014-06/2019 | 433MHz B123685020 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Forthing | Joyear X5 | 06/2017-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | Joyear X5 | 01/2014-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Ling zhi | 04/2020-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Ling zhi M5 | 06/2019-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Ling zhi M5 EV | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | Ling zhi PLUS | 10/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | M7 | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | M7 | 01/2018-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | S50 EV | 11/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | S50 EV | 01/2018-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | S50 EV | 01/2018-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | S500 | 11/2015-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | S60 EV | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Forthing | SX6 | 01/2018-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | SX6 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | SX6 | 07/2016-12/2017 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | T5 | 01/2020-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | T5 | 01/2020-12/2021 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | T5 | 01/2018-12/2019 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | T5 | 01/2018-12/2019 | 433MHz A2C14267301 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Forthing | T5 EVO/T5 HEV | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | T5L | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | T5L | 03/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | U-Tour | 01/2022-12/2024 | 433MHz CM5B3685020 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Forthing | U-Tour | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Foton | MengPaiKe S | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Foton | Toano | 01/2017-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Foton | Toano | 01/2017-06/2024 | 433MHz 6 Wheel | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Foton | Toano | 03/2022-06/2024 | 433MHz V131100000059 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| GMC | Acadia | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2024-12/2024 | 433MHz 13556202 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2024-12/2024 | 433MHz 13533166 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2024-12/2024 | 433MHz 13512347 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2022-12/2023 | 433MHz 13512347 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 09/2018-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 11/2016-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 11/2016-08/2018 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2016-10/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 06/2014-10/2016 | 315MHz 23445327 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2014-10/2016 | 315MHz 25920615 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2014-12/2015 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2013-12/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Acadia | 11/2008-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Acadia | 01/2006-10/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| GMC | Acadia | 01/2012-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-------------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| GMC | Canyon | 01/2025-12/2025 | 433MHz 13554170 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2003-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2010-06/2013 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2014-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2017-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2020-12/2022 | 315MHz 13512346 | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| GMC | Canyon | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Denali | 06/2020-06/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2007-12/2011 | 315MHz Snap in SCH | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2007-12/2009 | 315MHz Clamp in SCH | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2007-12/2007 | 315MHz Clamp in TRW | | ● | ● | ● | S | 315MHz | TRW | ● | ● |
| GMC | Envoy | 01/2006-12/2009 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2005-12/2005 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Envoy | 01/2006-12/2006 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Hummer | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| GMC | Hummer EV | 01/2025-12/2025 | 433MHz 13554170 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| GMC | Hummer EV | 01/2022-12/2025 | 433MHz 13530661 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| GMC | Hummer EV | 01/2021-12/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| GMC | Hummer EV Trailer | 01/2022-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Hummer EV Trailer | 01/2023-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2016-12/2025 | 433MHz 13556202 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2016-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2017-12/2024 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Savana | 01/2014-12/2015 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2017-12/2018 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2019-12/2025 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| GMC | Savana | 01/2009-12/2013 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| GMC | Savana | 01/2009-12/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Savana | 01/2014-12/2015 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| GMC | Savana | 01/2016-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2025 | 433MHz 13538761 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2016-12/2018 | 433MHz 13598773 | XL8 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2025 | 433MHz 13542523 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| GMC | Sierra | 01/2021-12/2023 | 433MHz 13530661 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2000-12/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2022-12/2023 | 433MHz 13542523 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2007-12/2008 | 315MHz Snap in SCH | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2009-12/2013 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 07/2009-12/2013 | 433MHz | GMT902 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2007-12/2007 | 315MHz Clamp in TRW | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| GMC | Sierra | 01/2007-12/2007 | 315MHz Clamp in SCH | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2010-12/2011 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2024 | 433MHz 13545366 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2021-12/2023 | 315MHz 13538759 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2018-12/2023 | 433MHz 13516165 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2017-12/2021 | 315MHz | XL7 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2013-12/2013 | 433MHz | K2XG2 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2014-12/2014 | 433MHz | K2XG2 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra | 01/2024-12/2025 | 315MHz 13538759 | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra Classic | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2024-12/2025 | 433MHz 13554170 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 07/2019-12/2023 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2017-12/2019 | 315MHz | XL7 | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2017-12/2019 | 433MHz | XL8 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Sierra DRW | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Sierra Trailer | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra Trailer | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Sierra Trailer | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2009-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2012-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2015-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|--------------------|-----------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| GMC | Terrain | 01/2015-12/2017 | 315MHz 13586335 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2010-12/2012 | 315MHz 20925924 | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2025-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2022-12/2024 | 315MHz 13512346 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2017-12/2017 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2018-12/2020 | 433MHz | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2018-12/2022 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Terrain | 01/2022-12/2024 | 433MHz 13512347 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon | 01/2022-12/2023 | 433MHz 13545366 | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2007-12/2007 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | TRW | ● | ● |
| GMC | Yukon A11 | 01/2004-07/2004 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2018-12/2019 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2021-12/2025 | 433MHz 13530661 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2021-12/2025 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2021-12/2025 | 433MHz 13542523 | | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2021-12/2023 | 433MHz 13533166 | | ● | ● | ○ | O/S/A | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2009-12/2013 | 433MHz | GMT922 (2) | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2020-12/2021 | 433MHz 13516165 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 08/2004-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2017-12/2020 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2016-12/2018 | 433MHz 13598773 | | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 03/2014-12/2016 | 315MHz 13598772 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2014-12/2014 | 315MHz 25920615 | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2014-12/2014 | 433MHz | K2UG/ GMT922 | ● | ● | ● | O/S | 433MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2010-12/2011 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2009-12/2013 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2008-12/2008 | 315MHz | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon A11 | 01/2007-12/2007 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| GMC | Yukon DRW | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Yukon DRW | 01/2024-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Yukon DRW | 01/2024-12/2025 | 433MHz 13542523 | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| GMC | Yukon Trailer | 01/2022-12/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| GMC | Yukon Trailer | 01/2023-12/2024 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Geely | Atlas | 01/2015-12/2023 | 433MHz QY1031 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | Atlas | 09/2019-12/2020 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas | 01/2022-12/2023 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Atlas L | 05/2023-12/2024 | 433MHz 6608064280 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| Geely | Atlas L | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Geely | Azkarra | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Azkarra | 01/2020-12/2023 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Coolray/Belgee | 07/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Coolray/Belgee | 01/2019-12/2024 | 433MHz 01741388 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | Coolray/Belgee | 01/2020-12/2024 | 433MHz 6600129664 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | EC7 | 01/2012-12/2020 | 433MHz 06703309 | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | EC7 | 01/2009-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EC7 | 01/2013-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Lear | ● | ● |
| Geely | EMGRAND GL | 07/2019-12/2020 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 01/2017-06/2019 | 433MHz 01732445 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 01/2021-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GL | 01/2021-12/2021 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | EMGRAND GL | 09/2016-06/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 01/2015-05/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 01/2016-12/2023 | 433MHz 1067030201 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Geely | EMGRAND GS | 06/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND L | 01/2016-12/2023 | 433MHz A2C14267302 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | EMGRAND RS | 08/2010-06/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Geely | EMGRAND S | 01/2021-12/2024 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Englon King Kong | 01/2006-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Geely | Haoyue | 01/2020-12/2023 | 433MHz 6600129664 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Haoyue | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | Haoyue | 01/2020-12/2023 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | OKAVANGO | 01/2022-12/2023 | 433MHz 6600129664 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | OKAVANGO | 01/2022-12/2023 | 433MHz 6600145881 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | OKAVANGO | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|-------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Geely | OKAVANGO | 12/2022-12/2024 | 433MHz 6608064280 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Geely | Tugella | 07/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Geely | Vision X3 | 06/2019-12/2023 | 433MHz G6 CVT | | ● | ● | ○ | C | 433MHz | Baolong | ● | ● |
| Geely | Vision X3 | 06/2019-12/2023 | 433MHz G6 MT | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X3 | 12/2017-12/2023 | 433MHz G5 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Geely | Vision X3 | 01/2017-11/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Geely | X7 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | M2 | 04/2014-12/2017 | 433MHz 3641110K80 | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| GreatWall | M4 | 01/2015-12/2017 | 433MHz | | ● | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| GreatWall | M4 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641101BKN01A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641100AKR02A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641100XKR02A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | ORA Cat | 11/2020-12/2024 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER | 06/2021-12/2024 | 433MHz Clamp in | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| GreatWall | POER | 09/2019-12/2024 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER | 09/2019-12/2022 | 433MHz Snap in | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER EV | 09/2020-12/2023 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | POER EV | 09/2020-12/2023 | 433MHz 3641100XKR02A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Voleex C20R | 09/2011-12/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C20R | 01/2014-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2018-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C30 | 01/2014-12/2017 | 433MHz 3641110AK80XA | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Voleex C50 | 04/2010-12/2016 | 433MHz 3641100AKZ16A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| GreatWall | Voleex C50 | 04/2010-12/2016 | 433MHz 3641100XKZ16B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|----------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| GreatWall | Wingle 5 | 01/2016-12/2024 | 433MHz 3641100XKU00A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 5 | 01/2011-12/2016 | 433MHz 3641110AK80XA | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 5 | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 6 | 01/2012-12/2015 | 433MHz 3641110AK80XA | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 6 | 01/2014-12/2015 | 433MHz 3641110K80 | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| GreatWall | Wingle 6 | 04/2014-11/2018 | 433MHz 3641100XSZ08A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 7 | 06/2018-12/2024 | 433MHz 3641100XKU00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| GreatWall | Wingle 7 | 06/2018-12/2024 | 433MHz 3641100XKU00A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| HaiMa | Family | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | Freema | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | Haima 7 | 01/2012-12/2013 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | M3 | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| HaiMa | QISHI | 01/2010-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HaiMa | S5 | 01/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| HaiMa | S7 | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | Steel Mate | ● | ● |
| HanTeng | X5 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| HanTeng | X7 | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 08/2020-12/2024 | 433MHz 3641100XKR02A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo | 08/2020-12/2024 | 433MHz 3641101BKN01A | | ● | ● | ○ | 0/A | 433MHz | SAT | ● | ● |
| Haval | Dargo | 08/2020-12/2024 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Dargo II | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Haval | F7 | 11/2018-12/2023 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | F7 | 11/2018-12/2023 | 433MHz 3641100BKR02A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | H1 | 01/2014-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H1 | 01/2022-06/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H2 | 01/2014-12/2023 | 433MHz 3641100XKU00A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Haval | H5 | 06/2010-12/2015 | 433MHz 3641110AK80XA | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| Haval | H5 | 06/2010-12/2015 | 433MHz 3641110K80 | | ○ | ● | ○ | S | 433MHz | SAT | ● | ● |
| Haval | H5 | 01/2016-06/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 | 01/2013-12/2022 | 433MHz 3641100AKZ16A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Haval | H6 | 01/2017-12/2021 | 433MHz 3641100BKR02A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | H6 | 08/2020-12/2024 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 | 08/2020-12/2024 | 433MHz 3641101BKN01A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 | 01/2019-12/2023 | 433MHz 3641100XKU00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 | 01/2017-12/2023 | 433MHz 3641100AKU00B | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Haval | H6 | 01/2017-12/2021 | 433MHz 3641100XKR02A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H6 | 01/2016-12/2019 | 433MHz 3641100XKZ16B | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Haval | H6 | 01/2011-12/2021 | 433MHz 3641100XKZ16A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | H6 | 06/2024-12/2024 | 433MHz 3641100XKV3AA | | ● | ● | ○ | 0/A | 433MHZ | Schrader | ● | ● |
| Haval | H6 | 05/2023-12/2024 | 433MHz 3641100XKN02A | | ● | ● | ○ | 0/A | 433MHz | Dias | ● | ● |
| Haval | H7 | 01/2016-12/2022 | 433MHz 3641100XKU00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H7 | 01/2023-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHZ | Schrader | ● | ● |
| Haval | H7 | 01/2016-12/2022 | 433MHz 3641100XKU00A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 01/2014-12/2019 | 433MHz 3641100XKU00A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | H9 | 08/2019-08/2024 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|----------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Haval | H9 | 08/2019-08/2024 | 433MHz 3641100XKR02A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641101BKN01A | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641100XKR02A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641100AKR02A | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641101XKN01A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Haval | Jolion | 08/2020-12/2023 | 433MHz 3641100BKR02A | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| Honda | Accord | 01/2008-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | Accord | 01/2013-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | CR-V | 01/2007-12/2011 | 315MHz Alloy/Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | CR-V | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Honda | CR-V | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | CR-V | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | CR-Z | 01/2016-12/2016 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | CR-Z | 01/2010-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Civic | 06/2005-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Civic | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Civic | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Clarity | 01/2016-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Crosstour | 01/2010-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Honda | Element | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Element | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Element | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | FCX Clarity | 01/2010-12/2010 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | Fit | 01/2018-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Fit | 01/2015-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Fit | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | Fit | 01/2009-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | GL1800 | 01/2009-12/2015 | 315MHz MOTOR Cycle | | ○ | ○ | ○ | S | 315MHz | LDL Technology | Activate Only | ● |
| Honda | Gold Wing | 01/2009-06/2017 | 315MHz MOTOR Cycle | | ○ | ○ | ○ | S | 315MHz | LDL Technology | Activate Only | ● |
| Honda | HR-V | 09/2014-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Honda | HR-V | 11/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | HR-V CROSSOVER | 01/2016-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | Insight | 01/2009-12/2016 | 315MHz 42753TR3A81 | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Honda | Insight | 05/2009-12/2022 | 315MHz 42753SNAA83 | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Insight | 01/2018-12/2022 | Indirect | | ○ | ○ | ○ | S | | N/A | Indirect | ● |
| Honda | Legend | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Legend | 01/2015-12/2021 | 315MHz | Hybrid | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | NSX | 01/2016-12/2020 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Honda | NSX | 01/2016-06/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 01/2021-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 01/2008-12/2010 | 315MHz | EX/EX-L | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Odyssey | 01/2006-12/2007 | 315MHz | EX/EX-L | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey | 01/2011-12/2020 | 315MHz | EX/EX-L | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey Touring | 01/2005-12/2007 | 315MHz | TOUR | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey Touring | 01/2008-12/2010 | 315MHz | TOUR | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey Touring | 01/2011-12/2019 | 315MHz | TOUR | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Odyssey Touring | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Passport | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2005-12/2005 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Pilot | 01/2018-12/2024 | 433MHz 42753T6NA01 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2023-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2016-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Pilot | 01/2009-12/2015 | 315MHz Alloy | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Honda | Pilot | 01/2009-12/2015 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Honda | Pilot | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Pilot | 01/2005-12/2005 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Prologue | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Honda | Ridgeline | 01/2017-12/2019 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2021-12/2024 | 433MHz 42753T3RA02 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Ridgeline | 01/2016-12/2019 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Honda | Ridgeline | 01/2009-12/2014 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2009-12/2014 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2006-12/2008 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | Ridgeline | 01/2006-12/2008 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Honda | S2000 | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Hummer | H2 | 01/2009-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2008-12/2008 | 315MHz 15922396 | | ● | ● | ● | 0/S | 315MHz | TRW | ● | ● |
| Hummer | H2 | 01/2008-12/2008 | 315MHz 13598771 | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Hummer | H2 | 01/2003-12/2007 | 315MHz | | ● | ● | ● | S | 315MHz | TRW | ● | ● |
| Hummer | H3 | 01/2005-12/2006 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Hummer | H3 | 01/2007-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|--------------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Accent | 04/2011-12/2021 | 433MHz Hi Line | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 10/2014-12/2021 | 433MHz Lo Line | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 01/2006-03/2011 | 315MHz 529332F000 | MC | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Accent | 04/2011-09/2014 | 433MHz | RB | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2011-12/2016 | 315MHz 529333N000 | RB | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2019-12/2024 | 433MHz Hi Line | HC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2019-12/2024 | 433MHz Lo Line | HC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Accent | 04/2011-09/2014 | 315MHz 529332M000 | RB | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Accent | 01/2006-12/2007 | 315MHz 529333E000 | MC | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Avante | 01/2019-12/2023 | 433MHz 52933F2000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 01/2024-12/2024 | 433MHz | GN7 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Azera | 01/2012-12/2019 | 433MHz | HG | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Azera | 01/2012-12/2014 | 315MHz | HG | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Azera | 01/2006-12/2011 | 315MHz | TG | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Azera | 01/2024-12/2024 | 433MHz 52940N1000 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Azera hybrid | 01/2024-12/2024 | 433MHz 52940N1000 | GN7 HEV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Azera hybrid | 01/2024-12/2024 | 433MHz | GN7 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | C-Sedan EV | 01/2024-12/2024 | 433MHz 52940E2100 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Hyundai | Centennial | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Creta | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2022-12/2022 | 433MHz | SU2r | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2021-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Creta | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Custin | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Hyundai | D-Cuv EV | 01/2024-12/2024 | 433MHz 52940E2100 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra | 10/2013-12/2019 | 315MHz Lo Line | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| Hyundai | Elantra | 10/2010-12/2013 | 315MHz | UD/MD | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Elantra | 01/2007-12/2010 | 315MHz | HD | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Elantra | 01/2012-12/2020 | 433MHz | AD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 07/2020-12/2024 | 433MHz 52940L1100 | CN7/CN7A | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 01/2024-06/2025 | 433MHz 52940L1100 | CN7 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra | 07/2020-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Elantra | 01/2014-12/2018 | 433MHz | MD/UD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | Elantra | 01/2021-12/2022 | 433MHz | AD | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2013-12/2015 | 315MHz | GD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 06/2017-12/2020 | 433MHz | PD | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2021-12/2021 | 433MHz | PD | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2016-06/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 07/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra GT | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Elantra N | 01/2022-12/2024 | 433MHz 52933J5000 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 01/2024-12/2024 | 433MHz 52940CG100 | CN7 N | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 01/2024-12/2024 | 433MHz 52933J5000 | CN7 N | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 01/2024-12/2024 | 433MHz 52940L8200 | CN7 N | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 01/2022-12/2024 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra N | 01/2022-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Elantra Touring | 01/2013-12/2017 | 315MHz 529333N000 | | ○ | ● | ○ | NA | 315MHz | Continental | ● | ● |
| Hyundai | Elantra Touring | 01/2009-12/2012 | 315MHz 529332L700 | FD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra Touring | 01/2009-12/2012 | 315MHz 529332L500 | FD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Elantra hybrid | 01/2024-06/2025 | 433MHz 52940L1100 | CN7 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Entourage | 10/2006-06/2008 | 315MHz | EP | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Entourage | 07/2008-12/2012 | 315MHz | EP | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Equus | 01/2010-02/2013 | 315MHz Hi Line | VI | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Equus | 03/2013-06/2016 | 315MHz Hi Line | VI | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Equus | 01/2010-07/2013 | 315MHz Lo Line | VI | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Equus | 01/2013-12/2019 | 433MHz | VI New | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis | 01/2013-12/2016 | 315MHz Lo Line | BK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 04/2008-12/2012 | 315MHz | BK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2013-12/2016 | 315MHz Hi Line | BK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2008-12/2014 | 315MHz TRW | BH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis | 01/2014-12/2017 | 433MHz | DH | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2011-12/2016 | 315MHz Hi Line | BK | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis Coupe | 01/2008-12/2012 | 315MHz Lo Line | BK | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Genesis G70 | 01/2018-12/2024 | 433MHz 52933J5000 | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Genesis G70 | 01/2017-12/2017 | 433MHz | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2024-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2024-06/2025 | 433MHz 52933J5000 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G70 | 01/2018-12/2024 | 433MHz 52940CG100 | IK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G80 | 07/2021-12/2024 | 433MHz 52940T6000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 01/2020-12/2022 | 433MHz | DH | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 07/2016-12/2019 | 433MHz 52933B1100 | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 07/2016-12/2019 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 | 01/2021-12/2024 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G80 EV | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2017-12/2024 | 433MHz | HI | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2022-12/2024 | 433MHz 52940CG100 | RS4 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis G90 | 01/2016-12/2016 | 433MHz | HI | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis G90 | 01/2022-12/2024 | 433MHz 52933D4100 | RS4 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV60 | 12/2021-12/2024 | 433MHz 52933D2100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV60 | 12/2021-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV70 | 01/2021-12/2024 | 433MHz 52933D2100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 12/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV70 | 01/2022-12/2022 | 433MHz | IK | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis GV70 EV | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 01/2024-12/2024 | 433MHz 52940T6000 | JX1 FL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 01/2024-12/2024 | 433MHz 52933D4100 | JX1 FL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 07/2021-12/2024 | 433MHz 52940T6000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 01/2020-12/2024 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Genesis GV80 | 01/2021-12/2022 | 433MHz 52933J5000 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Genesis Sedan | 01/2009-12/2014 | 315MHz | BH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Genesis Sedan | 01/2014-06/2016 | 433MHz | DH | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grand I10 | 01/2020-12/2024 | 433MHz 52940BV100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Grand I10 | 01/2014-12/2020 | 433MHz 52933B2100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Grand I10 | 01/2024-06/2025 | 433MHz 52940BV100 | AI3 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Grand I10 | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur | 01/2024-06/2025 | 433MHz | GN7 HEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Hyundai | Grandeur | 07/2021-12/2023 | 433MHz 52940T6100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Grandeur GN7 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H-1 | 01/2014-12/2023 | 433MHz | HR | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | H-1 | 01/2013-05/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | H-350 | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Hyundai | H-350 | 01/2014-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | H100 | 01/2010-12/2024 | 433MHz | TQ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | HB20 | 01/2020-06/2025 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq | 01/2016-12/2023 | 433MHz | AE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2025-06/2025 | 433MHz 52940L8200 | NE EV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Ioniq 5 | 01/2022-06/2025 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5 | 01/2022-06/2025 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Ioniq 5 | 01/2025-06/2025 | 433MHz 52940L1100 | NE EV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 5N | 01/2024-06/2025 | 433MHz 52940L8200 | NE EV N | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Ioniq 5N | 01/2024-06/2025 | 433MHz 52940L1100 | NE EV N | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Ioniq 6 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Kona | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | Continental | ● | ● |
| Hyundai | Kona | 01/2024-06/2025 | 433MHz | SX2 | ● | ● | ○ | A/0 | 433MHz | Continental | ● | ● |
| Hyundai | Kona N | 01/2022-12/2024 | 433MHz | OSN | ● | ● | ○ | A/0 | 433MHz | Continental | ● | ● |
| Hyundai | Kona electric | 01/2024-06/2025 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | Continental | ● | ● |
| Hyundai | Nexo | 04/2018-12/2024 | 433MHz | FE | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Nexo | 04/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Palisade | 01/2023-12/2024 | 433MHz | LX2 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Porter | 01/2006-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Cruz | 01/2022-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Santa Cruz | 01/2019-12/2021 | 433MHz 52940L1100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2024-12/2024 | 433MHz 52940AY200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2021-12/2024 | 433MHz | TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2019-12/2019 | 315MHz | NC | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 03/2018-12/2024 | 433MHz | TM/TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2024-12/2024 | 433MHz 52940E2100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2014-04/2017 | 433MHz Hi Line | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2008-12/2008 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 01/2006-12/2007 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Santa Fe | 10/2009-12/2012 | 315MHz | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|----------------|-----------------|----------------------|-------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Hyundai | Santa Fe | 01/2024-12/2025 | 433MHz 52940Q3100 | MX5/MX5 HEV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2024-12/2025 | 433MHz 52940AY200 | MX5/MX5 HEV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2015-12/2018 | 315MHz | NC | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 06/2024-12/2025 | 433MHz 52940E2100 | MX5 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe | 01/2008-12/2008 | 315MHz Hi Line | CM | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Santa Fe | 01/2008-12/2010 | 315MHz Lo Line | CM | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Santa Fe | 06/2012-12/2014 | 315MHz | NC | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 01/2017-06/2020 | 433MHz | NC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe | 03/2018-12/2024 | 433MHz 52940Q3100 | TM/TMA | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe Sport | 01/2019-12/2019 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2018-12/2018 | 433MHz 52933C1100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe Sport | 01/2018-12/2018 | 433MHz 52933D4100 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2019-12/2019 | 315MHz | DMA | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2019-12/2022 | 433MHz 52933C1100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Santa Fe Sport | 01/2013-12/2014 | 315MHz | DMA | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Santa Fe Sport | 01/2015-12/2018 | 315MHz | DMA | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Solati | 03/2014-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 12/2009-05/2014 | 315MHz 529332M000 | YF | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata | 12/2007-01/2010 | 315MHz 529332F000 | NF | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Sonata | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2006-12/2008 | 315MHz 529333E000 | NF | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Sonata | 05/2013-12/2016 | 315MHz Hi Line | Hi Line 315MHz | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata | 01/2024-06/2025 | 433MHz 52940L1100 | DN8 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata | 04/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata | 04/2014-12/2019 | 433MHz Hi Line | LF/LFA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata Hybrid | 01/2011-12/2015 | 315MHz Lo Line | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 01/2024-12/2024 | 433MHz 52940L1100 | DN8 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 01/2020-12/2023 | 433MHz 52940L1100 | DN8 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 01/2010-12/2019 | 315MHz | YF HEV | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | Sonata Hybrid | 03/2015-12/2019 | 433MHz Hi Line | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Sonata N | 01/2023-12/2024 | 433MHz 52940L1100 | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------------|-----------------|----------------------|---------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Hyundai | Starex | 01/2021-12/2023 | 433MHz 52940CG100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Starex | 03/2011-03/2021 | 433MHz | TQ | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Hyundai | Staria | 01/2023-12/2024 | 433MHz 52940E2100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Staria | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tiburon | 01/2008-12/2008 | 315MHz Lo Line | GK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tiburon | 01/2007-12/2007 | 315MHz Lo Line | GK | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2024-06/2025 | 433MHz 52940Q3100 | NX4E HEV/PHEV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2004-12/2007 | 315MHz | JM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 07/2024-06/2025 | 433MHz 52940BV100 | NX4/NX4E | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2008-12/2009 | 315MHz | JM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2010-07/2013 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 04/2014-12/2017 | 315MHz FUEL CELL | LM FCEV | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 09/2014-12/2015 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2021-12/2024 | 433MHz 52940Q3100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 07/2024-06/2025 | 433MHz 52940L1100 | NX4/NX4E | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Tucson | 01/2021-12/2024 | 433MHz 52940BV100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2021-09/2021 | 433MHz Hi Line | TL | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 05/2015-12/2020 | 433MHz Hi Line | TL | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 08/2013-08/2014 | 315MHz | LM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Tucson | 01/2021-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Tucson | 01/2024-06/2025 | 433MHz 52940BV100 | NX4 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson | 01/2021-12/2023 | 433MHz 52940Q3100 | NX4E HEV/PHEV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson hybrid | 07/2024-06/2025 | 433MHz 52940BV100 | NX4 HEV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | Tucson hybrid | 07/2024-06/2025 | 433MHz 52940L1100 | NX4 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Veloster | 01/2019-12/2020 | 433MHz 529332V100 | FS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | Veloster | 01/2011-12/2019 | 315MHz | FS | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Hyundai | Veloster | 01/2018-12/2024 | 433MHz | JS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Veloster N | 01/2019-06/2024 | 433MHz | JSN | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 01/2023-12/2024 | 433MHz 52933D4100 | QX | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 01/2022-12/2024 | 433MHz 52933D4100 | QXI | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | Venue | 01/2019-12/2022 | 433MHz 52933D4100 | QX/QXI | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Hyundai | Veracruz | 01/2014-12/2018 | 315MHz Lo Line | EN | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Veracruz | 01/2013-12/2013 | 315MHz Lo Line | EN | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Hyundai | Veracruz | 01/2006-12/2008 | 315MHz Hi Line | EN | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Hyundai | Veracruz | 01/2008-12/2012 | 315MHz Lo Line | EN | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| Hyundai | Verna | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i10 | 01/2020-12/2023 | Indirect | LA | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Hyundai | i10 | 11/2013-06/2020 | 433MHz 52933B2100 | IA | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Hyundai | i10 | 10/2007-10/2013 | 433MHz | IA/PA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | i20 | 10/2014-12/2020 | 433MHz | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i20 | 01/2021-12/2024 | 433MHz 52933C1100 | GB | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i30 | 04/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Hyundai | i30 N | 01/2018-12/2024 | 433MHz 52933F2000 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Hyundai | i30 N | 01/2018-12/2024 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | i40 | 01/2011-03/2014 | 433MHz Second | VF | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 01/2011-03/2014 | 433MHz | VF | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 04/2014-12/2020 | 433MHz | VF | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Hyundai | i40 | 01/2017-12/2019 | 433MHz | IF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Hyundai | ix35 | 01/2017-06/2020 | 433MHz | TL/TLE | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Hyundai | ix35 | 07/2020-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| INEOS | Grenadier | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Infiniti | EX Series | 03/2010-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | EX Series | 01/2008-12/2008 | 315MHz 40700CD001 | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | EX Series | 11/2007-03/2011 | 315MHz 40700JK00C | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 05/2008-04/2011 | 315MHz 40700JK00C | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 05/2008-04/2010 | 315MHz 40700JY10A | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | FX Series | 11/2002-06/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | FX Series | 07/2007-08/2010 | 315MHz 40700JK01B | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 07/2008-12/2010 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | FX Series | 12/2010-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | FX Series | 12/2010-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | FX Series | 07/2007-06/2008 | 315MHz 40700JA00B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | G Series | 08/2006-11/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | G Series | 01/2002-07/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | G Series | 08/2006-12/2007 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Infiniti | G Series | 07/2011-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | G Series | 01/2007-06/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | G Series | 03/2010-12/2015 | 315MHz 407001LA0E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | JX35 | 04/2012-01/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | M Series | 05/2010-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | M Series | 05/2008-04/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | M Series | 01/2008-12/2013 | 315MHz 407001AA0C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | M Series | 09/2007-08/2008 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | M Series | 07/2002-08/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | M Series | 08/2010-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q30 | 04/2016-12/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | Q40 | 06/2014-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q45 | 08/2002-08/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | Q45 | 09/2006-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | Q50 | 11/2013-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q50 | 01/2014-07/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Infiniti | Q60 | 07/2013-09/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q60 | 01/2017-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Infiniti | Q60 | 10/2016-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | Q60 | 09/2013-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q60 | 07/2013-09/2016 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | Q70 | 11/2014-12/2021 | 433MHz 407006WY0B | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q70 | 07/2013-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | Q70 | 07/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | Q80 | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX30 | 04/2016-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Infiniti | QX4 | 01/1996-12/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX40 | 01/2003-12/2003 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX50 | 04/2018-05/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX50 | 12/2016-03/2018 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Infiniti | QX50 | 09/2013-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX50 | 05/2014-03/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX50 | 06/2020-12/2024 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX55 | 04/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX55 | 08/2021-03/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX56 | 01/2004-04/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX56 | 05/2007-05/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Infiniti | QX56 | 01/2010-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX56 | 06/2010-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX60 | 11/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Infiniti | QX60 | 08/2018-12/2021 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX60 | 04/2012-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Infiniti | QX70 | 10/2013-04/2014 | 433MHz 407001LLOD | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX70 | 09/2013-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX70 | 05/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 05/2022-12/2024 | 315MHz 407006GPOA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 10/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 09/2014-12/2023 | 433MHz 407006WYOC | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 08/2024-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 10/2017-12/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Infiniti | QX80 | 10/2013-09/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Infiniti | QX80 | 09/2013-09/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Isuzu | Ascender | 01/2006-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Isuzu | D-Max | 01/2020-12/2024 | 433MHz 8974993680 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Isuzu | LingTuo | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Isuzu | Rodeo | 01/2004-12/2004 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Isuzu | i-290 | 01/2007-06/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Isuzu | i-370 | 01/2007-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| JAC | E-S2 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | JAC | ● | ● |
| JAC | HUNTER | 03/2021-12/2024 | 433MHz 3666200U7300 | | ● | ● | ○ | C | 433MHz | SAT | ● | ● |
| JAC | HUNTER | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | Dias | ● | ● |
| JAC | J4 | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J6 | 01/2011-12/2017 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | J7 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | J7 | 01/2020-12/2023 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | J7 PLUS | 06/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JAC | JS2 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | JS3 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | JAC | ● | ● |
| JAC | JS4 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | JS6 | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| JAC | JS7 | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | JS8 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Jiayue X4 | 06/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| JAC | Jiayue X7 | 04/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Jiayue X7 | 04/2020-12/2021 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | Refine M4 | 08/2020-02/2021 | 433MHz 3666200V5000 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | Refine M4 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| JAC | Refine S2 | 01/2016-12/2022 | 433MHz Steel | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S2 | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| JAC | Refine S2 | 09/2017-12/2022 | 433MHz 3666200V5000 | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | Refine S3 | 01/2014-12/2022 | 433MHz 3666200V5000 | | ● | ● | ○ | 0/S | 433MHz | JAC | ● | ● |
| JAC | Refine S3 | 01/2014-12/2022 | 433MHz TP3040001 | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| JAC | Refine S4 | 08/2019-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| JAC | Refine S5 | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | Refine S7 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| JAC | SUNRAY | 06/2019-12/2024 | 433MHz 3666200X4340 | | ● | ● | ○ | 0 | 433MHz | JAC | ● | ● |
| JAC | SUNRAY | 01/2021-12/2024 | 433MHz 3666200R0542 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| JAC | Sehol E10X | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Sehol E40X | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | JAC | ● | ● |
| JAC | Sehol E50A | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | Sehol X6 | 06/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JAC | Sehol X8 | 01/2020-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | T6 | 01/2015-12/2020 | 433MHz SCH | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| JAC | T6 | 01/2020-12/2024 | 433MHz 3666200V5000 | | ● | ● | ○ | S | 433MHz | JAC | ● | ● |
| JAC | T6 | 01/2020-12/2024 | 433MHz 3666200P3331 | | ● | ● | ○ | C | 433MHz | Dias | ● | ● |
| JAC | T8 | 01/2019-12/2022 | 433MHz | | ● | ● | ○ | C | 433MHz | Schrader | ● | ● |
| JAC | T8 | 01/2022-12/2024 | 433MHz 3666200P3331 | | ● | ● | ○ | C | 433MHz | Dias | ● | ● |
| JAC | T9 | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | SAT | ● | ● |
| JAC | e-J7 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | e-JS1 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |
| JAC | e-JS4 | 01/2021-06/2024 | 433MHz | | ● | ● | ○ | C | 433MHz | JAC | ● | ● |
| JAC | iEVS4 | 09/2019-12/2020 | 433MHz | | ○ | ● | ○ | NA | 433MHz | JAC | ● | ● |
| JAECOO | J7 | 05/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | DASHING | 09/2022-12/2024 | 433MHz F113114011BA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | DASHING | 09/2022-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | DASHING i-DM | 09/2022-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | ShanHai L7 | 08/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| JETOUR | ShanHai L9 | 10/2023-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | ShanHai L9 | 10/2023-12/2024 | 433MHz F113114011BA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | T2 | 09/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | X70 | 06/2018-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70 | 06/2018-12/2024 | 433MHz F113114011BA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | X70 | 06/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|--------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| JETOUR | X70 C-DM | 02/2024-12/2024 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70 C-DM | 02/2024-12/2024 | 433MHz F113114011BA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | X70 Coupe | 04/2020-12/2023 | 433MHz QY1051 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70 PLUS | 10/2020-12/2023 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70 PLUS | 10/2020-12/2024 | 433MHz F113114011BA | | ● | ● | ○ | 0 | 433MHz | BHSENS | ● | ● |
| JETOUR | X70 PLUS | 10/2020-12/2024 | 433MHz QY1051 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70M | 03/2020-12/2024 | 433MHz F023114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JETOUR | X70M | 03/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC | TeShun | 01/2020-06/2024 | 433MHz KC16508AA | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC Ford | Territory | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| JMC Ford | Territory EV | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Jaguar | E-Pace | 01/2022-12/2024 | 433MHz M8E21A159AA | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 01/2019-12/2022 | 433MHz | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | E-Pace | 01/2017-12/2018 | 433MHz | X540 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2022-12/2024 | 433MHz M8E21A159AA | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2015-12/2018 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Pace | 01/2019-12/2022 | 433MHz | X761 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 11/2012-04/2016 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 11/2012-04/2016 | 315MHz AH521A159CA | X152 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2021-12/2023 | 433MHz M8E21A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2019-12/2024 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 01/2019-06/2021 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 05/2016-12/2018 | 433MHz FW931A159AB | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 05/2016-12/2018 | 433MHz GX631A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | F-Type | 11/2012-04/2016 | 433MHz AH521A159AA | X152 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2019-12/2023 | 433MHz GX631A159AA | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2017-12/2018 | 433MHz | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | I-Pace | 01/2021-12/2024 | 433MHz M8E21A159AA | X590 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | S-Type | 10/1998-08/2011 | 315MHz | X200 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jaguar | S-Type | 10/1998-08/2011 | 433MHz | X200 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | Super V8 | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jaguar | Super V8 | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jaguar | Super V8 | 01/2005-12/2009 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | Vanden Plas | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | Vanden Plas | 01/2004-12/2006 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | Vanden Plas | 01/2004-12/2009 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | X-Type | 01/2001-12/2009 | 433MHz | X400 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | X-Type | 01/2001-12/2009 | 315MHz | X400 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XE | 04/2015-12/2018 | 433MHz FW931A159AB | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2019-12/2022 | 433MHz GX631A159AA | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2022-12/2023 | 433MHz M8E21A159AA | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XE | 01/2015-12/2018 | 433MHz GX631A159AA | X760 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2008-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XF | 01/2014-09/2016 | 433MHz FW931A159AB | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 09/2015-12/2018 | 433MHz | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 01/2019-12/2024 | 433MHz GX631A159AA | X260 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XF | 04/2009-08/2015 | 315MHz | X250 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XF | 01/2007-08/2015 | 433MHz | X250 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XFR | 01/2010-12/2012 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Jaguar | XFR | 01/2010-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 433MHz GX631A159AA | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 433MHz FW931A159AB | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 433MHz AH521A159AA | X351 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 12/2002-12/2009 | 315MHz | X350 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XJ | 12/2002-12/2009 | 433MHz | X350 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XJ | 01/2010-04/2020 | 315MHz AH521A159CA | X351 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XK | 01/2010-12/2015 | 433MHz | X150 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 01/2006-12/2009 | 315MHz | X150 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XK | 01/2006-12/2009 | 433MHz | X150 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK | 01/2010-12/2015 | 315MHz | X150 | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jaguar | XK-S | 03/2014-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jaguar | XK-S | 01/2013-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jeep | Cherokee | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2015-12/2017 | 315MHz | | ● | ● | ● | O/A | 315MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2005-12/2013 | 433MHz 56029359AC | KK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Cherokee | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2023 | 433MHz | KL | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2018-12/2018 | 433MHz 68324960AA | | ● | ● | ○ | O/A | 433MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Cherokee | 12/2015-12/2017 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 10/2013-11/2015 | 433MHz | KL | ● | ● | ● | O/A | 433MHz | TRW | ● | ● |
| Jeep | Cherokee | 01/2006-12/2012 | 315MHz | | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Cherokee | 01/2019-12/2022 | 315MHz | | ● | ● | ○ | O/A | 315MHz | TRW | ● | ● |
| Jeep | Commander | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Commander | 01/2008-12/2011 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2006-12/2007 | 315MHz | XK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Commander | 01/2006-12/2007 | 433MHz | XK | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Commander | 01/2022-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 05/2006-12/2014 | 433MHz VDO | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2007-12/2009 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 01/2019-12/2025 | 433MHz | MP/MX | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2010-12/2011 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 01/2012-12/2012 | 433MHz SCH | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2012-12/2015 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2012-12/2016 | 315MHz | MK49 | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 315MHz | | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2017-12/2017 | 433MHz | MP/MX | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Compass | 01/2019-12/2024 | 315MHz Continental | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Jeep | Compass | 01/2018-12/2018 | 433MHz | MP/MX | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Compass | 01/2019-12/2019 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Gladiator | 07/2021-12/2025 | 433MHz Conti | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Gladiator | 11/2019-12/2022 | 433MHz MRXAG4WA5 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Gladiator | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Gladiator | 01/2021-06/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2011-12/2016 | 433MHz Schrader | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 07/2010-12/2010 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 06/2006-12/2010 | 433MHz | WH | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2006-12/2007 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2005-05/2006 | 433MHz | | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 05/2004-12/2005 | 315MHz | WK | ● | ● | ● | O/A | 315MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2001-12/2004 | 433MHz | WK/WJ | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2008-06/2010 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2024-12/2025 | 433MHz Conti | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 11/2023-12/2025 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2022-12/2022 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Cherokee | 01/2021-12/2023 | 433MHz Conti | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2021-12/2023 | 433MHz | WL | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2018-12/2022 | 433MHz 68252493AB | WK | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | WK | ● | ● | ● | O/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee | 01/2016-12/2017 | 433MHz | | ● | ● | ● | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Jeep | Grand Cherokee L | 01/2021-12/2023 | 433MHz | WL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Cherokee L | 11/2023-12/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Commander | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Jeep | Grand Wagoneer | 01/2022-12/2022 | 433MHz 68193586AC | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Wagoneer | 01/2022-12/2023 | 433MHz 68339096AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Grand Wagoneer | 09/2023-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Grand Wagoneer | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | JT | 11/2020-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | JT | 01/2021-12/2024 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Liberty | 01/2002-12/2004 | 433MHz | KJ | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2010-12/2012 | 315MHz | KK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2005-12/2006 | 315MHz | KJ | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2006-12/2012 | 433MHz | KK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Liberty | 01/2007-12/2009 | 315MHz | KJ | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2007-12/2010 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Patriot | 01/2018-06/2019 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2012-12/2017 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Patriot | 01/2007-12/2016 | 315MHz | MK | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2015-12/2017 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2018-12/2024 | 433MHz 68193586AC | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2017-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2016-12/2017 | 433MHz 68252493AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2015-12/2016 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2019-12/2023 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Renegade | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Jeep | Scrambler | 01/2020-12/2021 | 433MHz DT 68293199AA | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 01/2019-12/2022 | 433MHz DT 68293199AA | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 08/2023-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wagoneer | 01/2023-12/2023 | 433MHz | WS | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wagoneer | 01/2022-12/2022 | 433MHz 68339096AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2007-12/2009 | 315MHz | JK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Wrangler | 06/2008-12/2010 | 433MHz | JK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2010-12/2012 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2010-12/2012 | 315MHz | JK | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2015-12/2017 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2013-12/2014 | 433MHz | JK | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Jeep | Wrangler | 07/2021-12/2025 | 433MHz Conti | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Jeep | Wrangler | 01/2019-12/2020 | 433MHz | JL | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Jeep | Wrangler | 01/2019-12/2019 | 433MHz | J3 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KARRY | K50 | 01/2018-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| KARRY | K60 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| KARRY | K60 | 01/2018-12/2023 | 433MHz F113114011 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| KAWEI | W150 | 06/2019-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | SAT | ● | ● |
| KIA | Amanti | 01/2009-12/2009 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Amanti | 01/2007-12/2007 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Amanti | 01/2010-12/2011 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Amanti | 01/2008-12/2008 | 315MHz | GH | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Bongo | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Bongo | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Borrego | 01/2008-12/2020 | 315MHz | HM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Cadenza | 01/2014-12/2017 | 433MHz | VG | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2013-12/2021 | 315MHz | VG | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Cadenza | 01/2016-12/2021 | 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Carens | 01/2006-12/2020 | 433MHz | RP/UN | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carens | 01/2022-12/2022 | 433MHz | KY | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carens | 01/2023-12/2024 | 433MHz | KY | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Carnival | 01/2022-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2024-12/2025 | 433MHz 52933D4100 | KA4 (PE) | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2022-12/2024 | 433MHz 52933D4100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carnival | 01/2024-12/2025 | 433MHz | KA4 (PE) | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carnival HEV | 01/2024-12/2025 | 433MHz 52933D4100 | KA4 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Carnival HEV | 01/2024-12/2025 | 433MHz | KA4 HEV | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Ceed | 05/2018-12/2019 | 433MHz | CD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Ceed | 01/2020-12/2020 | 433MHz | CD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Cerato | 01/2015-12/2016 | 433MHz | BD | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Cerato | 01/2019-12/2021 | 433MHz | BD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Cerato | 02/2009-12/2014 | 433MHz 529333X305 | TD | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Cerato | 01/2017-12/2018 | 315MHz | YD | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Cerato | 01/2022-12/2024 | 433MHz | BD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | E-Niro | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | E-Niro | 01/2023-12/2024 | 433MHz | SG2 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | E-Soul | 04/2019-12/2024 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | EV6 | 03/2021-12/2024 | 433MHz 52940CG100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV6 | 01/2025-06/2025 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | EV6 | 01/2025-06/2025 | 433MHz 52940E2100 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|-----------|-----------------|----------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | EV6 | 01/2025-06/2025 | 433MHz 52940Q3100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV6 | 01/2025-06/2025 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV6 | 03/2021-12/2024 | 433MHz 52940L8200 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV6 | 03/2021-12/2024 | 433MHz 52940BV100 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | EV9 | 07/2023-06/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Forte | 01/2009-04/2013 | 315MHz | TD | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Forte | 01/2022-12/2024 | 433MHz | BD/BDm | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Forte | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Forte | 01/2019-12/2021 | 433MHz | BD/BDm | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | Forte | 04/2015-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Forte | 02/2013-04/2015 | 315MHz | YD | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| KIA | K2500 | 06/2014-06/2024 | 433MHz | PU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K2700 | 06/2014-06/2024 | 433MHz | PU | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K3 | 01/2022-12/2023 | 433MHz | BD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | K3 | 07/2021-12/2021 | 433MHz | BD | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| KIA | K3000 | 06/2014-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2024-06/2025 | 433MHz | DL3/DL3 HEV (PE) | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2020-12/2024 | 433MHz 52933D4100 | Clamp In OE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K5 | 01/2020-12/2024 | 433MHz 52940L1100 | Snap In OE | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K5 Hybrid | 01/2016-06/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | K5 Hybrid | 12/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | K7 | 01/2008-12/2012 | 433MHz | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K7 | 01/2016-12/2021 | 433MHz | YG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K7 | 01/2013-12/2016 | 433MHz Hybrid | VG | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | K9 | 01/2011-12/2018 | 433MHz | KH | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | K900 | 01/2019-12/2020 | 433MHz | RJ | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | K900 | 01/2021-12/2023 | 433MHz | RJ | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | K900 | 01/2014-12/2018 | 433MHz | KH | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Magentis | 12/2005-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Mohave | 01/2019-12/2020 | 433MHz 529332J100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2017-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2016-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Mohave | 01/2009-12/2009 | 315MHz Hi Line | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Morning | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Niro | 01/2023-12/2024 | 433MHz 52940E2100 | SG2 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Niro | 01/2023-12/2024 | 433MHz 52940T6100 | SG2 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Niro | 07/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|---------------|-----------------|----------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Niro | 01/2019-06/2021 | 433MHz | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Niro | 01/2016-12/2022 | 433MHz 52933D4100 | DE | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Niro | 01/2023-12/2024 | 433MHz 52940CG100 | SG2 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Opirus | 01/2006-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| KIA | Optima | 09/2013-12/2015 | 315MHz | TF/QF | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Optima | 01/2020-12/2024 | 433MHz | DK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 12/2005-12/2010 | 315MHz | MG | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Optima | 07/2010-09/2013 | 315MHz | TF/QF | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| KIA | Optima | 09/2015-12/2022 | 433MHz | JF/JFA | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima | 01/2023-12/2024 | 433MHz | JF/JFA | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2014-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2016-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2011-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Optima Hybrid | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Picanto | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| KIA | Quoris | 06/2012-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Rio | 01/2017-12/2024 | 433MHz | SC | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Rio | 01/2006-12/2017 | 315MHz | JB | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Rio | 06/2011-12/2017 | 315MHz | UB | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Rio | 01/2017-12/2024 | 433MHz 529332J100 | SC | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Rondo | 01/2006-12/2011 | 315MHz | UN | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Rondo | 01/2014-12/2021 | 433MHz 529332J100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Rondo | 01/2013-06/2019 | 315MHz | RP | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| KIA | Sedona | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 01/2021-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sedona | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 01/2014-12/2014 | 433MHz | VQ | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Sedona | 06/2005-06/2008 | 315MHz | VQ | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| KIA | Sedona | 06/2008-12/2014 | 315MHz | VQ | ● | ● | ○ | 0 | 315MHz | Lear | ● | ● |
| KIA | Seltos | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sonet | 01/2021-06/2025 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sonet | 01/2024-06/2025 | 433MHz | QYC | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Sorento | 01/2014-06/2018 | 433MHz 529333N100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2020-12/2024 | 433MHz | MQ4/MQ4 PHEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2024-06/2025 | 433MHz 52940L1100 | MQ4/MQ4 HEV (PE) | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2024-12/2024 | 433MHz 52940L1100 | MQ4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2014-12/2015 | 315MHz | XM | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2011-12/2013 | 315MHz | XM | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2009-12/2010 | 315MHz TRW | BL/XM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------|----------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| KIA | Sorento | 01/2009-12/2010 | 315MHz Continental | BL | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2008-12/2008 | 315MHz | BL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sorento | 01/2005-12/2007 | 315MHz | BL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sorento | 01/2021-12/2023 | 433MHz 52933D4100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2017-12/2020 | 433MHz 52933D4100 | UMA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sorento | 01/2013-12/2013 | 315MHz 529332M550 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento | 01/2014-12/2015 | 315MHz 529332M550 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Sorento hybrid | 01/2025-06/2025 | 433MHz 52940L1100 | MQ4 PHEV | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Soul | 01/2009-10/2013 | 315MHz | AM | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| KIA | Soul | 01/2019-12/2019 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Soul | 01/2019-12/2019 | 433MHz | PS | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Soul | 01/2020-12/2022 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Soul | 01/2023-12/2024 | 433MHz | SK3 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Soul | 08/2013-12/2018 | 433MHz | PS | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul EV | 01/2019-12/2019 | 433MHz | PS EV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Soul EV | 01/2013-12/2018 | 433MHz | PS EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Soul Electric | 01/2019-12/2019 | 433MHz | SK3 EV | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Soul Electric | 06/2014-12/2018 | 433MHz | SK3 EV | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Spectra | 01/2006-12/2011 | 315MHz Lo Line | LD | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2005-12/2007 | 315MHz Lo Line | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2008-12/2008 | 315MHz Lo Line | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2008-12/2008 | 315MHz 529332F000 | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2007-12/2007 | 315MHz 529332F000 | KM | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2011-12/2013 | 315MHz Lo Line | KM/SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 09/2013-06/2014 | 315MHz | SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 06/2014-12/2016 | 315MHz | SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2016-12/2021 | 433MHz | QL | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| KIA | Sportage | 01/2022-12/2024 | 433MHz | QL | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Sportage | 01/2022-12/2024 | 433MHz 5294003100 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| KIA | Sportage | 01/2009-12/2010 | 315MHz Lo Line | KM/SL | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| KIA | Sportage | 01/2021-12/2024 | 433MHz 52940L1100 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| KIA | Stinger | 01/2018-12/2024 | 433MHz | CK | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| KIA | Stinger | 06/2017-12/2017 | 433MHz | CK | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Stonic | 01/2017-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| KIA | Telluride | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|---------------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| KIA | Telluride | 01/2023-12/2024 | 433MHz | ON | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| KIA | Telluride | 01/2024-12/2024 | 433MHz 52940E2100 | ON | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| KIA | Tuscany | 01/2007-12/2008 | 315MHz | YN | ○ | ● | ○ | NA | 315MHz | TRW | ● | ● |
| Karma | Revero | 01/2017-06/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| LDV | D60 | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | E-Deliver 9 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| LDV | EUNIQ5 | 07/2019-12/2023 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | EUNIQ5 | 07/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | EUNIQ6 | 05/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | EUNIQ6 | 05/2020-12/2023 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | EV30 | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| LDV | G10 | 01/2014-12/2024 | 433MHz GC91B50 | LTR | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | G10 | 01/2014-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | G10 | 01/2014-12/2024 | 433MHz GC91B50 | PCR | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | T60 | 01/2017-12/2024 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | T90 | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | T90 | 01/2021-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | V80 | 01/2024-12/2024 | 433MHz C00030048 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | V80 | 01/2022-12/2024 | 433MHz C00406825 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | V80 | 01/2015-12/2022 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | V80 | 01/2015-12/2022 | 433MHz TP3040001 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| LDV | V90 | 01/2020-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| LDV | V90 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Dias | ● | ● |
| Lada | Granta | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lada | Granta | 01/2017-12/2020 | 433MHz 407004CBOA | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Lada | Kalina | 05/2013-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Lada | Largus | 01/2014-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lada | Vesta | 01/2018-12/2019 | 433MHz Schrader | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Lamborghini | 140 Gallardo Superleggera | 01/2012-12/2016 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Aventador | 01/2010-12/2012 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Lamborghini | Aventador | 01/2011-12/2023 | 433MHz | LB834 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Gallardo | 01/2007-12/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 01/2014-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Huracan | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|-----------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lamborghini | Murcielago | 01/2007-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | One Off | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Reventon | 01/2007-12/2010 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Lamborghini | Urus | 01/2018-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Defender | 01/1997-12/2019 | 433MHz BH521A159AA | L316 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 03/2010-12/2019 | 433MHz | L316 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2020-12/2023 | 433MHz GX631A159AA | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2020-12/2024 | 433MHz M8E21A159AA | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Defender | 01/2020-12/2023 | 433MHz FW931A159AB | L663 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2017-12/2018 | 433MHz GX631A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2019-12/2022 | 433MHz GX631A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2021-12/2024 | 433MHz M8E21A159AA | L462 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery | 01/2002-05/2004 | 433MHz | L318 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Discovery Sport | 01/2015-12/2016 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 06/2014-12/2018 | 433MHz FW931A159AB | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2021-12/2024 | 433MHz M8E21A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2019-12/2022 | 433MHz BH521A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2019-12/2019 | 433MHz FW931A159AB | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 06/2014-12/2018 | 433MHz GX631A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2019-12/2022 | 433MHz GX631A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Discovery Sport | 01/2014-12/2018 | 433MHz BH521A159AA | L550 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2009 | 433MHz 4H231A159AB | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 433MHz BH521A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 315MHz 4H231A159CA | L359 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 433MHz GX631A159AA | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 315MHz BH521A159CA | L359 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 315MHz AH521A159CA | L359 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | LR2 | 01/2006-12/2014 | 433MHz FW931A159AB | L359 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR3 | 06/2004-11/2009 | 433MHz | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR3 | 06/2004-11/2009 | 315MHz | L319 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz BH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz FW931A159AB | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz GX631A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 433MHz AH521A159AA | L319 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | LR4 | 01/2009-12/2016 | 315MHz BH521A159CA | L319 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | LR4 | 12/2009-12/2016 | 315MHz AH521A159CA | L319 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2022-06/2022 | 433MHz FW931A159AB | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 315MHz AH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2019-12/2021 | 433MHz FW931A159AB | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2019-12/2021 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2016-12/2018 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2016-01/2018 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 315MHz BH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 02/2020-12/2021 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2013-12/2015 | 315MHz AH521A159CA | L405 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2005-12/2009 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2005-12/2009 | 315MHz | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2002-12/2004 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover | 01/2010-12/2012 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2022-12/2024 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover | 01/2022-12/2023 | 433MHz GX631A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2015-12/2017 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2019-12/2023 | 433MHz GX631A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|--------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Evoque | 07/2021-12/2024 | 433MHz M8E21A159AA | L551 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 433MHz FW931A159AB | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 315MHz BH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 433MHz AH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2015-12/2018 | 315MHz BH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2015-12/2018 | 433MHz GX631A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2015-12/2016 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2011-06/2015 | 315MHz AH521A159CA | L538 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 01/2011-12/2014 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Evoque | 07/2015-12/2018 | 433MHz BH521A159AA | L538 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz FW931A159AB | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz AH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz GX631A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2019-09/2022 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2016-12/2018 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 315MHz AH521A159CA | L494 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 315MHz AH521A159CA | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2005-12/2009 | 315MHz | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2005-12/2009 | 433MHz | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 07/2013-12/2015 | 433MHz AH521A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 315MHz BH521A159CA | L320 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2016-12/2018 | 433MHz FW931A159AB | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2010-06/2013 | 433MHz BH521A159AA | L320 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 10/2022-12/2024 | 433MHz | L461 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Land Rover | Range Rover Sport | 01/2021-09/2022 | 433MHz M8E21A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Sport | 01/2019-09/2022 | 433MHz GX631A159AA | L494 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2019-12/2023 | 433MHz GX631A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2021-12/2024 | 433MHz M8E21A159AA | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Velar | 01/2017-12/2018 | 433MHz | L560 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2022-12/2024 | 433MHz M8E21A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2016-01/2018 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 433MHz AH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 433MHz BH521A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 315MHz BH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 433MHz GX631A159AA | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2016-12/2018 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 433MHz FW931A159AB | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2005-12/2009 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2005-12/2009 | 315MHz | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2010-12/2012 | 315MHz AH521A159CA | L322 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2002-12/2004 | 433MHz | L322 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 315MHz AH521A159CA | L405 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 02/2020-12/2021 | 433MHz M8E21A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2019-12/2021 | 433MHz GX631A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2022-12/2023 | 433MHz GX631A159AA | L460 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Land Rover | Range Rover Vogue | 01/2013-12/2015 | 433MHz AH521A159AA | L405 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| LandWind | X5 | 01/2016-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| LandWind | X7 | 01/2015-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Levdeo | Mengo | 05/2021-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Unknown Manufacturer | ● | ● |
| Lexus | CT Series | 12/2010-08/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | CT Series | 12/2010-08/2017 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | CT Series | 12/2013-05/2021 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-----------|-----------------|-------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lexus | CT Series | 12/2013-12/2022 | 433MHz | 080A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 06/2012-01/2021 | 433MHz C210 | 980L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 07/2012-07/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 06/2018-12/2021 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | ES Series | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 08/2018-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 03/2006-01/2021 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | ES Series | 08/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2005-03/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2012-12/2022 | 433MHz | 920L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GS Series | 01/2012-12/2023 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GS Series | 10/2015-01/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 08/2003-04/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 08/2003-08/2017 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 08/2021-12/2023 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 01/2021-12/2023 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 09/2019-12/2022 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | GX Series | 08/2019-12/2022 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | GX Series | 04/2012-12/2022 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | HS Series | 07/2009-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 01/2006-12/2022 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 09/2020-10/2023 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 04/2013-01/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | IS Series | 04/2013-12/2020 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 08/2005-03/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 09/2020-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | IS Series | 12/2007-08/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LC Series | 11/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2017-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LC Series | 01/2020-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LFA | 12/2010-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS 430 | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Lexus | LS Series | 10/2017-12/2024 | 315MHz Hi | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 05/2014-08/2017 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2012-09/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 09/2012-12/2021 | 315MHz Lo | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 01/2007-08/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2020-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2020-10/2022 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LS Series | 10/2017-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2015-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 08/2006-09/2015 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 01/2022-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 11/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|--------------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Lexus | LX Series | 01/2013-12/2015 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | LX Series | 05/2005-08/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2014-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 11/2021-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | NX Series | 11/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | NX Series | 01/2014-12/2024 | 433MHz | 600A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RC Series | 01/2020-10/2023 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RC Series | 09/2014-01/2023 | 433MHz | XC1/720A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RC Series | 01/2014-01/2023 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 08/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 07/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 10/2015-12/2020 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 07/2013-09/2015 | 315MHz Japan | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2006-01/2021 | 315MHz 33021 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 09/2015-12/2024 | 433MHz C215 | 740A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RX Series | 02/2006-08/2019 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | RX Series | 01/2009-10/2015 | 433MHz | 640L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | RZ Series | 01/2023-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | RZ Series | 01/2023-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | SC Series | 08/2006-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2018-12/2024 | 433MHz C215 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 01/2020-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Lexus | UX Series | 10/2018-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lexus | UX Series | 05/2020-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Lifan | Maiwei | 01/2018-12/2021 | 433MHz Z71036 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Maiwei | 01/2016-12/2022 | 433MHz 1512191003530 059 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Myway | 01/2016-12/2022 | 433MHz 1512191003530 059 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | Myway | 01/2018-12/2021 | 433MHz Z71036 | | ● | ● | ○ | 0 | 433MHz | LiFan | ● | ● |
| Lifan | X50 | 01/2014-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | CheWan | ● | ● |
| Lincoln | Aviator | 05/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2004-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 05/2019-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2003-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Aviator | 01/2025-12/2025 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | CUV | 01/2014-12/2018 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 01/2018-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 07/2016-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 01/2021-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Continental | 07/2016-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|---------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Lincoln | Corsair | 01/2025-06/2025 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Corsair | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Corsair | 05/2019-12/2023 | 315MHz | | ● | ● | ○ | 0/A/S | 315MHz | Schrader | ● | ● |
| Lincoln | Corsair | 01/2025-06/2025 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Corsair | 05/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2020-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKC | 04/2014-12/2015 | 433MHz | 2. OF SEL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2016-12/2019 | 433MHz | 2. OF SEL | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 04/2014-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKC | 01/2017-08/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKC | 09/2017-08/2019 | 433MHz F2GZ1A189B | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKC | 09/2017-12/2019 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2013-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2013-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2011-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKS | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | MKS | 01/2009-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | MKT | 01/2010-07/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | MKT | 01/2013-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKT | 08/2010-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKT | 01/2013-12/2019 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKT | 01/2018-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 08/2015-12/2015 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2007-12/2007 | 315MHz with Chrome rims | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | MKX | 01/2016-12/2017 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2008-12/2010 | 315MHz no Chrome rims | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | MKX | 01/2008-12/2010 | 315MHz with Chrome rims | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | MKX | 01/2013-07/2015 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2016-12/2017 | 315MHz HC3Z1A189A | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2018-12/2019 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2016-12/2017 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2018-12/2020 | 315MHz HC3Z1A189A | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2018-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 07/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2021-12/2021 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 01/2021-12/2024 | 315MHz HC3Z1A189A | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKX | 05/2015-12/2015 | 433MHz F2GZ1A189B | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | MKX | 02/2012-06/2015 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Lincoln | MKX | 11/2006-12/2007 | 315MHz no Chrome rims | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | MKZ | 01/2021-12/2021 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2017-12/2020 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2017-12/2020 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2021-12/2021 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 10/2012-02/2016 | 433MHz BB5Z1A189A | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2013-12/2014 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 09/2015-12/2016 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | MKZ | 04/2016-12/2016 | 315MHz HC3Z1A189A | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2015-12/2016 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 02/2009-12/2009 | 315MHz Schrader | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 01/2008-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Lear | ● | ● |
| Lincoln | MKZ | 01/2010-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | MKZ | 08/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Mark LT | 01/2008-12/2014 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 08/2007-12/2008 | 315MHz Lear | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Mark LT | 07/2006-12/2008 | 315MHz VDO | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Mark LT | 01/2015-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Mark LT | 08/2012-12/2014 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 09/2023-12/2024 | 433MHz | CDX707 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 09/2023-12/2024 | 315MHz | CDX707 | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2019-12/2020 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 09/2023-12/2024 | 433MHz PR3Z1A189M | CDX707 | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2019-12/2020 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2025-12/2025 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Nautilus | 01/2021-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2018-12/2023 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2025-12/2025 | 433MHz PR3Z1A189M | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2016-12/2017 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2015-12/2017 | 433MHz | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2024-12/2024 | 433MHz PR3Z1A189M | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 09/2017-12/2017 | 433MHz F2GZ1A189B | | ● | ● | ● | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 09/2017-12/2017 | 315MHz HC3Z1A189A | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 08/2010-12/2014 | 315MHz Schrader | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 08/2012-12/2014 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Lincoln | Navigator | 01/2008-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | Navigator | 03/2002-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Lincoln | Navigator | 08/2004-12/2004 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Lincoln | Navigator | 08/2006-12/2006 | 315MHz Lear | | ● | ● | ○ | 0/S | 315MHz | Lear | ● | ● |
| Lincoln | Navigator | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Town Car | 01/2012-12/2013 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Lincoln | Town Car | 07/2005-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Zephyr | 01/2006-01/2009 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Lincoln | Zephyr | 02/2009-12/2012 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Lotus | 3-Eleven | 06/2017-12/2021 | 433MHz A132G6017F | | ○ | ● | ○ | A | 433MHz | LDL Technology | ● | ● |
| Lotus | 3-Eleven | 01/2014-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Elise | 01/2008-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Evora | 01/2010-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Lotus | Exige | 09/2000-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| MAXUS | D60 | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | E-Deliver 9 | 01/2020-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ5 | 07/2019-12/2023 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ5 | 07/2019-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ6 | 05/2020-12/2023 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | EUNIQ6 | 05/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | EV30 | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 01/2014-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 01/2014-12/2024 | 433MHz GC91B50 | PCR | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | G10 | 01/2014-12/2024 | 433MHz GC91B50 | LTR | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T60 | 01/2017-12/2024 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | T90 | 01/2021-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2024-12/2024 | 433MHz C00030048 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2015-12/2022 | 433MHz C00104713 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V80 | 01/2015-12/2022 | 433MHz TP3040001 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| MAXUS | V80 | 01/2022-12/2024 | 433MHz C00406825 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MAXUS | V90 | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Dias | ● | ● |
| MAXUS | V90 | 01/2020-12/2024 | 433MHz C00047579 | | ● | ● | ○ | 0 | 433MHz | Dias | ● | ● |
| MG | Cyberster | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | GS | 09/2016-12/2020 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| MG | HS | 07/2020-12/2024 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | HS | 01/2019-12/2021 | 433MHz 10290600 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | MG3 | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Dias | ● | ● |
| MG | MG3 | 09/2013-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG3 | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | MG5 | 01/2020-12/2024 | 433MHz 10718213 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG5 | 01/2020-12/2024 | 433MHz 10290600 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG6 | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | MG6 | 11/2017-06/2020 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MG | MG6 | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| MG | MG7 | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| MG | ZS | 01/2017-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| MHERO | MHERO 917/MHERO I | 08/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Mahindra | Alturas G4 | 01/2018-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | Bolero | 09/2003-12/2024 | 433MHz 1805BA0131NA | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Bolero | 06/2014-12/2023 | 433MHz 1805BA0131N | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Genio | 01/2014-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | KUV100 | 01/2016-12/2023 | 433MHz 1805BA0131NA | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | KUV100 | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Mahindra | NC | 01/2011-12/2021 | 433MHz | CL/MM | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Pick-Up Dual Cab | 06/2014-12/2023 | 433MHz | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mahindra | Quanto | 01/2015-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 06/2014-12/2023 | 433MHz | U202 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio | 12/2017-12/2023 | 433MHz 1805BAA00791N | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | Scorpio | 01/2015-12/2023 | 433MHz 1805BA0131N | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Mahindra | Scorpio-N | 09/2022-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | Thar | 06/2014-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XUV300 | 02/2019-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mahindra | XUV300 | 02/2019-12/2024 | 433MHz 1805BW600221N | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | XUV3X0 | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |
| Mahindra | XUV500 | 01/2013-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mahindra | XUV500 | 10/2011-12/2023 | 433MHz 1805BA0131N | | ○ | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mahindra | XUV500 | 01/2014-12/2023 | 433MHz 1805BAA00791N | | ○ | ● | ○ | S | 433MHz | Huf/Beru | ● | ● |
| Mahindra | XUV700 | 08/2021-12/2024 | 433MHz | | ○ | ● | ○ | S | 433MHz | BHSENS | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-------------------|-----------------|---------|---------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Mahindra | XYLO | 01/2017-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Alfieri | 01/2020-06/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | Coupe | 07/2009-12/2013 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Coupe | 01/2002-06/2009 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Ghibli | 10/2018-12/2023 | 433MHz | M156D | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Ghibli | 01/2018-12/2022 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 01/2013-12/2017 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Ghibli | 01/2014-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Maserati | Ghibli | 01/2018-12/2018 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Maserati | Ghibli | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | GranCabrio | 01/2010-12/2013 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranSport | 01/2005-12/2006 | 433MHz | | ● | ● | ○ | O | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2012-12/2015 | 315MHz | M145 GL | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2008-12/2010 | 433MHz | M145 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo | 01/2019-12/2021 | 433MHz | M156/ M157 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 01/2017-12/2018 | 433MHz | M156/ M157 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maserati | GranTurismo | 01/2011-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 08/2017-12/2018 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | GranTurismo Sport | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Grecale | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Grecale | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2015-12/2017 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 01/2018-12/2018 | 433MHz | M156D | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2019-12/2023 | 433MHz | M156D | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2018-12/2022 | 433MHz | M161 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Levante | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Levante | 01/2017-12/2019 | 315MHz | | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maserati | MC20 | 01/2020-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Maserati | Quattroporte | 01/2018-12/2023 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2013-12/2017 | 433MHz | M156 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2011-12/2013 | 433MHz | M139 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2004-12/2010 | 433MHz | M139 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2018-12/2018 | 315MHz | M156 | ● | ● | ○ | O/A | 315MHz | Schrader | ● | ● |
| Maserati | Quattroporte | 01/2010-12/2012 | 315MHz | M139 | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Maserati | Quattroporte | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maserati | Spyder | 07/2001-12/2008 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Maybach | GLS SUV | 01/2019-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 01/2015-12/2019 | 433MHz | | ● | ● | ○ | O/S | 433MHz | Schrader | ● | ● |
| Maybach | Landulet | 01/2009-12/2012 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 01/2002-12/2012 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 57 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | O/S | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|--------------|-----------------|-----------------------|------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Maybach | Maybach 62 | 01/2002-12/2012 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Huf/Beru | ● | ● |
| Maybach | Maybach 62 | 02/2002-12/2013 | 433MHz | Ma007 | ● | ● | ○ | 0/S | 433MHz | Huf/Beru | ● | ● |
| Maybach | S Series | 01/2021-12/2024 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 01/2021-12/2024 | 315MHz | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maybach | S Series | 01/2021-12/2024 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Maybach | S Series | 01/2021-12/2024 | 315MHz A0009058513 | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Maybach | S Series | 01/2015-12/2021 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Mazda | Atenza | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | B Series LCV | 01/2006-12/2010 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mazda | BT Pickup | 01/2006-12/2011 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mazda | BT Pickup | 01/2020-12/2022 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | CX-3 | 01/2021-06/2024 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-3 | 01/2015-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-3 | 01/2016-12/2020 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-30 | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-30 | 01/2019-12/2019 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2020-12/2021 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2021-12/2023 | 315MHz BDGF37140 | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2018-12/2019 | 433MHz | J53C/J72A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2017-12/2024 | 315MHz Direct | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-5 | 01/2016-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-5 | 01/2013-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-50 | 01/2022-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-6 | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-7 | 01/2011-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-7 | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-7 | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-70 | 01/2024-12/2024 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2013-12/2019 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-9 | 01/2016-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | CX-90 | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | CX-90 | 01/2023-12/2023 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-30 | 01/2022-12/2023 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 01/2021-12/2024 | 315MHz | ND | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 01/2011-12/2014 | 433MHz | NC/J04C/J12 A | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mazda | MX-5 | 01/2018-12/2020 | 315MHz | ND | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 12/2006-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 | 03/2010-04/2015 | 315MHz | NC/J04C/J12 A | ● | ● | ○ | A | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|---------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mazda | MX-5 | 05/2010-12/2018 | Indirect | ND | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | MX-5 Miata | 01/2005-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 Miata | 01/2011-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 Miata | 01/2016-05/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | MX-5 Miata | 06/2018-12/2020 | 315MHz BHA437140 | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | MX-5 Miata | 01/2020-12/2024 | 315MHz BDGF37140 | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 01/2019-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 2 | 06/2014-12/2016 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 2 | 01/2011-05/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2005-12/2006 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2014-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 3 | 01/2019-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2011-12/2013 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 3 | 01/2004-12/2004 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2014-12/2015 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 5 | 01/2011-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 5 | 01/2016-12/2018 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2014-12/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mazda | Mazda 6 | 01/2018-12/2021 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2011-12/2013 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2008-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2009-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Mazda 6 | 01/2021-06/2024 | 315MHz BDGF37140 | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2011-12/2012 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2009-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2005-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | RX-8 | 01/2003-12/2004 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Speed 3 | 01/2007-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Speed 6 | 01/2007-12/2008 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Mazda | Tribute | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | Tribute | 01/2011-12/2013 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | Tribute | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mazda | Tribute | 01/2009-12/2009 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mazda | Tribute | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| McLaren | 500 Series | 01/2015-12/2022 | 433MHz RDE011 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 500 Series | 01/2015-12/2024 | 433MHz RDE018 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| McLaren | 600 Series | 01/2014-12/2018 | 315MHz 36118378681 | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 03/2014-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | 600 Series | 04/2014-12/2015 | 315MHz F11001223002 | | ○ | ● | ○ | NA | 315MHz | Huf/Beru | ● | ● |
| McLaren | 700 Series | 01/2017-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Artura | 01/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Unknown Manufacturer | ● | ● |
| McLaren | GT | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | MP4-12C | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | P1 | 01/2013-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2020-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Senna | 01/2017-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Speedtail | 01/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Sports Series | 01/2015-06/2022 | 433MHz F11001648001 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| McLaren | Super Series | 01/2017-12/2023 | 433MHz F11001648001 | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 01/2012-03/2014 | 433MHz | 176 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | A Class | 06/2018-12/2024 | 315MHz A0009054204 | 177 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 06/2018-12/2024 | 433MHz | 177 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | A Class | 04/2014-05/2018 | 433MHz | 176 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG | 01/2013-06/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-12/2023 | 433MHz | 290 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 11/2018-12/2023 | 315MHz | 290 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 06/2023-12/2024 | 315MHz A0009058513 | 192 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 06/2023-12/2024 | 433MHz A0009058706 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 06/2023-12/2024 | 433MHz A0009058413 | 192 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG GT | 01/2014-12/2023 | 433MHz | C190 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | AMG SL | 09/2021-12/2023 | 315MHz | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | AMG SL | 09/2021-12/2023 | 433MHz | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | B Class | 02/2019-12/2024 | 315MHz | 247 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 02/2019-12/2024 | 433MHz A0009054104 | 247 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | B Class | 01/2011-12/2020 | 433MHz | 246 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 06/2018-12/2023 | 433MHz A0009053907 | C205 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 06/2021-12/2024 | 433MHz | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 09/2022-12/2024 | 433MHz A0009058413 | 206 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 06/2018-12/2021 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 09/2014-05/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 04/2007-12/2020 | 433MHz | W205 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | C Class | 01/2007-08/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | CL Class | 01/2000-12/2007 | 315MHz A0008223406 | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 01/1998-12/2006 | 433MHz | 215 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CL Class | 10/2006-12/2010 | 433MHz A0025408017 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | CL Class | 10/2006-12/2010 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | CL Class | 01/2010-12/2015 | 433MHz | 216 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 01/2014-12/2019 | 433MHz | 117 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLA Class | 05/2019-12/2024 | 315MHz A0009054204 | 118 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CLA Class | 05/2019-12/2024 | 433MHz | 118 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLC Class | 01/2008-06/2018 | 433MHz | 216 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 01/2022-12/2024 | 433MHz | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 06/2023-12/2024 | 315MHz A0009058513 | 236 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | CLE Class | 06/2023-12/2024 | 433MHz A0009058413 | 236 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 01/2002-12/2012 | 433MHz | 209 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLK Class | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 01/2006-12/2011 | 315MHz | 219 | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | CLS Class | 01/2005-12/2005 | 433MHz | 219 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | CLS Class | 09/2004-12/2011 | 433MHz A0025408017 | 219 | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | CLS Class | 01/2012-12/2017 | 433MHz | 218 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2018-12/2019 | 433MHz | C218 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2011-12/2017 | 433MHz A0009050030 | 218 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2018-12/2024 | 433MHz | 257 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | CLS Class | 01/2018-12/2024 | 315MHz | 257 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | Citan | 09/2021-12/2024 | 433MHz A4204012400 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mercedes | Citan | 01/2012-12/2023 | 433MHz | 415 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 10/2023-12/2024 | 315MHz A0009058513 | 214 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | E Class | 10/2023-12/2024 | 433MHz A0009058413 | 214 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 06/2010-12/2018 | 433MHz | W212 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 07/2009-05/2014 | 433MHz | W212/C207 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | E Class | 01/2006-05/2010 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | E Class | 01/1999-12/2005 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 01/2002-05/2005 | 433MHz | W211 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | E Class | 01/2016-12/2023 | 433MHz | W213/BR238 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | E Class | 01/2016-12/2023 | 315MHz | 213 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | EQA | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQA | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 01/2022-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Mercedes | EQB | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|-----------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Mercedes | EQC | 01/2019-12/2024 | 315MHz | 293 | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mercedes | EQC | 01/2019-12/2024 | 433MHz | 293 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 01/2022-12/2024 | 315MHz | 295 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQE | 09/2022-12/2024 | 433MHz A0009058413 | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQE | 09/2022-12/2024 | 315MHz A0009058513 | 295 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQE | 01/2022-12/2024 | 433MHz | 295 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 09/2022-12/2024 | 433MHz A0009058413 | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 09/2022-12/2024 | 315MHz A0009058513 | 297 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQS | 01/2021-12/2024 | 433MHz | 297 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | EQS | 01/2021-12/2024 | 315MHz | 297 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | EQV | 01/2024-12/2024 | 433MHz A0009057205 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | EQV | 01/2020-12/2020 | 433MHz | 447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 04/2007-05/2018 | 433MHz | G463/461 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-12/2024 | 433MHz | 463 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | G Class | 06/2018-12/2024 | 315MHz | 463 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | GL Class | 10/2009-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GL Class | 04/2006-09/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | GL Class | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | GLA Class | 01/2020-12/2024 | 315MHz A0009054204 | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | GLA Class | 01/2020-12/2024 | 433MHz A0009054104 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLA Class | 01/2014-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLB Class | 01/2019-12/2024 | 433MHz | 247 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLB Class | 01/2019-12/2024 | 315MHz | 247 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLC Class | 09/2022-12/2024 | 315MHz A0009058513 | 254 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 06/2015-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 06/2022-12/2024 | 433MHz | 254 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 09/2022-12/2024 | 433MHz A0009058413 | 254 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 01/2015-12/2021 | 315MHz | X253 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 09/2016-12/2022 | 433MHz A0009053907 | C253 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLC Class | 01/2022-12/2024 | 315MHz | 254 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 01/2021-12/2023 | 433MHz A0009052102 | C167 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLE Class | 01/2018-12/2024 | 315MHz | W167 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 10/2018-12/2024 | 433MHz | V167 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | GLE Class | 01/2012-12/2020 | 433MHz | X166 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLK Class | 01/2010-12/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | GLS Class | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | GLS Class | 07/2019-12/2024 | 433MHz | X167 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mercedes | GLS Class | 01/2015-06/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT | 01/2014-12/2022 | 433MHz | GT | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S | 01/2016-12/2019 | 433MHz | X166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2014-12/2019 | 433MHz | C190 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | GT-S AMG | 01/2019-12/2019 | 433MHz A0009052102 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2010-12/2014 | 433MHz | W166 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2015-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | M Class | 01/2005-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | M Class | 01/2005-05/2011 | 433MHz | W164 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | ML Class | 06/2010-12/2016 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | ML Class | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | ML Class | 01/2006-05/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | ML Class | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | Metris | 01/2015-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 01/2010-12/2018 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | R Class | 01/2006-12/2009 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | R Class | 01/2006-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 01/2010-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 06/2021-12/2024 | 433MHz | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 07/1999-09/2005 | 433MHz | W220 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 12/2005-12/2013 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | S Class | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | S Class | 01/2022-12/2024 | 315MHz | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 07/2020-06/2021 | 433MHz | C217 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | S Class | 01/2000-12/2006 | 315MHz A0008223406 | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | S Class | 09/2022-12/2024 | 315MHz A0009058513 | 223 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | S Class | 09/2022-12/2024 | 433MHz A0009058413 | 223 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | S Class coupe | 01/2013-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 01/2000-04/2005 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SL Class | 07/2012-12/2017 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 05/2005-12/2012 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Mercedes | SL Class | 05/2005-06/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Mercedes | SL Class | 09/2021-12/2024 | 315MHz | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 09/2021-12/2024 | 433MHz | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 09/2021-12/2024 | 433MHz A0009058413 | 232 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Mercedes | SL Class | 09/2021-12/2024 | 315MHz A0009058513 | 232 | ○ | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Mercedes | SL Class | 01/2018-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 01/2016-06/2020 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLC Class | 07/2020-12/2021 | 433MHz | R172 | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Mercedes | SLK Class | 04/2007-05/2019 | 315MHz | R172 | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 01/2007-12/2007 | 433MHz | A0025400217 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mercedes | SLK Class | 01/2007-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | SLR Class | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | SLR Class | 01/2008-12/2010 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Mercedes | SLR Class | 01/2001-12/2007 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SLR Class | 01/2000-12/2007 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2008-12/2009 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2011 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | SLR McLaren | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Mercedes | SLS Class | 01/2010-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2010-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2018-12/2020 | 433MHz A0009050030 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | Sprinter | 01/2018-12/2024 | 433MHz A0009054104 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Sprinter | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Mercedes | V Class | 01/2014-12/2024 | 433MHz | W447 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Mercedes | V Class | 01/2024-12/2024 | 433MHz A0009057205 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | Viano | 01/2015-12/2022 | 433MHz A0025409517 | W447 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mercedes | Vito | 01/2024-12/2024 | 433MHz A0009057205 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mercedes | X Class | 01/2017-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Mercury | Grand Marquis | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Mariner | 01/2005-12/2007 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Mariner | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Mercury | Mariner | 01/2011-12/2013 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Mercury | Mariner | 01/2010-12/2010 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mercury | Mariner | 06/2008-12/2009 | 315MHz Schrader | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Mercury | Milan | 08/2006-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Lear | ● | ● |
| Mercury | Milan | 01/2012-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Mercury | Milan | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Mercury | Milan | 02/2009-12/2009 | 315MHz Schrader | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Mercury | Montego | 01/2006-12/2009 | 315MHz | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Monterey | 01/2004-12/2004 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mercury | Monterey | 01/2005-12/2005 | 315MHz Banded | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Monterey | 01/2005-12/2005 | 315MHz | | ● | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Mercury | Monterey | 01/2004-12/2004 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercury | Monterey | 01/2005-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mercury | Monterey | 01/2006-12/2008 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Monterey | 01/2004-12/2004 | 315MHz Banded | | ○ | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Mountaineer | 01/2005-12/2005 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------|-----------------|-----------------------|-------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Mercury | Mountaineer | 01/2002-12/2003 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mercury | Mountaineer | 07/2005-12/2005 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Mountaineer | 01/2004-12/2004 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Mercury | Mountaineer | 01/2006-12/2012 | 315MHz | | ● | ● | ○ | S | 315MHz | Lear | ● | ● |
| Mercury | Sable | 04/2007-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Lear | ● | ● |
| Mini | Cabrio | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 07/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 12/2008-06/2014 | 433MHz 36106856227 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Cabrio | 11/2015-06/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Cabrio | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Mini | Clubman | 07/2015-06/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubman | 10/2006-06/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubman | 10/2006-07/2010 | 433MHz 36236798726 | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Clubvan | 01/2016-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Clubvan | 07/2012-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 01/2015-12/2023 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Convertible | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Convertible | 07/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 11/2023-12/2024 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2014-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Countryman | 07/2015-06/2024 | 433MHz Continental | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Coupe | 07/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Coupe | 07/2011-06/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Mini | 03/2006-06/2024 | 433MHz Continental | F55/F56/R56 | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Mini | 01/2009-12/2015 | 433MHz OYGTSSRE4D | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 07/2018-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Mini | Paceman | 01/2009-06/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Paceman | 07/2014-06/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 05/2014-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mini | Roadster | 01/2011-12/2014 | 433MHz 36106856227 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Mitsubishi | ASX | 01/2013-12/2024 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | ASX | 07/2012-03/2017 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse | 01/2006-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Eclipse | 01/2008-12/2014 | 315MHz 4250B875 | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | Eclipse Cross | 01/2018-12/2024 | 433MHz Snap in | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 11/2021-12/2024 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Cross | 01/2017-10/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Eclipse Spyder | 11/2006-08/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Endeavor | 01/2003-08/2010 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Endeavor | 09/2006-12/2012 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 07/2006-12/2013 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 01/2003-12/2006 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Mitsubishi | Galant | 07/2007-12/2013 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | L200 | 01/2014-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 01/2001-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 01/2006-12/2017 | 315MHz 4250C276 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer | 01/2008-12/2017 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Lancer Sportback | 12/2008-07/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 01/2013-12/2017 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 04/2021-12/2024 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage | 07/2013-03/2021 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 04/2021-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 08/2021-12/2024 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 01/2016-12/2017 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 09/2019-08/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Mirage G4 | 03/2016-03/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Montero | 01/2009-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Montero | 01/2014-12/2021 | 433MHz | V80 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero | 06/2000-08/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Montero Sport | 01/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 11/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 01/2017-10/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 01/2016-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Montero Sport | 01/2003-12/2012 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Schrader | ● | ● |
| Mitsubishi | Outlander | 10/2007-03/2013 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 08/2016-02/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 01/2006-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 03/2020-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 03/2018-12/2021 | 433MHz 4250C275 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Outlander | 02/2021-12/2024 | 315MHz 4250G122 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Mitsubishi | Outlander | 05/2017-12/2021 | 315MHz 4250D585 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 11/2017-12/2024 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 10/2022-12/2024 | 315MHz 4250G122 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander PHEV | 11/2017-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander Sport | 01/2010-12/2017 | 315MHz 4250A225 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander Sport | 04/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Pacific | ● | ● |
| Mitsubishi | Outlander Sport | 08/2020-12/2024 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Outlander Sport | 04/2017-12/2024 | 315MHz Snap in | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Pajero | 01/2016-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 06/2014-10/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Pajero Sport | 11/2022-12/2024 | 433MHz 4250G325 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | RVR | 01/2021-12/2023 | 315MHz 4250G326 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 01/2011-12/2020 | 315MHz 4250C276 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 07/2012-07/2016 | 315MHz 4250B975 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | RVR | 07/2012-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | Raider | 01/2005-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Mitsubishi | Triton | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | Xpander | 09/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 01/2010-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Mitsubishi | i-MiEV | 01/2012-12/2018 | 315MHz 4250C276 | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| NIO | ES7 | 06/2022-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| NIO | ET7 | 01/2021-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Nissan | 350Z | 01/2007-12/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 350Z | 01/2007-12/2010 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 350Z | 06/2002-12/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | 370Z | 07/2011-09/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | 370Z | 03/2010-06/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | 370Z | 09/2014-06/2022 | 433MHz 407006WY0B | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Nissan | 370Z | 10/2008-02/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | 370Z | 10/2009-06/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | 370Z | 10/2020-09/2022 | 433MHz 407006GNOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Altima | 11/2018-06/2020 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 05/2008-05/2009 | 315MHz 40700JA02B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima | 06/2012-10/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Nissan | Altima | 07/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Altima | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima | 09/2010-12/2011 | 315MHz 407001AA0B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Altima Coupe | 05/2008-07/2008 | 315MHz 40700JA02B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima Coupe | 05/2007-09/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima Coupe | 10/2010-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Altima Coupe | 01/2012-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Ariya | 01/2022-10/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Ariya | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Ariya | 11/2023-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Armada | 06/2016-06/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Armada | 08/2012-12/2018 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Armada | 01/2014-12/2019 | 315MHz 4321182Z00 | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 04/2009-05/2009 | 315MHz 40700JA02B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 04/2007-10/2011 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 06/2017-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Armada | 09/2024-06/2025 | 315MHz 407006LY0B | | ○ | ● | ○ | NA | 315MHz | Pacific | ● | ● |
| Nissan | Armada | 08/2003-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 11/2011-05/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Armada | 09/2022-12/2024 | 315MHz 407006GPOA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cabstar | 06/2014-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Caravan | 02/2017-07/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Caravan | 12/2021-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 11/2011-12/2015 | 315MHz 407001LA0E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 10/2010-12/2016 | 315MHz 407003AN1A | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Cube | 10/2009-02/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Cube | 07/2009-10/2009 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Cube | 02/2009-07/2009 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Cube | 01/2013-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Cube | 03/2012-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Frontier | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Frontier | 01/2020-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Frontier | 07/2021-12/2024 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Frontier | 01/2012-12/2021 | 315MHz 407003AN0B | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Frontier | 09/2010-03/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Nissan | Frontier | 05/2008-05/2009 | 315MHz 40700JA02B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 09/2006-08/2010 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 10/2004-12/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Frontier | 01/2003-09/2004 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 03/2008-12/2009 | 315MHz 40700JA01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 05/2020-03/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 05/2020-08/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 09/2022-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | GT-R | 11/2013-08/2022 | 433MHz 4070062B0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | GT-R | 12/2008-05/2011 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 06/2011-04/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | GT-R | 11/2010-04/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 03/2008-12/2010 | 315MHz 40700JA00C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | GT-R | 09/2022-12/2024 | 433MHz 407006GP1A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 07/2010-12/2020 | 315MHz 407001LA0E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 03/2012-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 01/2013-10/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Juke | 10/2019-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 05/2014-09/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Juke | 01/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Juke | 07/2011-02/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Juke | 07/2010-03/2012 | 315MHz 407001AA0B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Kicks | 06/2024-06/2025 | 315MHz | | ● | ● | ○ | C | 315MHz | Pacific | ● | ● |
| Nissan | Kicks | 04/2018-12/2020 | 433MHz 407005ZH0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Kicks | 03/2023-12/2024 | 433MHz 407006LY0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Kicks | 09/2019-12/2024 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Kicks | 01/2021-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Kicks | 09/2024-06/2025 | 433MHz | | ● | ● | ○ | C | 433MHz | Pacific | ● | ● |
| Nissan | Kicks | 11/2016-03/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 01/2013-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Leaf | 10/2010-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Leaf | 05/2014-02/2016 | 433MHz 407006WY0B | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Leaf | 11/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 01/2018-01/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Leaf | 02/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Livina | 04/2016-02/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Magnite | 02/2022-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | March | 04/2016-12/2020 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | March | 04/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | March | 01/2024-03/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | March | 04/2016-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Maxima | 01/2012-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Maxima | 11/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Maxima | 04/2015-12/2018 | 433MHz 407003JA0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Maxima | 06/2006-03/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 01/2013-12/2014 | 433MHz 40700JY00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Maxima | 08/2012-03/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Maxima | 08/2010-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Maxima | 04/2007-07/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Micra | 03/2017-12/2023 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 06/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Micra | 01/2014-12/2021 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Micra | 01/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 11/2018-12/2024 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 10/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Murano | 11/2024-06/2025 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Nissan | Murano | 01/2013-09/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Murano | 11/2011-12/2012 | 315MHz 40700JK00E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Murano | 10/2008-08/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Murano | 08/2006-09/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Murano | 09/2002-07/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | NP300 | 01/2008-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | NP300 | 06/2022-12/2024 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NP300 | 06/2022-12/2024 | 433MHz 407006YT0B | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NP300 | 01/2017-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV1500/2500/3500 | 01/2011-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | NV200 | 11/2012-12/2017 | 315MHz 407001AA0D | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | NV200 | 08/2014-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | NV350 | 10/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | NV350 | 12/2021-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | NV350 | 02/2017-10/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Navara | 06/2016-10/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Navara | 11/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Navara | 10/2004-05/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Note | 08/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Pathfinder | 08/2018-06/2021 | 433MHz 407009DJ0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 09/2012-02/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Pathfinder | 09/2010-08/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 01/1996-12/2005 | 315MHz 40700CD001 | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 08/2004-07/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 09/2006-08/2010 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 05/2008-05/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Pathfinder | 11/2011-08/2012 | 315MHz 407003AN0A | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Patrol | 09/2011-04/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Patrol | 11/2015-10/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 05/2017-08/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Patrol | 11/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Patrol | 01/2010-06/2016 | 433MHz 407001LLOD | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Primera | 01/2002-12/2009 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Qashqai | 12/2013-07/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 11/2016-12/2021 | 433MHz 407004CB0B | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 05/2021-12/2024 | 433MHz 40700E1B6A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Qashqai | 05/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Quest | 08/2007-10/2010 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Quest | 11/2010-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Quest | 05/2003-07/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Rogue | 08/2007-07/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Rogue | 01/2020-10/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Rogue | 10/2015-12/2020 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Rogue | 07/2011-12/2012 | 315MHz 40700JK00E | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Rogue | 08/2009-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Rogue | 10/2013-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue | 11/2023-12/2024 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Continental | ● | ● |
| Nissan | Rogue Select | 01/2014-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Rogue Select | 01/2014-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue Sport | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Rogue Sport | 12/2022-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 04/2016-09/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Sentra | 12/2022-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Nissan | Sentra | 10/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Sentra | 10/2019-12/2024 | 433MHz 407006LB0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Sentra | 02/2020-01/2024 | 315MHz 407006LBOB | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Sentra | 01/2016-07/2016 | 433MHz 407003AR1A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Sentra | 09/2012-01/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Sentra | 09/2012-01/2020 | 315MHz 407003ANOB | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Sentra | 01/2012-08/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Sentra | 08/2010-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Sentra | 05/2008-05/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Sentra | 09/2006-07/2010 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Sentra | 09/2006-08/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Tiida | 01/2016-10/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Tiida | 11/2017-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Tiida | 04/2016-09/2019 | 433MHz 407005ZHOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 01/2008-12/2008 | 315MHz 40700CD001 | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan | 04/2007-11/2011 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan | 10/2003-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan | 11/2015-12/2024 | 433MHz 40700EZ00A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 01/2016-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Titan | 01/2015-12/2017 | 433MHz 4070062BOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Titan | 09/2013-12/2015 | 315MHz 407003ANOC | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Titan | 08/2010-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Titan Pro 4X | 12/2013-08/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Titan XD | 01/2016-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa | 03/2020-12/2024 | 433MHz 407006LBOA | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa | 09/2014-08/2021 | 433MHz 407001AY0A | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Versa | 08/2012-08/2021 | 315MHz 407003AN1D | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa | 01/2012-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Versa | 06/2011-08/2018 | 315MHz 407003ANOD | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa | 09/2009-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa | 09/2014-08/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Versa | 05/2008-09/2009 | 315MHz 40700JA02B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa | 05/2006-06/2011 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa | 08/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa | 05/2006-12/2008 | 315MHz 40700CK001 | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|-----------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Nissan | Versa | 08/2019-01/2022 | 433MHz 407005ZH0A | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Nissan | Versa Hatchback | 01/2014-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa Hatchback | 01/2012-12/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Versa Hatchback | 01/2007-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Versa Note | 01/2013-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Versa Note | 01/2013-12/2021 | 315MHz 407003ANOD | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | X-Trail | 10/2023-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | X-Trail | 09/2022-09/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | X-Trail | 06/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 05/2017-04/2022 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | X-Trail | 02/2014-04/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Xterra | 09/2006-08/2010 | 315MHz 40700JA01B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 315MHz 407003ANOA | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Nissan | Xterra | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Nissan | Xterra | 09/2010-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Xterra | 05/2008-05/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Xterra | 01/2005-08/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Xterra | 09/2002-12/2004 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Nissan | Z | 03/2022-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Nissan | Z | 01/2022-12/2023 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Nissan | Z | 05/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Oldsmobile | Alero | 01/1999-12/2000 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Oldsmobile | Aurora | 01/2001-12/2003 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Adam | 08/2014-11/2019 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Adam | 08/2014-11/2019 | 433MHz S/Rocks | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 11/2010-05/2014 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 01/2016-12/2020 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Antara | 06/2014-12/2015 | 433MHz | C105 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 10/2011-05/2014 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra J | 06/2014-12/2016 | 433MHz 13581560 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra K | 09/2015-07/2019 | 433MHz | D2J0 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Astra K | 08/2019-07/2022 | 433MHz | | ● | ● | ● | 0/S/A | 433MHz | Huf | ● | ● |
| Opel/Vauxhall | Cascada | 01/2013-05/2014 | 433MHz | D1A0 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Cascada | 06/2014-12/2020 | 433MHz | D1A0 | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 05/2006-05/2014 | 433MHz | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 06/2014-11/2014 | 433MHz | GM S4400 | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 12/2014-12/2019 | 433MHz 13581561 | C0145 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Corsa | 01/2020-12/2024 | Indirect | F/Mk5 | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------------|-----------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Opel/Vauxhall | Corsa | 12/2014-12/2019 | 433MHz 13581560 | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Crossland | 01/2017-06/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Grandland | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Opel/Vauxhall | Insignia | 01/2008-08/2011 | 433MHz | GM G3700 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 10/2015-02/2017 | 433MHz | GM G3700 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 03/2017-07/2019 | 433MHz | | ● | ● | ● | 0/S/A | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Insignia | 08/2019-08/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf | ● | ● |
| Opel/Vauxhall | Insignia | 05/2014-09/2015 | 433MHz | GM G3700 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Meriva | 04/2010-12/2018 | 433MHz 13581562 | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Meriva | 04/2010-12/2018 | 433MHz 13581561 | GM S4470 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Mokka | 09/2015-12/2019 | 433MHz | G1U0 | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Opel/Vauxhall | Vivaro | 01/2015-06/2024 | 433MHz | X82/X83 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 107 | 03/2005-07/2014 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 108 | 01/2014-12/2022 | 433MHz | B3 | ● | ● | ○ | 0/S | 433MHz | Pacific | ● | ● |
| Peugeot | 2008 | 02/2013-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 207 | 10/2013-12/2016 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 207 | 11/2005-09/2013 | 433MHz | A7 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 208 | 01/2012-12/2019 | 433MHz | A9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 208 | 01/2012-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 3008 | 09/2013-12/2019 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 11/2008-08/2013 | 433MHz | T84 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 3008 | 06/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | 301 | 01/2012-12/2022 | 433MHz | | ● | ● | ○ | 0/S | 433MHz | Schrader | ● | ● |
| Peugeot | 307 | 03/2007-12/2008 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 307 | 01/2001-02/2007 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 308 | 01/2020-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 308 | 06/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 308 | 05/2007-05/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 4008 | 04/2012-01/2018 | 433MHz | | ● | ● | ○ | S | 433MHz | Continental | ● | ● |
| Peugeot | 407 | 01/2003-12/2012 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 408 | 07/2012-03/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 09/2013-12/2017 | 433MHz 9808859080 | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 09/2009-08/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 5008 | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 5008 | 09/2013-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | 508 | 09/2010-09/2013 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 508 | 07/2017-12/2024 | Indirect | R83 | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | 508 | 10/2013-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | 607 | 09/1999-09/2004 | 433MHz | 6042/Z8 | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Peugeot | 607 | 10/2004-12/2012 | 433MHz | Z8 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Peugeot | 807 | 10/2004-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Peugeot | 807 | 02/2002-09/2004 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Bipper | 12/2007-09/2018 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Bipper | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer | 01/2023-12/2024 | 433MHz | X2/50 | ● | ● | ● | 0/A | 433MHz | Continental | ● | ● |
| Peugeot | Boxer | 02/2006-11/2013 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Peugeot | Boxer | 01/2006-11/2013 | 433MHz 1612474480 | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Boxer | 12/2013-12/2022 | 433MHz | | ● | ● | ● | 0/A | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 01/2014-02/2016 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 10/2006-12/2013 | 433MHz | G9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Expert | 03/2016-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Landtrek | 01/2019-12/2024 | 433MHz | KP1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 06/2014-06/2018 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Partner | 07/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Partner | 01/2008-05/2014 | 433MHz | B9 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 10/2013-06/2017 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | RCZ | 12/2009-09/2013 | 433MHz | T75 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Peugeot | Rifter | 07/2018-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Peugeot | Traveller | 03/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Polestar | Polestar 1 | 07/2018-12/2022 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Polestar | Polestar 2 | 07/2020-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Polestar | Polestar 4 | 04/2024-12/2024 | 433MHz 8889081697 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Pontiac | Aztek | 01/2003-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Bonneville | 01/2000-12/2005 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | G3 | 01/2007-12/2011 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G5 | 01/2004-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G5 | 01/2009-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G6 | 01/2009-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G6 | 06/2007-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | G6 | 06/2007-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G8 | 01/2008-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | G8 | 01/2009-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | Grand Am | 01/1999-12/2007 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Grand Prix | 01/2006-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Grand Prix | 08/2007-12/2011 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | Grand Prix | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Montana | 01/2008-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Pontiac | SV-6 | 01/2008-12/2009 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Pontiac | Solstice | 12/2007-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Solstice | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Pontiac | Solstice | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Pontiac | Torrent | 01/2009-12/2009 | 315MHz Snap in | | ● | ● | ● | O/S | 315MHz | Schrader | ● | ● |
| Pontiac | Torrent | 01/2009-12/2011 | 315MHz Clamp in | | ● | ● | ● | O/S | 315MHz | Continental | ● | ● |
| Pontiac | Torrent | 01/2007-12/2008 | 315MHz Clamp in | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Pontiac | Torrent | 01/2008-12/2008 | 315MHz Snap in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Pontiac | Vibe | 01/2008-12/2010 | 315MHz | | ● | ● | ○ | O/S | 315MHz | Pacific | ● | ● |
| Pontiac | Vibe | 01/2005-12/2007 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Pontiac | Wave | 01/2004-12/2011 | 315MHz | | ● | ● | ○ | O | 315MHz | Schrader | ● | ● |
| Porsche | 718 Boxster | 01/2017-12/2024 | 315MHz | 982 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 718 Boxster | 01/2017-12/2024 | 433MHz | 982 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 718 Cayman | 01/2017-12/2020 | 315MHz | 982C | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 718 Cayman | 01/2017-12/2024 | 433MHz | 982C | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2014-12/2016 | 315MHz | 991T | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2019-12/2024 | 315MHz | 992 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2007-12/2009 | 315MHz | 997T | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2014-12/2016 | 433MHz | 991T | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2017-12/2019 | 315MHz | 991 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2017-12/2020 | 433MHz | 991 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2017-12/2020 | 315MHz | 991T | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2017-12/2020 | 433MHz | 991T | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2019-12/2024 | 433MHz | 992 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2009-12/2012 | 315MHz | 997 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2009-12/2012 | 433MHz | 997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2007-12/2009 | 433MHz | 997T | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2005-12/2008 | 315MHz | 997 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2005-12/2008 | 315MHz 99760602500 | 997 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2004-12/2008 | 433MHz | 997 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 01/2019-12/2024 | 315MHz | 992T | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 12/2011-12/2016 | 315MHz | 991 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | 911 | 02/2012-12/2016 | 433MHz | 991 | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 01/2014-12/2016 | 433MHz 5Q0907275 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | 918 Spyder | 01/2015-12/2015 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2012 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2004-12/2008 | 433MHz | 987 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2009-12/2012 | 315MHz | 987 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2012-12/2016 | 315MHz | 981/981SP | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2017-12/2024 | 315MHz | 982SP | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2004-12/2008 | 315MHz | 987 | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2017-12/2024 | 433MHz | 982/982SP | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Boxster | 01/2012-12/2016 | 433MHz | 981 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Carrera GT | 01/2004-12/2006 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|---------------------|---------------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Porsche | Carrera GT | 09/2003-12/2011 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 433MHz | 9PA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2002-12/2006 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2007-12/2010 | 433MHz | 9PA1 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2007-12/2010 | 315MHz | 9PA1 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2010-12/2014 | 315MHz | 92A | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2011-10/2014 | 433MHz | 92A | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 09/2017-12/2023 | 433MHz | 9YA | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 11/2014-08/2017 | 433MHz | 92A | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 01/2015-12/2023 | 315MHz | 9YA | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Porsche | Cayenne S | 01/2007-12/2009 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2008-12/2009 | 315MHz | 4. 8L | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2010-12/2012 | 315MHz | 4. 8L | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 01/2010-05/2014 | 433MHz | 4. 8L | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 06/2014-08/2017 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayenne S | 09/2017-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2016 | 433MHz | 987C/981C/G T4-1 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2008 | 315MHz | 987C | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2005-12/2008 | 433MHz | 987C | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2019-12/2024 | 315MHz | CT4-2 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 10/2019-12/2024 | 433MHz | CT4-2 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Cayman | 01/2009-12/2016 | 315MHz | 987C/981C/G T4-1 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2015-12/2015 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2012-12/2017 | 315MHz | 991 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2007-12/2011 | 315MHz | 997 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2007-12/2009 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2010-12/2016 | 433MHz | 996/997 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2018-12/2021 | 315MHz | 991 | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 01/2017-12/2021 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Porsche | GT3 | 03/2006-12/2011 | 433MHz | 996 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Porsche | Macan | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2014-12/2023 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2014-12/2023 | 433MHz | P0416/95B | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Macan | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Porsche | Panamera | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 09/2013-08/2017 | 433MHz | 970 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|---------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Porsche | Panamera | 09/2017-12/2023 | 433MHz | 970/971 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2017-12/2023 | 315MHz | 971 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2014-12/2016 | 315MHz | 970 | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2009-06/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera | 01/2010-12/2013 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Panamera S | 01/2009-06/2013 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Porsche | Panamera S | 06/2009-12/2013 | 315MHz | 4. 8L | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2024-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2019-12/2023 | 433MHz 9J1907275 | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 01/2020-12/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Porsche | Taycan | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Porsche | Taycan | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Renault | Alaskan | 01/2017-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Pacific | ● | ● |
| Renault | Captur | 03/2022-06/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Captur | 01/2013-12/2016 | 433MHz | J87 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Captur | 01/2013-12/2019 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Clio III | 01/2005-05/2014 | 433MHz | X85 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 01/2012-12/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Clio IV | 11/2014-02/2016 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Dokker | 03/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Dokker | 04/2020-03/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Dokker | 06/2014-03/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Duster | 12/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Duster | 01/2013-12/2018 | 433MHz | H79 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Renault | Espace V | 01/2020-12/2023 | 433MHz 407006UA0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Espace V | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Express | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Fluence | 01/2009-12/2020 | 433MHz | L38 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kangoo II | 10/2007-12/2021 | 433MHz | X61 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Kangoo II | 06/2017-12/2019 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Kangoo III | 01/2020-06/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Kangoo III | 12/2019-06/2024 | 433MHz 407004CB0B | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Renault | Koleos | 01/2010-12/2013 | 315MHz 407001AA0B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2010-07/2016 | 433MHz 407001AY0A | H45 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Koleos | 06/2010-07/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Renault | Koleos | 01/2014-07/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Koleos | 08/2016-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Koleos | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------------|------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Renault | Koleos | 01/2013-07/2016 | 433MHz 407003VU0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kwid | 01/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Kwid | 01/2020-12/2024 | 433MHz 407005642R | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna II | 12/2000-04/2009 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Laguna III | 05/2009-12/2014 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Latitude | 05/2009-12/2015 | 433MHz | L43 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Logan | 02/2010-12/2021 | 433MHz | L52/K52 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Renault | Master | 11/2009-12/2022 | 433MHz | X62 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Master | 09/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane II | 01/2005-12/2009 | 433MHz | B32/X84 | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane III | 01/2010-06/2017 | 433MHz | X95 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 06/2017-01/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 02/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Megane IV | 02/2021-12/2023 | 433MHz 407004CB0A | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Renault | Modus | 01/2004-12/2014 | 433MHz | J77 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Sandero II | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic I | 01/1997-12/2003 | 433MHz | J64 | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Renault | Scenic II | 01/2003-12/2009 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Scenic III | 01/2009-06/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Symbol | 01/2013-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Symbol | 03/2022-12/2023 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Trafic | 01/2014-09/2021 | 433MHz | X82 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Trafic | 10/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Trafic | 01/2022-12/2024 | 433MHz 407004CB0B | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Twingo | 01/2018-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault | Zoe | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 04/2018-12/2020 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault | Zoe | 01/2014-12/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault Samsung | QM3 | 01/2013-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Renault Samsung | SM3 | 01/2018-12/2020 | 433MHz 407004CB0A | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault Samsung | SM3 | 01/2009-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault Samsung | SM5 | 01/2009-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault Samsung | SM7 | 01/2016-06/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Renault Samsung | SM7 | 01/2012-12/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Retrofit | E-LEAD | 01/2020-12/2020 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | Honda-CRV | 01/2020-12/2021 | 433MHz | | ○ | ● | ○ | S | 433MHz | E-LEAD | ● | ● |
| Retrofit | Honda-fit | 01/2016-12/2021 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Cub | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------------|------------------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Retrofit | ORO W401 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | ORO | ● | ● |
| Retrofit | ORO W410/W403 | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W417 | 01/2015-12/2022 | 433MHz | | ○ | ● | ○ | S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W417-A | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Retrofit | ORO W418-A | 01/2018-06/2019 | 433MHz | | ○ | ● | ○ | A/S | 433MHz | ORO | ● | ● |
| Rivian | EDV | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rivian | R1S | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Rivian | R1T | 01/2022-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| Roewe | MARVEL R | 02/2021-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | RX5 | 08/2022-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | RX5 | 06/2020-12/2022 | 433MHz 10718213 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | RX5 | 01/2019-06/2020 | 433MHz 10290600 | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Roewe | RX8 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Baolong | ● | ● |
| Rolls Royce | Black Badge | 01/2019-06/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Cullinan | 01/2018-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Cullinan | 02/2018-12/2023 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 01/2016-12/2023 | 433MHz | RR6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Dawn | 04/2014-12/2023 | 433MHz 36106790054 | RR6 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 08/2020-06/2024 | 433MHz 36106887147 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Ghost | 01/2020-06/2024 | 433MHz 36106877937 | RR21 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 04/2014-12/2021 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Ghost | 12/2009-03/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2017-06/2024 | 433MHz MRXAG5SP4 | RR11/RR02 | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Rolls Royce | Phantom | 01/2012-12/2017 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 01/2007-12/2022 | 433MHz 36106798872 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom | 02/2003-12/2018 | 433MHz OYGTSSRE4TC | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Phantom Drophead Coupe | 01/2007-12/2018 | 433MHz | RR02 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Spectre | 08/2023-06/2024 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Rolls Royce | Spectre | 08/2023-06/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 05/2013-12/2023 | 433MHz 36106874830 | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Rolls Royce | Wraith | 01/2012-12/2021 | 433MHz 36106790054 | RR5 | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| SGMW | S3 | 01/2018-12/2024 | 433MHz 23576928 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| SGMW | S3 | 01/2018-12/2024 | 433MHz 23984663 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| SGMW | S3 | 01/2018-12/2024 | 433MHz 23548419 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| SWM | G01 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | SAT | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|------------|-----------------|-----------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| SWM | X7 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Mobiletron | ● | ● |
| Saab | 9-3 | 01/2008-12/2013 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-3 | 01/2003-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-4X | 01/2011-12/2012 | 315MHz | | ● | ● | ● | 0 | 315MHz | Schrader | ● | ● |
| Saab | 9-5 | 01/2010-12/2013 | 315MHz | | ● | ● | ● | 0/A | 315MHz | Schrader | ● | ● |
| Saab | 9-5 | 01/2008-12/2012 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-5 | 01/2003-12/2007 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saab | 9-7X | 01/2008-12/2009 | 315MHz | | ● | ● | ● | S | 315MHz | Schrader | ● | ● |
| Saab | 9-7X | 01/2005-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2008-12/2009 | 315MHz Snap in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2010-12/2010 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2007-12/2008 | 315MHz Clamp in | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2020-12/2020 | 433MHz | | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2019-12/2019 | 433MHz | Sedan NB4 | ● | ● | ○ | S | 433MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2010-12/2013 | 433MHz | | ● | ● | ● | 0/S | 433MHz | Schrader | ● | ● |
| Saturn | Astra | 01/2008-12/2009 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Saturn | Aura | 01/2006-12/2008 | 315MHz Snap in | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Aura | 01/2007-12/2008 | 315MHz Clamp in | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Saturn | Aura | 01/2009-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Lambda | 01/2007-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Saturn | Outlook | 01/2009-12/2012 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Outlook | 01/2007-12/2008 | 315MHz | | ○ | ● | ○ | S | 315MHz | Continental | ● | ● |
| Saturn | Sky | 01/2010-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Sky | 01/2009-12/2009 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Saturn | Sky | 01/2006-12/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Continental | ● | ● |
| Saturn | Vue | 11/2008-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Vue | 01/2008-10/2008 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| Saturn | Vue | 01/2007-12/2007 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| Scion | Corolla iM | 01/2015-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | FR-S | 01/2013-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | IQ | 07/2011-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | TC | 08/2010-05/2013 | 315MHz C11A | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | TC | 01/2006-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | TC | 01/2005-05/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Scion | XB | 01/2007-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | XD | 01/2008-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Scion | iA | 01/2015-06/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Scion | iM | 01/2015-05/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Seres | AITO M5 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Seres | AITO M7 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Seres | AITO M9 | 12/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Skoda | Kodiaq | 01/2016-06/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-----------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Skoda | Superb | 05/2015-12/2022 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Skoda | Superb | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Smart | 42 EV | 01/2013-12/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Smart | Forfour | 01/2005-12/2023 | 433MHz | A453 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 01/2008-12/2015 | 433MHz | A451 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Smart | Fortwo | 01/2014-12/2023 | 433MHz | A453 | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Soueast | A5 | 11/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Soueast | DX3 | 01/2016-12/2023 | 433MHz 25M01C031 | | ● | ● | ○ | 0 | 433MHz | TTE | ● | ● |
| Soueast | DX3 | 01/2016-12/2023 | 433MHz 25M01A031 | | ● | ● | ○ | 0 | 433MHz | Whetron | ● | ● |
| Soueast | DX7 | 10/2014-12/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Whetron | ● | ● |
| Soueast | DX7 | 01/2018-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Soueast | DX7 | 01/2014-06/2019 | 433MHz Steel Mate | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Ssangyong | Actyon | 01/2010-12/2014 | 433MHz QJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Actyon Sport | 10/2012-12/2019 | 433MHz | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Korando | 01/2006-12/2023 | 433MHz C200 | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Kyron | 01/2006-12/2016 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Ssangyong | Musso | 01/2023-06/2024 | 433MHz 4199036100 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Ssangyong | Musso | 06/2018-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Rexton | 01/2023-12/2023 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Rexton | 07/2012-12/2022 | 433MHz Y300 | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Ssangyong | Rexton | 01/2006-06/2012 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Huf/Beru | ● | ● |
| Ssangyong | Rodius | 05/2005-12/2022 | 433MHz AJ | | ○ | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Ssangyong | Tivoli | 01/2019-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Torres | 08/2023-12/2024 | 433MHz 4199037000 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Ssangyong | Torres EVX | 02/2024-12/2024 | 433MHz 4199037000 | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Subaru | Ascent | 01/2018-12/2024 | 433MHz | HR3 | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | B9 Tribeca | 11/2004-03/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | BRZ | 11/2011-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Subaru | BRZ | 01/2022-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Subaru | Crosstrek | 01/2015-12/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Crosstrek | 01/2018-12/2024 | 433MHz | HR3 | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2018-12/2024 | 433MHz | FM5/PF3 | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | Forester | 07/2013-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Forester | 01/2007-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 01/2008-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 01/2007-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Impreza | 09/2016-12/2024 | 433MHz | HR3 | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | Impreza | 07/2013-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 05/2017-12/2024 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | Legacy | 01/2019-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|--------------|-----------------|----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Subaru | Legacy | 11/2003-04/2008 | 315MHz 28103AG00B | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 12/2006-06/2013 | 315MHz 28103AG01C | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Legacy | 07/2013-06/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2004-12/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2008-06/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 07/2009-12/2017 | 315MHz 28103AJ00A | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Outback | 01/2018-12/2024 | 433MHz | BS/BT | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | Solterra | 01/2023-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Subaru | Solterra | 06/2022-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Subaru | Tribeca | 08/2013-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | Tribeca | 03/2008-07/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | WRX | 01/2022-12/2023 | 433MHz MRXSHR3 | | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | WRX | 11/2013-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | XV | 03/2017-12/2023 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | XV | 01/2012-12/2017 | 433MHz | MF1 | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 04/2017-12/2020 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 07/2013-06/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Subaru | XV Crosstrek | 04/2012-06/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Suzuki | APV | 01/2014-12/2024 | 433MHz | YC5/YRA | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Suzuki | Alto | 01/2014-06/2015 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Alto | 06/2014-12/2017 | 433MHz | YC5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Baleno | 01/2016-12/2024 | 433MHz | YR | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Celerio | 01/2014-12/2024 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Suzuki | Celerio | 01/2014-12/2024 | 433MHz | YLA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Ciaz | 01/2015-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Equator | 01/2009-12/2013 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | Forenza | 01/2003-12/2011 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | Grand Vitara | 01/2014-12/2024 | 433MHz | YT4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Grand Vitara | 01/2005-12/2014 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | Ignis | 01/2016-01/2021 | 433MHz | YJ | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Ignis | 02/2021-12/2024 | 433MHz | MF | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 01/2014-01/2021 | 433MHz | YR7/YW5 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Jimny | 02/2021-12/2024 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 01/2009-12/2019 | 433MHz | YW1 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Kizashi | 01/2009-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Continental | ● | ● |
| Suzuki | Reno | 01/2007-12/2008 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | S-Cross | 09/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | S-Cross | 01/2013-08/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 | 01/2006-12/2014 | 315MHz | | ● | ● | ○ | 0/S | 315MHz | Schrader | ● | ● |
| Suzuki | SX4 | 01/2013-12/2023 | 433MHz | YY1, YY3 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 09/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | SX4 S-Cross | 01/2013-08/2021 | 433MHz | YAA | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|---------------|-----------------|----------------------|----------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| Suzuki | Super Carry | 01/2019-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Orange | ● | ● |
| Suzuki | Swift | 02/2021-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Swift | 08/2013-01/2021 | 433MHz | YP6/YP7/YS | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Verona | 01/2003-12/2008 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Suzuki | Vitara | 09/2013-01/2021 | 433MHz | YFA/YG4/YH4 | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara | 02/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Suzuki | Vitara Brezza | 01/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Suzuki | Wagon R | 09/2020-12/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| Suzuki | XL-7 | 01/2005-06/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Schrader | ● | ● |
| Suzuki | XL-7 | 07/2006-12/2011 | 315MHz | | ● | ● | ● | 0/S | 315MHz | Schrader | ● | ● |
| TJFAW | Junpai A50 | 01/2018-06/2019 | 433MHz | | ● | ● | ○ | NA | 433MHz | Xiali | ● | ● |
| TJFAW | Junpai CX65 | 01/2018-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| TJFAW | Junpai D60 | 01/2019-12/2019 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Baolong | ● | ● |
| TJFAW | Junpai D60 | 10/2014-12/2020 | 433MHz 42621TFA00 | | ● | ● | ○ | S | 433MHz | Xiali | ● | ● |
| TJFAW | Junpai D60 | 07/2016-12/2017 | 433MHz QY1036 | | ● | ● | ○ | S | 433MHz | Xiali | ● | ● |
| Tesla | Model 3 | 01/2016-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model 3 | 01/2021-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model S | 10/2014-12/2020 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 01/2012-09/2014 | 433MHz | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Model S | 01/2021-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model S | 01/2021-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model X | 01/2021-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Model X | 01/2016-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Tesla | Model Y | 01/2020-12/2024 | 2.4GHz | | ○ | ● | ○ | A | 2.4GHz | Sysgration | ● | ● |
| Tesla | Roadster | 01/2010-12/2012 | 433MHz Baolong | | ○ | ● | ○ | A | 433MHz | Baolong | ● | ● |
| Tesla | Roadster | 01/2008-12/2010 | 433MHz Huf | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | 4 Runner | 08/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 01/2020-12/2024 | 315MHz Clamp in | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 08/2019-12/2024 | 315MHz Snap in | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 09/2006-08/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 08/2003-08/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 4 Runner | 09/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | 86 | 03/2012-12/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Allion | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 01/2021-12/2024 | 433MHz E100 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 01/2020-12/2024 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Alphard | 01/2015-01/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Auris | 01/2019-12/2019 | 315MHz | 130A/130L/142L | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 08/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 03/2019-12/2024 | 433MHz C215 | | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------------|-----------------|------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Avalon | 10/2015-08/2019 | 315MHz C015 | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 10/2012-03/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avalon | 01/2006-10/2012 | 315MHz Japan/USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avalon | 11/2012-12/2015 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Avanza | 08/2022-12/2024 | 433MHz E100 | URJ | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avanza | 09/2016-12/2024 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Avensis | 10/2008-12/2019 | 433MHz C210 | 312N/445L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Aygo | 01/2014-06/2023 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 01/2016-12/2024 | 433MHz | 560A | ● | ● | ○ | 0/A | 433MHz | Pacific | ● | ● |
| Toyota | C-HR | 01/2018-08/2022 | 315MHz 33050 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | C-HR | 10/2016-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | C-HR | 10/2016-12/2019 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2004-12/2005 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Camry | 01/2020-12/2024 | 315MHz Snap in | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 09/2014-12/2024 | 315MHz Clamp in | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 09/2014-06/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 09/2011-07/2020 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 10/2006-03/2021 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry | 01/2006-09/2011 | 315MHz Japan/USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 03/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 09/2017-12/2024 | 433MHz 60010 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Camry Hybrid | 09/2014-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Coaster | 01/2008-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2005-06/2007 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Corolla | 01/2019-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 08/2013-12/2019 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla | 01/2002-08/2013 | 315MHz Japan/USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla Cross | 07/2020-12/2024 | 315MHz Clamp in | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla Cross | 09/2021-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla Hatchback | 06/2018-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla NAP | 06/2007-08/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Corolla iM | 06/2015-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Crown | 12/2022-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Crown | 05/2024-12/2024 | 433MHz G101 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 01/2007-12/2014 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | FJ Cruiser | 06/2014-12/2023 | 433MHz | 155L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | FR-S | 03/2012-06/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | FR-S | 04/2014-06/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Fortuner | 12/2005-12/2023 | 433MHz | 669L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | GR 86 | 10/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-----------------------|-----------------|--------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | GR 86 | 10/2021-12/2024 | 315MHz Snap in | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | GR Supra | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Huf/Beru | ● | ● |
| Toyota | GT86 | 01/2017-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Grand Highlander | 06/2023-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Granvia | 02/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Hiace | 02/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Hiace | 06/2014-12/2024 | 433MHz 4260726030 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander | 12/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Highlander | 01/2021-12/2024 | 433MHz 426070E040 | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Toyota | Highlander | 10/2009-11/2013 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2014-12/2019 | 315MHz Standard Key | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Highlander | 01/2004-12/2006 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Highlander | 05/2007-01/2021 | 315MHz Japan/USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 03/2018-12/2024 | 315MHz Smart Key | | ● | ● | ○ | 0/A | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 12/2013-12/2020 | 315MHz Smart Key C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Highlander | 01/2020-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Highlander hybrids | 12/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Highlander hybrids | 08/2024-06/2025 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Hilux | 01/2015-12/2022 | 433MHz | 669L/640A | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Hilux | 05/2019-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Innova | 01/2014-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 08/2015-12/2024 | 315MHz Pacific C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2020-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 05/2005-08/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 09/2006-09/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 10/2015-12/2024 | 433MHz | 215L/611L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 11/2021-12/2024 | 433MHz 4260726040 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser | 01/2017-01/2021 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 01/2014-09/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Land Cruiser Prado | 10/2017-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Matrix | 01/2002-12/2016 | 315MHz Japan/USA | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Mirai | 06/2015-12/2024 | 315MHz C010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Mirai | 11/2020-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Mirai | 01/2019-12/2024 | 433MHz C215 | 045L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2016-12/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2019-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|--------|-------------|-----------------|--------------------|-------------------------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Toyota | Prius | 05/2014-12/2019 | 433MHz | 590L/030A/XW30/XW50/690A/277N | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2019-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 08/2003-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius | 12/2022-12/2024 | 433MHz G101 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius | 01/2013-12/2015 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius C | 12/2011-12/2023 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius C | 06/2017-12/2023 | 433MHz | 085X/085L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 12/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 01/2020-12/2024 | 315MHz Clamp in | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 09/2016-11/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius Prime | 01/2016-12/2021 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius V | 01/2017-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Prius V | 11/2014-11/2017 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Prius V | 09/2011-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2018-12/2024 | 433MHz | XA50 | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2013-12/2018 | 315MHz Pacific | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 11/2008-08/2014 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 11/2005-12/2012 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2012-12/2023 | 433MHz | 410A/XA40/120L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | RAV4 | 09/2022-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| Toyota | RAV4 | 01/2013-11/2018 | 315MHz TRW | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | RAV4 | 12/2018-12/2021 | 315MHz TRW | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | RAV4 | 10/2019-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | RAV4 | 01/2019-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Raize | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Rush | 01/2018-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sequoia | 02/2010-07/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sequoia | 11/2021-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Sequoia | 08/2017-12/2019 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sequoia | 01/2020-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Sequoia | 01/2008-01/2010 | 315MHz Alloy/Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sequoia | 08/2004-12/2007 | 315MHz Alloy/Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Sienna | 01/2021-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | TRW | ● | ● |
| Toyota | Sienna | 01/2010-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sienna | 01/2021-12/2021 | 433MHz C215 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Sienna | 01/2021-12/2024 | 433MHz 426070E040 | | ● | ● | ○ | 0/A | 433MHz | TRW | ● | ● |
| Toyota | Sienna | 01/2013-02/2016 | 433MHz | | ● | ● | ○ | 0 | 433MHz | TRW | ● | ● |
| Toyota | Sienna | 12/2006-12/2009 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Sienta | 11/2016-12/2023 | 315MHz Pacific | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|---------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Toyota | Solara | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Supra | 03/2019-12/2024 | 315MHz | | ○ | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Toyota | Supra | 03/2019-12/2024 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Toyota | Tacoma | 12/2005-07/2006 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 01/2010-08/2015 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 09/2015-12/2024 | 315MHz C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 01/2020-12/2022 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 08/2005-11/2005 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 08/2006-08/2014 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tacoma | 11/2020-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2007-12/2011 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 01/2007-12/2011 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 11/2006-07/2007 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 08/2004-12/2006 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 08/2004-12/2006 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 08/2004-10/2006 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 08/2017-12/2024 | 315MHz Steel | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 08/2017-12/2024 | 315MHz Alloy | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 01/2012-07/2017 | 315MHz | | ● | ● | ○ | 0 | 315MHz | TRW | ● | ● |
| Toyota | Tundra | 01/2020-12/2024 | 315MHz Steel C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Tundra | 01/2020-12/2022 | 315MHz Alloy C015 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Urban Cruiser | 06/2007-12/2020 | 433MHz | 260L | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 11/2008-12/2016 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Venza | 08/2014-07/2015 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Venza | 01/2020-12/2024 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Vios | 12/2019-12/2022 | 433MHz C210 | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Vios | 01/2012-12/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Yaris | 07/2016-01/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | Yaris | 08/2007-11/2012 | 315MHz 107J | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Yaris | 08/2011-01/2022 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Yaris | 07/2014-07/2019 | 315MHz OD010 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | Yaris GR | 08/2020-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | Yaris Sedan | 01/2020-12/2020 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Huf/Beru | ● | ● |
| Toyota | bZ4X | 03/2022-12/2024 | 315MHz E000 | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Toyota | bZ4X | 03/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Pacific | ● | ● |
| Toyota | iA | 01/2017-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Toyota | iM | 05/2015-05/2018 | 315MHz | | ● | ● | ○ | 0 | 315MHz | Pacific | ● | ● |
| Trumpchi | GA4 | 03/2021-12/2022 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GA4 | 01/2018-02/2021 | 433MHz | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GA4 | 03/2021-12/2022 | 433MHz 8060004BAF0100 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|---------|-----------------|--------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Trumpchi | GA4 | 03/2021-12/2022 | 433MHz 8060004BAF0200 | | ● | ● | ○ | 0 | 433MHz | Baolong | ● | ● |
| Trumpchi | GA5 | 01/2013-12/2017 | 433MHz | | ● | ● | ● | 0 | 433MHz | Schrader | ● | ● |
| Trumpchi | GA8 | 01/2016-03/2020 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 03/2023-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 10/2020-02/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 07/2019-09/2020 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS3 | 08/2017-06/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 07/2019-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 09/2018-06/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 07/2019-12/2022 | 433MHz 8060004BAD0000 | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 09/2018-06/2019 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS4 | 04/2015-08/2018 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS5 | 08/2018-12/2023 | 433MHz | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS7 | 08/2017-12/2020 | 433MHz 8060004CAD0000 | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GS7 | 01/2018-12/2018 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| Trumpchi | GS8 | 07/2019-08/2020 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GS8 | 01/2016-06/2019 | 433MHz | | ● | ● | ● | 0 | 433MHz | Steel Mate | ● | ● |
| Trumpchi | GS8 | 01/2018-06/2019 | 433MHz 8060004BAD0000 | | ● | ● | ● | 0 | 433MHz | Continental | ● | ● |
| VOYAH | Courage | 08/2024-12/2024 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | BHSENS | ● | ● |
| VOYAH | Dreamer | 05/2022-12/2024 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | BHSENS | ● | ● |
| VOYAH | Dreamer | 09/2024-06/2025 | 433MHz 792001003 | | ○ | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| VOYAH | FREE | 06/2021-12/2024 | 433MHz | | ● | ● | ○ | A/0 | 433MHz | BHSENS | ● | ● |
| VOYAH | Passion | 04/2023-12/2024 | 433MHz | | ● | ● | ○ | A | 433MHz | BHSENS | ● | ● |
| VPG | MV-1 | 01/2011-12/2016 | 315MHz | | ○ | ● | ○ | S | 315MHz | Schrader | ● | ● |
| VinFast | VF e34 | 01/2021-12/2024 | 315MHz | | ○ | ● | ○ | NA | 315MHz | BHSENS | ● | ● |
| VinFast | VF8 | 01/2022-12/2024 | 315MHz | | ○ | ● | ○ | NA | 315MHz | BHSENS | ● | ● |
| VinFast | VF9 | 01/2022-12/2024 | 315MHz | | ○ | ● | ○ | NA | 315MHz | BHSENS | ● | ● |
| Volkswagen | Amarok | 01/2023-12/2023 | 433MHz F2GZ1A189B | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Amarok | 11/2009-02/2018 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 01/2014-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Amarok | 03/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Amarok | 01/2023-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Volkswagen | Amarok | 01/2023-12/2024 | 433MHz 2HJ919331G | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Amarok | 01/2024-12/2024 | 433MHz 5Q0907275F | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 06/2020-12/2024 | 315MHz 5Q0907275G | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2017-06/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Arteon | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Atlas | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Atlas | 01/2017-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Atlas | 01/2017-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Beetle | 01/2012-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Beetle | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Bora | 01/2005-12/2010 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Volkswagen | Bora | 01/2005-12/2010 | 315MHz | | ○ | ● | ○ | NA | 315MHz | Continental | ● | ● |
| Volkswagen | CC | 01/2018-06/2023 | 433MHz MQB | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 06/2011-12/2020 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | CC | 01/2009-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Caddy | 11/2020-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 01/2006-12/2016 | 433MHz Continental | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Crafter | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Volkswagen | Crafter | 03/2018-12/2024 | 433MHz 2N0907275A | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Crafter | 07/2014-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | EOS | 01/2006-12/2017 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | GTI | 01/2006-12/2012 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | GTI | 01/2012-12/2023 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2006-12/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Golf | 01/2008-12/2014 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Golf | 01/2009-12/2012 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Golf | 01/2009-12/2023 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Golf | 01/2013-12/2022 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Jetta | 01/2005-12/2014 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Jetta | 01/2013-12/2019 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Jetta | 01/2011-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | New Beetle | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | New Beetle | 01/2012-12/2022 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Passat | 09/2014-12/2023 | 433MHz | B8 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2015-12/2024 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | O/A | 433MHz | BHSENS | ● | ● |
| Volkswagen | Passat | 01/2005-12/2011 | 433MHz | VW451 | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volkswagen | Passat | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | O/A | 315MHz | Continental | ● | ● |
| Volkswagen | Passat | 01/2010-12/2015 | 433MHz | B6/VW471 | ● | ● | ○ | O/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Passat | 01/2012-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|------------|-------------|-----------------|-----------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volkswagen | Passat CC | 01/2009-12/2012 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Passat CC | 03/2008-12/2020 | 433MHz 3AA907275 | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 01/2003-05/2007 | 315MHz | | ● | ● | ○ | A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2007-12/2010 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 06/2007-12/2010 | 315MHz | | ● | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | Phaeton | 01/2003-05/2007 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Phaeton | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Polo | 01/2009-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | R32 | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | R320 | 01/2008-12/2008 | 315MHz | | ○ | ● | ○ | A | 315MHz | Continental | ● | ● |
| Volkswagen | R36 | 01/2009-12/2011 | 433MHz | | ● | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Rabbit | 01/2006-12/2011 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Routan | 01/2009-12/2010 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volkswagen | Routan | 01/2005-12/2008 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Continental | ● | ● |
| Volkswagen | Routan | 01/2011-12/2015 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Sagitar | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Santana | 01/2006-12/2011 | 433MHz | | ○ | ● | ○ | A | 433MHz | Continental | ● | ● |
| Volkswagen | Santana | 09/2014-12/2023 | 433MHz | | ○ | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-Cross | 01/2019-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | T-ROC | 11/2017-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volkswagen | Teramont | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 09/2023-12/2024 | 433MHz 95C907275 | | ● | ● | ○ | 0/A | 433MHz | BHSENS | ● | ● |
| Volkswagen | Tiguan | 01/2016-12/2023 | 433MHz | VW376/5N2 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2016-12/2024 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2012-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Tiguan | 01/2011-12/2021 | Indirect | | ○ | ○ | ○ | S | N/A | N/A | Indirect | ● |
| Volkswagen | Tiguan | 01/2008-12/2011 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Continental | ● | ● |
| Volkswagen | Tiguan L | 01/2016-12/2023 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2012-12/2014 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2007-12/2016 | 315MHz 7PP907275G | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2024-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2015-12/2018 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 08/2014-12/2023 | 433MHz | 7P5/7P6108 | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 01/2007-12/2011 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Touareg | 02/2002-12/2007 | 433MHz | 7L | ● | ● | ○ | A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Transporter | 06/2024-12/2025 | 433MHz PR3T1A180CB | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volkswagen | Transporter | 03/2018-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Variant | 01/2024-06/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Huf/Beru | ● | ● |
| Volkswagen | Vento | 01/2005-12/2014 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2006-12/2010 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | C30 | 01/2006-03/2014 | 433MHz 31445474 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy) | Frequency | Sensor Manufacturer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------|-----------------|--------------------|------------|-----------------|--------------------|------------------------------|---|-----------|---------------------|------------------------------|-------------------------|
| Volvo | C30 | 01/2011-03/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C40 | 01/2021-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | C70 | 01/2006-12/2007 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2008-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2006-12/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | C70 | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | EX30 | 06/2023-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | Schrader | ● | ● |
| Volvo | EX90 | 06/2024-12/2024 | 433MHz | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Volvo | S40 | 01/2003-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2011-12/2014 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S40 | 01/2003-12/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 01/2019-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S60 | 01/2010-12/2019 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 | 01/2001-12/2010 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S60 | 07/2000-02/2010 | 433MHz 31329981 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | S60 | 01/2010-12/2021 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60 Cross Country | 01/2015-12/2019 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S60L | 01/2014-12/2020 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/1999-12/2007 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | S80 | 01/2013-12/2019 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S80 | 01/2010-12/2016 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2007-12/2009 | 433MHz 31302096 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S80 | 01/2006-01/2017 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | S90 | 05/2016-12/2023 | 433MHz 31362304 | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | S90 | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | S90L | 01/2017-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 | 01/2012-12/2021 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V40 Cross Country | 01/2017-12/2021 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V40 Cross Country | 01/2012-12/2017 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2011-12/2012 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2005-12/2010 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V50 | 01/2004-12/2014 | 433MHz 31445474 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |
| Volvo | V60 | 11/2017-12/2024 | 433MHz | | ● | ● | ○ | O/A | 433MHz | Schrader | ● | ● |
| Volvo | V60 | 01/2011-12/2019 | 433MHz 31341893 | | ● | ● | ○ | O/A | 433MHz | Continental | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|-------|-------------------|-----------------|-------------------------|------------|-----------------|--------------------|------------------------------|---|-----------|--------------------|------------------------------|-------------------------|
| Volvo | V60 | 01/2019-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V60 Cross Country | 01/2015-12/2018 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | V60 Cross Country | 01/2019-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V70 | 01/2000-12/2007 | 433MHz 31329981 | | ● | ● | ○ | A | 433MHz | Schrader | ● | ● |
| Volvo | V70 | 01/2007-12/2016 | 433MHz 31445474 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2008-12/2014 | 433MHz 31302096 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | V70 | 01/2000-12/2007 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | V90 | 01/2015-12/2022 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volvo | V90 | 01/2016-12/2023 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | V90 Cross Country | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC40 | 01/2017-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2015-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC60 | 01/2009-12/2010 | 315MHz | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Volvo | XC60 | 01/2008-12/2024 | 433MHz | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC60 | 01/2008-12/2014 | 433MHz 31302096 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2015-12/2017 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC70 | 01/2010-12/2014 | 433MHz 31302096 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2017 | 433MHz 31341893 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2008-12/2009 | 433MHz 31302096 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 315MHz 31200923 | | ● | ● | ○ | A | 315MHz | Schrader | ● | ● |
| Volvo | XC70 | 01/2003-12/2007 | 433MHz 31329981 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 06/2023-12/2024 | 433MHz 32134419 | | ○ | ● | ○ | NA | 433MHz | BHSENS | ● | ● |
| Volvo | XC90 | 01/2016-12/2024 | Indirect | | ○ | ○ | ○ | A | N/A | N/A | Indirect | ● |
| Volvo | XC90 | 01/2015-12/2022 | 433MHz 31362304 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2015-12/2021 | 433MHz 50662193 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2008-12/2008 | 433MHz 31302096 | | ● | ● | ○ | 0/A | 433MHz | Continental | ● | ● |
| Volvo | XC90 | 01/2003-12/2016 | 315MHz 31200923 | | ● | ● | ○ | 0/A | 315MHz | Schrader | ● | ● |
| Volvo | XC90 | 01/2003-12/2016 | 433MHz 31329981 | | ● | ● | ○ | 0/A | 433MHz | Schrader | ● | ● |
| YEMA | BOJUN | 03/2020-12/2023 | 433MHz 3641100XKU00B | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| YEMA | BOJUN | 01/2017-06/2020 | 433MHz XAA3638020 | | ● | ● | ○ | S | 433MHz | YEMA | ● | ● |

| Make | Model | Year Range | Feature | Model code | OBD-II Function | Programming Status | TireType/ Pressure Selection | Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy) | Frequency | Sensor Manufactuer | Support by Autel (MX-Sensor) | Support by Autel (Tool) |
|----------|----------|-----------------|-------------------|------------|-----------------|--------------------|------------------------------|---|-----------|----------------------|------------------------------|-------------------------|
| ZOTYE | T600 | 01/2013-12/2021 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Schrader | ● | ● |
| ZzNissan | MX6 | 01/2015-12/2016 | 433MHz QY1036 | | ○ | ● | ○ | NA | 433MHz | Xiali | ● | ● |
| ZzNissan | rich | 01/2017-12/2019 | 433MHz | | ● | ● | ○ | 0 | 433MHz | HSAE | ● | ● |
| ZzNissan | rich | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| ZzNissan | rich6 | 10/2018-12/2022 | 433MHz HSE6150F | | ● | ● | ○ | 0 | 433MHz | HSAE | ● | ● |
| ZzNissan | rich6 | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| ZzNissan | rich6 | 10/2018-12/2020 | 433MHz HTP1831 | | ● | ● | ○ | 0 | 433MHz | HSAE | ● | ● |
| ZzNissan | rich6 EV | 01/2021-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| ZzNissan | rich7 | 01/2022-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |
| ZzNissan | rich7 | 03/2024-12/2024 | 433MHz 403112ZG1A | | ○ | ● | ○ | NA | 433MHz | Unknown Manufacturer | ● | ● |
| ZzNissan | rich7 EV | 12/2023-12/2024 | 433MHz | | ● | ● | ○ | 0 | 433MHz | Unknown Manufacturer | ● | ● |